

Nacogdoches
Historic Site Survey
and
Preservation
Feasibility Study
1986

Prepared by

Victor & Victor Consultants, Inc.

P.O. Box 26189

Austin, Texas 78755

512-451-3708



1. County Nacogdoches 5. USGS Quad No. _____ Site No. 101
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 106 Church St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 7, Lot 13 Present Use Commercial
 10. Description 2-story brick rectangular commercial structure with flat roof; segmented arches and replacement aluminum windows at second floor; wood and glass panel entry doors; inset panels and corbeled cornice; new sheet metal awning shared with buildings to the north.

11. Present Condition Fair
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 2-story brick with awning, occupied as furniture storage and connected with 2-story frame structure (site #169).
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	7	to 7	7
Other					to	
					to	

Continuation sheet

Sp Coll
 F
 344
 .N32
 N26
 1986x
 v.B

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 102

City/Rural Nacogdoches UTM Sector _____

2. Name Gallery 107 6. Date: Factual _____ Est. 1900

Address 107 Church St. South 7. Architect/Builder _____

3. Owner Reese Kennedy Contractor _____

Address _____ 8. Style/Type Victorian Commercial

4. Block/Lot City Block 16, Lot 7 9. Original Use Commercial

Present Use Commercial

10. Description 3-story rectangular brick commercial structure with gable sheet metal roof; exterior stuccoed; brick chimney at southeast corner; 6/6 double-hung windows with segmental arches.

11. Present Condition Fair; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as a 2-story brick with basement and 2-story frame addition on north side; used a shoe repair, warehouse, and laundry.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975; Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	6	to 7	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 103

City/Rural Nacogdoches UTM Sector _____

2. Name Bartol & Perley Investigators 6. Date: Factual _____ Est. 1900

Address 108 Church St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

9. Original Use Commercial

4. Block/Lot City Block 7, Lot 12 Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; inset panels on stuccoed facade; sheet metal awning shared with neighboring buildings; wood and plate glass windows and wood and glass paneled entry doors flanked by blind turned posts.

11. Present Condition Fair

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as a 1-story brick with frame awning; used as a print shop with electric motor; a gasoline engine was not in use.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	8	to	7	8
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 104

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 110 - 118 Church St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot City Block 7, Lots 10, 11, & 11-A Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; tile coping; metal awning on southern part; stepped parapet; wooden awning on northern part; lights above awnings closed off on most fronts or hidden by sheet metal awnings; some 12-light entry doors; 1 plate glass windows; 118 N. Church is 2-story with stepped parapet; flat roof; windows and doors replaced with aluminum units; front closed off with board and batten; entry to 118 has fluted pilasters and molded cornice.

11. Present Condition Fair

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning, used as garage/auto repair, feed warehouse, and black restaurant.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		7	9	to	7	9
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 105

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890

Address 113 Church St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 8, Lot 7 9. Original Use Commercial

Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; chamfered corner entrance with replacement wood door; segmental arches over closed windows and door openings; projecting header course; corbeled dentils, and sawtooth motif at cornice; old steel and sheet metal curved awning wraps two sides of building; sheet metal shed-roof addition on west wall.

11. Present Condition Fair; some alterations.

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning wrapping around south and east facade; used as veterinary hospital and feed warehouse;

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	10	to 7	10
Other					to	
					to	

Continuation sheet

12. adjacent to large stable on north side.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 106
 City/Rural Nacogdoches UTM Sector _____
 2. Name La Merle K. Hunt Building 6. Date: Factual 1958 Est. _____
 Address 122 Church St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 7, Lot 9 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; metal double-hung windows and plate glass doors; inset entry with plate glass windows.

11. Present Condition Good
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as two parts, 1-story and 2-story brick buildings; the 1-story portion was vacant, roof destroyed by fire; the 2-story portion was a
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	11	to 7	11
Other					to	
					to	

Continuation sheet
 12. black barber shop and clothes presser.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 107

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 134 Church St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Chalet

4. Block/Lot City Block 7, Lot 1-A Present Use Commercial - Antique Shop

10. Description 1-story brick residential structure, rectangular plan, with gable composition shingle roof; steeply pitched roof over projecting bay; brick fireplace chimney on north wall; small 6/6 double-hung windows; wood entry door with six small lights, off-center.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides

/Thematic /Multiple-Resource _____ 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	12	to	7	12
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 108

City/Rural Nacogdoches UTM Sector _____

2. Name Jones Square Offices 6. Date: Factual _____ Est. 1890

Address 141 Church St. North 7. Architect/Builder Diedrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Queen Anne/Eastlake

4. Block/Lot City Block 8, Lot 8 Present Use Offices/Antique Shop

10. Description 2-1/2 story irregular plan frame residential structure with hipped composition shingle roof; hexagonal tower on northeast corner; two-story porch is heavily ornamented on the Eastlake style with extensive use of balls and spindles, turned posts, shouldered depressed arch brackets, friezes, half-moon bay dividing front steps, ornamented overdoors and brackets; clapboard siding; butt-cut and houndstooth shingles on gable ends; dormers have gable roof and sawn bargeboards; large brick interior chimney; pent skirts, shingles, between stories

11. Present Condition Good; recently renovated and painted; trees south of house removed for parking lot.

12. Significance RTHL; excellent example of style in East Texas; shown on the 1912 Sanborn Fire Insurance Map as a 2-story frame residence with 3-story tower; large frame out-building at

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1980; Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	13	to 7	13
Other					to	
					to	

Continuation sheet

10. on tower; projecting bay on south facade has chamfered bay at first level, curved bay with curved 1/1 double-hung windows at second; 1/1 double-hung windows, some Queen Anne; tall 1/1 double-hung windows open onto second floor porch; one circular window on first floor porch; north facade has projecting circular bay at first level, chamfered bay above. 12. southwest corner of lot; removal of trees on south side isolates structure amid parking lots and reduces the once residential character of the structure.

1. County Nacogdoches 5. USGS Quad No. Site No. 109

City/Rural Nacogdoches UTM Sector

2. Name ETEX Blind Co. 6. Date: Factual Est. 1900

Address 305 Commerce St. East 7. Architect/Builder

3. Owner Contractor

Address 8. Style/Type Victorian Commercial

4. Block/Lot City Block 8, Lot 3 9. Original Use Commercial

Present Use Commercial

10. Description 2-story rectangular brick commercial structure with flat roof; 4/4 double-hung windows set in openings with segmental arches outlined at second level by projecting headers laid in stilted arches connected by a double header course; arched entry has wood and glass panel double door; corbeled string courses at cornice; fan-shaped pediment at roof line over entry is flanked by stopped pilasters capped with curved brick finials.

11. Present Condition Good; some windows are blocked in; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with wraparound frame awning; freight elevator at rear; used as dry goods warehouse; partition on first floor only.

13. Relationship to Site: Moved Date Original Site XX

14. Bibliography ThC Survey, 1975; Sanborn Fire Insurance Map, 1912.

15. Informant

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. Old THC Code

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

Table with columns: NR File Name, YEAR, DRWR, ROLL, FRME, ROLL, FRME. Includes rows for 'Other' and a grid for photo data.

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 110

City/Rural Nacogdoches UTM Sector _____

2. Name Cason Monk #1 6. Date: Factual _____ Est. 1900

Address 307 Commerce St. East (Just east of 305 Commerce St. East) 7. Architect/Builder _____ Contractor _____

3. Owner _____ 8. Style/Type Commercial

Address _____ 9. Original Use Commercial

4. Block/Lot City Block 8, Lot 4 Present Use Commercial

10. Description 1-1/2 story rectangular brick commercial structure with flat roof; corbeled cornice; two large entries, one with double wood doors with three 1/1 double-hung windows above, one with double glass paneled doors with 4/4 fixed glass above; segmental arches; old style steel and sheet metal curved awning.

11. Present Condition Fair

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as hardware warehouse.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	4	to 7	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 111

City/Rural Nacogdoches UTM Sector _____

2. Name Cason Monk 6. Date: Factual _____ Est. 1900

Address 309 Commerce St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 8, Lots 5 and 6 9. Original Use Commercial

Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; tile coping; metal and plate glass doors and windows; structure appears to be infill between buildings to its east and west; openings (closed) to east of entrance, and type of brick, match building to the west; flat metal awning on west side; old steel and sheet metal curved awning on east side.

11. Present Condition Good

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as hardware and implements warehouse.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	5	to 7	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 112
 City/Rural Nacogdoches UTM Sector _____
 2. Name Muckleroy Building 6. Date: Factual _____ Est. 1950
 Address 115 Fredonia St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Office
 4. Block/Lot City Block 9, Lot 6 Present Use Office
 10. Description 2-story rectangular brick commercial structure with flat roof; metal casement windows; flat roof over walkway supported by square metal posts.

11. Present Condition Good
 12. Significance The 1912 Sanborn Fire Insurance Map shows there was a 2-story brick structure with frame awning at this site.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 6 21 to 6 21
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 113

City/Rural Nacogdoches UTM Sector _____

2. Name Milam Lodge #2, Masonic Hall 6. Date: Factual _____ Est. 1931

Address 129 Fredonia St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot City Block 9, Lot 5-B Present Use Fraternal/Social

10. Description 2-story ell-shaped brick structure with flat roof; tile coping; altered entry of metal and plate glass doors and windows protected by modern metal awning; second story has three arched windows with 15-light operating sashes, keyed arches, compound architrave separated by fluted pilasters; cast stone molding below cornice; stone panels with Masonic emblems above molding read, left to right, "1837," "Milam Lodge No. 2," and "1931."

11. Present Condition Good

12. Significance The 1912 Sanborn Fire Insurance Map shows a 2-story brick structure with frame awning; BPOE Lodge and second floor warehouse and print shop on first floor; this structure may

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally S. Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	22	to 6	22
Other					to	
					to	

Continuation sheet

12. been built in 1931 as indicated on cast stone ornamentation.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 114
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Abstract & Title Company 6. Date: Factual _____ Est. 1980
 Address 135 Fredonia St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Office
 4. Block/Lot City Block 9, Lot 4 Present Use Office
 10. Description 3-story rectangular brick commercial structure with flat roof; inset entry and second floor above with tinted plate glass windows.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	23	to 6	23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 115

City/Rural Nacogdoches UTM Sector _____

2. Name Fredonia Inn 6. Date: Factual 1952 Est. _____

Address 200 Fredonia St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot _____ 9. Original Use Hotel

Present Use Vacant

10. Description 6-story brick tower with flat roof surrounded by irregular plan one-story wings; porte cochere off lobby; symmetrical window arrangement of 1/1 panel flanking large center panel; extensive use of cast aluminum columns.

11. Present Condition Good; plans to rehabilitate are on-going.

12. Significance Constructed by Arthur Temple and local citizens as hospitality center; closed due to poor management and high debts; may be rehabilitated in the next few years.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	2	to 7	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 116

City/Rural Nacogdoches UTM Sector _____

2. Name Wardlaw's 6. Date: Factual _____ Est. 1960

Address 114 Hospital St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Modern

4. Block/Lot City Block 1, Lot 43-A 9. Original Use Commercial

Present Use Commercial

10. Description 1-1/2 story rectangular brick and cement block commercial structure; sheet metal gable roof; metal awning over plate glass and metal windows and doors.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	13	to 8	13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 117
 City/Rural Nacogdoches UTM Sector _____
 2. Name Metal Building 6. Date: Factual _____ Est. 1980
 Address 100 Hospital St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 1, Lot 42 Present Use Commercial
 10. Description 1-story rectangular sheet metal building with flat roof, fixed windows and plate glass doors.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	14	to 8	14
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 118

City/Rural Nacogdoches UTM Sector _____

2. Name All Parts 6. Date: Factual _____ Est. 1930

Address 146 Hospital St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Modern

4. Block/Lot City Block 1, Lot 41-A 9. Original Use Commercial

Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; stepped parapet with tile coping on sides; front of building has applied board and batten siding and cedar shake awning supported by iron posts; plate glass doors and display windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		8	16	to	8	16
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 119

City/Rural Nacogdoches UTM Sector _____

2. Name Central Appraisal District 6. Date: Factual _____ Est. 1960

Address 216 Hospital St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 1, Lot 41-B 9. Original Use Commercial

Present Use Commercial

10. Description 1-story rectangular masonry commercial structure with flat roof; metal awning over plate glass doors and windows.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		8	15	to	8	15
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 120
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mize Department Store 6. Date: Factual _____ Est. 1965
 Address 108 Hospital St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 10, Lot 1-A Present Use Commercial - Retail
 10. Description 1-1/2 story and 1-story rectangular brick commercial structure with flat roof; metal and plate glass doors and windows; covered walkway is continuous with that of Superior Savings (118 E. Hospital).

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	3	to 8	3
Other _____					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 121
 City/Rural Nacogdoches UTM Sector _____
 2. Name Superior Savings 6. Date: Factual _____ Est. 1965
 Address 118 Hospital St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 10, Lot 3 Present Use Commercial

10. Description 4-story rectangular glass masonry and metal commercial structure with flat roof; vertical metal members separate casement windows from fixed glass panels; horizontal bands of colored metal separate floors; masonry columns support a port cochere and covered drive-in, windows, and entry.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		8	2	to 8	2
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 122

City/Rural Nacogdoches UTM Sector _____

2. Name First United Methodist Church 6. Date: Factual _____ Est. _____

Address 201 Hospital St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Classical Revival

4. Block/Lot City Block 2, Lots 33 and 36 9. Original Use Church

Present Use Church

10. Description 2-story irregular plan brick church with gable slate roof; chapel has bell tower and steeple, pedimented portico with fluted Ionic columns, dentils at cornice, garlands and cartouche in tympanum; wood panel entry doors are set in monumental blind arch with carved stone sunburst above, flanked by blind arches; arched stained glass window in bell tower at lower level with carved stone sunburst above; bell tower has setbacks below wooden steeple with fluted pilasters at corners and arched windows upper portions of steeple are octagonal;

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	12	to 8	12
Other					to	
					to	

Continuation sheet

10. classroom buildings to east of chapel have 8/8 double-hung windows at second level and arched windows at first level; keyed semi-circular arches surround windows.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 123
 City/Rural Nacogdoches UTM Sector _____
 2. Name Trailways Bus Station 6. Date: Factual _____ Est. 1960
 Address 310 Hospital St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use _____
 4. Block/Lot City Block 8, Lot 2 Present Use Bus Station
 10. Description 1-story rectangular brick commercial structure with flat roof; plate glass windows and doors; iron columns with filigree.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	24	to	7 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 124

City/Rural Nacogdoches UTM Sector _____

2. Name Accessory Shop 6. Date: Factual _____ Est. 1880

Address 400 Hospital St. East 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Greek Revival

Address _____ 9. Original Use Residence

4. Block/Lot City Block 7, Lot 1-B Present Use Commercial

10. Description 1-story rectangular frame residential structure with composition shingle gable roof; flat roof addition to rear; horizontal clapboard siding; 9/6 double-hung windows; hall parlor plan with raised panel entry doors off wood porch with battered box columns; replacement front windows of multipane fixed glass; corbeled brick chimney.

11. Present Condition Fair; windows altered on main facade.

12. Significance Said to have been the Episcopal Church Rectory; may be older than 1880.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	22	to	7	22
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 125

City/Rural Nacogdoches UTM Sector _____

2. Name Grogan Cleaners 6. Date: Factual _____ Est. 1950

Address 403 - 411 Hospital St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Modern

4. Block/Lot City Block 3, Lot 17 9. Original Use Commercial

Present Use Commercial

10. Description 1-story rectangular textured brick commercial structure with sheet metal awning; flat roof; plate glass windows and doors.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	23	to	7	23
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 126

City/Rural Nacogdoches UTM Sector _____

2. Name Courtesy Travel 6. Date: Factual _____ Est. 1970

Address 404 Hospital St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Modern

4. Block/Lot _____ 9. Original Use Commercial

City Block 7, Lot 1-C Present Use Commercial

10. Description 1-story rectangular brick commercial structure with stone veneer front, flat roof; sheet metal awning; metal and plate glass entry door and side windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		7	21	to 7	21
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 127
 City/Rural Nacogdoches UTM Sector _____
 2. Name Dr. Leon F. Taylor, DDS 6. Date: Factual _____ Est. 1940
 Address 406 Hospital St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 7, Lot 1 Present Use Commercial
 10. Description 1-story brick rectangular commercial structure with flat roof; tile coping; metal windows; plate glass door.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	20	to 7	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 128

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 422 Hospital St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neoclassical

4. Block/Lot City Block 7, Lot 3-A Present Use Residence

10. Description 1-story frame residential structure, rectangular, with composition shingle hip roof; pedimented gable with brackets over wood porch with box columns and plain balusters; horizontal bull-nosed siding; 1/1 double-hung windows; glass and wood panel entry door.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	19	to	7	19
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 129
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches County Courthouse 6. Date: Factual _____ Est. 1950s
 Address 101 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner Nacogdoches County 8. Style/Type _____
 Address 101 Main St. West 9. Original Use Courthouse
 4. Block/Lot Block 12, Lot 8 Present Use Courthouse

10. Description 1-story masonry structure with carved limestone trim, modern brick; limestone segmental arches; 1-story arcade runs across three-fourths of the north facade; ell plan with projecting wing on west facade; 1-story basement; gable composition roof with blind pilasters at corners; 1 brick chimney, central; windows are 6/6 double-hung and casement.

11. Present Condition Excellent; remodeled in 1984.

12. Significance Three courthouses on this site; has 1976 marker honoring El Camino Real, placed by Texas Society, National Society Colonial Dames; marker for 1912 Nacogdoches

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	/RTHL	/HABS (no.) TEX-	PHOTO DATA			
NR:	/Individual	/Historic District	B&W 4 x 5s	slides		
	/Thematic	/Multiple-Resource	35 mm Negs.			
NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	11	to 3	12
Other					to	
					to	

Continuation sheet

12. Courthouse and 1964 RTHL honoring Spanish Cemetery at this site, Antonio Gil Y'barbo buried on this site.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 130

City/Rural Nacogdoches UTM Sector _____

2. Name Cane River Pecans & Watson Upholstery 6. Date: Factual _____ Est. 1930-40s

Address 117 - 119 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot Block 12, Lot 5-A Present Use Commercial

10. Description 1-story masonry structure with rectangular plan; flat roof; aluminum and glass storefront windows; tile and frame projecting awning; 8 bays; 2 overhead doors; awning windows have been painted and filled in.

11. Present Condition Fair

12. Significance Has architectural merit.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s slides _____
 Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1985		3	13	to	3	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 131
 City/Rural Nacogdoches UTM Sector _____
 2. Name Auto Warehouse 6. Date: Factual _____ Est. 1920-30s
 Address 203 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 12, Lot 5-B Present Use Commercial
 10. Description 1-1/2 story masonry structure; three bays with glass block awning windows and steel and glass storefront with small depending awning; decorative brickwork and cornice with central bay raised and articulated by blind pilasters.

11. Present Condition Good
 12. Significance Has architectural merit.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1985		3	14	to 3	14
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 132
 City/Rural Nacogdoches UTM Sector _____
 2. Name U. S. Post Office 6. Date: Factual _____ Est. 1960-70s
 Address 204 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Post Office
 4. Block/Lot Block 11, Lots 3 and 4 Present Use Post Office
 10. Description 1-story masonry structure with glass and aluminum storefront windows; parking lot in front of building.

11. Present Condition Good

12. Significance The post office is still a central and important communication center for the downtown area.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	15	to 3	15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 133
 City/Rural Nacogdoches UTM Sector _____
 2. Name Abundant Life Church 6. Date: Factual _____ Est. 1920s
 Address 331 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 12, Lot 1 Present Use Church
 10. Description 1-1/2 story masonry; 3 bays; flat roof; rectangular plan; decorative brickwork on cornice and inset panels; painted cream and brown; windows are 1/1, 3/1, 6/1 double-hung with lintels; loading dock covered by depending frame awning on east facade.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	20	to 3	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 134

City/Rural Nacogdoches UTM Sector _____

2. Name G I Surplus 6. Date: Factual _____ Est. 1920s

Address 315 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot Block 12, Part of Lot 3-A 9. Original Use Commercial

Present Use Commercial

10. Description 1-story masonry brick and clay tile block; rectangular plan; 3 bays with depending awning below frosted awning windows; decorative brickwork on cornice defined by two columns on either side; inset panel above awnings; flat roof.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	17	to 3	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 135
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Police Station 6. Date: Factual _____ Est. 1970-80s
 Address 312 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner City Of Nacogdoches 8. Style/Type Modern
 Address P.O. Box 648, Nacogdoches, TX 75963 9. Original Use Office
 4. Block/Lot Block 11, Lots 1 and 2 Present Use Police Station
 10. Description 1-story masonry, stucco, and aggregate-faced masonry panels; 12 bays on ell plan; aluminum and glass doorway and awning; parking lot in front of building.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1985 _____ 3 16 to 3 16
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 136
 City/Rural Nacogdoches UTM Sector _____
 2. Name Super Gym 6. Date: Factual _____ Est. 1930-40s
 Address 321 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 12, Part of Lots 1-A and 2 Present Use Commercial
 10. Description 2-story masonry; rectangular plan; 3 bays are actually two different structures; decorative brickwork on cornice and inset panels; colonized entryways and multiple paned windows.

11. Present Condition Fair; entries have been altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	18	to 3	18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 137
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1950-1960
 Address 416 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 43 Present Use Unknown
 10. Description 1-story masonry and stucco; rectangular plan; flat roof; three large plate glass windows and 2 doors across south facade.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	24	to 30	24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 138
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nocogdoches Automatic Gas Company 6. Date: Factual _____ Est. 1940s
 Address 422 - 424 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 43 Present Use Commercial
 10. Description 1-story masonry block; rectangular plan; triple string course rear cornice; 4 bays articulated by modest blind pilasters; windows and doors are steel and glass storefront; parking in front of building.

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 31 2 to 31 2
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 139

City/Rural Nacogdoches UTM Sector _____

2. Name Southern Pacific Railroad Station Depot 6. Date: Factual _____ Est. 1900-1910

Address 500 Main St. West 7. Architect/Builder _____

3. Owner Southern Pacific Railroad Contractor _____

Address _____ 8. Style/Type Victorian

9. Original Use Railroad Station

4. Block/Lot Block 44, Lot 43 Present Use Railroad Station

10. Description 1-1/2 story passenger station on cross plan; masonry construction with Spanish tile hip-and-gable roof; pierced by 2 corbeled chimneys and brick gable with decorative brickwork; octagonal turret capped by finial on west facade; deep overhang with decorative black iron brackets; windows are 1/1; doors are paneled; painted green since 1975.

11. Present Condition Fair; few alterations.

12. Significance Passenger station on main Southern Pacific Railroad line; very similar to passenger station in Lufkin, which was demolished.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1985		3	19	to	3 22
	1986		31	4	to	31 4
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 140
 City/Rural Nacogdoches UTM Sector _____
 2. Name Johnson Furniture Company #1 6. Date: Factual _____ Est. 1900
 Address 106 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 1 Present Use Commercial
 10. Description 1-story rectangular masonry commercial structure, stuccoed, with flat roof; cast iron columns; metal and glass doors and plate glass windows; heavily altered.

11. Present Condition Fair
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning with barber shop on one side and vacant on other side; later labeled as "Mahdeen" on west side
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 6 _____ 11 to 6 11
 Other _____ to _____
 _____ to _____

Continuation sheet

12. and hair tonic facility on east side.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 141

City/Rural Nacogdoches UTM Sector _____

2. Name Johnson Furniture Company #2 6. Date: Factual _____ Est. 1900

Address 106 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Commercial

4. Block/Lot City Block 13, Lot 2 9. Original Use Commercial

Present Use Commercial

10. Description 1-1/2 story rectangular masonry commercial structure with stepped parapet and flat roof; cast iron columns; recessed glass entry door and plate glass windows; stuccoed second story shows signs of corbeled cornice; pilasters.

11. Present Condition Fair

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; frame shed at rear is tin clad; grocery on west half, tin shop on east half.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	10	to 6	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 142

City/Rural Nacogdoches UTM Sector _____

2. Name Johnson Furniture Company #3 6. Date: Factual _____ Est. 1900

Address 106 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 13, Lots 3 and 4 9. Original Use Commercial

Present Use Commercial

10. Description 1-1/2 story masonry rectangular commercial structure with flat roof; applied metal siding at level 2; plate glass and terrazzo with glass entry doors at level 1.

11. Present Condition Good

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning, rear is tin clad; used as express office on east, bacon & lard warehouse on west.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	9	to	6 9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 143
 City/Rural Nacogdoches UTM Sector _____
 2. Name Triad Typewriter 6. Date: Factual _____ Est. 1913-1920
 Address 112 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Commercial/Fraternal Hall
 4. Block/Lot City Block 13, Lot 5 Present Use Commercial
 10. Description 2-story rectangular brick commercial structure with stepped facade and flat roof; inset entry with glass panel doors and sidelights; transoms over all; ribbon lights above awning; 2/2 double-hung replacement windows at level 2; decorative stone molding surrounds windows and panels at level 2.

11. Present Condition Good; few alterations.
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning, tin cladding on rear and west sides; does not touch side of site #149; used for hay and feed
 13. Relationship to Site: Moved Date _____ Original Site XX
 14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.
 15. Informant Mr. Shaw (across street)
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	8	to 6	8
Other					to	
					to	

Continuation sheet
 12. storage; current building probably constructed after 1912.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 144
 City/Rural Nacogdoches UTM Sector _____
 2. Name Johnson Furniture Company #4 6. Date: Factual _____ Est. 1910
 Address 111 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 10, Lots 8 & 9 Present Use Commercial
 10. Description 1-story; rectangular brick commercial structure with flat roof; 2-bay with plate glass windows and door; metal awning; sidewalk on north side marked "Jinkins Bros. Groceries".

11. Present Condition Good; some alterations.
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; tin cladding on west and north walls; used as grocery and meat market.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		4	7	to	4	7
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 145
 City/Rural Nacogdoches UTM Sector _____
 2. Name Costumes Props, Etc. 6. Date: Factual _____ Est. 1910
 Address 113 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 10, Lot 10 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with inset metal and plate glass entry; stepped parapet with tile coping; corbeled brick dentils at cornice; boarded-up lights above wood awning.

11. Present Condition Good; few alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as dry goods store.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	8	to 4	8
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 146

City/Rural Nacogdoches UTM Sector _____

2. Name Shaw's 6. Date: Factual _____ Est. 1910

Address 115 - 117 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 10, Lot 11 Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; 2-bay with plate glass display windows flanking glass panel entry doors with transoms; ribbon windows above new metal awning; facade is decorated with brick dentils and raised brick panel above awning; glazed tile below.

11. Present Condition Fair; few alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; wooden post supports down center of structure on interior; intact display area and front facade in

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant Mr. Shaw

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL _____ /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	9	to 4	9
Other					to	
					to	

Continuation sheet

12. very good condition; good example of style; used in 1912 as grocery.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 147

City/Rural Nacogdoches UTM Sector _____

2. Name Milford's Barber Shop/Wharton Telephone 6. Date: Factual _____ Est. 1910

Address 119 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

9. Original Use Commercial

4. Block/Lot City Block 10, Lot 12 Present Use Commercial

10. Description 1-story rectangular commercial structure with flat roof; 3-bay with unsigned cast iron columns; decorative brickwork above wood awning uses inset panels, string, and header courses, and sawtooth motif; plate glass windows and doors at entry level.

11. Present Condition Fair

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; tin cladding on rear; used for moving pictures, stage and scenery at rear.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____

1986		4	10	to	4	10
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 148

City/Rural Nacogdoches UTM Sector _____

2. Name Branch Patton Hardware 6. Date: Factual _____ Est. 1888

Address 123 Main St. East 7. Architect/Builder John H. Cox

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Commercial

4. Block/Lot City Block 10, Lot 7 9. Original Use Commercial

Present Use Commercial

10. Description 2-story rectangular commercial structure with flat roof; chamfered corner with plate glass doors; windows at second level are 2/4 double-hung with arched two-light panel above; segmental arches are outlined with protruding header course; decorative bands at cornice utilize protruding headers and sawtooth motifs; front facade has been stuccoed; side entry has fan light; awning anchors along side; 1888 on door sill.

11. Present Condition Fair; stucco facade added in 1930s; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning wrapping around west and south facades, chamfered corner entry; used for hardware and buggies;

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	11	to 4	11
Other					to	
					to	

Continuation sheet

12. warehouse on second floor; connected to site #226 by frame section with freight elevator; built by John H. Cox in 1888 as a hardware store; second floor used as funeral parlour; in 1930s Cox moved into Judge Blount's home on North Mound St.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 149
 City/Rural Nacogdoches UTM Sector _____
 2. Name Madeline's Country Corner 6. Date: Factual _____ Est. 1890s
 Address 124 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 9 Present Use Commercial

10. Description 2-story rectangular brick commercial structure, stuccoed, with flat roof; chamfered corner has metal and plate glass entry doors, metal and plate glass windows on ground floor; 1/1 double-hung windows at second level; pronounced banding between first and second stories; inset panels below cornice; cast iron columns visible on north facade at side entry.

11. Present Condition Fair; some alterations.
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning wrapping around west and south facades; chamfered entry; first floor used by barber and cobbler,
 13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	7	to 6	7
Other					to	
					to	

Continuation sheet
 12. Western Union Telegraph office; was once Wettermark State Bank.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 150

City/Rural Nacogdoches UTM Sector _____

2. Name Kennedy's Jewelry, Etc. 6. Date: Factual _____ Est. 1900

Address 201 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 9, Lots 11 and 12 9. Original Use Commercial

Present Use Commercial

10. Description 2-story brick commercial structure with flat roof; "Weeks" and "Hardeman" on parapet; 2-bays with inset plate glass entry and display windows; metal awnings; decorative brickwork uses protruding stretchers; corbeled pressed tin cornice; 2/1 double-hung windows at second level, some with cast concrete lintels and some with segmental brick arches.

11. Present Condition Good

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning; used as drugs and jewelry on west, dry goods on east; east side had ironclad enclosure on second

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	12	to 4	12
Other					to	
					to	

Continuation sheet
12. floor.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 151
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Public Library 6. Date: Factual 1917 Est. _____
 Address 206 Main St. East 7. Architect/Builder James Wetmore, (cont'd)
 Contractor _____
 3. Owner _____ 8. Style/Type Federal
 Address _____ 9. Original Use Post Office
 4. Block/Lot City Block 14, Lot 1 Present Use Library
 10. Description 1-story brick masonry structure with header course; cast concrete lintels and window surrounds; 6/9 double-hung windows; replacement plate glass entry door; arched openings over entry door and flanking windows have carved stone insets.

11. Present Condition Excellent
 12. Significance Site of Public Square unit 1917 construction of this building; excellent example of style imported for federal buildings; designed in Washington, D.C.; degree of ornamentation
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	6	to 6	6
Other					to	
					to	

Continuation sheet

7. Acting based Supervising Architect; Wayne Pope, Renovation Architect. 12. on dollar sales at this post office.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 152
 City/Rural Nacogdoches UTM Sector _____
 2. Name Boyett's Jewelry 6. Date: Factual _____ Est. 1900
 Address 207 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 9, Lot 13 Present Use Vacant
 10. Description 2-story rectangular brick commercial structure with flat roof; 1-bay plate glass entry with display windows; metal awning; 3 plate glass replacement windows at second level; cast concrete lintels; decorative inset panels have protruding header course below and corbeled dentils above; tile coping.

11. Present Condition Good
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with 2-story awning or gallery on west side; used as grocery on west side, dry goods on east side, Knights of
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		4	13	to	4 13
					to	
					to	

Continuation sheet
 12. Pythias Lodge on second floor.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 153

City/Rural Nacogdoches UTM Sector _____

2. Name Colony Mall 6. Date: Factual _____ Est. 1900

Address 209 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Commercial

4. Block/Lot City Block 9, Lot 14 9. Original Use Commercial

Present Use Commercial/Boutique Mall

10. Description 2-story brick rectangular commercial structure with flat roof; single bay has recessed wood and glass entry doors flanked by plate glass windows; fixed lights above awning; 1/1 double-hung windows at second level have limestone lintels; decorative brickwork on facade uses protruding headers and stretchers and corbeled dentils; interior of second floor is supported by independent steel frame structure not attached to walls.

11. Present Condition Good; gutted by fire in 1984; renovated 1984-85.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	14	to 4	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 154
 City/Rural Nacogdoches UTM Sector _____
 2. Name Commercial National Bank 6. Date: Factual _____ Est. 1930-50
 Address 215 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Romanesque
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 9, Lots 15-A and 17 Present Use Bank
 10. Description 2-story rectangular brick commercial structure with flat roof; 3-bay with colossal romaneseque arches framing entry and windows; cast stone pilasters are separated by blind arches; case stone cornice; large stagecoach lamp-style light.

11. Present Condition Excellent; west section gutted by fire in 1984 and reconstructed.
 12. Significance Site of Old Stone Fort; RTHL marker for Old Stone Fort and granite marker for Old San Antonio Road by the Daughters of the American Revolution.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge; Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	15	to	4
Other					to	15
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 155
 City/Rural Nacogdoches UTM Sector _____
 2. Name Stone Fort National Bank 6. Date: Factual _____ Est. _____
 Address 300 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Modern Commercial
 4. Block/Lot City Block 15, Lots 1-5 Present Use Bank
 10. Description 1-1/2 story and 2-story rectangular rock veneer commercial structure with flat roof; plate glass windows and doors.

11. Present Condition Excellent
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	5	to	6 5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 157

City/Rural Nacogdoches UTM Sector _____

2. Name J. B. White Company 6. Date: Factual 1908 Est. _____

Address 311 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 8, Lot 10 9. Original Use Commercial

Present Use Retail Clothing

10. Description 2-story rectangular masonry structure with flat roof; stuccoed facade with metal awning; first floor has metal and plate glass windows and doors; second level has 1/1 double-hung windows with decorative band above; stepped parapet is marked "1908".

11. Present Condition Good; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning, second floor is iron clad; used as dry goods store.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	17	to 4	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 158

City/Rural Nacogdoches UTM Sector _____

2. Name Schmidt's 6. Date: Factual _____ Est. 1910

Address 316 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 15, Lots 6 and 7 9. Original Use Commercial

Present Use Commercial

10. Description 1-1/2 story rectangular brick commercial structure with flat roof; metal and plate glass doors and display windows are topped by reflective glass at level 2.

11. Present Condition Excellent

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awnings; used as harness shop.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		6	4	to 6	4
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 159
 City/Rural Nacogdoches UTM Sector _____
 2. Name Cason, Monk & Co. Hardware 6. Date: Factual _____ Est. 1910
 Address 317 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 8, Lot 11 Present Use Retail Hardware and Furniture
 10. Description 2-story rectangular brick commercial structure with flat roof; metal awning over plate glass windows and doors; metal windows at second level.

11. Present Condition Good; altered facade.
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning; iron shutters at rear, elevator in northeast corner; used as hardware store.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	18	to 4	18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 160
 City/Rural Nacogdoches UTM Sector _____
 2. Name Greer's 6. Date: Factual _____ Est. 1910
 Address 318 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 15, Lot 7-A Present Use Commercial
 10. Description 1-1/2 story rectangular brick commercial structure with flat roof; applied siding covers second level facade; street level facade has inset metal and glass entry doors flanked by plate glass display area; standing seam metal awning.

11. Present Condition Fair; some alterations.
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning, divided into four long and narrow shops, office, millinery, confectioner and cigar shop, and barber
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	3	to 6	3
Other					to	
					to	

Continuation sheet
 12. shop.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 161

City/Rural Nacogdoches UTM Sector _____

2. Name Murphy Shoe Repair 6. Date: Factual _____ Est. 1910

Address 320 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 15, Lot 8 9. Original Use Commercial

Present Use Commercial

10. Description 1-1/2 story brick rectangular commercial structure with flat roof; corrugated sheet metal applied to second level facade, which has four 1/1 fixed sashes; street level has inset metal and glass entry doors flanked by plate glass display windows.

11. Present Condition Fair; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as furniture store.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	2	to 6	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 162
 City/Rural Nacogdoches UTM Sector _____
 2. Name World Finance Corp. 6. Date: Factual _____ Est. 1910
 Address 321 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 8, Lot 12 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; plate glass windows and doors; applied wood siding on awning and facade.

11. Present Condition Good; altered facade.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as restaurant.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	19	to	4 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 163

City/Rural Nacogdoches UTM Sector _____

2. Name McCroy 6. Date: Factual _____ Est. 1910

Address 322 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Art Moderne

4. Block/Lot City Block 15, Lot 9-A 9. Original Use Commercial

Present Use Commercial

10. Description 2-story rectangular masonry structure with flat roof; street level has plate glass windows and doors; metal awning; second level is stuccoed with 1/1 double-hung windows, inset panels, and corbeled banding.

11. Present Condition Fair; altered.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as a 2-story brick with frame awning; used as a pool room on west side, dry goods on east side.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		6	1	to	6	1
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 164

City/Rural Nacogdoches UTM Sector _____

2. Name Walker's Department Store 6. Date: Factual _____ Est. 1910

Address 323 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 8, Lots 13 and 14 9. Original Use Commercial

Present Use Retail

10. Description 1-story brick rectangular commercial structure with flat roof; 2-bay; one with inset glass doors, one with plate glass windows and door; metal awnings with fixed frosted glass lights above, stuccoed over on east side; two pointed pilasters separate inset panels with header course below and stretcher courses above; tile coping.

11. Present Condition Good; altered.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as grocery on west; meat market on east, had iron kettle for lard rendering at rear.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		4	20	to	4	20
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 165
 City/Rural Nacogdoches UTM Sector _____

2. Name Godtel Ministry 6. Date: Factual _____ Est. 1910
 Address 330 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 15, Lot 9 Present Use Ministry/Recording Studio
 9. Original Use Hotel

10. Description 3-story rectangular brick commercial structure with stepped facades, flat roof; 2/2 and 1/1 double-hung windows have segmental arches at levels 1 and 2; decorative concrete band/lintel at level 3; contrasting colored brick used to accent front facade arches and decorative bands; recessed entry is protected by three romanesque arches and one-story panel roof supported by plain pipe columns; entry door has corbeled cornice with dentils, sidelights, and fanlight with tracery; windows flanking entry have double 12-light outward-opening sashes with operating

11. Present Condition Fair

12. Significance Was Redland Hotel during the 1970s; shown on the 1912 Sanborn Fire Insurance Map as the "New Murphy Hotel", a 2-story brick structure with ell at rear housing a sample room,

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	24	to	5 24
Other					to	
					to	

Continuation sheet

- 10. interior screens; some side windows on level 1 and 16/1 double-hung; tile coping.
- 12. kitchen, and dining room.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 166
 City/Rural Nacogdoches UTM Sector _____

2. Name Cason Building/Sir Knight and Lady Kathryn's 6. Date: Factual _____ Est. 1910
 Address 329 Main St. East 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial

4. Block/Lot City Block 8, Lots 15 and 16 Present Use Retail/Clothing Rental

10. Description 2-1/2 story brick rectangular commercial structure with flat roof; stepped parapet marked "Cason"; street level, 2 bays, has plate glass windows and doors; wood awning; second level has metal casement windows; pilasters with pointed, chamfered tops flank panels of header courses and two inset metal screens; tile coping.

11. Present Condition Good; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning; used as dry goods and clothiers on west, grocery on east; second floor was opera house.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	21	to 4	21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 167
 City/Rural Nacogdoches UTM Sector _____
 2. Name Small Fry's 6. Date: Factual _____ Est. 1910
 Address 400 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 16, Lot 1 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; face brick facade; common brick side walls; glass panel entry door with side lights; multipane display windows; fabric awning; decorative panel above awning is outlined with protruding headers.

11. Present Condition Good
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as a 1-story brick structure with frame awning; used as a grocery.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	23	to 5	23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 168
 City/Rural Nacogdoches UTM Sector _____
 2. Name King's Smart Mart 6. Date: Factual _____ Est. 1910
 Address 402 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 16, Lot 1 Present Use Commercial
 10. Description 1-story rectangular brick structure with flat roof; sheet metal cornice; recessed entry with plate glass windows and door.

11. Present Condition Good
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as a 1-story brick structure with frame awning; used as a hay and feed store.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		5	22	to	5	22
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 169
 City/Rural Nacogdoches UTM Sector _____
 2. Name Sullivan Jewelry/McLain's 6. Date: Factual _____ Est. 1901
 Address 403 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 7, Lot 8 Present Use Retail Clothing and Jewelry
 10. Description 2-story brick rectangular commercial structure with flat roof; parapet is marked "M.C. Hazle 1901"; first level heavily altered with wood and glass doors and windows; shingle awning; second level has 2/2 double-hung windows with arched upper sash; segmental arches have compound archivolt; decorative string courses, panels, dentils; north facade has curvilinear gable.

11. Present Condition Good; numerous alterations.

12. Significance Known as the M.C. Hazle Building, location of Hazle Department Store; shown on the 1912 Sanborn Fire Insurance Map as a 2-story brick structure with frame awning wrapping

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		4	22	to 4	22
Other _____					to	
_____					to	

Continuation sheet

12. around south and west facade, used as a furniture store.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 170
 City/Rural Nacogdoches UTM Sector _____
 2. Name Fashion Shop 6. Date: Factual _____ Est. 1910
 Address 404 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 16, Lot 2 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; plate glass windows and doors; wood awning; applied glazed tile and metal facade; cast aluminum vine motif trim.

11. Present Condition Fair

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as a 1-story brick with frame awning; used as a grocery.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	21	to	5 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 171
 City/Rural Nacogdoches UTM Sector _____
 2. Name The Sewtique 6. Date: Factual _____ Est. 1915
 Address 405 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 7, Lot 8-B Present Use Retail
 10. Description 1-story rectangular brick commercial structure with flat roof; stepped facade identical to 407 and 409 Main St. East; double glass panel and wood entry doors flanked by plate glass windows; metal awning common with 407 East Main.

11. Present Condition Good
 12. Significance Added to 1912 Sanborn Fire Insurance Map; therefore, constructed after 1912; shown as 1-story brick building with frame awning; used as grocery.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 4 _____ 23 to 4 23
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 172
 City/Rural Nacogdoches UTM Sector _____
 2. Name Master's Touch 6. Date: Factual _____ Est. 1910
 Address 406 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 16, Lot 3 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; plate glass windows; replacement entry door with 9 lights; wood awning; applied glazed tile and metal covering as facade.

11. Present Condition Fair; altered.
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as a 1-story brick structure with frame awning; vacant in 1912.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____

YEAR	DRWR	ROLL	FRME		ROLL	FRME
1986		5	20	to	5	20
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 173

City/Rural Nacogdoches UTM Sector _____

2. Name The Treasure Trove 6. Date: Factual _____ Est. 1915

Address 407 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot City Block 7, Lot 8-A 9. Original Use Commercial

Present Use Retail

10. Description 1-story rectangular brick structure identical to 405 E. Main St. except for slightly different treatment of entry and display windows; plaque marks site on location of "Old Soledad," an Indian trading post.

11. Present Condition Good; altered.

12. Significance Not shown on 1912 Sanborn Fire Insurance Map; therefore, probably constructed after 1912.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	24	to 4	24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 174
 City/Rural Nacogdoches UTM Sector _____
 2. Name Toledo Finance 6. Date: Factual _____ Est. 1910
 Address 408 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 16, Lot 4 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; applied glazed tile and metal facade; plate glass windows and doors; wooden awning.

11. Present Condition Fair; altered.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; used as grocery.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	19	to 5	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 175
 City/Rural Nacogdoches UTM Sector _____
 2. Name The Seasons 6. Date: Factual _____ Est. 1915
 Address 409 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 7, Lot 14 Present Use Retail
 10. Description 1-story rectangular brick commercial structure with flat roof; one bay with plate glass windows flanking metal and glass door; fixed lights above metal awning; essentially identical to 405 and 407 E. Main St.

11. Present Condition Good; altered.

12. Significance Not shown on 1912 Sanborn Fire Insurance Map; therefore, probably built after 1912.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	2	to	5 2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 176
 City/Rural Nacogdoches UTM Sector _____

2. Name Woodman of the World 6. Date: Factual _____ Est. 1915
 Address 412 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 16, Lot 5 9. Original Use Commercial/Fraternal
 Present Use Commercial

10. Description 3-story rectangular brick commercial structure with flat roof; 4/1 double-hung windows with flat arches; red common brick sidewalk; face brick on street facade; plate glass windows and doors at street level have fixed glass ribbon lights above; decorative brickwork includes string courses, corbels, inset panels, pilasters.

11. Present Condition Good; recently renovated.

12. Significance Not shown on 1912 Sanborn Fire Insurance Map; therefore, probably built after 1912; Woodman of the World is an insurance and fraternal organization; structure is good

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	18	to 5	18
Other					to	
					to	

Continuation sheet

12. example of architectural style.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 177

City/Rural Nacogdoches UTM Sector _____

2. Name Crosslands and Old Town Jeans 6. Date: Factual _____ Est. 1915

Address 413 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 7, Lot 14 9. Original Use Commercial

Present Use Retail

10. Description 1-story rectangular brick commercial structure with flat roof; metal and glass entry doors and display windows; sheet metal awning; stepped facade; inset panel formed by header course above awning; facade topped by protruding header course; stepped facade on east wall; fixed lights above entry.

11. Present Condition Fair

12. Significance Not shown on 1912 Sanborn Fire Insurance Map; therefore, probably built after 1912.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	3	to 5	3
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 178
 City/Rural Nacogdoches UTM Sector _____
 2. Name Singer/Speech and Language Services 6. Date: Factual _____ Est. 1920
 Address 418 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 16, Lot 5-A Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; plate glass and metal windows; glass paneled wood entry doors; applied textured brick veneer.

11. Present Condition Good

12. Significance Not shown on 1912 Sanborn Fire Insurance Map; there was a frame building with iron cladding on site in 1912; therefore, this structure probably built after 1912.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____

Old THC Code _____

/RTHL /HABS (no.) TEX- _____

PHOTO DATA

NR: /Individual /Historic District

B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource

35 mm Negs. _____

NR File Name _____

YEAR DRWR ROLL FRME

ROLL FRME

1986		5	17	to	5	17
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 179
 City/Rural Nacogdoches UTM Sector _____
 2. Name D. D. Adams Law Offices 6. Date: Factual _____ Est. 1900
 Address 420 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 16, Lot 5-A Present Use Law Offices
 10. Description 2-story brick rectangular commercial structure, applied brick and wood siding at street level, stuccoed above; flat roof; new metal awning; metal casement windows on second level are in inset panels.

11. Present Condition Good
 12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning; used as grocery and bay and feed store.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	16	to	5
Other					to	16
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 180

City/Rural Nacogdoches UTM Sector _____

2. Name East Texas Art and Frame 6. Date: Factual _____ Est. 1890

Address 422 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

9. Original Use Commercial

4. Block/Lot City Block 16, Lot 6 Present Use Commercial

10. Description 2-story brick rectangular commercial structure with flat roof; 1/1 double-hung windows; segmental arch window openings on north facade; flat arched openings on east facade; pilasters at corners of north facade; 2 stopped pilasters at second level on east facade; plate glass and metal entry door and windows at street level; 1 glass panel door.

11. Present Condition Fair

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning extending through block to Pilar Street; used as flour warehouse.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	15	to 5	15
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 181
 City/Rural Nacogdoches UTM Sector _____
 2. Name Castleberry Insurance 6. Date: Factual _____ Est. 1960
 Address 424 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 16, Lot 6 Present Use Office
 10. Description 1-story irregular plan brick veneer residential structure with gable composition shingle roof; replacement non-operating windows.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	14	to 5	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 182

City/Rural Nacogdoches UTM Sector _____

2. Name Fina Station 6. Date: Factual _____ Est. 1950

Address 500 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot City Block 17, Lot 1 9. Original Use Service Station

Present Use Service Station

10. Description 1-story rectangular stuccoed commercial structure with flat roof; one sheltered pump island; two service bays with glass panel overhead doors; multi-light metal windows; transom over office door.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other	1986		5	13	to	5	13
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 183

City/Rural Nacogdoches UTM Sector _____

2. Name Western Auto 6. Date: Factual _____ Est. 1930

Address 503 Main St. East 7. Architect/Builder _____

3. Owner _____ 8. Style/Type _____

Address _____ 9. Original Use Commercial

4. Block/Lot City Block 6, Lot 6-A Present Use Retail

10. Description 1-story rectangular brick structure with flat roof; plate glass entry and windows; metal awning.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	986		5	4	to 5	4
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 184

City/Rural Nacogdoches UTM Sector _____

2. Name Main Theatre 6. Date: Factual _____ Est. 1920

Address 511 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Art Moderne

4. Block/Lot City Block 6, Lots 6-B and 7-A 9. Original Use Movie Theater

Present Use Vacant

10. Description 2-story rectangular brick commercial structure with flat roof; stepped facade; beige brick is accented by polychromatic textured brick trim and accent panels; curved neon sign above marquee.

11. Present Condition Good; altered.

12. Significance Good example of early 20th century movie theatre.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		5	5	to	5	5
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 185

City/Rural Nacogdoches UTM Sector _____

2. Name Big A Auto Parts 6. Date: Factual _____ Est. 1940

Address 510 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Art Moderne

4. Block/Lot City Block 17, Lot 2 9. Original Use Commercial

Present Use Auto Parts Store

10. Description 1-story rectangular brick commercial structure with flat roof; plate glass display windows and door have fixed frosted glass lights above; curved parapet has pronounced brickwork pilaster in center.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		5	12	to	5	12
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 186

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 516 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 17, Lot 3 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story rectangular brick residence with patterned metal shingle roof; hip-and-valley roof with dormer and gables; 1/1 double-hung windows; entry has glass paneled door and sidelights; door and windows screens have tracery; massive battered wood columns rest on brick bases; one column "missing" beside stoop; roof has finials; chamfered bay on wraparound porch has Queen Anne panel above fixed sash; porte cochere on east side of house; detached frame garage with sheet metal roof at southeast corner of house; brick and

11. Present Condition Excellent

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		5	11	to	5	11
					to		
					to		

Continuation sheet

10. wrought iron fence fronts street.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 187

City/Rural Nacogdoches UTM Sector _____

2. Name Pace Insurance 6. Date: Factual _____ Est. 1950

Address 517 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot City Block 6, Lot 7 Present Use Insurance Office

10. Description 1-story rectangular masonry commercial structure with two roof levels; one gable end and one shed-like, with the shed roof rising above a clerestory with multipaned windows; sheet metal roof; metal casement and plate glass windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		5	6	to	5	6
Other					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 188

City/Rural Nacogdoches UTM Sector _____

2. Name Price - Ruckel 6. Date: Factual _____ Est. 1975

Address 521 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Modern

4. Block/Lot City Block 6, Lot 1 9. Original Use Commercial

Present Use Office

10. Description 1-story rectangular sheet metal and rock veneer commercial structure with flat roof; sheet metal cornice; plate glass windows and doors.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

_____	1986		5	7	to	5	7
Other _____					to		
_____					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 189

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900

Address 522 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 17, Lot 4 Present Use Residence

10. Description 2-1/2 story irregular plan frame residence with hip-and-valley composition shingle roof; horizontal V-groove siding; 1/1 double-hung windows; chamfered bay has one tall window opening onto porch; one-story wraparound porch has plain round columns and square balusters with pedimented gable at northeast corner; latticed foundation skirt; gables have rounded shingles and half-moon lights with tracery; balcony over entry; entry door has glass panel and transom over door.

11. Present Condition Good

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		5	10	to	5	10
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 190
 City/Rural Nacogdoches UTM Sector _____
 2. Name Gary Anderson Insurance 6. Date: Factual _____ Est. 1975
 Address 531 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Office
 4. Block/Lot City Block 6, Lot 1 Present Use Office
 10. Description 1-story rectangular sheet metal and rock veneer commercial structure with flat roof; sheet metal cornice; plate glass windows and door.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		5	8	to 5	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 191

City/Rural Nacogdoches UTM Sector _____

2. Name Flower's Sunbeam Bakery Thrift Store 6. Date: Factual _____ Est. 1950

Address 601 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot City Block 6, Lot 2 9. Original Use Service Station

Present Use Bakery Thrift Store

10. Description 1-story rectangular masonry structure with flat roof; two apparent service bays infilled with windows and doors; other openings covered over.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		5	9	to	5	9
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 192

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900

Address 127 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 7, Lot 6 Present Use Office

10. Description 1-story T-plan frame residence with hip-and-gable composition shingle roof; vinyl siding; 2/2 double-hung windows; returned cornices; full-width front porch with 3 x 3 columns on brick piers.

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	17	to 7	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 193

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 130 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 6, Lot 3 9. Original Use Residence

Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle roof; horizontal bull-nosed siding; 3/1 double-hung windows; 2 entry doors protected by overlapping overdoors; large 9-light fixed glass windows beside entries; bull-nosed rafter ends.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	16	to	7	16
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 194
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Floral Co. 6. Date: Factual _____ Est. 1975
 Address 138 Mound St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use _____
 4. Block/Lot City Block 6, Lot 1-B Present Use Florist Shop
 10. Description 1-story rectangular commercial structure with composition shingle modified saltbox roof; structure is modular with some cement block and some vertical board and batten construction.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	14	to 7	14
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 195
 City/Rural Nacogdoches UTM Sector _____
 2. Name Shepherd's 6. Date: Factual _____ Est. 1960
 Address 102 North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 10, Lot 1 Present Use Restaurant
 10. Description 1-story rectangular brick commercial structure with flat roof; curved cornice; fixed glass windows, plate glass and metal doors; fabric awnings.

11. Present Condition Excellent

12. Significance Business was started in Nacogdoches circa 1949.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		8	11	to 8	11
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 196
 City/Rural Nacogdoches UTM Sector _____
 2. Name 7-11 6. Date: Factual _____ Est. 1980
 Address 107 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Drive-in Convenience Store
 4. Block/Lot City Blk 11, Fraction Lt So of Lt 7, & Lt 8 Present Use Drive-in Convenience Store
 10. Description 1-story rectangular brick commercial structure with flat roof; 7-11 logo and trademark orange metal awning over plate glass windows and doors; self-service gasoline island.

11. Present Condition Good
 12. Significance Site of home of William Clark, Jr.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	10	to	8 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 197
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 109 North St. (Next to 7-11) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 11, Fractional Lot 6, Lot 7 Present Use Vacant
 10. Description 1-story rectangular brick commercial structure with flat roof; hipped porch roof with brackets; plate glass windows and double 15-light entry doors.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		8	9	to	8	9
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 198
 City/Rural Nacogdoches UTM Sector _____
 2. Name American Supply 6. Date: Factual _____ Est. 1950
 Address 212 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 2, Lot 39-A Present Use Commercial
 10. Description 1-story rectangular textured brick commercial structure with flat roof; metal and plate glass windows and doors.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	6	to 8	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 199

City/Rural Nacogdoches UTM Sector _____

2. Name Bumper to Bumper Auto - East Texas Auto Shop 6. Date: Factual _____ Est. 1950

Address 113 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot Block 11, Lot 6 & Part of Fractional Lot 7 9. Original Use Commercial

Present Use Commercial

10. Description 1-story rectangular brick commercial structure with flat roof; tile coping; stepped parapet; front facade altered to install plate glass windows and doors; flat metal awning; lights above awning closed up.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		8	8	to	8	8
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 200

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1950

Address 119 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 11, Lot 5 9. Original Use Commercial

Present Use Vacant

10. Description 1-story rectangular brick commercial structure with flat roof; tile coping; modern tinted plate glass windows and doors; stepped parapet.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	7	to 8	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 201
 City/Rural Nacogdoches UTM Sector _____
 2. Name Le Glacier 6. Date: Factual _____ Est. _____
 Address 200 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 2, Lot 39 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; tile coping; plate glass windows; 15-light double entry doors; fabric awnings.

11. Present Condition Excellent
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	4	to 8	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 202
 City/Rural Nacogdoches UTM Sector _____
 2. Name Kerrville Bus Station 6. Date: Factual _____ Est. 1950
 Address 201 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial/Transportation
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 1, Lot 44 Present Use Bus Station
 10. Description 1-story rectangular brick commercial structure with flat roof; 1/1 double-hung metal windows; plate glass display area; open sheet metal shed at south end of building.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		8	5	to 8	5
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 203
 City/Rural Nacogdoches UTM Sector _____
 2. Name Commercial National Bank Drive-In 6. Date: Factual _____ Est. 1975
 Address 100 Pecan St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Drive-in Bank
 4. Block/Lot City Block 9, Lot 5-C Present Use Drive-in Bank
 10. Description 5-lane drive-in bank with rectangular brick teller office; flat roof supported by square columns.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 6 19 to 6 19
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 204
 City/Rural Nacogdoches UTM Sector _____
 2. Name Texas Furniture #2 6. Date: Factual _____ Est. 1910
 Address 104 Pecan St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 7 Present Use Commercial
 10. Description 1-story brick rectangular commercial structure with flat roof; pent awning with cedar shakes; metal and plate glass entry doors and display windows.

11. Present Condition Fair; altered.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-story brick with frame awning; north half was meat market with iron kettle for lard rendering; south half was grocery.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	18	to 6	18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 205
 City/Rural Nacogdoches UTM Sector _____
 2. Name Texas Furniture #1 6. Date: Factual _____ Est. 1900
 Address 106 Pecan St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 8 Present Use Retail Sales

10. Description 2-story rectangular brick commercial structure with stepped parapet and flat roof; metal awning; metal and plate glass entry doors and display windows at street level; second story stuccoed, with four replacement fixed glass windows; metal awning.

11. Present Condition Fair; some alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 1-1/2 story brick with second story gallery on interior supported by wood posts, frame awning on front; used as dry goods store.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		6	17	to	6	17
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 206
 City/Rural Nacogdoches UTM Sector _____
 2. Name Jinkins Seed Company 6. Date: Factual _____ Est. 1900
 Address 108 Pecan St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 9 Present Use Commercial - Seed Store

10. Description 1-1/2 story rectangular brick commercial structure with stepped parapet and flat roof; cast iron columns marked "Mesker Brothers" support stuccoed facade; inset glass panel entry door is flanked by plate glass windows on three bays; metal awning.

11. Present Condition Fair
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as a 1-story brick with frame awning; used by tailor in northeast corner.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	16	to 6	16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 207
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mini Blinds To Go 6. Date: Factual _____ Est. 1900
 Address 110 Pecan St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 10 Present Use Commercial
 10. Description 1-1/2 story rectangular brick commercial structure with flat roof; 3 bays; cast iron columns support stuccoed facade; 2 glass panel entry doors are flanked by plate glass display windows; wood awning.

11. Present Condition Fair
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as a 1-story brick with frame awning; used as a pool room.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 6 15 to 6 15
 _____ to _____
 _____ to _____

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 208
 City/Rural Nacogdoches UTM Sector _____
 2. Name East Texas Land Services, Inc. 6. Date: Factual _____ Est. 1900
 Address 112 / 114 Pecan St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 11-A Present Use Commercial - Offices
 10. Description 1-1/2 story rectangular brick commercial structure with stepped parapet and flat roof; 4 bays separated by cast iron columns supporting the stuccoed facade; heavily altered at street level to provide two entry doors and two windows; flat wood awning.

11. Present Condition Good; exterior heavily altered.
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as a 1-story brick with partition running east/west with frame awning; used by photographer on north side, sample room on south
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		6	14	to	6	14
				to		
				to		

Continuation sheet
 12. side.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 209

City/Rural Nacogdoches UTM Sector _____

2. Name East Texas Land & Title II 6. Date: Factual _____ Est. 1900

Address 116 Pecan St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Commercial

4. Block/Lot City Block 13, Lot 11 9. Original Use Commercial

Present Use Office

10. Description 2-story rectangular brick commercial structure with flat roof; 3-bays with heavily altered street level to provide 1 entry door flanked by two windows; 3 arched openings, closed up, at second level; stuccoed; flat wood awning; south facade, unstuccoed, shows extensive decoration using beige brick against dark brick for segmental arches at second level, with window openings outlined by a double course of projecting headers laid in stilted arches, connected by a double string course; beige brick is also used in banding between first and second stories,

11. Present Condition Fair; exterior extensively altered.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with wood awning; used as grocery on first floor, Masonic Hall on second floor; built by Charles Hoya, who also

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource _____ 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	13	to	6
Other					to	13
					to	

Continuation sheet

10. and above the arches; pilasters of dark brick rise above the roof line and are crowned with a double stringer course of beige brick and a brick cane; in the center of the south facade is a fan-shaped arch with beige brick accents above a circle of beige brick. 12. owned the land office across the street.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 210
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 200 Pecan St. South at Craven 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 32, Lot 30-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 211

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-15

Address 206 Pecan St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shotgun

4. Block/Lot Block 32, Lot 30-C Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; central entry rectangular plan shotgun; hip roof with galvanized sheet metal roofing; inset porch with 4 x 4 posts; wood entry door with four upper glass lights; windows 4/4 wood double-hung with half-screens; 2 shed additions at rear.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 212
 City/Rural Nacogdoches UTM Sector _____
 2. Name Texas Department of Health 6. Date: Factual _____ Est. 1940s
 Address 206 - 204 Pilar St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Warehouse
 Address _____ 9. Original Use _____
 4. Block/Lot Block 12, Lot 4 Present Use Office
 10. Description 2-story masonry with load-bearing walls; flat roof; rectangular plan; glass brick on either side of two entry doors, small depending awnings over each entry; steel casement windows.

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		29	3	to	29	3
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 213
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40s
 Address 208 Pilar St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Commercial

4. Block/Lot Block 12, Lot 1-B 9. Original Use Commercial
 Present Use Commercial/Storage

10. Description 1-story masonry with load-bearing walls; wirecut brick on applied facade; rectangular plan; flat roof; 3 bays with two plate glass windows and double entry doors; aluminum awning depending on south facade.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		29	4	to 29	4
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 214
 City/Rural Nacogdoches UTM Sector _____
 2. Name Gin 6. Date: Factual _____ Est. 1900
 Address 210 Pilar St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Industrial
 Address _____ 9. Original Use Gin
 4. Block/Lot Block 12, Part of Lot 1 Present Use Storage
 10. Description 2-story sheet metal and brick; rectangular plan; gable sheet metal roof with 3-story tower; ventilators at ridge cap of roof.

11. Present Condition Poor
 12. Significance One of the few cotton gins still standing within the City of Nacogdoches and the county.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		29	6	to 29	6
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 215
City/Rural Nacogdoches UTM Sector _____

2. Name Old Pilar St. Antiques 6. Date: Factual _____ Est. 1910-20
Address 108 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Commercial
9. Original Use Commercial

4. Block/Lot Block 24, Lot 2 Present Use Commercial

10. Description 1-1/2 story painted masonry and sheet metal; rectangular plan; three bays with two large plate glass windows; depending frame awning; concrete steps; old fashioned lamp post at northwest corner of building; flat roof with terracotta coping.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	7	to 29	7
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 216
 City/Rural Nacogdoches UTM Sector _____

2. Name Hoya Land Office 6. Date: Factual 1897 Est. _____
 Address 120 Pilar St. East 7. Architect/Builder Frank E. Rue
 Contractor _____

3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Office

4. Block/Lot Block 24, Lots 3-A & B Present Use Vacant

10. Description 1-story masonry; rectangular plan; flat roof with terracotta coping; depending awning on three sides; three bays articulated by two windows and entry with iron shutters; corbeled brickwork at cornice; segmental arches over windows and doors; projecting parapet at center of cornice has "Chas. Hoya 1897 Land Office."

11. Present Condition Good; new brick and iron fence around exterior.

12. Significance Said to be the first fireproof building in city; RTHL; architectural plans still exist; good example of style; associated with prominent Nacogdoches family, the Charles Hoya

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975; Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	<input type="checkbox"/> RTHL	<input type="checkbox"/> HABS (no.) TEX-	PHOTO DATA			
NR:	<input type="checkbox"/> Individual	<input type="checkbox"/> Historic District	<input type="checkbox"/> B&W 4 x 5s	<input type="checkbox"/> slides		
	<input type="checkbox"/> Thematic	<input type="checkbox"/> Multiple-Resource	<input type="checkbox"/> 35 mm Negs.			
NR File Name		YEAR	DRWR	ROLL	FRME	ROLL FRME
		1986		29	8	to 29 8
Other						to
						to

Continuation sheet

12. family, who owned a number of buildings in the central business district and several residences, including the Stern-Hoya Home on S. Lanana St. and the Hoya sister houses on N. Logansport Rd.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 217

City/Rural Nacogdoches UTM Sector _____

2. Name Gladys Hampton Building 6. Date: Factual _____ Est. 1910

Address 202 Pilar St. East 7. Architect/Builder _____

3. Owner Texas Department of Human Resources 8. Style/Type Commercial

Address _____ 9. Original Use Commercial

4. Block/Lot City Block 23, Lot 1 Present Use Commercial

10. Description 3-story rectangular brick commercial structure; first floor facade altered with plate glass windows and doors; square masonry columns support 1-story balcony with plain railing and posts; replacement windows.

11. Present Condition Good; alterations to facade.

12. Significance Site of first house in Texas owned by Sam Houston; shown on 1912 Sanborn Fire Insurance Map as 2-story brick with frame awning; used as hotel with furnished rooms on

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	2	to 4	2
Other					to	
					to	

Continuation sheet

12. second floor.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 218

City/Rural Nacogdoches UTM Sector _____

2. Name John S. Wyatt 6. Date: Factual 1918 Est. _____

Address 204 / 208 Pilar St. East 7. Architect/Builder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Commercial

4. Block/Lot City Block 23, Lot 2 9. Original Use Commercial

Present Use Commercial

10. Description 3-story rectangular brick commercial structure with load bearing walls and timber infrastructure; four bays at street level, apparently altered; 1/1 double-hung windows at levels 2 and 3; plate glass windows and doors at street level; decorative parapet rises above dentiled cornice and decorative string course; banding above windows. On the third floor chamfered columns measure 11.5 inches in width. At the first and second floors there are wood and a few metal pipe columns; two chimney's on the east side vented the wood burning stoves in

11. Present Condition Good; some alterations.

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as the site of Nacogdoches County Courthouse. After new courthouse was constructed at North and Main Streets, this 3-story

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; 1985 article, Nacogdoches Daily Sentinel.

15. Informant Mr. Whitten

16. Recorder Larry Hodge, Sally Victor, Dorothy Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		4	3	to 4	3
Other _____					to	
					to	

Continuation sheet

10. in the building. On the third floor, wood flooring and beaded wood ceiling are still intact, some plaster remains on the walls. Toward the front of the building there is an original wood frame stair to the second floor; at the rear of the building is an enclosed stair from the second to third floors; an early elevator is intact at the rear of the building, however it is no longer in use. At the second floor, the early car dealership offices are partially intact. Varnished wood with patterned glass office partitions and doors, some early cypress panel doors with ornate hardware are also intact. On the third floor some remains of the Mahdeen Company's tonic and shampoo works are intact, including wood and metal vats, plumbing and electrical wiring. On the west side near the front is a mezzanine office with counters. The windows on the building are 1/1 wood double hung on the north facade, 2/2 and 4/4 with arched upper lights on the east and south. 12. brick building was erected in 1918 with elevator at rear; occupied by Mahadeen Company, a hair tonic and shampoo company founded by a banker named Needham (Mahadeen is his name spelled backwards). His formulas were patented and sold in the United States and Europe. A prosperous financial backer helped Needham to develop his products. The business occupied the third story of this structure; there are still wood and metal vats associated with Mahadeen on the third floor. The building also housed Ford and Chevrolet auto dealerships, a furniture store, and an office supply store. The top sash on the third floor windows had Mahadeen spelled out until a few years ago.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 219

City/Rural Nacogdoches UTM Sector _____

2. Name Richard Tallent Insurance 6. Date: Factual _____ Est. 1890

Address 210 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 23, Lot 3 9. Original Use Commercial

Present Use Commercial

10. Description 2-story rectangular brick commercial structure with arched glass panel entry door flanked by arched glass side lights; 4 windows at second level with segmental brick arches, 1/1 double-hung windows with fake muntins; brick string courses at eave above and below inset panels; wood second entry door with transom; wood awning.

11. Present Condition Good

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 2-story brick with 2-story frame gallery; was F. I. Tucker Law offices for many years; good example of architectural style.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		4	4	to	4	4
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 220
 City/Rural Nacogdoches UTM Sector _____
 2. Name Municipal Building 6. Date: Factual _____ Est. 1920
 Address 212 Pilar St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Office
 4. Block/Lot City Block 23, Lots 4 and 5 Present Use Office
 10. Description 2-story rectangular brick commercial structure with flat roof; plate glass entry and windows on west; overhead doors to fire trucks on east; metal windows at second level; wood awning depends from facade.

11. Present Condition Good; some alterations.
 12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 2-story brick; used as fire department and town hall; still has same usage at the present time.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912.
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		4	5	to	4	5
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 221
 City/Rural Nacogdoches UTM Sector _____

2. Name Oldtime String Shop 6. Date: Factual _____ Est. 1890
 Address 216 Pilar St. East (Southwest corner) 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Commercial

4. Block/Lot City Block 23, Lot 6 Present Use Commercial

10. Description 1-1/2 story rectangular brick commercial structure with flat roof, 3-bay facade with wood and glass entry doors with transoms set in openings with segmental arches; corbeled string course above and below inset panels; sheet metal awning; stepped parapet on east wall, which has 2/2 double-hung windows.

11. Present Condition Fair

12. Significance Shown on the 1912 Sanborn Fire Insurance Map as 1-story brick with basement; ironclad room in center; front portion used as restaurant, rear was warehouse.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		4	6	to 4	6
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 222

City/Rural Nacogdoches UTM Sector _____

2. Name Wm. A. Stewart & Assoc. 6. Date: Factual _____ Est. 1890

Address 122 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 6, Lot 4 9. Original Use Residence

Present Use Offices

10. Description 1-1/2 story irregular plan frame residence with hip-and-gable roof with composition shingles; horizontal clapboard siding; 1/1 double-hung windows; dog-eared shingles on gables; Tuscan columns on wraparound stone porch and port cochere; double windows on tympanae of gables; replacement entry door and sidelights; interior chimney; finials on roof; stone fence at street; 1-story frame garage at rear.

11. Present Condition Excellent

12. Significance Known as the Nelson House; structure was a Victorian cottage, remodeled extensively in 1912.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		7	18	to	7	18
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 223
 City/Rural Nacogdoches UTM Sector _____

2. Name Creative Photography by Steve Kozak 6. Date: Factual _____ Est. 1930
 Address 131 Mound St. North (Next to Nacogdoches Floral) 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow
 9. Original Use Residence

4. Block/Lot City Block 6, Lot 1-A Present Use Office

10. Description 1-story house; rectangular plan, with hip composition shingle roof; vinyl siding; 1/1 double-hung windows; gabled dormer over front porch protecting two entry doors; 1 glass and wood paneled, 1 wood; replacement wood porch with plain columns and balusters; latticework around foundation.

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge; Sally Victor Date January 6, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		7	15	to 7	15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 224
 City/Rural Nacogdoches UTM Sector _____
 2. Name 24-Hour Bail Bonds 6. Date: Factual _____ Est. 1900
 Address 107 - 109 South St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 1 Present Use Commercial
 10. Description 1-story rectangular brick commercial structure with flat roof; stepped parapet; tile coping; plate glass doors and display windows; small metal awnings (originals removed); ribbon lights above awnings.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		8	17	to	8	17
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 225
City/Rural Nacogdoches UTM Sector _____
 2. Name Anderson Co. Insurance 6. Date: Factual _____ Est. 1980
 Address 115 South St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial/Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 13, Lot 12 Present Use Commercial
 10. Description 1-1/2 story rectangular brick commercial structure with composition shingle Dutch gambrel roof, flared to extend over porch; fixed glass windows; plate glass door; fabric awnings over west-facing windows.

11. Present Condition Excellent
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		8	18	to	8	18
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 226
 City/Rural Nacogdoches UTM Sector _____

2. Name Branch Patton #2 6. Date: Factual 1891 Est. _____
 Address 111 Pecan St. North (Taliaferro Cigar Co. Building) 7. Architect/Builder John A. Cox
 Contractor _____

3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Cigar Factory

4. Block/Lot City Block 10, Lot 6 Present Use Warehouse

10. Description 2-story red brick rectangular commercial structure with flat roof; 6/6 double-hung windows; segmental arches; inset brickwork panels and pilasters; projecting header course below cornices; entrances are both large with wood doors; date of 1891 appears on door facing.

11. Present Condition Fair; few alterations.

12. Significance Shown on 1912 Sanborn Fire Insurance Map as 2-story brick with iron shutters on south facade; elevator at rear and between this site and site #148 (Cox Hardware); cigar factory,

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography Sanborn Fire Insurance Map, 1912; THC Survey, 1975.

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	20	to	6 20
Other _____					to	
					to	

Continuation sheet

12. tobacco stored on first floor; rolled into cigars on second floor.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 227

City/Rural Nacogdoches UTM Sector _____

2. Name Gulf Station 6. Date: Factual _____ Est. 1940s

Address 428 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot Block 43 9. Original Use Service Station

Present Use Service Station

10. Description 1-story clay tile; ell plan; triple decorative string course near cornice; awning over drive-through area; awning windows over aluminum and glass storefront.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	3	to 31	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 228

City/Rural Nacogdoches UTM Sector _____

2. Name Far Away Places 6. Date: Factual _____ Est. 1910-30

Address 101 Tyler Rd. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial/Industrial

4. Block/Lot Block 43 9. Original Use Lumber Shed/Commercial

Present Use Commercial

10. Description Two 1-story buildings; south structure looks like old lumber shed with washboard siding under sheet metal; gable sheet metal roof; north structure is covered in sheet metal, gable roof.

11. Present Condition Fair - Good; altered considerably.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		37	11	to	37	11
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 229
 City/Rural Nacogdoches UTM Sector _____

2. Name City of Nacogdoches Annex 6. Date: Factual _____ Est. 1920
 Address 209 Pecan St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type _____

4. Block/Lot Block 23 9. Original Use Office _____
 Present Use City Offices

10. Description 4-story T-shaped brick commercial structure with flat roof; replacement plate glass windows and doors; flat stone lintels; corbeling at first, third, and fourth stories; dentils at second story; flat metal awning; metal fire escape ladder on south facade.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		6	12	to 6	12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 301
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 917 Amos Alley (Between Moore & Shawnee) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Part of Lot 63 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 303
 City/Rural Nacogdoches UTM Sector _____

2. Name Slay House 6. Date: Factual _____ Est. ca. 1900
 Address 2421 Appleby Sands Rd. 7. Architect/Builder _____

3. Owner Mrs. Chester Collins Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot Block 54 9. Original Use Residence/Farmstead
 Present Use Residence

10. Description 1-story; wood frame with lapped board siding; brick pier foundation; ell plan with additions; intersecting gable roofs with cornice returns, composition shingles; exterior brick chimney on north side; projecting porch with hip roof, turned wood columns with slender brackets, turned spindle railing; central entry door with sidelights; windows 3/1 wood double-hung.

11. Present Condition Good; ell plan with 2 additions at rear-- one with board and batten siding, other with

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant Mrs. Geneva Pulsipher (4/24/86)

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	/RTHL	/HABS (no.)	TEX-	PHOTO DATA
NR:	/Individual	/Historic District	B&W 4 x 5s	slides
	/Thematic	/Multiple-Resource	35 mm Negs.	
NR File Name	YEAR	DRWR	ROLL	FRME
Other				

Continuation sheet

11. bull-nosed siding. According to a neighbor, this was a dogtrot house.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 304
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. ca. 1930s
 Address 3512 Appleby Sands Rd. 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence
 Present Use Residence

10. Description _____

11. Present Condition Good; altered metal porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides .
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 305

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 3614 Appleby Sands Rd. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence

10. Description _____ Present Use Residence

11. Present Condition Good; altered by asphalt siding; turned wood porch supports and lattice railing.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 306
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. ca. 1920
 Address 3925 Appleby Sands Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description 1-story; wood frame with beveled siding; gable roofs; ell plan; porch across front with boxed columns; windows 6/6; carport on north.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 307
 City/Rural Nacogdoches UTM Sector _____
 2. Name Armsworth 6. Date: Factual _____ Est. ca. 1920
 Address 3903 Appleby Sands Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by aluminum siding; metal porch supports; brick foundation skirt.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 308
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. ca. 1930
 Address 4014 Appleby Sands Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Good; porch blocked by plastic sheeting.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 309
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
Address 304 Arnold 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Neo-classical

4. Block/Lot City Block 3, Lot 4 Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle cross-gable roof; vinyl siding; replacement aluminum windows; pedimented portico over poured concrete porch with brick columns; multi-light entry door with side lights; 2 brick fireplace chimneys; 1 interior chimney.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		22	7	to	22	7
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 310

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 306 Arnold 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot City Block 3, Lot 5-A Present Use Residence

10. Description 1-story rectangular frame residence with cross-gable composition shingle roof; horizontal bull-nosed siding; 1/1 double-hung windows; 1/1 double-hung window on tympanum of gable over wood porch with brick columns, 2 "missing" at stoop; returned cornices; added porte cochere on east wall; brick fireplace on west wall.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	8	to	22 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 311
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 310 Arnold 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Residence

4. Block/Lot City Block 3, Lot 5-B Present Use Beauty Shop

10. Description 1-story rectangular frame residential structure with composition shingle gable roof; horizontal drop siding; 2/2 double-hung windows; double pent roof across front facade, wood porch with turned posts and balusters; multi-pane entry door.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		22	9	to 22	9
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 312

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 117 Austin St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot College Park S/D, City Block 50, Lot 13 Present Use Residence

10. Description 1-story, wood frame construction with bull-nosed siding; brick foundation and skirt; T-plan; intersecting gable roof with extended rafters, composition shingles; small gable roof over entry door and concrete steps; windows 4/1 wood frame double-hung in doubles and triples; brick chimney on north facade; addition to east and south with brick veneer.

11. Present Condition Good; altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1985		1	8	to	1 8
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 313
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 123 Austin St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot College Park S/D, City Block 50, Lot 14 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; rectangular plan with projecting bay at west; intersecting gable roof with extended rafter ends; small gable over entry door; concrete porch with wrought iron railing and posts; single paneled entry door; windows 6/6 wood double-hung in pairs; brick chimney on east facade; two-car garage at rear; apartment addition at southeast.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	7	to	1 7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 314

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 202 Austin St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot College Park S/D, City Block 50, Lot 5 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick foundation and skirt; ell plan; intersecting gable roof with clipped gable ends, extended rafters, composition shingles; inset porch with wood floor and single entry door, battered wood columns over brick piers, prefabricated concrete steps; windows 6/6 wood double-hung in doubles and triples; carport at rear; central brick chimney; large juniper trees on south and west.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	6	to	1 6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 315

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940s

Address 211 W. Austin 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot _____ 9. Original Use Residence

College Park S/D, City Block 50, Lot 19 Present Use Residence

10. Description 1-story; wood frame structure with lapped aluminum siding; ell plan; gable roofs with cornice returns, composition shingles; inset porch with concrete floor, wrought iron posts and railing, concrete steps; windows 2/2 aluminum double-hung with shutters on the front bay; single entry door; carport and addition to the west.

11. Present Condition Good; windows altered, aluminum siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other	1985		1	5	to	1	5
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 316

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1945

Address 215 Austin St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Stone Cottage

4. Block/Lot CollegePkS/D, CityBk 50, Part Lts 19&20 9. Original Use Residence

Present Use Residence

10. Description 1-story, frame structure with rock-faced stone; ell plan; intersecting gable roofs with composition shingles; eave of roof extends over entry door and concrete steps; windows 6/6 and 1/1 wood frame double-hung; brick apartments at rear; front yard -- asphalt parking lot.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1985		1	4	to 1	4
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 317
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1945
 Address 218 Austin St. West 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot College Park S/D, City Block 50, Lot 8 Present Use Residence/Apartments

10. Description 1-story, wood frame with lapped wood siding; brick foundation; rectangular plan with projecting bay on west and carport on the east at rear; front-facing staight gable roof with composition shingles, clipped gable ends and extended rafters; inset entry porch on southeast corner with corner posts on a brick pier, two entry doors; addition at rear; windows are 4/1 double-hung, wood, in pairs and singly.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1985		1	3	to	1	3
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 318

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 229 Austin St. West 7. Architect/Builder Mr. Dewey Clark & Father

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot College Park S/D, City Block 50, Lot 22 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation skirt, rectangular plan with projecting bays on west and south facades; straight, front-facing gabled roofs with clipped gable ends; composition shingles, simple brackets under eaves and extended rafter ends; projecting porch with battered wood columns and brick piers, wooden floor and brick steps; windows - wood double-hung with 4/1 lights, with four vertical lights, singly and paired; symmetrically placed entry doors of paneled wood with four vertical lights above; metal

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1985		1	2	to	1	2
Other					to		
					to		

Continuation sheet

10. awnings on west windows; 2-story detached garage to southeast; juniper trees planted by the Clark family on the east, south, and west.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 319
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 112 Austin St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Tudor Cottage

4. Block/Lot Stephen F. Austin S/D, City Blk 50, Lot 4 9. Original Use Residence
 Present Use Residence

10. Description 1-story, brick veneer - running band; rectangular plan; steep intersecting gables with composition shingles; projecting asymmetrical porch with segmental arch openings and rectangular piers; windows wood double-hung 6/1, mostly in pairs with brick sill; entry door multipaned glass; chimney on west elevation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	9	to 1	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 320

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 114 Austin St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Stephen F. Austin S/D, City Blk 50, Lot 4 9. Original Use Residence

Present Use Residence

10. Description 1-story, wood frame with asbestos siding; brick foundation; rectangular plan; front-facing straight gable with composition shingles, extended rafter ends; extended porch with concrete floor, wrought iron posts, concrete precast steps; symmetrical entry doors with three small glass lights; windows 2/2 wood and aluminum double-hung.

11. Present Condition Fair; roof damage at rear; altered porch and windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	10	to	1 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 321
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 115 Austin St. East 7. Architect/Builder _____

3. Owner William Gibson Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Stephen F Austin S/D, City Blk 50, Lot 33 9. Original Use Residence
 Present Use Residence

10. Description 1-1/2 story, wood frame; board and batten with pseudo half-timber at front gables; ell plan with intersecting gables, decorative fascia boards, composition shingles; porch stoop with roof; windows wood double-hung 4/1 in triples and pairs; wood entry door with arched upper light; brick chimney at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Terresa Kirkham

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	11	to	1 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 322

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 129 Austin St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Brick Tudor Cottage

4. Block/Lot _____ Present Use _____

Stephen F Austin S/D, City Blk 50, Lot 30 Apartments

10. Description 1-1/2 story, wood frame with running band brick veneer; brick foundation; massed plan with porte cochere; cross-gabled roof with eyebrow dormer, composition shingles, ptd. fascia trim; entry porch with arched opening and low brick wall and decorative brickwork; windows wood double-hung 6/6 paired; flattened arch at porte cochere.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1985		1	12	to	1	12
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 323
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 212 Austin St. East 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Stephen F Austin S/D, Block 50, Lot 11 Present Use Residence

10. Description 1-story, wood frame with asbestos siding; brick foundation; rectangular plan; front-facing straight gable with composition shingles; inset porch on northwest corner with concrete floor; windows 3/1 wood frame double-hung; solid panel entry door.

11. Present Condition Good-Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	13	to	1 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 324

City/Rural Nacogdoches UTM Sector _____

2. Name W. E. Boone 6. Date: Factual _____ Est. 1935-40

Address 218 Austin St. East 7. Architect/Builder _____

3. Owner Paul Carter Contractor _____

Address Cedar City, Utah 8. Style/Type Bungalow

4. Block/Lot Stephen F Austin S/D, City Blk 50, Lot 12 9. Original Use Residence

Present Use Residence

10. Description 1-story, wood frame with horizontal board siding; brick foundation; ell plan; side-gabled roof with extended rafter ends and brick chimney turned diagonally to the ridge; inverted wraparound porch with tapered wooden Tuscan columns; paneled wood entry door with three upper glass lights; sun porch with lattice on east elevation; garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1985		1	14	to	1	14
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 325
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
Address 219 Austin St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot Stephen F Austin S/D, City Blk 50, lot 25 9. Original Use Residence
Present Use Residence

10. Description 1-1/2 story, wood frame with bull-nosed siding; brick foundation; ell plan; cross-gabled roofs with extended beams at corners, composition shingles; wraparound asymmetrical porch with turned wooden porch supports and brick piers; wood floor, concrete steps; entry door with louvers; windows 1/1 wood double-hung in pairs and triples; interior brick chimney; detached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource _____ 35 mm Negs.

NR File Name _____

YEAR	DRWR	ROLL	FRME		ROLL	FRME
1985		1	15	to	1	15
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 326

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 300 Austin St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Craftsman Bungalow

4. Block/Lot Stephen F Austin S/D, City Blk 50, Lot 14 9. Original Use Residence

Present Use Residence

10. Description 1-story, wood frame with bull-nosed siding; brick foundation; massed plan; side-facing gable with clipped gable ends and smaller intersecting gable and hipped roofs; extended beams and rafter ends and composition shingles; porch stoop with roof; multi-paned wood entry door and brick steps; windows 6/1 in pairs with a sunroom on the northeast corner; exterior brick chimney on the north facade; red-brown stone retaining wall at east boundary of property; detached garage.

11. Present Condition _____

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1985		1	16	to	1	17
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 327

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 301 Austin St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Tudor Bungalow

4. Block/Lot Stephen F Austin S/D, City Blk 50, Lot 23 9. Original Use Residence

Present Use Residence

10. Description 1-story, wood frame with running band brick veneer; brick foundation; rectangular plan; side-facing gable with smaller intersecting gables (tent roof) ; small entry porch with arch; wood entry door with small glass lights; glazed arched opening at sun porch; 1/1 wood double-hung window with soldier course at head; exterior splayed brick chimney; detached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	18	to 1	18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 328
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1202 Austin St. East 7. Architect/Builder _____

3. Owner Trammell C. Lacey Contractor _____
 Address 1118 Garner 8. Style/Type _____

4. Block/Lot _____ 9. Original Use Residence
 Present Use Vacant

10. Description 2-story, wood frame with horizontal board siding; brick foundation; rectangular plan; straight side-facing gable, composition shingles; entry steps - concrete with cast iron railing; shutter windows wood double-hung 6/6 with simple hood mold; entry door multi-paned over wood paneling; interior brick chimney with corbeled cap; long octagonal glass lights on either side of entry; second story balcony on west facade; coach house to east with pyramidal roof; estate grounds; circular drive.

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1985		1	19	to	1	19
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 329
 City/Rural Nacogdoches UTM Sector _____

2. Name Joe Wright 6. Date: Factual _____ Est. 1930
 Address 1430 Austin St. East 7. Architect/Builder _____

3. Owner Joe A. Wright 8. Style/Type Bungalow & Metal Barns, Pastures
 Address _____ 9. Original Use House & Farmstead

4. Block/Lot _____ Present Use House & Farmstead

10. Description 1-story wood frame with horizontal board siding; brick foundation; rectangular plan; straight, front-facing gable with composition shingles; entry moved to rear; windows 6/6 wood double-hung in pairs; doors not visible; modern barns, pens, paddock; large oak and sycamore in yard; several acres.

11. Present Condition Good; altered entry.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant Walter Williams (says it's 50 years old)

16. Recorder Dorothy Victor Date November 11, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	20	to 1	21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 330
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 200 Bailey 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 45-C 9. Original Use Residence
 Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle crossed-gable roof; wraparound screened porch with box columns and brick piers; horizontal bull-nosed siding; 4/1 double-hung windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		23	24	to	23 24
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 331

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 211 Bailey 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 45, Lot 25 9. Original Use Residence

Present Use Residence

10. Description 1-story rectangular frame residence with hip-and-gable roll roof; horizontal siding; 4/1 double-hung windows; inset wood porch with replacement columns; three-light entry.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		24	2	to	24	2
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 332

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 311 Bailey 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 30-C 9. Original Use Residence

Present Use Residence

10. Description 1-story irregular plan frame residence with composition shingle cross-gable roof with one clipped gable; horizontal bull-nosed siding; 6/6 double-hung windows; inset wood porch with box columns, square porch rail and balusters.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		24	3	to	24	3
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 333

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 515 Bailey 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 33-A 9. Original Use Residence

Present Use Residence

10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 334

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900

Address 1514 Baker 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neo-classical

4. Block/Lot _____ 9. Original Use Residence

Reese&StriplingS/D(574), City Blk 45, Lt 2 Present Use Residence

10. Description 1-story cross-shaped frame residence with composition shingle hip roof; horizontal clapboard siding; 1/1 double-hung windows; full-width brick porch with box columns; oval glass light entry door; hip roof dormer centered over porch with wavy glass on tympanum.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	14	to	36 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 335

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 1515 Baker 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 10-F Present Use Residence

10. Description 1-story T-plan frame residence with composition shingle cross-gable roof; horizontal bull-nosed siding; 9/9 double-hung windows; pedimented gable over poured concrete porch with replacement iron columns; three-light entry door; brick piers.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	13	to 36	13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 336
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1601 Baker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 10-0 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 337
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1607 Baker 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot City Block 45, Lot 10-A Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle hip-and-valley roof with pedimented gable over wood porch with box columns; horizontal bull-nosed siding; 1/1 double-hung windows; non-operating shutters; brick piers.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		36	12	to	36 12
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 339

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900

Address 1616 Baker 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neo-classical

4. Block/Lot Reese&StriplingS/D(574), City Blk 45, Lt 7 9. Original Use Residence

Present Use Residence

10. Description 1-story ell plan frame residence with composition shingle gable roof; horizontal bull-nosed siding; 1/1 double-hung windows; inset wood porch with box columns; brick chimney on north wall; central pedimented gable; returned cornices; glass panel entry door.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		36	11	to	36	11
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 340
 City/Rural Nacogdoches UTM Sector _____

2. Name Liz Kerridge 6. Date: Factual _____ Est. 1930s
 Address 1923 Banita 7. Architect/Builder _____

3. Owner Jarvis Ammons Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot TJLloyd 1st, City Blk 50, Bk 2, Lts 2B or 3 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; shingles at the porch; brick foundation; square plan; pyramidal roof with dormer w/ attic vent, deep overhang, composition shingles; inset porch; shingles, large half-circle arches supported by short columns over a shingled porch rail; wood floor, concrete steps; windows 1/1 wood double-hung with wood shutters on the front facade; diamond mutins above window on front facade; two entry doors on porch, wood paneled w/ upper glass, screen doors w/ decorative

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Yes, date? _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	22	to	2 22
Other					to	
					to	

Continuation sheet

10. spindlework; carport on south.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 341

City/Rural Nacogdoches UTM Sector _____

2. Name Nacogdoches Leasing 6. Date: Factual _____ Est. 1930

Address 2123 Banita 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot T. J. Lloyd 1st, City Blk 50, Lt 5 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; ell plan; intersecting gable roof with composition shingles; inset porch with wrought iron corner post, one remaining wood boxed column, concrete floor, side entry; windows 1/1 wood double-hung singly and in pairs.

11. Present Condition Fair; altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	21	to	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 342

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 2126 Banita 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot TJLloyd 1st, City Blk 50, Block 1, Lot 12 Present Use Residence

10. Description 1-story; wood frame construction with grooved horizontal wood siding; brick foundation; massed plan; multiple hip roof with deep overhangs, vents in soffit, composition shingles; projecting porch with Tuscan boxed wood columns (no base) and simple stick railing; wood floor, brick steps; windows 1/1 wood double-hung; single entry door; carport/shed on south and east sides; other windows 3/1, 12/12 and picture window.

11. Present Condition Good; altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1985		2	20	to	2	20
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 343

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 2201 Banita 7. Architect/Builder _____

3. Owner Mr. Sparks, Sparks TV Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot TJLloyd 2nd S/D, City Blk 50, Blk 6, Lot 5 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick foundation; I-plan; intersecting gable roofs with cornice returns, attic vents in the pediment and composition shingles; projecting porch with battered wood columns over brick piers, wood floor; windows 4/1 wood double-hung casement with simple hood mold; shutters on the front facade; two symmetrical entry doors with multi-paned glass; half basement at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	19	to	2 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 344

City/Rural Nacogdoches UTM Sector _____

2. Name Duncan House 6. Date: Factual _____ Est. 1898

Address 109 Baxter Duncan 7. Architect/Builder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Steamboat or Italianate Victorian

9. Original Use Residence

4. Block/Lot Block 1, Lots 25 & 25-C Present Use Residence

10. Description 2-story; wood frame with lapped siding and shingle siding at gable ends and around windows; brick foundation; symmetrical plan with steamboat configuration, chamfered bay on east facade, boxed bay on west facade; hip-and-gable roofs with cornice returns, ornamented gable ends, enriched modillion brackets at the 2-story bay, composition shingles, finials at the crests of the two dominant gables on the north (front) facade; porch is symmetrical, 1-story, wrapping around the central chamfered bay with a 3-bay pedimented entry, chamfered wood porch post supports

11. Present Condition Good

12. Significance Architectural significance.

13. Relationship to Site: Moved Date Yes, date unknown Original Site Moved west one city lot from corner of North and Baxter Duncan.

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		33	14	to	33 14
Other					to	
					to	

Continuation sheet

10. with capitols, lattice flanking the central entry, arched fascia openings between porch supports, plain wood railing, the frieze at the porch is enriched with relief fretwork and brackets; windows are 2/2 wood double-hung and 1/1 wood double-hung, with lattice awnings at the second story bay, a Palladian window arrangement on the east gable end; detached wood frame garage; fenced yard with thick ivy growth and low retaining wall of dark red sandstone, drylaid.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 345
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 203 Beall 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Beall S/D, City Blk 50, Part of Lots 4&5 9. Original Use Residence
 Present Use Vacant

10. Description 1-story; wood frame construction with bull-nosed siding; brick foundation; massed plan; straight front-facing gable roof with smaller intersecting gables; blunt-nosed extended rafter ends, composition shingles, extended beams; projecting porch with pipe columns, concrete floor and steps; windows 1/1 wood double-hung in pairs; single entry door with vertical upper lights; attached carport.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	11	to 2	11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 346
 City/Rural Nacogdoches UTM Sector _____

2. Name A Child's World Day Care 6. Date: Factual _____ Est. 1940
 Address 114 Bowie 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot College Park S/D, City Block 50, Lot 7 9. Original Use Residence
 Present Use Commercial

10. Description 1-story, wood frame with bull-nosed siding; brick foundation; ell plan; intersecting gable roof with extended rafter ends, composition shingles, roof ventilator; extended porch with battered wood box columns, concrete floor; paneled wood entry door with two upper glass lights; windows wood double-hung 1/1 inpairs and singly; front yard partially graveled for parking.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	23	to 1	23
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 347

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 202 Bowie 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot College Park S/D, City Block 50, Lot 40 9. Original Use Residence

Present Use Residence

10. Description 1-story, wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with extended rafter ends, composition shingles, roof ventilator; porch roof: front-facing gable; extended porch with wrought iron posts, concrete floor, brick steps; windows 1/1 wood double-hung in pairs; entry door wood with three small lights above.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	22	to 1	22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 348

City/Rural Nacogdoches UTM Sector _____

2. Name Nacogdoches Advertising Association 6. Date: Factual _____ Est. 1900-1920

Address 101 Bremond 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Vernacular Commercial

Address _____ 9. Original Use Commercial

4. Block/Lot Block 43 Present Use Commercial

10. Description 2-story; load-bearing brick; masonry foundation; rectangular plan; 3-bay facade with suspended canopy, storefront filled in with plywood, narrow band of windows, double entry doors wood paneled with upper glass; flat roof with tile coping; brick loading dock; small steelframe windows at second floor.

11. Present Condition Good - Fair

12. Significance Adjacent to railroad.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		32	18	to	32	18
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 349

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 230 Bremond 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 35, Lot 25 Present Use Commercial

10. Description 1-story frame with bull-nosed siding; sheet metal gable roof; extended loading dock across west facade; windows are 4/4 wood double-hung; rectangular plan; vents in gables have hood molds.

11. Present Condition Fair; numerous alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		32	19	to	32 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 350

City/Rural Nacogdoches UTM Sector _____

2. Name Bremond Doll Shoppe & Hospital 6. Date: Factual _____ Est. _____

Address 416 Bremond 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 35, Lot 9 Present Use Residence

10. Description 1-story frame with beveled siding; ell plan; composition hip-and-gable roof; large board on projecting bay; inset porch; windows are set in single pane glass with hood mold; numerous additions at rear.

11. Present Condition Poor; extensively altered; little architectural merit remains.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		32	22	to	32 22
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 351
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 400 Bremond (Across from railroad brick warehouse) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use _____
 4. Block/Lot Block 35, Lot 8-A Present Use _____
 10. Description 1-story frame with bull-nosed siding; composition gable roof pierced by one interior stack; rectangular plan; windows are 4/1 double-hung; entry door has multiple lights; foundation skirted with brick.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		32	21	to	32	21
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 352

City/Rural Nacogdoches UTM Sector _____

2. Name Mississippi Chemical Corp., Tx Limestone Dist. 6. Date: Factual _____ Est. _____

Address 323 Bremond (Next to railroad) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Commercial

4. Block/Lot City Block 35, Lot 25 9. Original Use Commercial

Present Use Commercial

10. Description 1-story; brick load-bearing; brick foundation; rectangular plan; flat roof altered with galvanized metal roofing; canopy across front resting on pipe columns; brick and wood loading dock; 2 entry doors -- one modern wood, one wood paneled with upper glass light; pair of wood frame windows on front, small windows on sides.

11. Present Condition Good - Fair

12. Significance Adjacent to railroad line.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District _____ B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		32	20	to	32	20
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 353
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 523 Bremond 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 33, Lot 4 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 354
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 211 Brewer 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), City Blk 62, Blk 26, Lt 5 Present Use Residence
 10. Description _____

11. Present Condition Fair; vinyl siding.
 12. Significance _____
 13. Relationship to Site: Moved _____ Date _____ Possible _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 355

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 218 Brewer 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JGOrton S/D, City Blk 62, Block 24, Lot 1 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; U-plan; brick infill between pier foundation; intersecting gable roofs with trimmed rafter ends; knee braces, corrugated sheet metal roof; side porch entry on the northeast, entry door on the east; windows 1/1 wood double-hung; car shed at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		42	14A	to	42 14A
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 356
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 713 Bois D'Arc 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Shotgun

4. Block/Lot City Block 5, Lot 10-A-1 9. Original Use Residence
 Present Use Residence

10. Description 1-story rectangular frame shotgun house with straight gable sheet metal roof; horizontal clapboard siding; 4/4 double-hung windows; wood panel entry door off wood porch with skirt roof; red brick piers.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		22	5	to	22 5
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 358
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 717 Bois D'Arc 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular

4. Block/Lot City Block 5, Lot 10-C 9. Original Use Residence
 Present Use Residence

10. Description 1-story rectangular frame residence with saltbox sheet metal roof; asbestos siding; small 4/4 double-hung windows; hall parlor plan with two wood panel doors off wood pent roof porch with 4 x 4 posts; fireplace on north wall.

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	4	to 22	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 359

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1880

Address 720 Bois D'Arc 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 5, Lot 12-C 9. Original Use Residence

Present Use Residence

10. Description 1-story ell-shaped frame residence with composition shingle hip-and-gable roof; horizontal clapboard siding; 2/2 double-hung windows with corbeled hood molds; brick fireplace on projecting bay on north wall; gable overdoor beside fireplace; shed roof addition on west wall.

11. Present Condition Poor

12. Significance Good example of architectural; however, condition is poor.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge, Sally Victor Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other	1986		22	3	to	22	3
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 360

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 724 Bois D'Arc 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 5, Lot 12-D 9. Original Use Residence

Present Use Residence

10. Description 1-story rectangular frame residence with clipped gable sheet metal roof; horizontal bull-nosed siding; 1/1 double-hung windows; inset wood porch with three grouped 4 x 4 posts at outside corner; two glass panel entry doors.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		22	2	to	22	2
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 361

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 728 Bois D'Arc 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot City Block 5, Lot 12-E Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle cross-gable roof with some clipped gables; horizontal bull-nosed siding; 4/1 double-hung windows; small wood porch with gabled overdoor with arch, plain posts.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		21	24	to	21	24
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 362

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915

Address 204 Burk St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 42, Lot 51 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with composition shingles, plain entablature under eaves; extended porch with gable roof, 4 x 4 paired porch supports; central entry door wood and multi-paned glass lights; wood frame windows 1/1, 2/2, 2/1 double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides _____

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____			11	04	to	11	04
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 363
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
Address 214 Burk St. 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Present Use Residence
9. Original Use Residence

10. Description 1-story; wood frame with asbestos siding; brick foundation; rectangular plan; clipped gable roof with extended rafter and beam ends; extended clipped gable porch cover with diagonal bracing, curved fascia and ceiling; wood and multi-paned light entry door with side lights; windows 9/9 and 6/6 wood frame double-hung; exterior brick chimney on north; small frame garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____			11	05	to	11 05
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 364

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 308 Burk St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot H. R. Mast Subdivision 379, Lot 4 Present Use Residence

10. Description 1-story frame with steel applied siding; asphalt gable roof with knee braces and extended rafter ends; projecting wood porch upheld by boxed columns; windows are 1/1 double-hung wood with aluminum diamond pattern screens.

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1985		11	6	to	11 6
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 365
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 314 Burk St. 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence

4. Block/Lot H. R. Mast Subdivision 379, Lot 5 Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt hip-and-gable roof with extended eaves; plain entablature; windows 2/2 aluminum single-hung; inset porch; brick skirt on foundation; garage of similar style at rear.

11. Present Condition Good; window replaced, some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		11	7	to 11	7
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 366
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1915-25
 Address 400 Burk St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Classical Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 64 Present Use Residence

10. Description 1-story; wood frame with beveled wood siding; irregular plan; brick foundation and partial brick apron on east; hip roofs with composition shingles, plain entablature under boxed eaves, shed dormer on east; inset porch with triglyphs on entablature above oversized cylindrical wood columns with plain capitol and base; similar treatment on a side porch on south; two entry doors set at 90-degree angle with classical raised entablature and pilaster door surrounds; screened doors and wood panel doors with upper glass light; windows 1/1

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1985		11	8	to	11	8
				to		
				to		

Continuation sheet
 10. wood double-hung with diamond pattern screens and wood shutters; attic vent at the dormer; lot slopes away from the street corner, several large pecan trees.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 367
 City/Rural Nacogdoches UTM Sector _____
 2. Name Ferguson 6. Date: Factual _____ Est. 1940-50
 Address 309 Burrow St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Rock Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 67 Present Use Residence
 10. Description Note outdoor fire box across street at creek, also native stone; 1-story house, rough dressed fieldstone; gable roofs with composition shingles, rectangular plan; multi-pane steel casement windows; inset entry.

11. Present Condition Good.
 12. Significance Very good example of a fieldstone-faced house.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 368
 City/Rural Nacogdoches UTM Sector _____
 2. Name Elee Littles 6. Date: Factual _____ Est. 1925-35
 Address 1216 Old Butt St. (S) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Cleaver S/D(129), City Blk 53, Blk 1, Lt 10 Present Use Residence
 10. Description 1-story; wood frame; bull-nosed siding; brick pier foundation; rectangular plan; addition on east side; gable roof with composition shingles; porch across front with metal porch supports, single entry door; windows 6/6, 4/4 wood double-hung.

11. Present Condition Fair; altered.
 12. Significance _____
 13. Relationship to Site: Moved Date ca. 1976 Original Site from S. Fredonia on the creek bank.

14. Bibliography _____
 15. Informant Mr. Elee Littles, 4/1/86.
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 369

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 1224 Old Butt St. (S) 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Cleaver S/D (129), City Blk 53, Blk 1, Lt 8 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan, symmetrical facade; gable roofs with composition shingles, extended rafter ends; extended porch with boxed columns, centered door; windows 1/1 wood double-hung; internal brick chimney at ridge.

11. Present Condition Fair; altered, siding at center of porch.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 370
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-25
 Address 1300 Old Butt St. (S) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Cleaver S/D (129), City Blk 53, Blk 1, Lt 7 Present Use Residence
 10. Description _____

11. Present Condition Fair; later addition at rear.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 371
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 1305 Butt St. at Railroad Tracks 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow and Barn

4. Block/Lot Block 19, Lot 17 Present Use Unknown
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation and partial skirt; rectangular plan; pyramidal hip roof with composition shingles; interior brick chimney on east; porch across front with 4 x 4 posts; centered entry door flanked by windows; windows 1/1 wood double-hung; 3-bay facade; pyramidal roofed barn at rear overgrown with vegetation; house surrounded by fields, creek, and railroad.

11. Present Condition Fair; barn in poor condition.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 372
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1411 Butt 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Part of Lot 65-D or E Present Use Residence
 10. Description _____

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 373

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1419 Butt 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot City Block 53, Lot 65-B Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; intersecting gable roofs with extended rafter and beam ends, composition shingles; extended porch with boxed columns over low wall, screened; replacement aluminum windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 375
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1509 Butt 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Jeff Burrows S/D (101), City Blk 53, Lot 4 Present Use Residence
 10. Description _____

11. Present Condition Good; altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 376
 City/Rural Nacogdoches UTM Sector _____
 2. Name Stafford House 6. Date: Factual _____ Est. 1930s
 Address 1513 Butt 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Jeff Brown S/D (101), City Blk 53, Lot 3 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; hip roof; rectangular plan; inset porch with wood post; entry door with upper glass light; 3/1, 6/6 wood windows, composition shingles.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 377
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1514 Butt 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JThorn S/D (599), City Blk 53, Blk 6, Lot 3 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 379
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925
Address 1807 Butt 7. Architect/Builder _____
Contractor _____

3. Owner _____ 8. Style/Type Bungalow
Address _____ 9. Original Use Residence

4. Block/Lot JGOrton S/D(437),CityBk 62, Bk 19, Lt10A Present Use Residence

10. Description 1-story; wood frame with horizontal siding; brick pier foundation; rectangular plan; clipped gable roof with extended rafter ends, composition shingles; extended porch with boxed columns, entry door with four vertical upper glass lights; windows 4/1 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____
NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
Other _____
to _____
to _____
to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 380
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1909 Butt 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437),CityBlk 62, Bk 24, Lt 10 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 381

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 2009 Butt 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JGOrtonS/D(437), City Blk 62, Blk 26, Lt 8 Present Use Residence

10. Description 1-story; wood frame with lapped board siding; rectangular plan; gable roof with extended rafter ends; extended porch with metal supports; two entry doors; windows 6/6 wood double-hung; composition shingles on roof.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 382

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 130 California St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot T. J. Lloyd 2nd S/D, City Block 50, Lot 6 Present Use Residence

10. Description 1-story; wood frame construction with asbestos siding and brick veneer skirt; brick foundation; ell plan; intersecting gable roof with extended beam and rafter ends, composition shingles; projecting porch with battered wood columns and brick piers, concrete floor and semi-circular brick steps; windows 6/1, singly and in pairs; two symmetrical entry doors; porte cochere at rear; large magnolia tree in front yard.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1985		2	17	to	2	17
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 383

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 204 California St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Farmhouse

4. Block/Lot T. J. Lloyd 2nd S/D, City Block 50, Lot 7 Present Use Residence

10. Description 2-story; wood frame construction with asbestos siding; brick foundation; rectangular plan; straight side-facing gambrel roof with shed dormer and smaller gables; cornice returns, attic vent; composition shingles; projecting porch stoop with corner posts and awning (metal slats); concrete and brick steps; windows 6/6 wood double-hung in pairs and triples; rock chimney and sway wall rusticated on east facade; detached 1-story garage apartment.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1985		2	16	to	2	16
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 384
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930's
Address 214 California St. West 7. Architect/Builder _____

3. Owner Libby Daly Contractor _____
Address Lloyd St. 8. Style/Type Bungalow

4. Block/Lot T. J. Lloyd 2nd S/D, City Block 50, Lot 9 9. Original Use Residence
Present Use Residence

10. Description 1-story, wood frame construction with asbestos siding; rectangular plan; intersecting gable roof with cornice returns, composition shingles; projecting porch with wrought iron corner posts, brick porch and steps; windows 4/1 wood double-hung in singles and triples; entry door wood panel with vertical glass lights; exterior brick chimney with corbeled cap; carport on east (contemporary).

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	15	to 2	15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 385
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 113 California St. East 7. Architect/Builder _____

3. Owner C. B. Davis Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot M C Johnson S/D, City Block 50, Lot 29-B 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame construction with asbestos siding; brick pier foundation; massed plan; intersecting gable roofs with clipped gable ends on east/west gables; attic vents and dormer, composition shingles; projecting porch - remodeled with wrought iron posts, concrete porch and steps; windows 4/1 wood double-hung in singles and triples, later 2/2 double-hung; entry door wood solid panels; brick chimney with corbeled cap; 2 detached garage buildings, one 2-story on west side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	18	to	2 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 386
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-30
 Address 2629 Canyon (next to St. James Church) 7. Architect/Builder _____
 Contractor _____
 3. Owner Henry Malone 8. Style/Type Log House
 Address 2629 Canyon 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story log and lap frame; cross plan; composition gable roof pierced by metal chimney flue; extended rafter ends; logs are square-notched; windows are 4/4 wood double-hung; small projecting porch upheld by 4 x 4 wood posts.

11. Present Condition Fair
 12. Significance Built just after Civil War; former owner now lives on Durst St.; may be named Aldridge.
 13. Relationship to Site: Moved Date 1967 Original Site Moved from Appleby Sands Road.

14. Bibliography _____
 15. Informant Henry Malone
 16. Recorder Sally Victor, Larry Hodge Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 35 17 to 35 17
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 387
 City/Rural Nacogdoches UTM Sector _____
 2. Name St. James Baptist Church 6. Date: Factual _____ Est. _____
 Address 2633 Canyon 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Church
 Address _____ 9. Original Use Church
 4. Block/Lot Block 61 Present Use Church

10. Description 1-story; wood frame with horizontal board siding and bull-nosed siding; pier foundation; rectangular plan with additions at northwest corner; gable roof with composition shingles, extended rafter ends; extended entry with double wood panel doors; windows replacement 2/2 sited in pine groves.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	16	to	35 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 388
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925
 Address 604 Cariker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Ira Land Resub (336), Block 62, Lot 12 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; corrugated metal foundation skirt; irregular plan; gable roof with extended rafter ends, beam ends, composition shingles; inset porch with corner post; wood panel entry door with upper glass; windows 2/2 aluminum replacement.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		18	9	to	18	9
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 389
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 608 Cariker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Ira Land Resubdivision (336), Lot 11 Present Use Residence
 10. Description 1-story frame with gable composition roof; rectangular plan; projecting porch; 4/4 wood double-hung windows; wood bull-nosed siding; foundation skirted.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1986		18	10	to	18	10
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 390

City/Rural Nacogdoches UTM Sector

2. Name _____ 6. Date: Factual _____ Est. 1930-35

Address 612 Cariker 7. Architect/Builder _____

3. Owner _____ Contractor Mr. Land

Address _____ 8. Style/Type Bungalow

4. Block/Lot Ira Land Resub (336), City Block 62, Lot 10 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; gable roof with extended rafter ends, composition shingles; rectangular plan; extended porch with 4 x 4 posts; 2/2 aluminum replacement windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		42	10A	to	42	10A
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 391
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-35
 Address 620 Cariker 7. Architect/Builder _____
 Contractor Mr. Land
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Ira Land Resub (336), City Block 62, Lot 8 Present Use Residence
 10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends; tarpaper roofing; inset porch with boxed column; windows 4/4 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		42	11A	to	42 11A
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 392
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 621 Cariker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonSD(437), City Blk 62, Blk 20, Lt Present Use Residence
 10. Description _____

11. Present Condition Good; altered by brick apron across front, carport on north.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 393
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1940
 Address 713 Cariker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 62, Bk 19, Lt 8A Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 394
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 717 Cariker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrton S/D(437), CityBlk 62, Blk 19, Lt 9 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; ell plan; brick pier foundation; gable roof with extended rafter ends and beam ends, composition shingles; inset porch with shed roof, chamfered corner post; windows 4/4 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1986		42	12A	to	42	12A
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 395
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-42
 Address 721 Cariker 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 62, Bk 19, Lt 9A Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with extended rafter ends, composition shingles, interior brick chimney; extended porch with 4 x 4 posts; windows 1/1 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		42	13A	to	42	13A
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 396

City/Rural Nacogdoches UTM Sector _____

2. Name Grapevine Cape 6. Date: Factual _____ Est. _____

Address 110 Carolyn 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot LL.Sturdevant S/D (580), City Blk 45, Lt 4 9. Original Use Residence

Present Use Residence

10. Description 2-story rectangular frame residential structure with composition shingle straight gable roof; horizontal clapboard siding; 6/6 double-hung windows; cedar shakes on gable; fabric awning over added patio; brick entry porch is protected by pent-roof over door with plain box columns; wood door with 1 light; windows on first floor replaced.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		24	16	to	24	16
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 398
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 116 Carolyn 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Chalet
 Address _____ 9. Original Use Residence
 4. Block/Lot LL.Sturdevant S/D (580), City Blk 45, Lt 6 Present Use Residence
 10. Description Vinyl siding.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 400
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1603 Castleberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story; wood frame with lapped board siding, brick pier foundation; ell plan; gable roofs with composition shingles (deteriorating); inset porch with paired 2 x 4 supports; 2 entry doors set at 90 degrees; windows 1/1 wood double-hung arranged in pairs.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18	24	to	18 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 401

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1604 Castleberry 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 58 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with aluminum siding; fiberglass foundation skirt; rectangular plan; gable roof with knee braces, extended rafter ends, composition shingles; extended porch with boxed wood columns, 2 wood panel entry doors with upper glass; windows 4/4 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18	25	to	18 25
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 402
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1616 Castleberry 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 58 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; concrete pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends; extended porch with boxed columns, 2 wood panel entry doors with 4 vertical glass lights; windows 4/4 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		18	26	to	18	26
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 403
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1618 Castleberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; raised pier foundation; rectangular plan; gable roofs with composition shingles; extended porch with chamfered 4 x 4 posts; 2 wood panel entry doors with upper glass; windows 4/4 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 19 1 to 19 1
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 404
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1619 Castleberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story frame with vinyl siding; rectangular plan; sheet metal gable roof with extended rafter ends; projecting porch upheld by iron columns; windows are 2/2 aluminum double-hung; pier and beam foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	2	to 19	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 405
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1620 Castleberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story frame with bull-nosed and 105 siding; massed plan; composition gable roof with extended rafter ends; addition on south side; pier and beam foundation; windows are 4/4 wood double-hung; projecting porch upheld by wood columns, decorative wood scrolls.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	3	to 19	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 408
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1112 Cedar 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 19-A Present Use Residence
 10. Description 1-story; wood frame; rectangular plan; clipped gable roof, composition shingles; 1/1 wood double-hung windows; central entry door wood with upper glass light.

11. Present Condition Fair; altered by asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 38 23 to 38 23
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 409
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1204 Cedar 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 40 Present Use Residence
 10. Description 1-story frame with drop siding; composition gable roof with extended rafter ends; projecting porch supported by 4 x 4 posts; windows are 4/4 wood double-hung; brick pier foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 38 24 to 38 24
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 411
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1300 Cedar 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 53, Lot 32 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; gable roofs with composition shingles; metal awning over entry on north; roof with wood posts at porch on west; entry door on north wood with multipane glass above; windows 1/1 wood double-hung and picture window.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	2	to 39	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 412
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1307 Cedar 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Nannie Blount S/D 63, Block 53, Lot 6 Present Use Residence

10. Description 1-story frame with lap siding; sheet metal gable roof pierced by 2 interior stacks; windows are 4/4 wood double-hung or filled in with sheet metal; 2 projecting porches; brick pier foundation.

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

PHOTO DATA
 /RTHL /HABS (no.) TEX- _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	3	to 39	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 416
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 2101 Center Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence

10. Description 1-story frame with bull-nosed siding; ell plan; composition gable roof; inset porch supported by iron columns; windows are 4/1 wood double-hung, modern bay window on south facade; brick pier foundation; garage at rear.

11. Present Condition Good; porch and bay have been modernized.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	5	to 39	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 417
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Auto Parts 6. Date: Factual _____ Est. 1930s
 Address 2309 Center Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Storage Shed
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 54 Present Use Commercial - Vacant
 10. Description 1-story masonry with stucco; awning across front; modern windows and 8/8 wood double-hung; paneled doors; bungalow-style garage on east side.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	6	to 39	6
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 418
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2401 Center 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Fair; brick apron added to main facade.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

PHOTO DATA
 /RTHL /HABS (no.) TEX- _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 419
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2412-A Center 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Altered windows, aluminum siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 421
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2500 Center 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
					to		
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 422
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 2510 Center Road 7. Architect/Builder _____

3. Owner Lewis L. Cook Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 Present Use Residence
 9. Original Use Residence

10. Description 1-story frame with vinyl siding; composition hip roof with extended eaves; projecting porch supported by iron columns, on brick base; 1/1 wood double-hung windows; garage at rear.

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		39	7	39	7

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 423
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 2606 Center 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 424
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2631 Center Road 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition clipped gable roof; projecting porch and porte cochere supported by boxed columns on brick piers; extended rafter ends and knee braces; 3/1 wood double-hung windows in twos and threes; 1 exterior brick chimney on east facade; brick pier foundation.

11. Present Condition Excellent

12. Significance Very good example of style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	8	to 39	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 426
 City/Rural Nacogdoches UTM Sector _____
 2. Name James A. Spratley 6. Date: Factual _____ Est. 1910-30
 Address 2715 Center Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 427
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 2823 Center Rd. 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 54 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof; large exterior chimney on south facade; windows are 1/1 wood double-hung with shutters; extended rafter ends and knee braces; stoop porch supported by iron columns; brick pier foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	9	to 39	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 428

City/Rural Nacogdoches UTM Sector _____

2. Name J. Mayes 6. Date: Factual _____ Est. 1910-30

Address 2902 Center 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 64 Present Use Residence

10. Description 1-story frame with green asbestos siding; composition gable roof with extended rafter ends; massed plan; inset porch upheld by decorative columns; 4/1 wood double-hung windows; 2 garages at rear.

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	10	to 39	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 429

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 2912 Center 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 64 9. Original Use Residence

Present Use Residence

10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 430

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890-1910

Address 3105 Center 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 54 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story frame with drop siding; composition hip-and-gable roof pierced by 3 gables on south facade; inset porch supported by Doric columns; brick porch; brick pier foundation; bannister on porch; 1/1 and 6/6 wood double-hung windows; garage at rear.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	11	to	39 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 431
 City/Rural Nacogdoches UTM Sector _____

2. Name T. H. Farr 6. Date: Factual _____ Est. 1900-30
 Address 3202 Center 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 64 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with green asbestos siding; composition gable roof; projecting porch supported by wood posts; windows are 4/4 and 6/6 wood double-hung; foundation skirted.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		39	12	39	12

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 432
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-20
 Address 3312 Center Rd. 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 64 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof pierced by dormer; projecting porch supported by boxed columns; 2 entry doors; windows are 1/1 wood double-hung with hood mold; another house at rear is bungalow with no porch.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1986		39	13	to	39	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 433
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 3506 Center Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 434

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 3823 Center Rd. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; projecting porch upheld by boxed columns; addition on east side; windows are 6/6 wood double-hung; 2 entry doors with multiple lights; foundation skirted.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	14	to 39	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 438
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 905 Cason 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description _____

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 439
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual 1942 Est. _____
 Address 1606 Chandler 7. Architect/Builder Mr. Thomas

3. Owner Mr. Willie Thomas Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot JThorn S/D(599), City Blk 53, Blk 4, Lt 15 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; newer brick foundation skirt; rectangular plan; gable roof with composition shingles, central interior brick chimney; extended porch with battered boxed columns over brick piers; windows 6/6 wood double-hung with shutters; carport on west.

11. Present Condition Good

12. Significance About 3 houses on street when Mr. Thomas moved here; mostly trees all the way to the highway. Mr. Thomas built the house with lumber from the J. E. Stone Lumber Co.,

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mr. Willie Thomas

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

12. where he worked; also worked for Frost/Johnson - they closed in 1956. Mr. Thomas is 80 years old.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 440
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1700 Chandler 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JThorn S/D(599), City Blk 53, Blk 6, Lt 23 Present Use Residence
 10. Description _____

11. Present Condition Fair; windows altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 441
City/Rural Nacogdoches UTM Sector _____

2. Name Mrs. Velma Farnay 6. Date: Factual _____ Est. 1910-25
Address 1013 Cherry 7. Architect/Builder _____
Contractor _____

3. Owner _____ 8. Style/Type Vernacular w/ Greek Revival Inf
Address _____ 9. Original Use Residence

4. Block/Lot Block 53, Part of Lot 35 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding and beveled siding; raised pier foundation; rectangular plan; intersecting gable roofs with corrugated metal roofing; shed roof over porch with boxed columns, central door; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date ca. 1967 Original Site Moved from S.

Fredonia

14. Bibliography _____

15. Informant Velma Forney, 4/1/86

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 442
 City/Rural Nacogdoches UTM Sector _____

2. Name Cleaver Cemetery 6. Date: Factual _____ Est. Before 1910
 Address 0000 Cherry St. 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Historic Cemetery

4. Block/Lot Block 53, Lot 43 9. Original Use Cemetery
 Present Use Cemetery

10. Description Unfenced cemetery on hill at Cherry and Cleaver Streets; large juniper trees; earliest marked grave 1902, large percentage of graves dated 1920-50s; several veterans of WWI and WWII; family names: Cleaver, Blount, Campbell, Brooks and others; surveyors stakes on east boundary, Cherry Street to be widened and paved.

11. Present Condition Good

12. Significance Cleaver family owned a large part of the land in this part of Nacogdoches, older family; historic cemetery; families from this neighborhood are buried here.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Geraldine Brown, 4/1/86

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 443
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 210 Church St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 3, Lot 17-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick foundation; ell plan; intersecting gables with composition shingles, corner brackets and extended rafter and beam ends; inset porch with short boxed wood columns over brick piers, single 4 x 6 rail with faceted ends; windows 1/1 wood double-hung; 2 entry doors set at 90 degrees, wood with geometric glass light pattern, west door with side lights; exterior brick chimney on north side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 24 17 to 24 17
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 444
 City/Rural Nacogdoches UTM Sector _____

2. Name Edwin H. Moore, Atry. 6. Date: Factual _____ Est. 1900
 Address 216 Church St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Folk Victorian

4. Block/Lot Block 3, Lot 13 9. Original Use Residence
 Present Use Residence and Office

10. Description 2-story; wood frame construction with lapped siding; brick foundation; intersecting gable roofs with composition shingles, plain entablature; windows wood double-hung 2/2 with some 4/4 at rear; 1-story asymmetrical wrapped porch with Tuscan columns; single entry door with upper glass light and relief ornamentation; ell plan.

11. Present Condition Good; altered, entry door now single-hung window; back wing bull-nosed siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	18	to	24 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 445
 City/Rural Nacogdoches UTM Sector _____

2. Name S. S. Bagley / T. H. Summers House 6. Date: Factual 1890 / 1913 Est. _____
 Address 304 Church St. North 7. Architect/Builder Dietrich Rulfs
 Contractor _____

3. Owner Dr. Jere Jackson 8. Style/Type Victorian
 Address 304 Church St. North 9. Original Use Residence

4. Block/Lot Block 3, Lot 9 Present Use Residence

10. Description 1-1/2 story; wood frame construction with bull-nosed siding; brick foundation; ell plan; hipped roof with hipped dormers, composition shingles, overhangs with beaded soffit and plain entablature, 1st floor with cornice moulding; inset asymmetrical wraparound porch with wood floor, boxed wood columns and simple balusters, beaded ceiling, portion of south porch enclosed for sun porch; windows 1/1 wood double-hung, single-hung in dormers; entry door wood paneled w/ large vertical glass light, simple hood mold above door & 1st floor

11. Present Condition Excellent; remodeled in 1913; 2nd floor, new siding, and porch remodeled.

12. Significance Architecturally significant.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor, Sally Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		24	19	to 24	19
					to	
					to	

Continuation sheet

10. windows; raised sidewalk with curb on Church Street side; fenced yard on west and north sides.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 447
 City/Rural Nacogdoches UTM Sector _____

2. Name Mrs. Sarah Richardson House 6. Date: Factual 1897, 1915 Est. _____
 Address 315 Church St. North 7. Architect/Builder Dietrich Rulfs

3. Owner Mr. & Mrs. Eugene Sanders Contractor _____
 Address 315 Church St. North 8. Style/Type Victorian Bungalow

4. Block/Lot Block 3, Lot 5 Present Use Residence
 9. Original Use Residence

10. Description 1-1/2 story; wood frame construction with bull-nosed siding; brick foundation; rectangular plan with projecting chamfered bays on north and south and projecting entry on east; intersecting hip-and-gable roofs with composition shingles, hipped dormers and second story balcony over entry; gallery porch on three sides with boxed wood columns and simple wood railing, wood floor, beaded ceiling, plain entablature; windows 1/1 wood double-hung with wood trim string course above; upper story windows fixed with diamond and prism-shaped

11. Present Condition Good; rebuilt as 1-story in 1915.

12. Significance Built at ornate 2-story; fire in 1915 destroyed Eastlake style porches, and second floor.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975; Fires and Fireman, pp. 71-72.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor, Sally Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	/RTHL	/HABS (no.) TEX-	PHOTO DATA			
NR:	/Individual	/Historic District	B&W 4 x 5s	slides _____		
	/Thematic	/Multiple-Resource	35 mm Negs.			
NR File Name	YEAR	DRWR	ROLL	FRME	ROLL FRME	
	1986		24	20	to	24 20
Other					to	
					to	

Continuation sheet

10. obscured glass; entry door wood paneled with large glass light and side lights; interior brick chimneys on north and south; 2-car garage at rear, wood frame with gable roof; large oak trees on Church Street side.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 448
 City/Rural Nacogdoches UTM Sector _____

2. Name Lee Hardeeman House Antiques 6. Date: Factual 1892 / 1912 Est. _____
 Address 316 Church St. North 7. Architect/Builder Dietrich Rulfs
 Contractor _____

3. Owner Dr. Jere Jackson 8. Style/Type Victorian
 Address 304 Church St. North, Nacogdoches, Texas 9. Original Use Residence

4. Block/Lot Block 3, Lot 6 Present Use Commercial

10. Description 2-1/2 story; wood frame construction with bull-nosed siding; brick foundation; ell plan; intersecting hip roofs with composition shingles, hipped dormer, plain entablature; asymmetrical wraparound porch with Tuscan wood columns and spindle railing, wood floor; windows 1/1 wood double-hung, window in dormer fixed with diamond and prism-shaped muntins; entry door wood paneled with upper glass light and transom light; interior brick chimneys on north and south, north chimney with barrel vault cap; projecting bays on north

11. Present Condition Excellent; altered in 1912.

12. Significance Was residence of Miss Gladys Hardeeman.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor, Sally Victor Date January 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

	<input type="checkbox"/> RTHL	<input type="checkbox"/> HABS (no.) TEX-	PHOTO DATA			
NR:	<input type="checkbox"/> Individual	<input type="checkbox"/> Historic District	<input type="checkbox"/> B&W 4 x 5s	<input type="checkbox"/> slides		
	<input type="checkbox"/> Thematic	<input type="checkbox"/> Multiple-Resource	<input type="checkbox"/> 35 mm Negs.			
NR File Name		YEAR	DRWR	ROLL	FRME	ROLL FRME
		1986		24	21	to 24 21
Other						to
						to

Continuation sheet

10. and south sides, north bay chamfered, south bay with one chamfered side at first floor porch; raised sidewalk with concrete curb on Church Street side.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 449

City/Rural Nacogdoches UTM Sector _____

2. Name Old Nacogdoches University Bldg. 6. Date: Factual 1859 Est. _____

Address 0000 Washington Square, N. Church St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Federal

4. Block/Lot Block 3, Lot 1 Present Use Museum

10. Description 2-story brick masonry w/ load-bearing walls; rectangular plan; entry has 2-story portico w/ entablature, 4 colossal Doric columns; 3 bays on main facade are defined by 4/4 light double-hung windows & double door entry w/ side lights & transom & four brick pilasters; east& west facades have similar facades; the 6 bays defined by windows & pilasters; cedar shingle roof pierced by corbeled brick chimney and frame belvedere topped by pineapple finial; newer masonry load-bearing addition at rear; north facade has 6/6 light double-hung

11. Present Condition Good; alteration at rear.

12. Significance Listed on the National Register (1971) and as a Recorded Texas Historic Landmark. Has HABS drawings.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC marker files.

15. Informant _____

16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		24	23	to	24	23
Other					to		
					to		

Continuation sheet

10. windows.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 450
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Public Schools Auditorium & Gym 6. Date: Factual 1927 Est. _____
 Address 0000 Church St. North between Church & Fredonia 7. Architect/Builder Shirley Simons, Arch.
 Contractor F. A. Mote, Builder
 3. Owner Nacogdoches Independent School District 8. Style/Type Georgian Revival
 Address _____ 9. Original Use Educational
 4. Block/Lot Block 3, Lot 1 Present Use Educational
 10. Description 2-story masonry; load-bearing walls with articulated quoins; brick foundation; carved limestone entry with pilasters and garlands; east facade has six bays, 3 with dormers over Palladian-style windows; doorways have fan lights; gable roof with composition shingleshas dormers and side gables breaking the pediment, octagonal cupola at ridge, cornice returns; rectangular plan; windows are in pairs or triples, double-hung with relief panel spandrel panel with shield and swag ornamentation, shell and scroll pediment above the entablature;
 11. Present Condition Good
 12. Significance Architect, Shirley Simons had substantial practice in Lufkin and Tyler; also designed structures in Gregg County near Gladewater.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	/RTHL	/HABS (no.) TEX-	PHOTO DATA						
NR:	/Individual	/Historic District	B&W 4 x 5s	slides					
	/Thematic	/Multiple-Resource	35 mm Negs.						
NR File Name			YEAR	DRWR	ROLL	FRME	ROLL	FRME	
			1986		24	22	to	24	22
Other							to		
							to		

Continuation sheet

10. windows placed in symmetrical arrangements on facade. Primary entry on south facade, two-story stone frontispiece with classical entablature and pilasters, three bays. Symmetrical arrangements of facades with variations in windows and arches, elliptical on east, semicircular on west, both facades use Palladian arrangement of windows at second floor; south facade with windows on either side of frontispiece entry, lunette window above; dedication cornerstones at southeast corner. Brick chimney breaks the cornice at the northwest corner; four bay facade on north face, small double hung multi paned windows.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 451
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 212 Church St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 23, Lot 8. Present Use Residence
 10. Description Twin to 216 S. Church St.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 452
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 216 Church St. South 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 23, Lot 7 & Part of Lot 9 Present Use Residence

10. Description 1-story; wood frame with asbestos siding; brick pier foundation; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; inset porch with turned wood post, side-facing entry door wood with multipane glass; windows 3/1 wood double-hung in ones, twos, and threes.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	/RTHL	/HABS (no.)	TEX-		PHOTO DATA				
NR:	/Individual	/Historic District		B&W 4 x 5s	slides				
	/Thematic	/Multiple-Resource		35 mm Negs.					
NR File Name			YEAR	DRWR	ROLL	FRME		ROLL	FRME
			1986		29	10	to	29	10
Other							to		
							to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 453

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 304 Church St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 23, Part of Lot 10 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding, brick pier foundation; rectangular plan; hip roof with composition shingles; inset porch with boxed columns over low wall, 2 entry doors set at 90 degrees wood panel with upper glass light, storm doors; windows 4/4 wood double-hung; frame shed at rear.

11. Present Condition Fair - Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRI No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		29	11	to	29	11
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 454
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 305 Church St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 22, Part of Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by vinyl siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 455
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 308 Church St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 23, Lot 11 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 456

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920s

Address 319 Church St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 22, Part of Lot 8 Present Use Residence

10. Description 1-story; wood frame with composition shingles over bull-nosed siding; pier foundation; rectangular plan; projecting porch with battered wood columns, 2 entry doors wood paneled with upper glass lights; gable roof with composition shingles, tarpaper patches; windows 1/1, 4/4 wood double-hung, 2/2 aluminum replacement; central brick chimney; large sycamore in front.

11. Present Condition Good -- Roof in fair condition.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 25, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		29	12	to	29	12
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 457
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 323 Church St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 22, Part of Lot 8 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roofs with extended rafter ends, beam ends; composition shingles; extended porch with cylindrical columns; entry door wood with multi-paned glass, storm door; windows 3/1 wood double-hung in pairs, multi-paned picture window on west (front) with shutters and awning above.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		29	13	to	29 13
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 458

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-25
Address 402 Church St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Victorian Cottage/Double Shotgun

4. Block/Lot Block 23, Part of Lot 11-A or 11_C 9. Original Use Residence
Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; raised brick pier foundation; rectangular plan; gable roof with extended rafter ends, brackets; extended porch with boxed wood columns over brick piers, screened porch; 2 entry doors wood paneled with upper glass; windows 3/1 wood double-hung in pairs.

11. Present Condition Good - Fair; roof has deteriorated shingles.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

PHOTO DATA

NR: RTHL HABS (no.) TEX- _____
 Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1986		29	14	to	29	14
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 459
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 412 Church St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 23, Lot 11-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with narrow horizontal board siding; raised brick pier foundation; rectangular plan; gable roof with composition shingles; extended rafters, brackets; small, extended gabled porch with boxed columns with fretwork above, central entry door wood paneled with upper glass light; windows 1/1 wood double-hung with half screens; adjacent to Banita Creek.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	15	to 29	15
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 461

City/Rural Nacogdoches UTM Sector _____

2. Name Anderson Grain Company 6. Date: Factual _____ Est. _____

Address 401 Church St. South & Railroad Siding 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot Block 22, Lot 9 Present Use Grain Storage

10. Description Two wood frame, 1-story warehouse buildings; rectangular plan; pier foundation; gable roofs with ptd corrugated sheet metal roofing; replacement aluminum windows on west building; 2 load docks with sliding panel doors on east building; tower with grain distribution mechanism at northeast corner, metal sheathed; railroad siding on north.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	16	to	29 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 464

City/Rural Nacogdoches UTM Sector _____

2. Name Southern - Davidson - Graves House 6. Date: Factual _____ Est. 1900 - 1908

Address 618 Church St. South (South of 610) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage & Outbuildings

9. Original Use Residence

4. Block/Lot City Block 30, Lots 9 and 10 Present Use Residence

10. Description 1-story; wood frame with lapped board siding; brick pier foundation; symmetrical plan; hip-and-gable roofs with patterned composition shingles; extended hipped porch with gable above, turned wood porch supports with scroll brackets, central projecting entry, wood paneled door with upper glass light, screened door; windows 2/2 wood double-hung with hood mold; shed roof addition at rear (fairly early) with 2/2 windows; 2 wood frame, vertical board outbuildings at rear with galvanized metal roofing; interior brick chimney at rear of the

11. Present Condition Fair - Good; roof has some deteriorated areas, paint weathered off siding.

12. Significance Architectural merit.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	18	to	29 18
Other					to	
					to	

Continuation sheet
10. house.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 465

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 1310 Cleaver 7. Architect/Builder _____

Contractor _____

3. Owner Mrs. Davis 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Cleaver S/D (129), City Block 53, Lot 4-A Present Use Residence

10. Description 1-story, wood frame with bull-nosed siding; foundation skirt; rectangular plan; gable roof with composition shingles, extended rafter and beam ends; shed roof over porch with 2 x 4 braces; inset porch with boxed corner post, screened porch with lattice trim; 2 entry doors set at 90 degrees; 3/1 wood double-hung windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date 1940s Original Site Frost/Johnson Mill area

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 466

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1938-45

Address 1311 Cleaver 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot Cleaver S/D (129), City Blk 53, Blk 2, Lt 5 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with composition shingles; windows 6/6 wood double-hung.

11. Present Condition Fair

12. Significance Purchased by or rented by Lily Brewer's mother in the early 1940s.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Lily Brewer

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 467
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-45
 Address 1312 Cleaver 7. Architect/Builder _____

3. Owner Lily Brewer Contractor _____
 Address _____ 8. Style/Type Cottage

4. Block/Lot CleaverS/D(129), City Blk 53, Blk 3, Lt 3B 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding, tarpaper siding; rectangular plan; gable roof with composition shingles; central brick chimney; shed porch over roof with boxed columns, 2 entry doors; windows 6/6 wood double-hung; one room added after the house was moved; carport on the east side.

11. Present Condition Good - Fair

12. Significance Mill house on Frost Johnson property.

13. Relationship to Site: Moved Date 1940s Original Site Frost Johnson Mill
area; purchased from Mr. Roy Gray.

14. Bibliography _____

15. Informant Mrs. Lily Brewer

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 468
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1316 Cleaver 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot CleaverS/D(129), City Blk 3A, Blk 3, Lt 3A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with composition shingles; extended porch with cylindrical columns, 2 entry doors; windows 4/4 wood double-hung.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Yes, date unknown _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource _____ 35 mm Negs.
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 469
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1413 Cleaver 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Cottage

4. Block/Lot J Thorn S/D (599), City Blk 53, Blk 2, Lt 2 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding, brick pier foundation; rectangular plan; hip roof with extended rafter ends; inset porch on southwest corner with boxed corner columns, 2 wood paneled entry doors set at 90 degrees; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 470
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1507 Cleaver 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Cottage

4. Block/Lot J Thorn S/D (599), City Blk 53, Blk 2, Lt 5 9. Original Use Residence
 Present Use Residence

10. Description _____

11. Present Condition Fair; altered by vinyl or aluminum siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 471
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1508 Cleaver 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot J Thorn S/D (599), City Blk 53, Blk 3, Lt 3 Present Use Residence
 10. Description _____

11. Present Condition Fair - Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 472
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-40
Address 1517 Cleaver 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Cottage

4. Block/Lot Julia Thorn S/D (599), Block 2, Lot 8 9. Original Use Residence
Present Use Residence

10. Description 1-story; wood frame with narrow board siding; brick pier foundation; rectangular plan; composition shingles with extended rafter ends, gable roof; extended porch with builtup 2 x 4 supports; wood panel entry door with upper glass; windows 4/4 wood double-hung.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 473
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1601 Chandler 7. Architect/Builder _____
 Contractor _____
 3. Owner Lonnie White 8. Style/Type Board & Batten Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JThorn S/D (599), City Blk 53, Blk 3, Lt 19 Present Use Residence
 10. Description _____

11. Present Condition Fair; aluminum replacement windows.

12. Significance Lonnie White owns about three other houses on the street; lived here in the early 1940s.

13. Relationship to Site: Moved Date 1960-65 Original Site Moved ca. 1960-65

14. Bibliography _____

15. Informant Mr. Willie Thomas

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 474
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-40
Address 1609 Cleaver 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot JThorn S/D (599), City Blk 53, Blk 2, Lt 12 9. Original Use Residence
Present Use Residence

10. Description 1-story; wood frame with beveled wood siding; brick foundation; rectangular plan; gable roof with extended rafter ends, composition shingles; hipped roof over extended porch, boxed columns, wood paneled entry door with upper glass; windows 6/6 wood double-hung; frame shed and carport at rear.

11. Present Condition Good; altered by brick foundation skirt at front; small addition on east side.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 475
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 110-112 College St. West 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Duplex

4. Block/Lot Lacy Hunt S/D (301), City Block 50, Lot 3 Present Use Duplex

10. Description 1-story; wood frame with bull-nosed siding; brick foundation, bull-nosed siding; foundation skirt; rectangular plan with addition at rear, carports on east and west; clipped gable roofs with front dormer, closed gable ends, composition shingles, deep eaves; symmetrical extended porches with paired 4 x 4 porch supports and railing, central wood and multipane door; windows 3/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	5	to 36	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 476
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 115 College St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50, Lot 17-4 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 477
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 118 College St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Lacy Hunt S/D (301), City Block 50, Lot 5 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 478
 City/Rural Nacogdoches UTM Sector _____

2. Name L & R Discount Batteries 6. Date: Factual _____ Est. 1920-30
 Address 119 College St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

9. Original Use Residence
 4. Block/Lot City Block 50, Lot 17-3 Present Use Commercial

10. Description 1-story; wood frame with bull-nosed siding; brick foundation with metal skirt; rectangular plan; clipped gable roof with composition shingles, extended rafter and beam ends; inset porch with boxed wood columns, 2 entry doors set at 90 degrees; wood with upper glass light; windows 1/1 wood double-hung, generally in pairs.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	6	to 36	6
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 479
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 123 College St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50, Lot 17-2 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 480
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 124 College St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Lacy Hunt S/D (310), City Blk 50, Lt 6-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roofs with composition shingles, extended rafter and beam ends, central brick chimney with deteriorating cap; brick pier foundation with brick infill; extended porch with boxed wood columns, entry door with screened door; windows 4/1 wood double-hung; detached wood frame garage.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 11, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1986		36	7	to	36	7
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 481

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 203 College St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50, Lot 17-10 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces; projecting porch has battered columns on brick piers; windows are 4/1 wood double-hung; rectangular plan; entry door has vertical lights; foundation skirted; garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____

1986		36	8	to	36	8
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 482
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 207 College St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50, Lot 17-11 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by vinyl siding, metal porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 483
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 213 College St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50, Lot 17-12 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with extended rafter and beam ends, composition shingles, vents at north gable ends; extended porch with battered, boxed wood columns on brick piers, entry door wood paneled with upper glass lights; windows 3/1 wood double-hung, generally in pairs; detached wood frame garage in poor condition.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	9	to 36	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 485
 City/Rural Nacogdoches UTM Sector _____
 2. Name Lumber Jack Shack 6. Date: Factual _____ Est. 1930s
 Address 109 College St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Langford Pl S/D 339, Block 50, Lot 25 Present Use Retail
 10. Description _____

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 486
 City/Rural Nacogdoches UTM Sector _____
 2. Name Catholic Student Center 6. Date: Factual _____ Est. 1930s
 Address 211 College St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Tudor Frame
 Address _____ 9. Original Use Residence
 4. Block/Lot Langford Pl S/D 339, Block 50, Lots 32-33 Present Use Religious
 10. Description _____

11. Present Condition Good; extensively altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 487

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
Address 000 East Main at Community Grocery Road 7. Architect/Builder _____

Contractor _____

3. Owner Otis and Pauline Alexander 8. Style/Type Bungalow
Address _____ 9. Original Use Residence

4. Block/Lot Block 64 Present Use Residence

10. Description 1-story; wood frame with beveled siding; rectangular plan; brick foundation; gable roofs with extended rafter and beam ends, composition shingles, exterior brick chimney on north; inset porch with 2 multipane wood entry doors set at 90 degrees; 4 x 4 posts; windows wood double-hung 4/1, 6/6; second porch on southeast side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography Otis and Pauline Alexander

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	18	to	19 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 488
 City/Rural Nacogdoches UTM Sector _____
 2. Name Cooper Home 6. Date: Factual 1898 Est. _____
 Address 100 Cooper 7. Architect/Builder Capt. Cooper
 Contractor _____
 3. Owner Mrs. W. B. Bates 8. Style/Type Victorian
 Address 2929 Buffalow Spwy, Hou, & Nacogdoches 9. Original Use Residence
 4. Block/Lot Block 43, Lot 25 Present Use Residence
 10. Description 2-1/2 story; wood frame with asbestos siding; brick foundation; irregular plan; deck on hip roof with intersecting gables on east, south, and west with pedimented gable ends, Palladian window arrangements at south gable, central window filled with a louver; composition shingles; chamfered bays on east and west; 1-story porch across south and east, screened with ball and spindle fretwork, quatrefoil brackets, turned post porch supports and spindle railing, chamfered bay on south porch, single entry door at southwest corner -- wood paneled with 2
 11. Present Condition Good; altered with siding, carport on north.
 12. Significance Architectural; local history; Capt. Cooper was postmaster & Phi Beta Kappa; stairway said to be designed by Masonic principles; Miss Mary Cooper sold house to Mrs. Bates in
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant Mrs. W. B. Bates, 2/25/86.
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME	
	1986		32	24	to	32	24
Other					to		
					to		

Continuation sheet
 10. narrow upper glass lights; 2 interior brick chimneys on east and north; windows 1/1 wood double-hung, stair landing window with outline of squares of obscure colored glass; large sweet gum and oak trees in yard at the top of the hill on West Main. 12. August 1944.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 490
City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1915-25
 Address 135 Cooper 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Hillenkamp S/D (271), City Block 43, Lot 2 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by brick veneer and wainscot on front.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 492
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 906 Cottonwood 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles; porch cover with 4 x 4 post supports; 1/1 wood double-hung windows, arranged in pairs.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource _____ 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 493
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 910 Cottonwood 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description Similar in plan and details to 918; 1/1 wood double-hung windows.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 494

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 918 Cottonwood 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; foundation with composition brick patterned siding at foundation skirt; rectangular plan; gable roof with composition shingles, extended rafter ends and knee braces; inset porch - screened with boxed wood supports; 2 wood panel entry doors with upper glass lights set at 90 degrees; windows 9/9 wood double-hung arranged in pairs.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 495

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 1002 Cottonwood 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 Present Use Residence

10. Description 2-story; wood frame with bull-nosed siding; irregular plan; gable roofs with extended rafter ends and beam ends, knee braces, composition shingles; extended porch with screening over a low wall, square plastered porch supports; windows 1/1 wood double-hung; exterior brick chimney on south and north.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 496
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1021 Cottonwood 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 497
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-25
 Address 1211 Cottonwood 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Unknown
 10. Description _____

11. Present Condition Poor; windows, porch altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 498
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-25
 Address 1212 Cottonwood 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with lapped board siding; brick pier foundation; hip roof with composition shingles, extended rafter ends; porch with builtup 2 x 4 supports, 2 wood paneled entry doors; windows 4/4 wood double-hung; symmetrical front.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 499

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 1214 Cottonwood 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; intersecting gable roofs with composition shingles, extended rafter and beam ends; extended porch with boxed battered columns over brick piers; wood entry door with upper glass; windows - 3/1 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- PHOTO DATA
/Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 500
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-25
 Address 1215 Cottonwood 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Lot 56 Present Use Unknown
 10. Description _____

11. Present Condition Deteriorated
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 501

City/Rural Nacogdoches UTM Sector _____

2. Name Thomas R. Hamilton 6. Date: Factual _____ Est. 1930

Address 501 Cox 7. Architect/Builder _____

3. Owner Dorothy Wilkerson Contractor _____

Address Orange, Texas 8. Style/Type Bungalow

4. Block/Lot City Block 35, Lot 14A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; hip-and-gable roofs with composition shingles, plain entablature below eaves; projecting porch with battered boxed wood columns over brick piers; windows 3/1 wood double-hung; entry door wood with large rectangular glass lights; exterior brick chimney on front facade; detached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Thomas R. Hamilton, 2/17/86.

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	16	to	13 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 502
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mrs. Opal Bradbury 6. Date: Factual _____ Est. 1890-1900
 Address 507 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 35, Lot 14 Present Use Residence

10. Description 1-1/2 story; wood frame with beveled horizontal wood siding; brick foundation with brick apron across front (later); ell plan; hip-and-gable roofs with wood shingles, bargeboards, chamfered shingles at front pedimented gable end; with chamfered bay below; asymmetrical porch with flat curved roof, ornamented metal porch supports, single wood entry door paneled with oval upper light (beveled glass), ornamented screen door, hood mold above; windows 1/1 wood double-hung with hood mold, front window with diamond and prism panes in upper sash, half screens on
 11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		13	14	to	13	15
Other					to		
					to		

Continuation sheet

10. some windows; carport on east side with turned wood supports on a brick wall; large magnolia in front yard.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 503
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 511 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 35, Lot 13A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; ell plan; gable roofs with galvanized metal; inset porch with 1 wood boxed column; single entry door with glass light; windows 1/1 wood double-hung, on front bay aluminum single-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	13	to	13 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 504

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890s

Address 513 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot City Block 35, East part of Lot 13 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame construction with horizontal lapped siding; ell plan; hip-and-gable roofs with composition shingles; front porch screened; windows aluminum replacement, majority of house obscured by sheds (later additions); exterior brick chimney on east side; shed carport on west side.

11. Present Condition Fair; additions obscure the elements of the older house beneath.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		13	11	to	13	12
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 505

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890s

Address 523 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Classical Cottage

4. Block/Lot _____ 9. Original Use Residence

City Block 35, North part of Lot 13 Present Use Residence

10. Description 1-story; wood frame with beveled horizontal siding; brick pier foundation; ell plan; steep hip roof with composition shingles; inset porch across front with boxed wood columns, plain railing; 2 wood paneled entry doors set at 90 degrees to one another with ornamented screen doors; windows 4/4 wood double-hung with hood mold, shutters on front.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	10	to	13 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 506
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 602 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 1-E Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation with infill skirt; irregular plan; gable roofs with composition shingles; extended porch with boxed wood columns; 1/1 wood double-hung windows; single wood paneled entry door.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		13	1	to 13	1
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 507
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890s
 Address 609 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Classical Cottage

4. Block/Lot Block 35, Lot 12 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation with lattice infill; ell plan; pyramidal hip roofs with composition shingles; plain entablature beneath eaves; asymmetrical wraparound porch with boxed wood columns with plain capitols, plain wood railing, 2 wood and beveled glass doors set at 90 degrees; windows 1/1 wood double-hung; detached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		13	9	to 13	9
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 508
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 614 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner Burch 8. Style/Type Bungalow
 Address 614 Cox 9. Original Use Residence
 4. Block/Lot Block 35, Lot 1-C Present Use Residence

10. Description 1-story frame with lap bull-nosed siding; rectangular plan; brick pier foundation ; hip asphalt roof with extended rafter ends; windows are 3/1 double-hung wood; projecting gable roofed porch supported by boxed columns; knee braces; shed addition on west facade.

11. Present Condition _____
 12. Significance About 100 years old; 14-foot ceilings.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Mr. Burch
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 13 1 to 13 1
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 509
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 620 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Classical Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 1-B Present Use Residence
 10. Description 1-story frame with lap bull-nosed siding; massed plan; hip asphalt roof with plain entablature; brick pier foundation; inset porch supported by boxed columns; windows are 1/1 double-hung wood; entry is paneled with sidelights; concrete steps.

11. Present Condition _____

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder _____ Date _____

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		13	4	to 13	4
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 510
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1890s
 Address 621 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner Tim Maveergeorge 8. Style/Type Vernacular Classical Cottage
 Address 621 Cox 9. Original Use Residence
 4. Block/Lot City Block 35, Lot 11 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation with aluminum foundation skirt; ell plan; hipped roof with composition shingles, plain entablature; inset porch with boxed wood columns with plain capitals; 2 entry doors set at 90 degrees with screen doors; windows wood double-hung 6/6, 4/4, 1/1.

11. Present Condition Good
 12. Significance Was Mrs. McClaine's house; McClaine's Men's Store is her son.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant Tim Maveergeorge
 16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		13	8	to	13	8
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 511
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890s
 Address 701 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot Block 35, Lot 10 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with horizontal beveled siding; brick foundation; irregular plan; steep hip-and-gable roof with composition shingles, boxed cornices, plain entablature, modern skylight at peak of hip roof; inset porch, partially filled in, boxed wood columns, wood paneled entry door with upper glass light and ornamental moulding; windows 2/2, 1/1 wood double-hung, many with hood molds; detached garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		13	7	to	13	7
Other					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 512

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915

Address 702 Cox 7. Architect/Builder _____

Contractor _____

3. Owner Mrs. Gee 8. Style/Type Vernacular Classical Cottage

Address 702 Cox 9. Original Use Residence

4. Block/Lot Block 35, Lot 1-A Present Use Residence

10. Description 1-story; wood frame with horizontal wood siding; brick pier foundation with brick infill; irregular ell plan; hip roofs with hip dormer, composition shingles, deep plain entablature, medium overhang; asymmetrical inset wraparound porch with boxed wood columns, plain wood railing, stick-style lattice on east side; 2 entry doors on front set at 90 degrees, with decorative screen doors, side entry door at rear of porch wood paneled with two upper glass lights; windows 1/1 wood double-hung; hipped dormer on south facade with attic vents; frame double garage at

11. Present Condition _____

12. Significance About 85 years old.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Gee, 2/17/86

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	3	13	3
Other						

Continuation sheet

10. rear with sliding doors with upper glass lights.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 513

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890-1910

Address 708 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 42, Lot 85 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed, lapped and plywood siding; brick pier foundation with brick infill; originally ell plan with recent infill; hip-and-gable roofs, gable dormer, composition shingles; porches on east and west with 4 x 4 posts, windows 2/2 and aluminum replacement; entry doors wood.

11. Present Condition Fair - Good; several alterations about 1979.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		13	4	to 13	4
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 514

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890-1910

Address 709 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot _____ 9. Original Use Residence

Block 42, East part of Lot 90 and Lot 90A Present Use Residence

10. Description 1-story; wood frame with asbestos siding; brick pier foundation with brick infill; irregular plan; steep hip-and-gable roofs with composition shingles; inset porch with boxed columns; two wood paneled entry doors with upper glass lights, set at 90 degrees; windows 2/2 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		13	6	to 13	6
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 515
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-22
 Address 714 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

9. Original Use Residence
 4. Block/Lot Block 42, Lot 74-B Present Use Residence

10. Description 1-1/2 story ; wood frame with bull-nosed siding; brick foundation; rectangular plan with addition; gable roof with extended rafters, beam ends, composition shingles; inset porch screened with brick columns resting upon brick piers; windows 1/1 wood double-hung; rear entry door wood paneled with upper glass lights.

11. Present Condition Good

12. Significance Mrs. Gee lived here ca. 1933-44; In 1923 when college opened, Mr. Mast put up rent houses in this area; they were built by Mr. A. T. Mast's interests.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	5	to	13 5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 516
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 818 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Moorer S/D 399, Block 42, Lot 15 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 517
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 908 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Moorer S/D 399, City Block 42, Lot I-2 Present Use Residence
 9. Original Use Residence

10. Description 1-story with basement; wood frame with stucco; masonry foundation; rectangular plan; gable roof with composition shingles, shed roof over porch with square columns and low wall; central entry wood panel door with three upper glass lights; windows 6/6 wood double-hung; interior brick chimney; lot slopes away from street to small creek.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	9	to 11	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 518
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 912 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Moorer S/D 399, Block 42, Lot I-1 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 519
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 918 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Moorer S/D 399, City Block 42, Lot H 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation skirt across front, galvanized metal skirt along sides; L-plan with garage addition at rear; extended porch with boxed wood columns; gable roof with hip roof at garage, composition shingles, extended beam ends; 4/1 wood double-hung windows; central entry door wood paneled with 4 upper glass lights; garage converted to living space.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		11	11	to 11	11
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 520

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 922 Cox 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Moorer S/D, City Block 42, Lot G 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding, brick foundation skirt; irregular plan; clipped gable roofs, with extended rafters and beam ends, composition shingles; extended small porch with decorative metal porch supports over brick piers, arched entry, entry door wood with rectangular glass lights; windows 3/1 wood double-hung; detached wood frame garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		11	10	to 11	10
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 521
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1007 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use _____
 4. Block/Lot Moorer S/D 399, City Block 42, Lot 65-C Present Use _____
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 522
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1014 Cox 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Moorer S/D 399, City Block 42, Lot E Present Use Residence

10. Description 1-story frame with green asbestos siding; asphalt clipped gable roof with extended rafter ends and braces; projecting wood porch upheld by brick columns; windows are 1/1 double-hung; entry door has decorative glass panels; foundation skirted at rear; one exterior chimney on east facade.

11. Present Condition Good; for sale; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		11	12	to	11 12
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 523
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1018 Cox 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use _____
 4. Block/Lot Moorer S/D 399, City Block 42, Lot D Present Use _____
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 524
 City/Rural Nacogdoches UTM Sector _____
 2. Name W. T. Wilson Grain Co. 6. Date: Factual _____ Est. 1910
 Address 000 Craven 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial Warehouse
 Address _____ 9. Original Use Warehouse
 4. Block/Lot Block 32, Lot 10 or 12 Present Use Storage
 10. Description 1-story with loft; wood frame (floor joists are full 2 x 6); brick foundation, sheathed with corrugated metal; gable roof with metal roof sheeting; faces onto railroad track; inset sliding doors sheathed with metal, 3 doors on south, 2 on east; 2 covered openings at gable end on west.

11. Present Condition Fair - Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	19	to 39	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 525
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 106 Craven 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 1 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends and brackets; inset porch with boxed wood columns; 4/1, 5/1 wood double-hung windows; interior brick chimney.

11. Present Condition Good - Fair
 12. Significance Built a few years before a big flood.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 39 16 to 39 16
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 526
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mrs. Brown 6. Date: Factual _____ Est. 1910-20
 Address 110 Craven 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 2-1, Block 38 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; gable roofs with composition shingles; inset porch with posts; two entry doors; windows 4/4 wood double-hung; rectangular plan.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		39	17	to	39 17
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 527
 City/Rural Nacogdoches UTM Sector _____
 2. Name Dal & Betty Morris 6. Date: Factual _____ Est. 1910-20
 Address 114 Craven 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 2-3 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by aluminum siding and aluminum replacement windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 528
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 126 Craven 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 3-A Present Use Residence
 10. Description _____

11. Present Condition Good; 1/2 to 2/3 of windows are replacement aluminum windows.
 12. Significance _____
 13. Relationship to Site: Moved Date Possibly Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 529

City/Rural Nacogdoches UTM Sector _____

2. Name Clifford & Annie Anderson 6. Date: Factual _____ Est. 1925-35

Address 130 Craven 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 38, Lot 3 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick skirt up to window sills; intersecting clipped gable roofs with extended beam and rafter ends, composition shingles; irregular plan; extended porch with metal supports, at one time wrapped around to east; windows 4/1 wood double-hung, picture windows on north (front).

11. Present Condition Good; windows on front altered to picture windows, brick foundation skirt applied.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		39	18	to	39	18
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 530
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1054 Crisp 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence/Farm Complex
 4. Block/Lot Block 54 Present Use Residence/Farm Complex
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 531
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 0000 Crisp (North of 606) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board & Batten Hay Barn
 Address _____ 9. Original Use Residence/Farm Complex
 4. Block/Lot Block 54 Present Use Hay Barn
 10. Description 1-story frame, rectangular plan; board and batten siding; sheet metal gable roof; 4/4 wood double-hung windows; horseshoe over door.

11. Present Condition Poor; Deteriorated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 19 19 to 19 19
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 532
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1102 Cross 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 9-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 533

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1106 Cross 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shotgun

4. Block/Lot Block 53, Lot 10 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with lap siding; sheet metal gable roof with extended rafter ends; projecting porch supported by boxed columns; windows are 1/1 wood double-hung; foundation skirted.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		38	17	to	38	17
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 534

City/Rural Nacogdoches UTM Sector _____

2. Name American Legion - John Ligon Post 6. Date: Factual _____ Est. 1930-40s

Address 1201 Cross 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow w/ Neo-classical Elemts

Address _____ 9. Original Use Residence

4. Block/Lot Block 53, Lot 6 Present Use American Legion Meeting Hall

10. Description 1-story; wood frame with asbestos siding; brick foundation; rectangular plan; hip roof with deep overhang; composition shingles; projecting portico with boxed wood columns, arched sunburst over wood paneled entry door with sunburst light; windows 12/12 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	18	to	38 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 535
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1204 Cross 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 22-C Present Use Residence
 10. Description _____

11. Present Condition Good; some alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 536
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-20
 Address 1208 Cross 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 23 Present Use Residence

10. Description 1-story frame with bull-nosed siding; ell plan with projecting chamfered bays; pendant brackets; composition hip-and-gable roof pierced by 1 exterior chimney stack, windows are 1/1 wood double-hung; brick pier foundation; inset porch has turned columns and brackets.

11. Present Condition Good - Fair; some alterations.

12. Significance Good example of style in this neighborhood.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	19	to	38
Other					to	19
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 537
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1214 Cross 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 23 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 538
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-35
 Address 106 / 108 Dan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered - two or three structures put together.
 12. Significance _____
 13. Relationship to Site: Moved Date Possibly Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 • /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 539
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 111 Dan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 541
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 213 Dan 7. Architect/Builder _____
 Contractor _____

3. Owner Mrs. Williamson 8. Style/Type Bungalow
 Address _____ 9. Original Use Dorm Residence at SFA

4. Block/Lot City Block 70 Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; ell plan; gable roofs with composition shingles; inset porch with decorative metal support; wood panel door with upper glass; windows 4/1 wood double-hung in pairs, brick skirt around base; large dormer on west with bull-nosed siding, shed roof.

11. Present Condition Fair

12. Significance Was a dormitory at Stephen F. Austin University; buildings moved from SFA campus; streets in this addition was named for Mrs. Williamson's sons.

13. Relationship to Site: Moved Date Unknown Original Site SFA Campus

14. Bibliography _____

15. Informant Resident at 213 Dan

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 542
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 217 Dan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Dormitory at SFA
 4. Block/Lot City Block 70 Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick skirt around foundation perimeter; ell plan; intersecting gable roofs with composition shingles; porch without canopy, side entry door wood with upper glass light; windows 1/1 wood double-hung generally in pairs.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date Unknown Original Site SFA Campus

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		36	3	to	36	3
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 543
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 221-B Dan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date Unknown Original Site on SFA University campus

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 544

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 401 Dennis 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Moorer S/D 399, Block 42, Lot L-3 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; projecting porch supported by boxed columns; windows are 3/1 wood double-hung; concrete porch; brick foundation skirt; shutters on windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		12	17	to	12	17
	1986		33	8	to	33	8
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 545
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 408 Dennis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 42, Part of Lots 9 & 67-B Present Use Residence
 10. Description _____

11. Present Condition Extensively altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 33 9 to 33 9
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 546
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 409 Dennis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Moorer S/D (399), City Block 42, Lot M Present Use Residence
 10. Description _____

11. Present Condition Good; altered porch, vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		33	10	to	33 10
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 547

City/Rural Nacogdoches UTM Sector _____

2. Name Stephens 6. Date: Factual _____ Est. 1930-35

Address 502 Dennis 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

City Block 42, Lot OL D Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan with bay at front; gable roofs with extended rafter and beam ends, composition shingles; roof extends over small entry porch with metal porch support, side-facing door with diamond light; windows 3/1 wood double-hung with shutters on the front; detached frame garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		12	19	to	12	19
Other	1986		33	11	to	33	11
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 548
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 503 Dennis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Moorer S/D (399), Block 42, Lot N Present Use Residence
 10. Description 1-story frame with pink asbestos siding; composition clipped gable roof with extended rafter ends; inset wood porch supported by boxed columns; 1/1 wood double-hung windows; flat roofed garage on south side; foundation skirted with brick.

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	18	to	12 18
Other	1986		33	12	to	33 12
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 550

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10

Address 1006 Deveraux 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 53, Lot 8 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed and lapped board siding; brick pier foundation, rectangular plan; gable roofs with sheet metal roofing; projecting porch with metal supports; 2 wood paneled doors; windows 4/4 wood double-hung.

11. Present Condition Fair - Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		38	10	to	38	10
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 551
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1009 Deveraux 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 4-B Present Use Residence
 10. Description 1-story frame with bull-nosed siding; sheet metal gable roof; projecting porch supported by 4x4s; window are 4/4 wood double-hung; brick pier foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 38 11 to 38 11
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 552
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1201 Dolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 16-A North Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 553
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1207, 1209, 1211 Dolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Part of Lots 16-A & 16-B North Present Use Residence
 10. Description Burned and removed since first inventoried.

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 554
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address Southwest Corner of Dolph and Nash 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 16-C Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 555
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1407 Dolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 1, S/D of Lot 16-D (005) Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 556
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1409 & 1411 Dolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 2, S/D of Lot 16-D (005) Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 557
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1513 Dolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 2, S/D Lot 16-D (005) Present Use Residence
 10. Description _____

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 558
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1824 Dolph (Rear) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 14-I Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 559
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1000 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage/Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 24-B Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with composition shingles; inset entry porch with boxed wood columns, 2 entry doors set at 90 degrees; wood panel with upper glass, screen doors; windows 1/1 wood double-hung.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		32	7	to	32 7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 560
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1018 Douglass St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 24-E 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with composition shingles, extended rafter and beam ends; porch on southwest corner, screened with wood post porch supports, low brick wall (more recent), 2 wood paneled entry doors set at 90 degrees; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		32	8	to	32 8
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 561
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1104 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 37-2 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 562
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925
Address 1110 Douglass St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 42, Lot 37-1 Present Use Residence

10. Description 1-story; wood frame with lapped board siding; brick pier foundation; ell plan; gable roof with extended rafter ends, brackets; composition shingles; boxed wood column supports at porch, 2 entry doors set at 90 degrees; windows 1/1 wood double-hung with wide board trim; frame garage, detached, at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		32	9	to	32	9
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 563
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1119 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 362 Present Use Residence

10. Description 1-story; wood frame with vinyl siding; brick foundation; rectangular plan; clipped gable roof with composition shingles, extended rafter ends and brackets; extended porch with boxed wood columns over brick piers, central entry, wood paneled door with upper glass light, screen door; windows 4/4 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		32	10	to	32 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 564
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1121 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 36-3 Present Use Residence
 10. Description Twin to 1119 W. Douglass, except for window arrangement.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 565
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1211 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Berger S/D (48), City Block 42, Lot 9 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 566

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1215 Douglass St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Berger S/D 48, City Block 42, Lot 10 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; clipped gable roof with sheet metal roofing, extended rafter and beam ends, 2 interior brick chimneys; extended porch with wood posts, central wood paneled entry door; windows 4/1 wood double-hung, arranged generally in pairs.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		32	11	to	32	11
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 567

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 1319 Douglass St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Berger S/D (48), City Block 42, Lot Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; gable roof with composition shingles, extended rafter ends, brackets; inset porch across front with boxed wood columns resting on brick piers, two entry doors wood paneled with upper glass lights; 1/1 wood double-hung windows with 1/2 screen; rectangular plan.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		32	12	to 32	12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 568
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1915-25
 Address 1424 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 91-H Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roofs with sheet metal roofing, extended rafter ends and brackets; extended porch with boxed wood columns, 2 entry doors, wood paneled with screen doors; windows 4/4 wood double-hung with half screens.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		32	13	to	32 13
Other _____					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 570

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 1510 Douglass St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 91-F 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends; boxed wood columns under hipped roof at porch, central entry door wood paneled with upper glass light; windows 4/4 wood double-hung generally arranged in pairs, carport on west side.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		32	14	to	32 14
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 571
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925
 Address 1604 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 91-D Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 572
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1723 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Rockface Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66, Lot 5-A Present Use Residence

10. Description 1-story; wood frame with rockface; irregular plan; intersecting gable roofs with composition shingles; extended porch with square columns, side-facing wood door with upper glass light; windows 6/6 wood double-hung; exterior rockface chimney on north; wood frame and steel pipe carport on southeast, detached rockfaced garage or storage building at rear.

11. Present Condition Good
 12. Significance Good example of rockface cottage.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		32	15	to	32 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 573
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1805 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66, Lot 5-E Present Use Residence
 10. Description 1-1/2 story; wood frame with bull-nosed siding; rectangular plan; side-facing gable roof with gabled dormers; composition shingles, extended rafter ends; porch across front with paired wood posts, wood paneled entry door; windows 4/1 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		32	16	to	32	16
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 574

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 2213 Douglass St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 66, Lot 9-A East 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter ends, brackets; paired boxed columns on brick piers, entry door with screen door; windows 1/1, 4/4 wood double-hung with awnings on west.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		32	17	to	32 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 576
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 2800 Douglass St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66, Lot 1-E Present Use Residence
 10. Description _____

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 577
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890-1900
 Address 905 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot Block 43 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with lapped siding; brick foundation; irregular plan with chamfered bay on north; gable roofs with boxed cornices, composition shingles; decorative shingles at north gable ends; shed roof over screened porch with narrow porch supports, 2 entry doors set at 90 degrees, wood paneled; windows 2/2 wood double-hung with Queen Anne upper sash in front window of north bay, hood molds above; exterior brick chimney on northeast facade with corbeled brick cap; sunporch and possible additions at rear.

11. Present Condition Good

12. Significance Architectural significance.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 578
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 922 Durst 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 42, Lot 80-D Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with extended rafter and beam ends, composition shingles; inset porch with decorative metal supports over brick piers, 2 entry doors set at 90 degrees, wood paneled with upper glass light; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	1	to 12	1
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 579

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1001 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Burke S/D 98, City Block 42, Lot 1 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt gable roof of extended rafter ends; wraparound concrete porch supported by metal columns; windows are wood 4/1 double-hung; foundation skirted with brick; newer additions at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		12	3	to	12	3
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 580

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1880-190

Address 1002 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Ell Cottage

4. Block/Lot Block 42, Lot 80-C 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with lap siding; asphalt hip-and-gable roof pierced by 1 corbeled brick interior chimney stack; ell plan with 2 chamfered bays with fishscale shingles, bargeboard, and corner brackets; inset porch is concrete supported by metal columns; brick pier foundation skirted with masonry; windows are 2/2 and 1/1 double-hung wood with pediments; 2 paneled entry doors, 1 boarded up.

11. Present Condition Fair; porch altered; 1 doorway filled in.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		12	2	to	12	2
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 581
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890s
 Address 1020 Durst 7. Architect/Builder _____

3. Owner Hall Contractor John Spradley
 Address 1020 Durst 8. Style/Type Victorian Cottage

4. Block/Lot _____ 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with lap siding; asphalt gable roof pierced by 1 exterior chimney on east facade; ell plan with projecting chamfered bay has fishscale shingles, bargeboard, and corner brackets; windows are 4/4 and 1/1 double-hung wood with hood molds; entry door is paneled; inset concrete porch supported by metal columns.

11. Present Condition Good; porch columns have been altered.

12. Significance John Spradley built this house in pre-1900. It was built for the John Spradley family; crepe myrtles were planted to screen the cow barn from the house.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Hall

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	4	to 12	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 582
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1123 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 51-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with asphalt siding; ell plan; brick foundation; gable roofs with extended rafter and beam ends; composition shingles; inset porch with boxed wood columns with plain capitol, side-facing entry door with glass light; windows 1/1 wood double-hung; vertical wood siding with pointed ends in the north gable end; frame garage at rear.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	5	to 12	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 583

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 1201 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 69-C 9. Original Use Residence and Farm Buildings

Present Use Residence and Farm Buildings

10. Description 1-story; wood frame with asphalt shingles; brick foundation; rectangular plan; gable roofs with exposed rafter ends, brackets, composition shingles; small porch with cylindrical columns over brick piers, wood entry door with upper glass lights; windows 6/6 wood double-hung; barns at rear wood frame with asphalt and plywood siding, gable roofs with composition shingles.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	6	to	12 6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 584
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1200 Durst 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 585
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1206 Durst 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Mize S/D 393, City Block 42, Lot 8 Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 586
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1211 Durst 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 69-A Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 587

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 1212 Durst 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Mize S/D 393, City Block 42, Lot 7 Present Use Residence

10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 588

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1221 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 52 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt gable roof with extended rafter ends and knee braces; porte cochere on west facade; projecting porch supported by boxed columns; windows are 12/12 double-hung; multiple lights in door; 1 interior chimney stack; brick pier foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	7	to	12 7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 589

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 1303 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 53-A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with beveled siding, bull-nosed siding; brick pier foundation with wood foundation skirt; irregular plan; hip-and-gable roofs with extended rafter ends, composition shingles; porch across front with 4x4 supports, plain wood rail, 2 entry doors, wood paneled with upper glass light, on wood with multipane glass; windows 1/1 wood double-hung; frame garage on west with galvanized metal roof; large magnolia tree; shed former with window on north.

11. Present Condition Fair - Good; altered siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides _____

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		12	8	to	12	8
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 590
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1517 Durst 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 42, Lots 57 & 57-D Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt hip-and-gable roof with extended rafters and knee braces; rectangular plan; projecting concrete porch is supported by boxed columns, two paneled multi-light entry doors; brick pier foundation; windows are 1/1 wood double-hung; garage of same style on east side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		12	9	to	12 9
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 591
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1613 Durst 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 42, Lot DL A2 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; clipped gable roofs with extended rafter ends, faceted beam ends, composition shingles; inset porch with diagonal brace supports, entry door with screen door; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	10	to	12 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 592

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 1615 Durst 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow Commercial

4. Block/Lot Block 42, Lot OLA-4 9. Original Use Commercial

Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt gable roof with extended rafter ends and knee braces; windows are 1/1 wood and 2/2 aluminum double-hung; metal awning over doorway; chamfered north facade; rectangular plan; brick pier foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		12	11	to	12	11
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 593
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2117 Durst 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description _____

11. Present Condition Fair; extensively altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 594
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 2508 Durst 7. Architect/Builder _____
 Contractor W. C. Reedy
 3. Owner W. C. Reedy Estate 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 65, Lot 1 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; asphalt multi-gable roof; 3/1 double-hung windows; 1 exterior chimney on east facade; projecting porch upheld by boxed columns; paneled and multi-light door, garage on east side; brick foundation skirt.

11. Present Condition Good
 12. Significance W. C. Reedy was a carpenter; he built several houses in the area.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Joe Reedy
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		12	12	to	12	12
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 595
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mrs. D. H. Hyde 6. Date: Factual _____ Est. 1930
 Address 3114 Durst 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 65, Lot 4-E Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; clipped gable roofs; inset porch with 4 x 4 supports; windows 6/6 wood double-hung; metal shed at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		12	13	to	12	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 596
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-20
 Address 3400 Durst Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description 1-story frame with bull-nosed siding; rectangular plan; composition hip roof; inset porch; windows are 1/1 wood double-hung; pier and beam foundation.

11. Present Condition Altered; recently renovated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	14	to	20 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 597

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-20

Address 3522 Durst Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan; hip sheet metal roof with extended rafter ends; inset porch upheld by boxed columns; 2 paneled entry doors open onto porch; windows are 1/1 wood double-hung; pier and beam foundation; garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		20	13	to	20 13
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 598
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1509 Eliza 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), City Blk 53, Blk 9, Lt 16 Present Use Residence
 10. Description 1-story; wood frame with horizontal lapped siding; concrete pier foundation; rectangular plan; gable roof with extended rafter ends; clipped gable ends, composition shingles; extended porch with boxed columns; wood paneled entry door with vertical upper glass lights; windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date Possibly Original Site

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 599

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 1513 Eliza 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Cottage

Address _____ 9. Original Use Residence

4. Block/Lot JGOrtonS/D(437), City Blk 53, Blk 9, Lt 1 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; T-plan; gable roofs with composition shingles, extended rafter ends; extended porch with metal porch supports; wood door with small glass lights; windows 4/4 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 600
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-45
 Address 1512 Eliza 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), City Blk 53, Blk 8, Lt 5 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 602

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
Address 1611 Eliza 7. Architect/Builder _____

3. Owner _____ Contractor Mr. Ordner, Mr. Land

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Ira Land Resub (336), City Block 62, Lot 5 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; inset porch on southwest corner with boxed columns over brick piers; wood paneled entry door; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Iole Roundtree, 4/7/86

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 603

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. ca. 1930

Address 1615 Eliza 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Ira Land Resub (336), City Block 62, Lot 6 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, composition shingles; inset porch with metal supports; wood panel entry door; windows 4/4 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Iole Roundtree

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 604

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 1708 Eliza 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

JGOrtonS/D(437), City Blk 62, Blk 19, Lt 5 Present Use Residence

10. Description 1-story; wood frame with asbestos siding over board siding; brick pier foundation; rectangular plan; gable roof with corrugated metal roofing, interior brick chimney; inset porch with 4 x 4 corner post; windows 4/4 wood double-hung.

11. Present Condition Fair - Poor

12. Significance 1710 and 1712 Eliza are of similar layout and construction.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 606
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1711 Eliza 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBlk 62, Bk 20, Lt1A Present Use Residence
 10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends and beam ends; inset entry; windows 6/6 wood double-hung.

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 607
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1713 Eliza 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBlk 62, Blk20, Lt 1B Present Use Residence
 10. Description Similar in construction to 1711 Eliza.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 608
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2519 Elizabeth 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 609
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 123 Ellington 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence
 10. Description _____

11. Present Condition Good; extensively altered by brick veneer.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 610
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual 1923 Est. _____
 Address 210 Ellington 7. Architect/Builder _____
 Contractor _____

3. Owner Mrs. Frank Hathcock 8. Style/Type Bungalow - Neoclassical
 Address 210 Ellington 9. Original Use Residence

4. Block/Lot City Block 50 Present Use Residence

10. Description 1-story; wood frame with lapped wide board siding; brick foundation; rectangular plan; parallel clipped gable roofs, deep eave, composition shingles, pedimented gable ends; through gable end brick chimney on southeast corner; 3-bay facade articulated by Doric pilasters with pedimented portico on brick porch, boxed Doric columns; relief ornamentation at gable end; windows are wood double-hung with 8/8, 9/9 lights, paired multi-pane French doors flank the portico entry; carport on east.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date January 1966 Original Site Moved from North St.

14. Bibliography _____

15. Informant Mrs. Frank Hathcock

16. Recorder Dorothy Victor, Larry Hodge Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	10	to 36	10
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 611
 City/Rural Nacogdoches UTM Sector _____
 2. Name Church 6. Date: Factual _____ Est. 1930-40
 Address 98 Ellis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Unknown
 4. Block/Lot Block 50 Present Use Church
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles; extended porch with wood post supports, double entry door wood with upper glass lights; windows 8/8 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	10	to 35	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 612
 City/Rural Nacogdoches UTM Sector _____
 2. Name Church 6. Date: Factual _____ Est. 1930s
 Address 100 Ellis at Matthew 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Church
 4. Block/Lot Block 50 Present Use Church

10. Description 1-story frame with drop siding; rectangular plan with two projecting towers; composition gable roof with extended rafter ends; raised brick pier foundation; windows are 1/1 wood double-hung.

11. Present Condition Poor; may be vacant.
 12. Significance Good example of small vernacular Protestant church.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		35	11	to	35	11
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 613
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1206 Ella 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board & Batten Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 614

City/Rural Nacogdoches UTM Sector _____

2. Name Mr. Chandler 6. Date: Factual 1924 _____ Est. _____

Address 108 Elm 7. Architect/Builder Mr. Hammock

Contractor _____

3. Owner Mr. H. E. Chandler 8. Style/Type Bungalow

Address 108 Elm 9. Original Use Residence

4. Block/Lot North Mound Pl S/D, City Block 50, Lot 18 Present Use Residence

10. Description 1-story; wood frame structure with horizontal lapped aluminum siding; brick foundation; rectangular plan; straight side-facing gable roof with composition shingles; projecting porch with wrought iron porch supports and brick piers; concrete porch and steps; entry door wood with vertical glass lights; windows 1/1 wood double-hung in pairs with aluminum storm windows; detached carport.

11. Present Condition Good; altered, aluminum siding and wrought iron posts; original siding 117 wood.

12. Significance Mr. Hammock was the first owner; he was a painter and wall paper hanger.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mr. Chandler

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	10	to 2	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 615

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 112 Elm 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ Present Use Residence

North Mound Pl S/D, City Block 50, Lot 19

10. Description 1-story; wood frame structure with horizontal wood siding; brick foundation; rectangular plan; front-facing straight gable with extended rafter ends, sun rays motif at pediment; inset porch with battered wood box columns over wood piers; simple wooden balustrade and wood floor steps; windows wood double-hung, 3/1, singly and in pairs; entry door wood with vertical glass panes.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		1	25	to	1 25
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 616

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 115 Elm 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Craftsman Bungalow

4. Block/Lot North Mound Pl S/D, City Block 50, Lot 35 9. Original Use Residence

Present Use Residence

10. Description 1-story, wood frame construction with bull-nosed siding; brick foundation; ell plan with carport on east; intersecting gables with extended beams, simple brackets, extended rafter ends, composition shingles; clipped gable ends; extended porch with Tuscan boxed wood columns over brick piers; concrete floor and steps; wood paneled entry door; attic vents under gable ends; windows 1/1 wood double-hung in pairs, wood shutters on front facade; exterior brick chimney on west.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	2	to 2	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 617
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 116 Elm 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot North Mound Pl S/D, City Block 50, Lot 20 Present Use Residence

10. Description 1-story; wood frame with running bond brick veneer; brick foundation; ell plan; straight front-facing gables with extended end beams and rafters; composition shingles; attic vent and painted asphalt shingles in pediment; slightly extended porch with Tuscan wood boxed columns and brick piers, concrete floor and steps, wood entry door with vertical glass panes; windows 1/1 wood double-hung in pairs and fours; detached garage; native persimmon in yard; twin to 120 Elm.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	3	to 2	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 618
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
Address 120 Elm 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

9. Original Use Residence
4. Block/Lot North Mound Pl S/D, City Block 50, Lot 20 Present Use Residence

10. Description 1-story; wood frame construction with running bond brick veneer; brick foundation; ell plan; straight front-facing gables with exposed beam and rafter ends, painted fishscale shingles and attic vent in pediment, composition shingles; slightly extended porch with tuscan, boxed columns and brick piers; concrete floor and steps; entry door wood with vertical glass panes; windows 1/1 wood double-hung in pairs; single detached garage; twin to 116 Elm.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1985		2	4	to	2	4
Other				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 619
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 123 Elm 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot North Mound Pl S/D, City Block 50, Lot 37 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame structure with lapped wood siding; brick foundation; I-plan; intersecting gable roof with simple brackets and extended rafter ends, composition shingles; extended wraparound porch with wrought iron posts, lattice, concrete floor and steps; windows 4/1 wood double-hung, singly, in pairs, and in threes; wood entry door; wood shutters on windows at front facade.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	5	to 2	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 620

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
Address 127 Elm

7. Architect/Builder _____
Contractor _____

3. Owner _____ 8. Style/Type Bungalow
Address _____

9. Original Use Residence
4. Block/Lot North Mound Pl S/D, City Block 50, Lot 30 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick foundation; rectangular plan with bays to east and west; intersecting gables with simple brackets and extended rafter ends; attic vent and composition shingles; projecting porch with boxed wood Tuscan columns, concrete floor and steps; single entry door; windows 2/2 aluminum double-hung in pairs; attached garage at rear.

11. Present Condition Good; windows altered; possible addition at rear.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1985		2	6	to	2	6
Other					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 621
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 133 Elm 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot North Mound Pl S/D, City Block 50, Lot 39 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; straight front-facing gable roof with extended beam ends, attic vent; projecting porch with Tuscan wood box columns, wood floor and prefabricated concrete steps; windows 4/1 wood double-hung singly and in pairs; single entry door.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	7	to 2	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 622

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 210 Elm 7. Architect/Builder _____

3. Owner Bill Bell Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot North Mound Pl S/D, City Block 50, Lot ? 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; intersecting gable and hip roof with extended beam and rafter ends, composition shingles; asymmetrical wraparound porch with Tuscan boxed columns and brick piers, wood floor and brick steps; windows 4/1 wood double-hung in pairs; detached garage at southwest; large cedar, elm trees in front yard.

11. Present Condition Good

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	8	to	2 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 623
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 225 Elm 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Eclectic
 Address _____ 9. Original Use Residence

4. Block/Lot North Mound Pl S/D, City Block 50, Lot 43 Present Use Residence - Apartments

10. Description 2-story; wood frame construction with bull-nosed siding; brick foundation; rectangular plan; hip roof with extended rafter ends, composition shingles; inverted entry with three doors; concrete floor, brick steps; windows 1/1 wood double-hung in pairs; detached garage apartment.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 12, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1985		2	9	to	2 9
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 624
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 804, 808, 812, 816 Ernest 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18-C Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		21	23	to	21	23
Other					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 625
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 807, 813 Ernest 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type 2 Bungalows
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18-A Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 626
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 817 Ernest 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18 Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 627
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 824 Ernest 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 628
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 605 Esther, nw corner Esther & Goldberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 632
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 910 Evelyn 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Hillenkamp S/D (271), City Blk 43, Lot 11 Present Use Residence

10. Description 1-story; wood frame with beveled wood siding; brick foundation; rectangular plan; gable roof, composition shingles; gable roof over entry door wood paneled with four narrow upper lights; windows 4/1 wood double-hung; shed at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		33	2	to 33	2
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 633

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 918 Evelyn 7. Architect/BUILDER _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

Hillenkamp S/D (271), City Blk 43, Lot 15 Present Use Residence

10. Description 1-story; wood frame with beveled siding; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter and beam ends, central brick chimney; small projecting entry porch with gable roof, boxed wood columns, central wood paneled entry door with upper glass light; windows 4/1 wood double-hung; detached frame garage with galvanized metal siding; addition on east.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		33	3	to	33	3
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 634
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 923 Evelyn 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Hillenkamp S/D (271), City Blk 43, Lot 18 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 635

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 115 Feazell 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot ILSturdevant S/D (580), Blk 45, Lot 17 9. Original Use Residence

Present Use Residence

10. Description 1-story; rectangular brick residence with composition shingle hip-and-gable roof; 6/1 double-hung windows; interior brick chimney; pedimented portico with box columns on brick piers flanked by curvilinear walls; hall parlor plan with multilight entry doors.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	10	to 24	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 636

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 122 Feazell 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot J.F.Feazell S/D (186), City Block 45, Lot 6 9. Original Use Residence

Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle straight gable roof; horizontal bull-nosed siding; 6/1 double-hung windows; one arched 8/1 double-hung window; pedimented portico with depressed shouldered arch; side porch with depressed shouldered arches.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	11	to	24 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 637
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 202 Feazell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neo-classical
 Address _____ 9. Original Use Residence
 4. Block/Lot J.F.Feazell S.D (186), City Block 45, Lot 4 Present Use Residence
 10. Description 1-story rectangular frame residence with crossed gable composition shingle roof; horizontal bull-nosed siding; 3/1 double-hung windows; pedimented portico with box columns over poured concrete porch; wood panel entry door with aluminum storm door; returned cornices.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		24	12	to	24 12
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 638
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 208-210 Feazell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J.F.Feazell S/D (186), City Block 45, Lot 3 Present Use Residence
 10. Description 1-story rectangular frame duplex residence with composition shingle gable roof; asbestos siding; 8/8 and 6/6 double-hung windows; three-light entry doors; pedimented porticoes with 4 x 4 columns over poured concrete porches.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		24	13	to	24	13
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 639
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910
Address 214 Feazell 7. Architect/Builder _____
Contractor _____

3. Owner _____ 8. Style/Type Neo-classical
Address _____ 9. Original Use Residence

4. Block/Lot J.F.Feazell S/D (186), City Block 45, Lot 2 Present Use Residence

10. Description 1-1/2 story rectangular frame residence with high-pitched composition shingle straight gable roof; horizontal bull-nosed siding; 6/6 double-hung windows; pedimented portico with box columns protects wood panel entry door; returned cornices.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Lary Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		24	14	to	24	14
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 640
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 220 Feazell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neo-classical
 Address _____ 9. Original Use Residence
 4. Block/Lot J.F.Feazell S/D (186), City Block 45, Lot 1 Present Use Residence
 10. Description 1-story rectangular frame residence with composition shingle straight gable roof; horizontal siding; 6/6 double-hung windows; central pedimented portico with returned cornices and box columns over wood porch; wood panel entry door.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	15	to 24	15
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 642

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 916 Ferguson 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Craftsman

9. Original Use Residence

4. Block/Lot ROFerguson S/D (189), City Blk 40, Lot 3 Present Use Residence

10. Description 1-story irregular plan frame residence with composition shingle cross-gable roof; horizontal bull-nosed siding; 6/1 double-hung windows; 2 interior brick chimneys; pedimented portico with box columns; poured concrete porch; 12-light entry doors off porch and on south side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		23	18	to	23	18
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 643
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 917 Ferguson 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot ROFerguson S/D(189), City Blk 40, Lot 11 Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle crossed gable roof; horizontal bull-nosed siding; 1/1 double-hung windows with only lower half screened; fireplace on south wall; inset wood porch with battered wood columns on brick piers; one column "missing" at stoop; knee braces.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	19	to 23	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 644
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 920 Ferguson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ROFerguson S/D (192), City Blk 45, Lot 4 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 645
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1002-1004 Ferguson 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Neo-classical

4. Block/Lot ROFerguson S/D (192), City Blk 45, Lot 5 9. Original Use Residence
 Present Use Vacant

10. Description 1-story; rectangular frame residence with hip composition shingle roof; horizontal bull-nosed siding; wide 1/1 double-hung windows; inset wraparound wood porch with box columns and square balusters; dormer ventilator above porch; 2 glass panel and wood entry doors off porch.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		23	20	to	23	20
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 647
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1008 Ferguson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ROFerguson S/D (192), City Blk 45, Lot 6 Present Use Residence
 10. Description Vinyl siding.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 648
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1009 Ferguson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ROFerguson S/D (192), City Blk 45, Lot 14 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 649
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1021 Ferguson 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Craftsman

4. Block/Lot ROFerguson S/D (189), City Blk 45, Lot 16 Present Use Residence
 9. Original Use Residence

10. Description 1-story irregular plan frame residence with composition shingle gable roof; horizontal siding; 6/1 double-hung windows; returned cornices; projecting pedimented bay beside entry; projecting porch with gable roof on south wall; brick fireplace on east wall.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	21	to	23 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 650
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1119 Ferguson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow w/ Greek Revival motifs
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 41-B Present Use Residence

10. Description 2-story rectangular frame residence with composition shingle gable roof; wide horizontal clapboard siding; 6/1 double-hung windows; dormer with clipped gable centered on front facade; centered entry, wood panel door, with side lights and transom, is protected by gabled porch with paired Tuscan columns.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	22	to	23 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 651

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 1220 Ferguson 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 45-G 9. Original Use Residence

Present Use Residence

10. Description 1-story irregular plan frame residence with composition shingle gable roof; horizontal lap siding; 12/12 double-hung windows; gabled porch with exposed purlins and attached pergola; box columns; chamfered bay on south wall; 8-light entry door; fireplace chimney on north wall.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	23	to	23 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 652

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 102 First 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

Haltom & Brewer S/D (81), City Blk 62, Lt 2 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; rockface foundation; irregular plan; intersecting gable wood shingle roof with extended rafter and beam ends; inset corner porch on northeast corner with 4 x 4 posts, wood and multipane glass entry door set at 90 degrees to double French doors; second entry on east, wood with multipane glass door; windows 6/6 wood double-hung; detached wood frame garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 654
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 208 First 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Halton&Brewer S/D (81), City Blk 62, Lt 6 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; hip-and-gable roof with extended rafter and beam ends, brick chimney on north side, composition shingles; extended porch with boxed columns, 2 wood multipane glass doors; windows 6/6 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 655
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
Address 213 First 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot Haltom&BrewerS/D(81), City Blk 62, Lt 23 9. Original Use Residence
Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends and beam ends; inset porch with boxed wood columns, stick ornamentation; wood paneled entry door; windows 6/6 wood double-hung; detached wood frame garage; picket fence surrounds the yard.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 656
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
Address 312 First 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot Haltom&BrewerS/D(81), City Blk 62, Lt 11 9. Original Use Residence
Present Use Residence

10. Description _____

11. Present Condition Fair; altered by asphalt siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 657
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 611 First 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ADHaltomS/D(78), CityBk 62, Bk 3, Lt 2 S Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; raised pier foundation; rectangular plan; gable roof with extended beam ends; extended screened porch with low wall; windows aluminum replacement.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 658
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 617 First 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ADBrewerS/D(78), City Blk 62, Blk 3, Lt 3 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, beam ends, composition shingles; extended porch with boxed columns, 2 wood paneled entry doors; windows 1/1 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 659
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 809 First 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board and Batten Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot ADBrewerS/D(78), City Blk 62, Blk 7, Lt 2 Present Use Residence
 10. Description _____

11. Present Condition Fair; aluminum replacement windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 660
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 817 First 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot ADBrewerS/D(78), City Bk 62, Bk 7, Lt 2A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation skirt at front; irregular plan; intersecting gable roofs with extended rafter ends, composition shingles; shed roof over porch with metal porch supports, wood panel entry door with upper glass; windows 1/1 wood double-hung, 9-pane fixed picture window on front.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 661

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 922 First 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot ADBrewerS/D(78), City Blk 7, Blk 8, Lt 7 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter ends, beam ends; aluminum awning over entry door; windows 1/1 wood double-hung; brick chimney at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 662
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1002 / 1000 First 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board & Batten Cottages
 Address _____ 9. Original Use Residence
 4. Block/Lot ADBrewerS/D(78), City Blk 62, Blk 8, Lt 8 Present Use Residence
 10. Description 1-story; wood frame with board and batten siding; pier foundation; rectangular plan; gable roofs with composition shingles, extended gable ends, interior brick chimneys; shed roof over porch, wood panel entry door; windows 4/4 wood double-hung.

11. Present Condition Good - Fair
 12. Significance Structures are mirror images of each other.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 663
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 209 Flora 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Part of Lot 37-2 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 664

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920s

Address 219 Flora 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 37-3 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter and beam ends, knee braces; inset porch, battered boxed columns on brick piers; 2 entry doors multipane glass with wood, set at 90 degrees; windows 3/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 23, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District _____ B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		20	5	to	20	5
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 665

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s

Address 223 Flora 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 42, Lot 37-4 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof; projecting porch upheld by battered columns on brick piers; windows 4/1 wood double-hung; rectangular plan; pier and beam foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	6	to 20	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 666
 City/Rural Nacogdoches UTM Sector _____
 2. Name R. D. Burrows House 6. Date: Factual _____ Est. 1899
 Address 500 Forbes 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 5-B Present Use Residence

10. Description 1-story frame with lap wood siding; ell plan with projecting chamfered bay; asphalt shingle roof pierced by 1 interior stack; end gables have ornate bargeboards; 2 inset porches upheld by boxed columns with simple balustrade appear to be altered; windows are 2/2 wood double-hung with hood molds; newel post at street; deck at rear; 2 garages at rear.

11. Present Condition Excellent; minimal alterations.
 12. Significance Said to have been in family since original construction.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.
 15. Informant _____
 16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____

YEAR	DRWR	ROLL	FRME		ROLL	FRME
1986		10	17	to	10	18
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 667
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. ca. 1885
 Address 514 Forbes 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot _____ 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; T-plan with additions; gable roofs with composition shingles; 3-bay entry porch with cylindrical wood columns; entry door at each end of porch - wood paneled door with fan light; windows 9/9 wood double-hung with narrow shutters on front; carport with secondary entry on east.

11. Present Condition Good; altered porch, windows, shutters.

12. Significance House has a sign on the front which says it was built in 1885.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		10	19	to 10	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 668

City/Rural Nacogdoches UTM Sector _____

2. Name Burch 6. Date: Factual _____ Est. 1925-35

Address 820 Ford 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 48 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; pier foundaton; extended porch with 4 x 4 posts, plain railing; windows 4/1 wood double-hung; 2 entry doors set at 90 degrees; garage attached at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		20	7	to	20	7
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 669
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2013 Fore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story frame with asbestos siding; composition gable roof; extended rafter ends; inset porch supported by iron columns; windows are aluminum replacement; brick pier foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	2	to 35	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 670

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 2016-B Fore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

9. Original Use Residence

4. Block/Lot Block 61 Present Use Residence

10. Description 1-story; wood frame with roll composition siding; brick and pier foundation; rectangular plan; gable roof with sheet metal roofing; inset porch with boxed wood columns, 2 entry doors set at 90 degrees; windows 1/1 wood double-hung and aluminum replacement.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		35	3	to 35	3
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 671

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 2201 Fore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with lap siding; composition gable roof with extended rafter ends; windows are 4/4 wood double-hung; projecting porch supported by wood columns; foundation skirted; 2 interior brick stacks.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		35	4	to	35	4
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 672

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 2209 Fore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; clipped gable roof with composition shingles, extended rafter ends; extended porch, gable roof, builtup 2 x 4 supports, wood panel door with upper glass lights; windows 1/1, 4/4.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		35	5	to	35	5
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 673

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 2316 Fore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; ell plan; gable roofs with extended rafter ends, composition shingles; inset porch with metal supports, 2 entry doors set at 90 degrees; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	6	to 35	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 674
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2319 Fore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 675
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2401 Fore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Severely deteriorated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 676

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 2405 Fore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with lap siding; rectangular plan; sheet metal composition roof with extended eaves; inset porch supported by boxed columns; raised brick pier foundation, replacement aluminum windows.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		35	7	to	35	7
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 677
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1940s
 Address 2407 Fore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story frame with drop siding; composition gable roof; rectangular plan; extended rafter ends; 1 dormer and 1 interior chimney stack; windows are aluminum replacement; stoop porch; foundation skirted.

11. Present Condition Good
 12. Significance Owner says it was built about mid-1940s.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Larry Hodge Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 35 8 to 35 8
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 678

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-25

Address 2415 Fore 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Cottage

Address _____ 9. Original Use Residence

4. Block/Lot Block 61 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; raised pier foundation; rectangular plan; gable roof with sheet metal roofing, extended rafter ends and beam ends; inset porch with paired posts, 2 entry doors set at 90 degrees; windows 4/4 wood double-hung.

11. Present Condition Good - Fair

12. Significance Tornado came through this area in 1945 and destroyed many homes.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		35	9	to	-35	9
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 679

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 706 Fourth St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Hollywood S/D (283), City Blk 63, Lot 38 Present Use Residence

10. Description 1-story; wood frame with yellow aluminum siding; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter ends; extended porch with boxed columns; 2 wood panel entry doors with upper glass; windows 4/4 wood double-hung.

11. Present Condition Good; altered by aluminum siding.

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		18	7	to	18	7
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 680
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 711 Fourth 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot HollywoodS/D(283), City Blk 63, Lts 13-14 Present Use Residence
 10. Description 1-story frame with lap siding; composition multiple gable roof; 4/1 wood double-hung windows; inset porch supported by turned wood columns; foundation skirted.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 18 6 to 18 6
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 681
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 802 Fourth 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Hollywood S/D (283), City Blk 63, Lot 35 Present Use Residence
 10. Description _____

11. Present Condition Fair; addition on north side with 105 siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 682
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 803 Fourth 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Hollywood S/D (283), City Blk 63, Lot 18 Present Use Residence
 10. Description 1-story; wood frame with horizontal board siding; rectangular plan; brick pier; gable roof with corrugated metal roofing, extended rafter ends; inset porch with corner support; windows 2/2 aluminum replacement.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		18	5	to	18	5
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 683

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 808 Fourth 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Board and Batten Cottage

4. Block/Lot Hollywood S/D (283), City Blk 63, Lot 33 Present Use Residence

10. Description 1-story; wood frame with board and batten siding; rectangular plan; brick pier foundation; gable roof with sheet metal roofing; extended porch with 4 x 4 posts; 2 entry doors; windows aluminum replacement.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		18	4	to	18	4
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 684
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 811 Fourth St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Hollywood S/D (283), City Blk 63, Lot 20 Present Use Residence
 10. Description 1-story; wood frame with beveled wood siding; galvanized metal foundation skirt; rectangular plan; gable roof with composition shingles, extended rafter ends; extended porch cover with paired 2 x 4 supports, wood entry door; windows 4/1 wood double-hung.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date 1951 Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 18 3 to 18 3
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 685

City/Rural Nacogdoches

UTM Sector _____

2. Name _____

6. Date: Factual _____ Est. 1935-40

Address 829 Fourth St.

7. Architect/Builder _____

Contractor _____

3. Owner _____

8. Style/Type Bungalow

Address _____

9. Original Use Residence

4. Block/Lot City Block 63, Lot 23

Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; galvanized metal foundation skirt; rectangular plan; gable roof with extended rafter ends, knee braces, composition shingles; extended porch with box columns, wood panel entry door with upper glass, storm door; windows 1/1 wood double-hung.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor

Date April 22, 1986

DESIGNATIONS : TNRIS No. _____

Old THC Code _____

RTHL HABS (no.) TEX- _____

PHOTO DATA

NR: Individual Historic District

B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource

35 mm Negs. _____

NR File Name _____

YEAR DRWR ROLL FRME

ROLL FRME

1986		18	2	to	18	2
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 686

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-35

Address Fox & Chandler & Brown Complex 7. Architect/Builder _____

1000 ~~Chandler~~

Contractor _____

3. Owner Mize Family 8. Style/Type Shotgun Cottage

Address _____ 9. Original Use Residences

4. Block/Lot Block 62 Present Use Residences

10. Description 23 separate structures of similar design; 1-story; wood frame with asbestos shingles; brick pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends, inset porch or some with extended porch, 4 x 4 wood posts, windows 4/4 wood double-hung; bathroom/toilet shed addition at rear.

11. Present Condition Fair - Poor

12. Significance Rental housing, tightly spaced; streets were named in the late 1950s; houses were already there.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Geraldine Brown

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		18		to	18	
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 687
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 317 Fredonia St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 2, Lot 26 Present Use Residence

10. Description 1-1/2 story; rusticated concrete block; concrete foundation with concrete watertable course roof with hipped dormers, deep overhang with plain entablature, composition shingles; inset front porch with concrete block porch supports and low walls; windows wood single-hung 3/1 and 5/1, diamond multipaned paired windows in dormers; single wood entry door with three vertical lights; 3 interior concrete block chimneys with caps on east, south, and north; shed garage at rear.

11. Present Condition Good

12. Significance Architectural, good example of style.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	10	to 22	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 688

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 431 Fredonia St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 2, Lot 18 9. Original Use Residence

Present Use Apartments

10. Description 1-story; wood frame construction with bull-nosed siding and brick veneer on east facade; brick foundation; rectangular plan; intersecting gable roof with composition shingles, extended faceted beams and rafter ends; attic vent on east facade with stepped brackets below; inset entry porch, wood floor concrete steps; windows 1/1 double and single-hung; windows on east and north with patterned muntins in upper lights and flanking casements; entry door wood with large glass light, side and transom lights; projecting bays on north and south;

11. Present Condition Good - Fair; altered with brick veneer on east facade.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		22	11	to	22	11
Other					to		
					to		

Continuation sheet

10. porte cochere on south.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 689
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 710 Fredonia St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow, Shingle Style

4. Block/Lot Block 40, Lot 19 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame construction with wood shingle; masonry foundation; massed plan; hip-and-gable roofs with brackets and exposed beam ends, deep overhang, composition shingles; extended porch with battered wood columns resting on rusticated concrete block piers, simple wood railing, fixed windows at gable end with diamond and rectangular muntins; windows wood frame, mixture of multipaned double-hung on sides and 1/1 single-hung with multipaned or Queen Anne upper sash; stick-style trim around windows and

11. Present Condition Very Good

12. Significance Architectural, good example of type.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	14	to	22 14
Other					to	
					to	

Continuation sheet

10. doors; single entry door; porte cochere on northwest corner; central chimney, brick with a tapered cap; sunporch on south facade.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 690
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. ca. 1935
 Address 616 Fredonia St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 2, Lot 9 Present Use Residence

10. Description 1-story; wood frame with lapped and 105 wood siding; brick foundation; massed plan; intersecting gable roofs with extended beam and rafter ends, composition shingles; brick porch supports resting upon a low brick wall, wooden beams perpendicular to the house rest upon the porch supports; windows 2/2 wood double-hung; entry door wood paneled with 4 small upper lights, side lights similar; porch is asymmetrical and wraps around, sun porch on northwest corner; interior brick chimney; interior - wood floors with linear inset of dark

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District _____ B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		22	12	to	22	12
				to		
				to		

Other _____

Continuation sheet

10. wood running along perimenter of at least the two front rooms.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 691
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10
 Address 702 Fredonia St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot Block 40, Lot 20 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with asbestos siding; brick foundation skirt, lot slopes down from the street; ell plan; deck on hip and hip roofs with composition shingles, plain entablature; inset porch with paired porch supports with simple capitols, simple entablature with dentils; porch supports rest on brick piers; windows 2/2 wood double-hung with hood mold, in twos and threes; entry door multipane glass and wood with hood mold.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	13	to	22 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 692
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1309 Fredonia St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neo-classical
 Address _____ 9. Original Use Residence
 4. Block/Lot N Fredonia Pl S/D (415), City Blk 45, Lt 12 Present Use Residence
 10. Description _____

11. Present Condition Fair to Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 693

City/Rural Nacogdoches UTM Sector _____

2. Name Maria A. Davidson Apts. 6. Date: Factual _____ Est. 1910

Address 214 Fredonia St. South 7. Architect/Builder Dietrich Rulfs

Contractor _____

3. Owner _____ 8. Style/Type Mission Revival

Address _____ 9. Original Use Apartments

4. Block/Lot Block 23, Lots 11 & 11-B Present Use Apartments

10. Description 2-story; load-bearing brick with brick foundation; U-plan with central hall; flat roof with parapets, at east and south entries a central mission-style parapet flanked by low parapets capped by hipped eaves, with Spanish tile and ornamental brackets; entry porches on east (arched opening without canopy) and south with two-story Palladian arched entry; windows 1/1 wood double-hung with double header course above at second floor, double doors wood with multipaned glass lights; exterior brick chimney on north facade; above east entry a

11. Present Condition Good

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District _____ B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		29	9	to	29	9
					to		
					to		

Continuation sheet

10. concrete dedication plaque about Maria A. Davidson; basement under west half of building; 1-story wood frame car garages, one is original with brick facade.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 694
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
Address 601 Fredonia St. South 7. Architect/Builder _____
Contractor _____

3. Owner _____ 8. Style/Type Victorian
Address _____ 9. Original Use Residence

4. Block/Lot Block 30, Lot 7 Present Use Residence

10. Description 2-1/2 story ; wood frame with horizontal board siding, bull-nosed siding; brick pier foundation; ell plan; gable roofs with composition shingles, shed roofs on porch and small rear addition; entry porch with 4 x 4 posts, plain railing, spindle fretwork and scroll brackets at sides; entry door with decorative screen door; windows 1/1 wood double-hung with hood mold; windows on front bay with Queen Anne light in upper sash.

11. Present Condition Good - Fair

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource _____ 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	19	to 31	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 696

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 608 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 32, Lot 25-A 9. Original Use Residence

Present Use Duplex

10. Description 1-story; wood frame with bull-nosed siding; foundation skirt; rectangular plan; gable roofs with extended rafter and beam ends, composition shingles; porch across front with battered columns over brick piers, 2 entry doors side by side -- wood with large rectangular glass; windows 4/1 wood double-hung.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		31	20	to	31	20
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 697

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1895-1905

Address 609 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 30, Lot 6 Present Use Residence

10. Description 1-story; wood frame with narrow and wide lapped board siding; brick foundation; central hall plan with projecting central chamfered bay on west (front) facade; deck on hip roof with intersecting gables on north, west, and south; cornice returns, rolled ridge cap, composition shingles, decorative wood shingles at west gable end with arched opening; extended curved porch wrapping around the front bay plain Doric columns, central entry door wood paneled with large rectangular glass light, transom and hood mold above, similar door on north

11. Present Condition Good

12. Significance Architectural.

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		31	21	to	31	21
					to		
					to		

Continuation sheet

10. corner of porch; on door at southwest appears to have been altered to a floor-to-ceiling 1/1 double-hung window; windows 1/1 and 4/4, some with simple hood mold, some with pedimented hood mold; twin brick exterior chimneys on north and south, penetrating the gable ends, chimney stacks are separated from the main wall of house; interior chimney on east.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 698
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 616 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Classical Cottage

4. Block/Lot Block 32, Lot 25 9. Original Use Residence
 Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roofs with deep eaves, hipped dormer on east, composition shingles; porch across front with extended portico, large boxed wood columns with capitol and base, entry door wood with beveled glass with beveled glass side lights; windows 1/1 wood double-hung, sunporch with windows on southeast corner; interior brick chimney.

11. Present Condition Good

12. Significance Architectural significance.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	22	to	31 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 699

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1898

Address 619 Fredonia St. South 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Victorian

Address _____ 9. Original Use Residence

4. Block/Lot Block 30, Lot 5 Present Use _____

10. Description 2-story; wood frame with lapped board siding; concrete and brick pier foundation; ell plan with 1-story chamfered bay on west (front); gable roofs with flat roof over porch, composition shingles, diamond pattern punched on fascia boards at gable ends; shingles at front gable end; 2-story gallery porch with boxed columns, plain wood railing; 2 entry doors set at 90 degrees; main entry is wood with rectangular glass, side and transom lights; windows 2/2 with pedimented hood mold, some 4/4 windows at back, zigzag shingle pattern

11. Present Condition Good

12. Significance Architectural significance.

13. Relationship to Site: Moved Date Possibly Original Site

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	23	to	31 23
Other					to	
					to	

Continuation sheet

10. over windows at chamfered bay; detached garage, fenced yard.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 700
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1850s
 Address 623 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner Fredonia Lodge 8. Style/Type Greek Revival
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 30, Lot 4 Present Use Vacant
 10. Description 1-1/2 story; wood frame with beveled wood siding; brick and concrete pier foundation; rectangular central hall plan with 2 rooms on either side, 2 large rooms in attic; porch across front with boxed columns; central door - wood paneled; windows 6/6, 8/8, 1/1 wood double-hung.

11. Present Condition Fair, badly altered.
 12. Significance Architectural and historical significance; has been apartments. However, current deteriorated condition deters historic designation.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography THC Survey, 1975
 15. Informant Dr. Jere Jackson, 1975
 16. Recorder Dorothy Victor, Sally Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 31 24 to 31 24
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 701
 City/Rural Nacogdoches UTM Sector _____
 2. Name NIBCO 6. Date: Factual _____ Est. 1930-40s
 Address 723 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Industrial Complex
 Address _____ 9. Original Use Industrial Complex
 4. Block/Lot Block 30, Lot 1-A Present Use Industrial Complex
 10. Description 1-story; concrete block; masonry foundation; 9-bay facade broken by pilasters, rectangular plan; stepped parapet; entry gate on southwest corner; windows on front facade are ptd. steel central pivot awnings, 3 bays with glass block window areas; industrial complex at rear.

11. Present Condition Good
 12. Significance Important industrial complex in city.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		32	2	to	32	2
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 702

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 800 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shotgun

9. Original Use Residence

4. Block/Lot City Block 32, Lot 30-D Present Use Residence

10. Description 1-story; wood frame with board and batten and horizontal board siding; masonry foundation; ell plan; gable roofs with composition shingles, extended rafter ends; inset porch with 4 x 4 porch supports, wood paneled entry door with screen door, secondary entry at rear; windows 4/4 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		32	3	to	32	3
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 703
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 802 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Double Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 4 Present Use Residence
 10. Description _____

11. Present Condition Good; porch supports altered.
 12. Significance _____
 13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 704

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 806 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Double Shotgun

4. Block/Lot Block 38, Lot 4-B Present Use Residence

10. Description 1-story; wood frame with board and batten and wood shingle siding; rectangular plan; hip roof with extended rafter ends, composition shingles; extended gabled porch with 4 x 4 porch supports, aluminum storm door at entry; windows aluminum 1/1 double-hung replacement; attached covered walk and garage on south.

11. Present Condition Good; altered, shed addition at rear, second entry door closed.

12. Significance _____

13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		32	4	to	32	4
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 705
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-35

Address 1114 Fredonia St. South (on hill across from Wright St.) 7. Architect/Builder _____
Contractor _____

3. Owner _____ 8. Style/Type Vernacular Classical Cottage
Address _____ 9. Original Use Residence

4. Block/Lot Block 38, Lot 6 Present Use Residence

10. Description 1-1/2 story; wood frame with brick veneer; irregular plan; brick foundation; gable roofs with pedimented gable ends, semi-circular light at east gable end, composition shingles; porch across front with oversized boxed wood columns with plain capitol and base; central entry door wood with multipane glass; windows 6/1 wood double-hung; porte cochere on north side; house on hill, set above street, large oaks and pecans in front yard.

11. Present Condition Good; may have been bricked over at a later date.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		32	5	to	32	5
Other				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 706
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 1221 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 10 or 10-C, Part of Block 39 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with composition shingles, extended rafter ends and beam ends with braces; inset porch with boxed column, plain railing; entry door on side; windows 1/1 wood double-hung in twos, threes, and fours; shed porch, partially screened, on north side.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 32 6 to 32 6
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 708
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. ca. 1895
 Address 1500 Fredonia St. South 7. Architect/Builder _____

3. Owner Mrs. Perry Contractor _____
 Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot _____ Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; ell plan; intersecting gable roofs with extended rafter ends, composition shingles; extended porch with turned wood porch supports, sawtooth fretwork, clipped wood shingles at the gable end, 2 entry doors wood paneled; windows 4/4 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		40	4	to 40	4
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 709
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1502 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner Villa Apartments 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Apartments
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 710

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 1608 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 56 Present Use Apartments

10. Description 1-story; wood frame with horizontal wood siding; brick pier foundation; rectangular plan; gable roof with composition shingles, exposed beam and rafter ends; side porch under shed roof, boxed wood porch supports; 3 entry doors wood with upper glass light; windows 1/1 wood double-hung, sunporch on southwest; brick chimney on north; garage apartments at rear.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District _____ B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		40	5	to	40	5
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 711
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-30
 Address 1808 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roofs with brackets, extended rafter and beam ends; composition shingles; porch across front on the south and east with boxed battered columns resting on brick piers, wood and multipane glass entry door; windows 1/1 wood double-hung in threes; garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

• /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		40	6	to 40	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 712
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2209 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 713
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 2210 Fredonia St. South 7. Architect/Builder _____
 Contractor _____

3. Owner Dennis O'Keeffe 8. Style/Type Victorian Cottage
 Address Houston 9. Original Use Residence

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation ; ell plan; gable roofs with extended rafter ends and beam ends; inset porch with ornamental metal porch supports, side-facing entry door wood with multipane glass; windows 1/1 wood double-hung in singles and pairs; front-facing brick chimney, extending through the ridge; rear porch.

11. Present Condition Good; porch supports altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		40	7	to 40	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 714
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 2218 Fredonia St. South 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roofs with extended rafter and beam ends, composition shingles; inset porch with 2 paired 4 x 4 porch supports; side-facing wood paneled entry door with 3 vertical upper glass lights; windows 3/1 wood double-hung windows in twos and threes, side entry on west; large oak trees.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		40	8	to	40 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 715
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 2226 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Rock Cottage

4. Block/Lot Block 56 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with rockface; masonry foundation; irregular plan; gable roofs with composition shingles, vents at gable ends; porch across front with arched openings at 90 degrees meeting at one squared rock face column; wood paneled entry door with upper glass lights; arch surrounds have coursed stone with brick course below; windows 8/8, 6/6 wood double-hung with keyed brick surround; attached rockface garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		40	9	to	40 9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 716
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1915-30
 Address 2308 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good; windows altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 717

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 2331 Fredonia St. South at Wells 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage/Bungalow

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; brick pier foundation; gable roofs with extended rafter and beam ends; projecting porch with boxed wood columns, wood panel entry door with upper glass light; windows 1/1 wood double-hung, predominantly in pairs.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		40	13	to	40	13
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 719
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-10
 Address 2412 Fredonia St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage with pyramidal roof
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Poor; deteriorated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 720
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 2418 Fredonia St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Cottage

4. Block/Lot Block 56 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with brick-patterned roll siding; pier foundation; eil plan; gable roof with galvanized metal roofing; inset porch with post and pipe column porch supports, 2 entry doors set at 90 degrees with screen doors; windows 4/4 wood double-hung; shed addition at rear.

11. Present Condition Fair - Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		40	10	to	40 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 721

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 2504 Fredonia S. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot Block 56 Present Use Residence

10. Description One story wood frame with lapped board siding; rectangular plan; gable roof with composition shingles; projecting gabled porch with 4x4 porch supports; central entry door, wood paneled with upper glass lite, screen door; windows 4/4 doublehung in pairs; sheet metal awnings above; garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy L. Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		40	11	to	40	11
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 722

City/Rural Nacogdoches UTM Sector _____

2. Name Thomas E. Booth Residence 6. Date: Factual _____ Est. 1920-30

Address 2821 Fredonia St. S. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 56 9. Original Use Residence

Present Use Residence

10. Description one story wood frame with bull-nose siding, brick foundation; ell plan; gable roofs with extended rafter and beam ends, composition shingles; awning over entry door, wood door with small glass lites; windows 1/1 double hung in pairs. Wood frame barn with galvanized metal sheathing and stock pens.

11. Present Condition _____

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy L. Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

1986		40	12	to	40	12
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 723
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10
 Address 707 Fulham 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Greek Revival cottage

4. Block/Lot Block 53, lot 6-B Present Use Residence
 9. Original Use Residence

10. Description One story wood-frame with lapped board siding; brick pier foundation; rectangular plan; hip roof with composition shingles; exterior chimney on north; porch across front with paired 2x4 columns; centered wood panel door, wheel chair ramp to one side; windows 4/4 double hung.

11. Present Condition Fair to poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy L. Victor/Sally S. Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	20	to 38	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 724

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 812 Fulgham 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, lot 12-B Present Use Residence

10. Description one story frame with lap siding; composition pyramidal roof with extended rafter ends; windows 2/2 metal single hung; stoop porch; foundation skirted.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally S. Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		38	21	to	38	21
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 725
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1023 Fulgham 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, lot 41 Present Use Residence

10. Description One story wood frame with v-groove siding; raised foundation; ell plan; gable roof with composition shingles; knee braces; porch screened, boxed wood columns; wood entry door with screen; windows 4/1 double hung, 2/2 aluminum replacements; detached garage at rear.

11. Present Condition Good to fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy L. Victor/Sally S. Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	22	to 38	22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 726
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1302 Garner 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot L 6, Lindsey s/d (351), city block 45 9. Original Use Residence
 Present Use Residence

10. Description one story rectangular frame residence with hip and gable composition shingle roof. Horizontal bullnose siding. 6/1 double hung windows. Pedimented porch with box columns. 18-lite entry door.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry D. Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	5	to	24 5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 727
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1309 Garner 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type bungalow
 Address _____ 9. Original Use _____
 4. Block/Lot L 14, blk 2, Blount (066), city blk 45 Present Use _____
 10. Description _____

11. Present Condition fair
 12. Significance NAM
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry D. Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 728
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1316 Garner 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot L 4, Lindsey s/d (351), city block 45 Present Use Residence

10. Description one story rectangular frame residence with composition shingle multigable roof. Horizontal double-grooved drop siding. 6/6 double hung windows. Pedimented gable porch with 4x4 posts on brick piers. Queen and king posts; brackets with diagonal braces. Fireplace on north wall.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry D. Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	4	to 24	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 730
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1408 Garner 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot L 2-A, Lindsey s/d (351), city blk 45 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry D. Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 731
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 806 Gene 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot L 11-A, city block 5 Present Use Residence
 10. Description _____

11. Present Condition poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry D. Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		21	22	to	21	22
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 732
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 810, 814, 816 Gene 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot L 11-B, city block 5 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry D. Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		21	22	to	21	22
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 735
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 903 Gene 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot L 11-F, city block 5 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry D. Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 736
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1221 Greer 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot City Block 51, Lot 53-5 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; clipped gable roof with corrugated metal roofing, extended rafter ends; inset porch on southwest corner, screened with 4 x 4 corner post; 2 entry doors set at 90 degrees; windows 4/1 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		42	6A	to	42 6A
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 737
 City/Rural Nacogdoches UTM Sector 1311 Greer
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1311 Greer 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, JG Orton S/D(437) Blk 4, Lot 1 Present Use Residence
 10. Description One story; wood frame with asbestos siding; brick foundation; rectangular plan; gable roof with extended rafter ends and knee braces, composition shingles; inset porch with metal porch support; windows are 4/1 wood double hung, some with awnings.

11. Present Condition Good, altered by asbestos siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 738
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-45
 Address 304 Grey 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 51, Lot 38-B Present Use Residence
 10. Description 1-story; wood frame with horizontal board siding; brick foundation; irregular plan; gable roofs with composition shingles; extended porch with paired 4 x 4 posts; entry door with storm door; windows 6/6 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 41 12 to 41 12
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 739
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-30
 Address 309 Grey 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Cottage

4. Block/Lot City Block 51, Lot 46 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with asbestos siding; ell plan with addition at rear; hip-and-gable roof with composition shingles; extended porch, shed roof, metal porch supports; windows 4/4, 3/1 wood double-hung; pressed metal foundation skirt at porch, plastered foundation wall at part of the house.

11. Present Condition Fair - Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	2986		41	11	to 41	11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 740
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 911 Hackberry 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence
 Present Use Residence

10. Description One story; wood frame with bull nose siding; brick pier foundation; rectangular plan; hip roof with gable over porch extended beam ends, wide fascia board; composition shingles; extended porch with boxed wood columns, single entry door; windows are 1/1 wood double hung in arrangements of 2 and 3.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 741
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 915 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Vacant
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 742
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 925 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Vacant

10. Description 1-story; wood frame with horizontal board siding; masonry foundation; rectangular plan; clipped gable roofs with composition shingles, extended beam ends; extended porch with boxed wood columns; windows 1/1 wood double-hung arranged in pairs.

11. Present Condition Good; altered foundation skirt and fascia board at eaves.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

	<input type="checkbox"/> RTHL	<input type="checkbox"/> HABS (no.) TEX-	PHOTO DATA			
NR:	<input type="checkbox"/> Individual	<input type="checkbox"/> Historic District	<input type="checkbox"/> B&W 4 x 5s	<input type="checkbox"/> slides		
	<input type="checkbox"/> Thematic	<input type="checkbox"/> Multiple-Resource	<input type="checkbox"/> 35 mm Negs.			
NR File Name		YEAR	DRWR	ROLL	FRME	ROLL FRME
						to
Other						to
						to

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 743
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1007 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 744
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
Address 1011 Hackberry 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence
Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick foundation; rectangular plan; clipped gable roofs with composition shingles, extended curved rafter ends; inset porch with boxed wood columns; 2 entry doors at 90 degrees; windows 1/1 wood double-hung; garage apartment at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 745
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1105 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with asbestos siding; rectangular plan; gable roof with composition shingles, extended rafter and beam ends; extended porch with metal porch supports; windows 1/1 wood double-hung.

11. Present Condition Good; altered by asbestos siding and metal porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 746
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1109 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 747
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1117 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Apartments
 10. Description _____

11. Present Condition Fair; altered porch.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 748
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1125 Hackberry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; hip roof with gable porch roof, boxed eave, composition shingles; extended porch with paired posts, entry door wood with multipane glass; windows 1/1 wood double-hung, arranged in pairs.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 749
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 314 Harris 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____

8. Style/Type Bungalow with Classical Eleme
 9. Original Use Residence

4. Block/Lot Block 48, Lot 43-A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; clipped gable roofs with composition shingles, boxed cornice and eave; inset porch, cylindrical columns with plain capital and base, 2 entry doors set at 90 degrees, wood with multipane lights; windows 6/6 wood double-hung; exterior brick chimney with corbeled cap; wood frame garage and shed at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		11	13	to	11 13
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 750
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1008 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Spanish Colonial Revival
 Address Same 9. Original Use Residence
 4. Block/Lot Block 48, Lot 48 Present Use Residence

10. Description 2-story; pink stucco; massed plan; red tile gable roof; exterior chimney with 3 pots on east facade; extended rafter ends; arched entry recessed; windows wood casement with some shutters; stucco has rough texture; 1-story garage of same style at rear; very large corner lot; extensive landscaping.

11. Present Condition Excellent
 12. Significance Good example of style.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	14	to	11 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 751
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 416 Harris 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 36-A Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 752
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 522 Harris 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 55-A Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 753
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 606 Harris 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 48, Lot 55-D 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; clipped gable roofs with composition shingles, boxed eave; inset porch with 4 x 4 supports, plain wood rail, 2 entry doors at 90 degrees wood with rectangular glass lights; windows 1/1 wood double-hung; wood frame garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	15	to	11 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 754
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 624 Harris 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 48, Lot 55-G 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; T-plan; clipped gable roofs with extended rafter ends, composition shingles; small roof over entry supported by diagonal braces, entry door wood with 3 small glass lights; windows 1/1 wood double-hung with small wood shutters.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	16	to	11 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 755
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 814 Harris 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 48, Lot 56-D Present Use Residence

10. Description 1-story wood frame with bull-nosed siding; rectangular plan; hip-and-gable roof with extended rafter and beam ends, composition shingles; extended porch with brick columns over brick piers; central wood entry door with upper glass light; windows 4/4 wood double-hung; site slopes upward from the street.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	17	to 11	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 756
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1102 Harris 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 57 Present Use Residence
 10. Description _____

11. Present Condition Good; extensively altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy L. Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 757
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1315 Harris 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot PDFore S/D #1, City Blk 48, Blk 205, Lt 3 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; ell plan; gable roof with extended rafter and beam ends; inset porch with boxed columns, entry door wood with upper glass light; windows 1/1 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 11 18 to 11 18
 Other _____ to _____
 _____ to _____

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 758
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1325 Harris 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot PDFore S/D #1, City Blk 48, Blk 205, Lt 1 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 759
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1415 Harris St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board and Batten Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 65 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 760
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 309 Hasley 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Haltom&Brewer S/D (81), Blk 62, Lt 10-M Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides _____
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
					to		
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 761

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 122 Hayter 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Vernacular w/ Neo-classical Elemts

Address _____ 9. Original Use Residence

4. Block/Lot City Block 50 Present Use Residence - Apartments

10. Description 2-story; wood frame with bull-nosed siding; brick foundation skirt; rectangular plan; gable roof with 2 dormers on north, composition shingles; classical portico with cambered roof, narrow Doric boxed columns, sunburst transom over multipane glass and wood door; windows wood 6/6 double-hung, generally in pairs, symmetrical facade arrangement; detached 2-story garage and apartment.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		28	13	to	28	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 762
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 502 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Cleaver S/D 128, Block 53 Present Use Demolished
 10. Description Included in survey, however, demolished before photograph could be taken.

11. Present Condition Demolished.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 763
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20
Address 507 Hayward 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow
9. Original Use Residence

4. Block/Lot Block 51 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; ell plan; gable roof; brick pier foundation; inset porch with turned wood columns, wood paneled door with glass light; windows wood double-hung 4/4.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		38	7	to 38	7
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 764
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 601 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53 Present Use Residence
 10. Description _____

11. Present Condition Burned
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 765
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 605 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 2-A Present Use Residence

10. Description 1-story; wood frame, bull-nosed siding; brick piers; ell plan; gable roofs with extended rafter ends, composition shingles; porch across front with boxed columns, entry door with screen door; 411 wood double-hung, fixed windows.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs.
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 38 8 to 38 8
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 766
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 611 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 2-B Present Use Residence
 10. Description 1-story frame with drop siding; composition gable roof with extended rafter ends; windows are 2/2 wood double-hung; projecting porch has 2 x 4 posts; foundation skirted.

11. Present Condition Good; some alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	9	to 38	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 767
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 704 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 19 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition clipped gable roof with extended rafter ends; projecting porch has 2 x 4 posts; replacement aluminum windows; brick pier foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	12	to	38 12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 768
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 708 / 706 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 10 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; pier foundation; rectangular plan; projecting porch with wood posts, wood paneled entry door with upper glass lights; windows 4/4 wood double-hung; gable roofs with sheet metal roofing, extended rafter ends.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 38 13 to 38 13
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 769
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 800 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 14 Present Use Residence
 10. Description _____

11. Present Condition Good; applied siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 770
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 723 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 4-B Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 771
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10
 Address 804 Hayward 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 53, Lot 15 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with board and batten siding; ell plan; pyramidal and gable roof with sheet metal roofing, porch with wood post support, 2 doors at 90 degrees; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	14	to 38	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 772
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 805 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 9-A Present Use Residence
 10. Description _____

11. Present Condition Poor; applied siding, numerous alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 773
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 811 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 12-A Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; pyramidal roof with metal roofing; inset porch with boxed columns; windows 3/1 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 38 15 to 38 15
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 774
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 909 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 18 Present Use Residence
 10. Description _____

11. Present Condition Severely Deteriorated.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 775
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1001 Hayward 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 19 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with composition shingles; extended porch with box columns; windows replacement aluminum single-hung.

11. Present Condition Fair; windows altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	16	to 38	16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 778

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900

Address 1314 Herbert 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 43, Lot O L 8-E 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; lapped siding on addition; ell plan with addition; brick pier foundation; gable roofs with composition shingles, extended rafter ends; gable roof over porch with builtup 2 x 4 porch supports, central entry door; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		33	22	to	33	22
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 780
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 611 Hill Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 781
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 114 Hillencamp St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow / Vernacular Classical
 Address _____ 9. Original Use Residence
 4. Block/Lot Clark S/D (122), City Block 43, Lot 11 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; steep hip roof with galvanized metal roofing, plain entablature; inset porch with boxed wood columns, 2 entry doors with screened doors; windows 2/2 aluminum double-hung; shed addition on rear.

11. Present Condition Fair - Good; windows altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		32	23	to	32	23
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 782
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 115 Hillencamp 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43, Lot 24 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 783
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1116 Hilltop 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 51, Lot 42-B Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roofs with composition shingles; extended rafter ends; inset porch on northwest corner; boxed wood columns; wood panel entry door with upper glass light; windows 3/3 wood double-hung; foundation obscured by skirt.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	10	to	41 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 784

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1898

Address 307 Houston St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 40, Lot 8 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with horizontal board siding; brick foundation; steep hip-and-gable roofs with composition shingles, ornamental brackets at eave of projecting front bay; inset porch with boxed wood columns, spindle rail, entry door with beveled glass light; windows 2/2, 6/6 wood double-hung; Queen Anne sash at first and second floor of south bay; decorative siding and shingle work at gable ends.

11. Present Condition Good; roof in fair to poor condition.

12. Significance Architectural; good example of style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
	1986		23	5	to	23	5
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 785
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Plaza Mast House 6. Date: Factual _____ Est. 1910-20
 Address 507 Hospital St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 6 Present Use Commercial
 10. Description 2-1/2 story; wood frame with lapped board siding; brick foundation; irregular plan; intersecting hip roofs with pressed metal (patterned) roofing with ridge caps and finials; deep eaves with extended beam ends acting as modillion blocks; dormer on west with arched windows with vertical panes; original entrance and porch on south obscured; brick piers with cast stone cap for porch supports; 2 recessed entry doors, one double wood door with glass, one single door with 3 vertical panes and stained glass in transom; windows 1/1 double-hung
 11. Present Condition Good; extensively altered at entry and southwest corner of first floor.
 12. Significance Built by Mr. Mast for his second wife; funeral home from 1937 to 1985.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 21 3 to 21 3
 Other _____ to _____
 _____ to _____

Continuation sheet
 10. and 4 or 5 panes set in a wood sash; detached 2-story garage on east.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 786
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1890
 Address 518 Hospital St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 6 Present Use Apartments

10. Description 1-story; wood frame with lapped board siding; brick pier foundation; irregular plan; gable roofs with composition shingles, cornice returns on front bay; gallery porch on northeast corner, boxed wood columns, side-facing entry doors; windows 1/1 wood double-hung, casement windows on front bay.

11. Present Condition Fair - Good; early and later additions have altered the original house.

12. Significance House has 1 x 12 studs with weatherboard on both sides.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		21	2	to	21 2
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 787

City/Rural Nacogdoches UTM Sector _____

2. Name Tucker House 6. Date: Factual _____ Est. 1923

Address 118 Houston St. East 7. Architect/Builder Herbert Schindler, Builder

Contractor _____

3. Owner Wyatt Tucker 8. Style/Type Bungalow

Address 118 Houston 9. Original Use Residence

4. Block/Lot Block 2, Lot 1-A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; shed roof over porch with 4 x 4 posts; windows wood double-hung 12/12, 12/1; entry door wood and multipaned glass; roof is gabled with clipped gable ends, extended rafter ends and extended beam ends; planter boxes under windows with brackets; exterior brick chimney on west; sunporch on the east.

11. Present Condition _____

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	22	to	22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 788

City/Rural Nacogdoches UTM Sector _____

2. Name Mrs. J. M. Colley 6. Date: Factual _____ Est. 1925

Address 117 Houston St. East 7. Architect/Builder Judge Hodges, Builder

Contractor _____

3. Owner Mrs. J. M. Colley 8. Style/Type Bungalow

Address 117 Houston St. East 9. Original Use Residence

4. Block/Lot Block 40, Lot 5-A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with extended rafter and beam ends, composition shingles; concrete porch steps; windows 4/1 wood double-hung; entry door wood with jalousie door on exterior; side entry on west facade; detached garage.

11. Present Condition Good

12. Significance Mrs. Colley's parents moved to the house about 1928.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. J. M. Colley, 1/21/86

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		33	13	to	33	13
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 789
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 205 Houston St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian Bungalow

4. Block/Lot Block 40, Lot 21-B 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with hipped dormer on south facade, composition shingles, plain entablature; inset 3-bay porch across front with wood boxed columns; windows 2/2 and 1/1 wood double-hung; entry door wood paneled with upper glass light; brick chimney at north facade.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	2	to 23	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 790
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 209 Houston St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 40, Lot 22 Present Use Residence
 10. Description 1-story; wood frame; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter ends and corner brackets; porch on two sides with boxed columns; windows 1/1 wood double-hung; entry door wood paneled with upper glass light; detached garage.

11. Present Condition Good; porch altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	4	to	23 4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 791

City/Rural Nacogdoches UTM Sector _____

2. Name Jordan House 6. Date: Factual _____ Est. 1899-1905

Address 123 Houston St. East 7. Architect/Builder Dietrich Rulfs, possibly

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 40, Lot 5-B 9. Original Use Residence

Present Use Residence

10. Description 2-story; wood frame construction with lapped wood siding and shingles at bays and gable ends; brick foundation; irregular plan with 2-story chamfered bay on east facade; gable and flat roofs with enriched modillion brackets at second story eaves, composition shingles, cornice returns; 1-story two-bay porch with flat roof and brick porch supports resting on brick piers, low brick wall; windows 2/2 and some 6/6 at rear wood double-hung with hood molds on front facade; entry door with side lights and transom above with low relief ornamentation; front yard is

11. Present Condition Good - Fair

12. Significance Architectural

13. Relationship to Site: Moved Date ca. 1925 Original Site Originally on North St. at Houston, per Mrs. J. M. Colley.

14. Bibliography _____

15. Informant Mrs. J. M. Colley

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	23	to	22 23
Other					to	
					to	

Continuation sheet

10. is heavily planted and partially obscures the view of the house from the street.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 792
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-20
 Address 127 Houston St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian Bungalow

4. Block/Lot Block 40, Lot 21-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with hipped dormer on south facade, composition shingles, beaded board soffit, plain entablature; inset 3-bay porch across front with boxed wood columns, simple wood railing; windows 2/2 wood double-hung; entry door wood paneled with upper glass light; brick chimney on north facade.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource _____ 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	to	ROLL	FRME
Other _____	1986		22	24	to	22	24
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 793

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 206 Houston St. 7. Architect/Builder _____

Contractor _____

3. Owner Mr. Collins 8. Style/Type Bungalow

Address Garrison, Texas 9. Original Use Residence

4. Block/Lot Block 2, Lot 2-A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with composition shingles, extended trimmed rafter ends, faceted beam ends; bargeboards; inset porch with boxed wood columns, simple wood railing; windows 4/1 wood double-hung, with some in pairs; entry door wood paneled with 3 upper glass lights; detached garage shed.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		23	3	to	23	3
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 794
 City/Rural Nacogdoches UTM Sector _____

2. Name Pat Walkers 6. Date: Factual _____ Est. 1930-40
 Address 114 Hughes 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 2, Lot 5-C Present Use Vacant

10. Description 1-story; wood frame with asphalt siding; brick foundation; massed plan; gable roof with clipped gable ends on east and west, cornice returns, composition shingles; entry porch with arched portal, boxed and cylindrical columns paired; window 1/1 double-hung; exterior brick chimney on east facade.

11. Present Condition Good; windows altered to horizontal 2/2 double-hung.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____

YEAR	DRWR	ROLL	FRME		ROLL	FRME
1986		22	15	to	22	15
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 795
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925
 Address 118 Hughes 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 2, Lot 5-B Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; gable roof with corner brackets; gable roof over entry porch with trussed porch supports with faceted ends; windows 3/1 wood double-hung; entry door multipaned glass and wood; exterior brick chimney; detached car shed; rectangular plan.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	16	to	22 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 796
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
Address 121 Hughes 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 2, Lot 3-A Present Use Health Clinic
9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation with flared wood siding foundation skirt; hip roof with hip dormer, extended rafter ends; porch across front facade, decorative metal porch supports resting low wall; ramp at front steps; windows oversized 1/1 wood double-hung; entry door multipaned glass and wood; porte cochere with altered pipe columns; central brick chimney; sunporch on east facade.

11. Present Condition Demolished, before photograph could be taken.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Larry Hodge Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 797
 City/Rural Nacogdoches UTM Sector _____
 2. Name Graham Financial Corporation 6. Date: Factual _____ Est. 1940
 Address 124 Hughes 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 2, Lot 5-A Present Use Commercial Office
 10. Description 1-story; wood frame with vinyl siding; brick foundation; rectangular plan; gable roof; porch altered with modern wood columns, porch floor removed; 1/1 wood windows; wood entry door; exterior brick chimney on north facade.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	17	to	22 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 798

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 203 Hughes 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 2, Lot 4-A Present Use Residence

10. Description 1-story; wood frame with asphalt siding; brick foundation; massed plan; gable roofs with extended beam and rafter ends; entry porch with plain entablature, altered with metal porch supports and porch floor removed, brick steps at door; windows 3/1 wood double-hung in twos and threes; entry door wood paneled; carport at northwest corner; interior brick chimney.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		22	18	to	22	18
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 799
 City/Rural Nacogdoches UTM Sector _____

2. Name Matt B. Tucker 6. Date: Factual _____ Est. 1910
 Address 210 Hughes 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Folk Victorian Cottage

4. Block/Lot Block 2, Lot 9-A 9. Original Use Residence
 Present Use Offices

10. Description 1-story; wood frame with asbestos shingles; T-plan; hip-and-gable roofs with boxed cornice and lapped seam galvanized metal roof; shed roof over porch, 4 x 4 porch supports with scroll brackets; surrounded on two sides by asphalt parking lot.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		22	19	to	22 19
					to	
					to	

Continuation sheet