

Nacogdoches
Historic Site Survey
and
Preservation
Feasibility Study
1986

Prepared by

Victor & Victor Consultants, Inc.

P.O. Box 26189

Austin, Texas 78755

512-451-3708

VOLUME e

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 800

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 309 Hughes 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Brick Tudor Cottage

Address _____ 9. Original Use Residence

4. Block/Lot Block 40, Lot 20-A Present Use Residence

10. Description 1-story; wood frame construction with brick veneer; brick foundation; hip-and-gable roof with flared eaves, composition shingles; brick entry porch with arched entry, no roof; U-plan; windows 6/6 wood double-hung and wood casement with stained glass on south facade, arched window in attic gable; entry door wood paneled with fan light above, storm door; carport at northwest corner; enclosed sunporch on southeast corner with elliptical arches.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		22	20	to 22	20
Other					to	
					to	

Continuation sheet

Sp 6011
F
394
.N32
N26
1986x
v. C

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 801
 City/Rural Nacogdoches UTM Sector _____
 2. Name Jones 6. Date: Factual _____ Est. 1930s
 Address 311 Humphrey Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Fair; asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 802
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 320 Humphrey Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date March 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 803
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 412 Humphrey Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 804
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2720 Hunter (Across from VFW) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 805
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 911 Jacklock 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; rectangular plan; composition clipped gable roof with extended rafter ends; projecting porch upheld by iron columns; windows are 3/1 wood double-hung; carport on south side.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	15	to	20 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 806
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 919 Jacklock 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence

10. Description 1-story frame with massed plan; composition hip roof with 1 exterior chimney; extended rafter ends, projecting porch with triple columns on brick base; porte cochere on north side; windows are 6/1 wood double-hung; pier and beam foundation.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	16	to	20
Other					to	16
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 807
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 4918 Jean 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Unknown
 4. Block/Lot City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by brick apron at perimeter.

12. Significance _____

13. Relationship to Site: Moved Date _____ Possibly _____ Original Site Possibly from SFA
campus.

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 808

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
Address 4922 Jeane 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____

8. Style/Type Bungalow
9. Original Use Residence or Dorm

4. Block/Lot City Block 70 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation apron; irregular plan; gable roofs with composition shingles, knee braces; inset porch with turned wood porch supports, plain wood railing, 2 entry doors set at 90 degrees, wood paneled with upper glass light; 6/6, 4/1 wood double-hung windows.

11. Present Condition Good; altered by brick perimeter apron.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site Possibly from SFA campus.

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		36	4	to 36	4
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 809
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1120 Jeffries 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered replacement windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 810
 City/Rural Nacogdoches UTM Sector _____
 2. Name Proctor 6. Date: Factual _____ Est. 1930s
 Address 1214 Jeffries 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Fair; vinyl siding, numerous alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 811
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1614 John St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair; vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 812

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 1902 John St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; raised brick pier foundation; 4/4 wood double-hung; inset porch supported by 2 x 2 wood posts.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		34	24	to	34	24
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 813

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1910 John St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description _____

11. Present Condition Fair; extensively altered windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 814

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 0000 John Richardson Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding, horizontal siding; rectangular plan; 4/4 wood double-hung windows; gable roof with composition shingles; extended porch with wood posts.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		19	21	to	19	21
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 815
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 0000 John Richardson Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Fair - Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 816

City/Rural Nacogdoches UTM Sector _____

2. Name Henry Richardson, Willie Bell House 6. Date: Factual _____ Est. 1935

Address 0000 John Richardson & Crisp Rds (Near 2213, facing north) 7. Architect/Builder Mr. John Richardson

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence & Farm Complex

10. Description 1-story; wood frame with beveled siding; T-plan; gable roofs with corrugated metal roofing; interior brick chimney; extended porch with metal supports; wood panel entry door; 4/4 wood double-hung windows; brick foundation; small log storage house, outbuildings of frame and wide board siding, pens.

11. Present Condition Good - Fair

12. Significance Mr. John Richardson farmed this land all this life; he inherited it from his father and mother, Sylvia and Henry Richardson.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography

15. Informant Mrs. Bessie Mae Menefee, Ms. Mary Bell.

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	20	to	19 20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 817
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 702 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 818
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 707 Jordan (Rear) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
_____					to		
Other _____					to		
_____					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 819
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 706 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 820
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 715 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 821

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920s

Address 817 Jordan 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shotgun

4. Block/Lot Block 66 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with board and batten siding; pier foundation; rectangular plan with small addition for bathroom; gable roof with metal roofing; extended porch with 4 x 4 supports; windows 1/1 wood double-hung, centered entry door.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	4	to	20 4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 822
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 901 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 823
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 905 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 824
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 909 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; pier foundation; gable roof with extended rafter and beam ends, composition shingles; inset porch with 4 x 4 supports with capitol and base, plain wood railing; windows 4/4 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	3	to 20	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 825
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1001 Jordan 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 826
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1602 John St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 827
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 204 King 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 3 1/2 - D - 1 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 828
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 220 King 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____

8. Style/Type Neo-classical
 9. Original Use Residence

4. Block/Lot City Block 40, Lot 3 1/2 - D Present Use Residence

10. Description 1-story rectangular frame residence with hexagonal asphalt shingle hip roof; horizontal bull-nosed siding; 2/2 double-hung windows; hall parlor plan with twin glass panel entry doors, screens with tracery; full-width wood porch with Tuscan columns; turned balusters.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	6	to	23 6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 829
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 305 King 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 40, Lot 2-A Present Use Residence
 10. Description 1-story rectangular frame residence with cross-gable roof; horizontal bull-nosed siding; 6/6 and 12/12 double-hung windows; brick porch with box columns; multi-light entry door with side lights.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		23	7	to	23	7
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 830

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 413 King 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 40, Lot 3-S 9. Original Use Residence

Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle clipped gable roof; horizontal bull-nosed siding; 6/1 double-hung windows; small wood entry porch with box columns and exposed purlins; side entry has clipped gable overdoor with collar beam.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	8	to 23	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 831
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 511 King 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Rock Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 26, Lot 1-A Present Use Residence
 10. Description 1-story ell-shaped rock residence with composition shingle gable roof; 6/6 double-hung windows; three-light entry doors with shouldered depressed arch lights; fireplace on projecting bay.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

YEAR	DRWR	ROLL	FRME	ROLL	FRME
1986		23	9	23	9

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 832
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 514-A King 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 2-B Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with composition shingles, trimmed rafter ends, faceted beam ends, bargeboards; inset porch with turned wood posts with Ionic-style caps; windows 3/1 wood double-hung; entry door wood paneled with three upper glass lights.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	10	to 23	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 833
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 518 King 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 2-C 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with composition shingles, curved rafter ends, corner brackets with faceted beam ends; inset porch with boxed wood columns, plain wooden porch rail; windows 4/1 wood double-hung; single entry door on side; one-room apartment at rear.

11. Present Condition Good

12. Significance Twia to 524 King.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	11	to 23	11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 834
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 524 King 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 2-D 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with composition shingles, curved rafter ends, faceted beam ends, segmental arch vents at gable ends; inset porch with boxed wood columns; windows 4/1 wood double-hung; entry door wood paneled with upper glass light; one-room apartment at rear.

11. Present Condition Good

12. Significance Twin to 518 King.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	12	to 23	12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 835

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 528 King 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Tudor Cottage

4. Block/Lot Block 26, Lot 2-F 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with yellow vinyl siding; brick foundation; ell plan; steep gable roofs with diamond pattern composition shingles; corner entry porch without roof; windows 6/6 wood double-hung; entry door wood with round head and three small lights, flanked by small arched windows with shutters; detached wood frame garage.

11. Present Condition Good; altered by vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	13	to	23 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 836
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 604 / 606 King 7. Architect/Bulder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type American Four-Square

4. Block/Lot Block 26, East Part of Lot 2-E Present Use Apartments
 9. Original Use Residence or Duplex

10. Description 2-story; wood frame with bull-nosed siding, largely covered by asbestos shingles; brick foundation; rectangular plan; hip-and-gable roofs with diamond-patterned composition shingles with ridge cap; extended entry porch with square brick columns over brick piers, diamond-patterned railing; windows 1/1 wood double-hung; entry doors wood paneled with four upper glass lights, gabled dormer on north facade; interior brick chimney; detached board and batten garage.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	14	to	23 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 837

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 613 King 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Stick-style Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Section 26, Lot 13-5 Present Use Residence

10. Description 1-story; wood frame with vinyl siding; brick pier foundation; rectangular plan; extended porch with square brick columns over brick piers; gable roofs with composition shingles, rectangular brackets with faceted ends; windows wood double-hung 4/1; single entry door; exterior brick chimney on east; detached car shed.

11. Present Condition Good; altered by vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	15	to	23 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 838
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 623 King 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 26, Lot 13-3 Present Use Residence
 10. Description 1-story; wood frame with asbestos siding; brick foundation; irregular plan; gable roofs with extended rafter and beam ends, composition shingles; extended porch with brick columns and low wall; windows 1/1 wood double-hung; entry door wood with glass lights.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	16	to	23 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 839
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 627 King 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 26, Lot 13-2 Present Use Residence
 10. Description _____

11. Present Condition Good; porch altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 840
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 631 / 633 King 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 26, Lot 13-1 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; symmetrical irregular plan; gable roofs with composition shingles, extended rafter ends and brackets with faceted beam ends; twin entry porches with boxed wood columns; windows 6/1 wood double-hung; entry doors wood with multipane glass; central brick chimney with corbeled cap; detached wood frame garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		23	17	to	23 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 841
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 217 Lake St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by continuous brick foundation, metal porch support.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 842
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-35
 Address 0000 Lake & Press Rd. (Southwest Corner) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Vacant
 10. Description _____

11. Present Condition Deteriorated; boarded windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 843

City/Rural Nacogdoches UTM Sector _____

2. Name Building behind Calvary Baptist Church 6. Date: Factual _____ Est. 1930-40

Address 2220 Main St. East (rear on Lamar St.) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular

4. Block/Lot Sutton&Gound S/D(583), Bk 63, Bk1, L15 9. Original Use Possibly School

Present Use Church Related Use

10. Description 1-story; wood frame with bull-nosed siding; concrete pier foundation; rectangular plan with projecting bay on north; hip roof with composition shingles, intersecting gable roof supported on diagonal braces on north; inset porch with boxed column; 2 entry doors, one secondary entry door on northeast; windows 4/1, 8/8 wood double-hung, multipane casement windows. Long building, horizontal lines, dominant roof.

11. Present Condition Fair - Good; early addition at rear.

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 844

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 219 Lamar 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Sutton&Ground S/D (583), Blk 63, Lot 10 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition clipped gable roof; projecting porch; windows are wood 4/1 double-hung; pier and beam foundation; extended rafter ends.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		18	12	to	18	12
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 845
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 223 Lamar 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Sutton&Grounds/D(583), CityBlk 63, Lt 12 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; pier foundation; rectangular plan; clipped gable roof with extended rafter and beam ends, composition shingles; gable roof over porch with paired 4 x 4 posts; windows 4/1 wood double-hung in pairs.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18	11	to	18 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 846
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 306 Lamar 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63, Lot 10-M or Lot 10-S Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 847
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 2403 Lampkin 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by later addition on north, some aluminum replacement windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 848
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2408 Lampkin 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 849
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2613 Lampkin 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair; vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 850
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2615 Lampkin 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair; vinyl siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 851
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 2617 Lampkin 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story; wood frame with roll composition siding; brick pier foundation; rectangular plan; gable roof with sheet metal roofing; inset porch with wood post; windows 4/4 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 35 15 to 35 15
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 852

City/Rural Nacogdoches UTM Sector _____

2. Name Oak Grove Cemetery 6. Date: Factual 1837 Est. _____

Address 200 Lanana St. North 7. Architect/Builder _____

3. Owner City of Nacogdoches Contractor _____

Address _____ 8. Style/Type Historic Cemetery

4. Block/Lot Block 5, Lots 9, 13, 13-A, & 14 Present Use Cemetery

10. Description Large well-maintained cemetery surrounded by decorative cast iron fence; most of cemetery is covered with San Augustine grass; however, a handful of graves are swept and mounded; many are curbed; vegetation includes magnolia, lagustrum, holly, cedar, and other trees; markers are upright, flat, false crypt, and mausoleum.

11. Present Condition Excellent

12. Significance One of the oldest known Anglo cemeteries in state; 4 signers of the Texas Declaration of Independence are buried here: Thomas J. Rusk; Charles S. Taylor, John S. Roberts, William

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	4	to	21 4
Other _____					to	
					to	

Continuation sheet

12. Clark; surrounded by black residential area.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 853
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-1920s
 Address 321 Lanana St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow / Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 4, Lot 4-B Present Use Residence
 10. Description 1-story frame; rectangular plan; gable asphalt roof; bull-nosed siding; windows are 4/4 double-hung, 6/6 and 8/8; foundation skirted with brick; small concrete stoop at front; attached garage on north facade.

11. Present Condition Fair
 12. Significance Part of an intact historic black neighborhood - Zion Hill.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	5	to	21 5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 854

City/Rural Nacogdoches UTM Sector _____

2. Name Zion Hill Baptist Church 6. Date: Factual 1914 Est. _____

Address 324 Lanana St. North 7. Architect/Builder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Gothic

4. Block/Lot City Block 5, Lot 12-A 9. Original Use Religious

Present Use Religious

10. Description 1-story; wood frame with beveled wood siding; brick foundation with basement; irregular plan with two corner towers; intersecting pyramidal hip-and-gable roofs with wood shingles, flared eaves, cornice return, octagonal dome with fixed windows atop the main roof, towers and dome with metal finials; corners of the church have blind pilasters; small entry porch with gable roof with bargeboards resting on simple boxed wood columns over brick piers, double wood entry door paneled with arched transom above, three trefoil lights in the transom; windows are wood

11. Present Condition Excellent

12. Significance Architectural and local history. Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography 1975 THC Survey

15. Informant Dr. Jere Jackson

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	6	to 21	6
Other					to	
					to	

Continuation sheet

10. frame double-hung and center pivot awning-type, 1/1 and 2/2 lights, windows around the sanctuary have lancet arch heads with colored obscured glass, other windows have obscured glass; basement windows are 3/3 awning-type; rear entry to the basement with double wood panel doors, ornate brackets under the eave.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 855
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 401 Lanana St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 4, Lot 3-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with composition shingles, extended rafter ends, faceted beam ends; inset porch with boxed wood columns, single entry door, paneled wood with upper glass light; windows 1/1 wood double-hung with shutters on the front, half screens; lattice attic vent at gable end.

11. Present Condition Good

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	7	to 21	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 856

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 406 Lanana St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shotgun Cottage

4. Block/Lot Block 5, Lot 10-A-1 Present Use Residence

10. Description 1-story; wood frame with bull-nosed and board and batten siding; brick pier foundation; 2 bays, appears to be 2 shotguns joined with shed addition at rear, shed roof at front with 4 x 4 posts, windows 4/4 wood double-hung; two entry doors wood paneled.

11. Present Condition Fair - Good

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	8	to	21 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 857
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 412 Lanana St. North 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 5, Lot 9-B Present Use Residence

10. Description 1-story frame with bull-nosed lap siding; massed plan; asphalt clipped gable roof with extended eaves and braces; vent dormer on front facade; projecting wood porch upheld by fluted columns on brick base; windows are 6/1 wood double-hung; 2 entry doors paneled with six lights opening onto porch.

11. Present Condition Fair - Good; some alterations.

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	9	to 21	9
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 858

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s

Address 422 Lanana St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 5, Lot 4 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed flat siding; asphalt clipped gable roof with extended rafter ends; inset wood porch; rectangular plan; brick pier foundation, 6/6 wood double-hung windows; 1 brick chimney stack at rear.

11. Present Condition Fair; some alterations.

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	10	to	21 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 859
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 500 Lanana St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 5, Lot 4-A Present Use Residence

10. Description 1-story frame with bull-nosed lap siding; asphalt clipped gable roof; rectangular plan; 1 brick chimney at rear; windows are 6/6 and 6/4 wood double-hung; projecting front porch upheld by boxed columns; painted bright blue like three other surrounding structures; extended rafter ends.

11. Present Condition Fair; some alterations.

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	11	to	21 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 860
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 504 Lanana St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 5, Lot 4-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with beaded wood siding; rectangular plan; clipped gable roof with composition shingles; porch across front with battered boxed wood columns; windows 6/6 wood double-hung; 2 wood paneled entry doors.

11. Present Condition Fair - Good

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	12	to	21 12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 861

City/Rural Nacogdoches UTM Sector _____

2. Name Anna Mae & Aaron Reed 6. Date: Factual _____ Est. 1943

Address 505 Lanana St. North 7. Architect/Builder Mr. & Mrs. Blum Mast, Bldrs

3. Owner Aaron Reed Contractor _____

Address same 8. Style/Type Cottage

4. Block/Lot Block 4, Lots 2-D & 2-G 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with board and batten siding; brick foundation; rectangular plan; gable roofs with shed roof at porch, composition shingles; windows 6/6 wood double-hung with hood mold and shutters.

11. Present Condition Good - Excellent

12. Significance Additions on north and south side both given by the Masts to former maid, Anna Mae Reed. Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		21	13	to	21	13
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 862
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 506 Lanana St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 5, Lot 3 9. Original Use Residence
 Present Use residence

10. Description 1-story; wood frame with wood siding; concrete pier foundation; ell plan; clipped gable roofs with composition shingles, extended rafter and beam ends; inset porch on northwest corner with oversized boxed wood columns and plain railing; windows wood 4/1 double-hung in pairs and triples; 2 entry doors at 90 degrees; wood paneled with 3 upper glass lights; detached singled-car garage.

11. Present Condition Good

12. Significance Part of an intact historic black neighborhood - Zion Hill.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	14	to	21 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 863
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1890-1900
 Address 512 Lanana St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner Clarence McMichael 8. Style/Type Victorian Cottage
 Address 512 Lanana St. North 9. Original Use Residence
 4. Block/Lot Block 5, Lot 2 Present Use Residence

10. Description 1-story frame with lap bull-nosed siding; massed plan; asphalt hip-and-gable roof with cornice returns pierced by one brick chimney stack; 1 gable dormer on front facade; projecting wood porch upheld by boxed columns; windows are 4/4 and 1/1 double-hung; brick pier foundation.

11. Present Condition Fair; several alterations to windows and additions to rear; foundation sagging.
 12. Significance Part of an intact historic black neighborhood - Zion Hill; good example of the architectural style; built by Lawson Reed, original pastor and founder of Zion Hill Church.
 13. Relationship to Site: Moved _____ Date _____ Original Site _____

14. Bibliography _____
 15. Informant Aaron Reed
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		21	15	to	21 15
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. 3194312 Site No. 864
 City/Rural Nacogdoches UTM Sector 15-343400-3497100
 2. Name Sterne-Hoya Residence 6. Date: Factual 1830 Est. _____
 Address 211 Lanana, South 7. Architect/Builder _____
 Contractor _____
 3. Owner Friends of the Adolphus Sterne House 8. Style/Type Classical Revival
 Address Same 9. Original Use Residence
 4. Block/Lot Block 19, Lot 1-A Present Use Residence
 10. Description One and 1/2 story; wood frame with lapped board siding with beaded drip edge; ell plan with central hall or dogrun, addition at rear, porch and room on southeast corner; gable roofs with wood shingles, brick exterior chimney on north facade and rock chimney on south facade; shed roof over gallery porch with turned wood posts; wood railing; windows are 9/6 and 1/1 wood double hung; double wood paneled entry doors; brick pier foundation, stacked rock foundation under porch; well in rear yard, picket fence; 2 room outbuilding has gable corrugated metal roof;
 11. Present Condition Excellent, recently restored, Victorian features removed.
 12. Significance Architectural and historical. Listed on the National Register and is a Recteded Texas Historic Landmark, H.A.B.S. drawings in 1936, Texas Centennial Marker 1936. Built for Adolphus
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC files, 1956 State of Texas Marker "Home of Adolphus Sterne.
 15. Informant _____
 16. Recorder Dorothy L. Victor Date June 6, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- PHOTO DATA
/Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	20	to	20 20
Other					to	
					to	

Continuation sheet

10. shed on south side with boxed wood columns; lapped board siding, stacked rock pier foundation; 9/6 wood double hung windows; parking area on north side. Substantial additions were made to the house ca. 1885. 12. Sterne (1801-1852), a German Jewish immigrant, attorney, 1831-1833 city official, a financier of the Texas Revolution, and Nacogdoches postmaster; sold in 1869 to Joseph T. von der Hoya. Site is now the Hoya Library and Museum.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 865
 City/Rural Nacogdoches UTM Sector _____
 2. Name Dietrich Rulfs' Workshop 6. Date: Factual _____ Est. 1890s
 Address 113 Lanana St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Residence; Shop at some time
 4. Block/Lot Block 18 Present Use Residence

10. Description 1-story with partial basement; wood frame with vinyl siding; brick foundation skirt; somewhat symmetrical, central hall plan; gable roofs with curved fascia ends; chamfered bay on northwest corner with spindle brackets; pedimented gable over porch with dentil blocks at the entablature, turned wood posts with floral gingerbread, brick wainscot - modern, central entry door wood with 2 arched upper glass lights, stained glass transom above; central brick chimney; 2/2, 4/4 wood windows.

11. Present Condition Good; altered by vinyl siding; brickwork at porch and around foundation.

12. Significance Workshop of Dietrich Rulfs, architect, who designed many significant buildings in Nacogdoches.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975
 15. Informant Dr. Jere Jackson, 1975
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		30	4	to	30	4
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 866

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890s

Address 210 Lanana St. South 7. Architect/Builder _____

3. Owner Ab Abernathy Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 20, Lot 1 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with horizontal lapped siding; brick pier foundation with wood lattice infill; irregular plan with chamfered bay on east (front); intersecting gable roofs with cornice returns and pedimented gable ends, bargeboards, composition shingles; extended porch on northeast corner with entry on the diagonal, extended chamfered entry with centered door, wood panel door with etched glass, turned wood posts with brackets, simple wood railing; extends down porch steps; windows 4/4, some with pedimented hood mold; two exterior brick

11. Present Condition Good

12. Significance Lawn adjacent and to north is RTHL Site of Bivouac and Banquet for the New Orleans Grays. Was the residence of Charles Hoya.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography 1975 THC Survey

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	5	to 30	5
Other					to	
					to	

Continuation sheet

10. chimneys, one on the north, one on the south; chimney flue is pulled away from the main wall of house; carport at rear.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 867
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 221 Lanana St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 20 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter and beam ends, wood shingles; inset porch with turned wood posts, brackets, 2 entry doors set at 90 degrees, wood panel with three upper glass lights; windows 4/1 wood double-hung with vertical board shutters.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		30	6	to 30	6
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 868
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 321 Lane 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 869
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 114 Leila 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 870

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 214 Lelia 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JGOrtonS/D(437), City Bk 51, Bk 11, Lt 12 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; foundation skirt of sheet metal; gable roofs with extended rafter ends, knee braces; composition shingles; inset porch with turned wood posts; 2 wood panel entry doors with upper glass set at 90 degrees; windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____

1986		41	15	to	41	15
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 871

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 218 Lelia 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Board and Batten Cottage

4. Block/Lot JGOrtonS/D(437), CityBk 51, Bk 11, Lt 12 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with board and batten siding; foundation skirt; rectangular plan; intersecting gable roofs with extended rafter ends, composition shingles; extended porch with boxed columns, wood entry door with small glass; windows 4/4, 6/6, 8/8 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	16	to	41 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 872
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1319 Leroy 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roof with pent roof over porch, metal porch supports, wood entry door; windows 6/6 wood double-hung with wood shutters; detached frame garage; composition shingles on roof.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 19 11 to 19 11
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 873
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40s
 Address 1401 Leroy 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; rectangular plan; composition gable roof; stoop porch; pier and beam foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 19 10 to 19 10
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 874
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1813 Leroy 7. Architect/Builder _____
 Contractor _____
 3. Owner H. L. Simon 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; raised brick pier foundation; rectangular plan; gable roof with composition shingles; extended porch with boxed columns, wood paneled entry door with 2 vertical glass lights; windows 4/4 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	9	to 19	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 875
 City/Rural Nacogdoches UTM Sector _____
 2. Name Stephenson 6. Date: Factual _____ Est. 1930s
 Address 2815 Lily 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence

10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 876
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2822 Lily 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 877

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940s

Address 1107 Lock 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Rock Cottage

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with native rock veneer; asphalt gable roof; inset porch has 2 arches articulated by brick windows are 8/8 and 6/6 double-hung wood; paneled door; frame garage on south facade is attached.

11. Present Condition Good

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	24	to	11 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 878

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 1218 Lock 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

Stone S/D, City Blk 48, Blk 561, Lt 10-B-1 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation skirt; eli plan; gable roofs with extended rafter and beam ends; inset porch with one boxed wood column, side-facing entry door with screened door; windows 1/1 wood double-hung; frame garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____ 1986 _____ 11 23 to 11 23

_____ to _____

_____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 879
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1230 Lock St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 880

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 607 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 11-7 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with metal siding; brick foundation; ell plan with porte cochere; inset entry porch with brick porch supports over a brick pier, low brick wall and piers capped with concrete; windows 6/1 wood double-hung in pairs; entry door wood with multipaned glass lights; roof gabled with metal shingles.

11. Present Condition Good; altered by siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other _____ 1986 _____ 26 3 to 26 3

_____ to _____

_____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 881

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 613 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Brick Cottage (Tudor)

4. Block/Lot Block 26, Lot 11-6 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with brick veneer; brick foundation; massed plan; steep gable roofs with hip roof at rear, composition shingles, shed dormer at east facade, flared eave at front facade, with segmental arched attic window below; shallow arched entry with gable above; windows 6/6 wood double-hung in pairs and diamond-paned wood casements on front, one pair set beneath a flattened arch; exterior brick chimney on east facade with twin chimney pots and decorative geometric brickwork; detached wood frame garage; entry door wood with diamond-paned circular

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		26	4	to	26	4
					to		
					to		

Continuation sheet

10. window and a fan transom above.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 882

City/Rural Nacogdoches UTM Sector _____

2. Name Jennie Hoya Mast House 6. Date: Factual 1914 Est. _____

Address 616 Logansport 7. Architect/Builder Dietrich Rulfs

Contractor _____

3. Owner _____ 8. Style/Type Prairie-Style Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Block 41, Lot 8 Present Use Residence

10. Description 1-story; wood frame construction with brick veneer; brick foundation; irregular plan; low hipped roofs with gable dormers (south and west) and porte cochere (north), deep overhang, extended rafter ends; porch across front and a portion of north and south sides, strong horizontal emphasis with deep overhangs and full porch, short posts rest on large brick piers with pointed concrete caps, sides of piers flare into the brick pier and wood railing, with wooden elements and pier caps painted a contrasting white; porch is symmetrical with a central entry; the entry is flanked

11. Present Condition Excellent

12. Significance Architectural. One of the twin residences built for the Hoya sisters by their parents.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		26	5	to 26	5
Other _____					to	
					to	

Continuation sheet

10. brick chamfered bays; windows are wood double-hung with diamond panes in the upper sash; entry door is wood with three rectangular lights, flanked by side lights with 2 slender beveled glass lights; dormers on south and west have extended rafter and beam ends, vertical wood siding, small diamond-paned windows; secondary entries on south and northwest corners; brick chimneys on north and south; sunporch on north with diamond-paned casement windows; porte cochere on north echoes detailing at the porches; detached brick veneer over frame garage with hipped roof with Spanish tile. Property is surrounded by a low brick wall with piers with concrete coping similar to the porch; 616 is very similar to 620, and they share an entry drive which splits and continues to each porte cochere.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 883
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 617 Logansort 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Brick Cottage (Tudor)

9. Original Use Residence

4. Block/Lot Block 26, Lot 11-5 Present Use Residence

10. Description 1-1/2 story; wood frame with brick veneer; brick foundation; massed plan; steep gable roofs with composition shingles, extended rafter ends; entry with plaster and wood trim gable end, arched entry way; windows 6/1 wood double-hung, on front (east) facade, one casement windows with an arched head; entry door wood with circular window and oversized hinges; exterior chimney on east facade with tapered stack and one clay chimney pot.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	7	to 26	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 884

City/Rural Nacogdoches UTM Sector _____

2. Name Clara Hoya House 6. Date: Factual 1914 Est. _____

Address 620 Logansport 7. Architect/Builder Dietrich Rulfs

Contractor _____

3. Owner _____ 8. Style/Type Prairie-Style Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Block 41, Lot 7 Present Use Residence

10. Description Very similar to 616 Logansport in style and plan; 1-story; wood frame with brick veneer on front, board and batten over a brick skirt at the rear; brick foundation; low hipped gable tiled roof with gable dormer on west and porte cochere on the south, deep overhang with exposed rafter ends; porch across west (front) facade wrapping around to the south, very short wood posts rest upon rectangular brick porch supports with flared sides, terminating in short brick piers, wood railing between the piers and pier caps are painted a contrasting white; windows are wood

11. Present Condition Excellent

12. Significance Architectural. One of the twin residences built for the Hoya sisters by their parents.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		26	6	to	26	6
				to		
				to		

Other _____

Continuation sheet

10. casement and single-hung with upper sash of geometric panes; central entry with a wood door with long, narrow geometric panes and matching side lights, flanked by small globe porch lights; dormer on west facade has extended rafter and beam ends with three small fixed windows, vertical board siding; exterior brick chimneys at the north and south; porte cochere on southwest corner with piers and detailing which matches the porch; sunporches on north and south. Property bounded on west by brick wall which continues across to 616 Logansport.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 885

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 623 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 17 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; hip-and-gable roofs with deep overhang, extended rafter and beam ends, composition shingles; extended front porch with plain entablature, square brick porch supports and 1/2 piers with urns; windows 1/1 wood double-hung with simple hood mold, screens with 3/1 profile; entry door wood paneled with three upper lights, porch lamps on each side; interior brick chimney and exterior brick chimney on north, carport with hipped roof and brick columns.

11. Present Condition Very Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	8	to	26 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 886
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 624 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 41, Lot 6-B 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hipped roof with composition shingles and attic dormer on north side; flat porch roof over entry with decorative metal porch supports; windows 1/1 wood double-hung with burglar bars on lower half; pergola on north side filled in with windows to make a sunroom.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	9	to 26	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 887

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 716 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 41, Lot 6 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with lapped siding; brick foundation; rectangular plan; hip-and-gable roof with composition shingles, plain entablature; projecting porch, now glazed, brick porch supports and brick wall; windows 1/1 wood double-hung; side entry; porte cochere with brick columns, brick chimney on north side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	10	to 26	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 888
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 722 Logansport 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 41, Lot 5-B Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; hipped roofs with composition shingles, plain entablature; porch, screened in, boxed wood columns, bull-nosed siding skirt, side entry and offset front entry doors; porte cochere extends from porch on south side with boxed columns over brick piers and low wall; windows 1/1; entry door wood with upper glass lights; brick chimneys, one interior at the roof ridge, one interior on east side; turban attic vents, one attic dormer on west facade with windows closed up.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 26 11 to 26 11
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 889

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-20

Address 723 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 26, Lots 16-C, 16-B 9. Original Use Residence

Present Use Residence

10. Description 2-1/2 story; wood frame with bull-nosed siding; brick pier and beam foundation; irregular plan, 3-bay facade, 1-story gallery porch which extends to south side, plain entablature and Ionic columns, beaded ceiling; windows wood double-hung 1/1, entry door wood with rectangular glass, side lights and transom lights, storm door and windows over entry; second story balcony over entry with boxed columns and spindle railing; roof is hipped with pedimented gables, Palladian window arrangement at the gable ends; chamfered 2-story bay on north facade;

11. Present Condition Very Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	12	to	26 12
Other					to	
					to	

Continuation sheet

10. projecting sunporches at first and second floor on south facade; two interior brick chimneys; detached wood frame garage; lattice foundation skirt; decorative iron post at entry walk, remaining part of an older fence.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 890

City/Rural Nacogdoches UTM Sector _____

2. Name Cason House 6. Date: Factual _____ Est. 1920

Address 811 Logansport 7. Architect/Builder _____

3. Owner Mrs. Irene Cason Contractor _____

Address _____ 8. Style/Type Neo-classical

4. Block/Lot Block 26, Lots 16-A & 16-B 9. Original Use Residence

Present Use Residence

10. Description 2-story; frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with pedimented gable end; 1-story porch across front with balcony above, boxed column porch supports, simple entablature; windows symmetrical, wood 1/1 double-hung with screens, shutters on front facade, simple hood mold; entry door wood paneled with eight small upper glass lights, simple hood mold and shutters; additions at rear and south side; interior brick chimney.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	13	to	26 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 891

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 819 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow with Victorian motifs

4. Block/Lot Block 26, Lot 15 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hipped roof with hipped dormers on north, east, and south, trimmed, extended rafter ends, composition shingles; porch across front with boxed columns and simple wood railing; windows 1/1 wood double-hung and single-hung with geometric pattern glass on upper sash; some windows with simple hood mold and shutters; centered entry door, wood paneled with multipaned side lights; north and east dormers with diamond-paned window sash, south dormer with ventilator grille;

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	14	to 26	14
Other					to	
					to	

Continuation sheet

10. internal brick chimney; detached carport at rear.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 892

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 902 Logansport 7. Architect/Builder _____

Contractor _____

3. Owner Mr. & Mrs. Jack R. McKinney 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Block 41, Lot 3-B Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with cornice returns, composition shingles; pedimented gable end over front porch with applied scrollwork and medallion; simple entablature with dentils, simple Tuscan columns; classical entry with fluted pilasters, entry door wood paneled; windows 6/6 (modern) with storm windows; low ornamental iron fence across front yard; exterior brick chimney.

11. Present Condition Good; windows and porch altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Jack R. McKinney, 1/20/86

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		26	15	to	26	15
Other					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 893

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 908 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 41, Lot 3-A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roofs with extended rafter ends, composition shingles; extended porch with L-shaped porch supports with siding and trim, concrete porch floor; windows 4/1 wood double-hung; entry door wood paneled; detached wood frame garage.

11. Present Condition Good; porch altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	16	to	26 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 894

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920s

Address 918 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 41, Lot 3 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with vinyl siding; brick foundation; rectangular plan; gable roofs with extended rafter ends and faceted beam ends; slightly extended porch with boxed wood columns, side entry door with oval light; windows 1/1 wood double-hung; exterior brick chimney on north.

11. Present Condition Good; altered by vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		26	17	to	26	17
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 895
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 919 Logansport 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 26, Lot 13-B Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with extended rafter ends and faceted beam ends, composition shingles, corner brackets, brick and concrete entry porch with ornamental metal railing; windows wood double-hung 1/1, entry door wood with three small lights; garage, exterior brick chimney on north.

11. Present Condition Good; front porch filled in with windows and addition of brick porch.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		26	18	to	26	18
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 896
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 922 Logansport (at corner of Martinsville) 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 41, Lot 2 Present Use Residence

10. Description 1-story; wood frame with lapped siding; brick foundation; rectangular plan; gable roof with clipped gable ends, composition shingles; inset corner porch with paired wood porch supports over brick piers with scrollwork and jigsaw-cut railing; windows 3/1 wood double-hung; entry doors set perpendicular to each other wood with multipaned glass; detached wood garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	19	to	26 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 897
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1004 Logansport 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 41, Lot 1-J Present Use Residence

10. Description 1-story; wood frame with asbestos siding; rectangular plan; gable roof with composition shingles; corner inset porch with turned wood porch support; windows wood double-hung 6/6, entry door wood paneled with decorative molding and upper glass light; detached wood frame garage with bull-nosed siding.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	20	to	26 20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 900
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1009 Logansport 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Brick Tudor Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 45, Part of Lot 73 Present Use Apartments
 10. Description 1-story; wood frame with brick veneer; brick foundation; gable roofs with flared eave at front gable, composition shingles; projecting porch with brick porch supports, arched openings; windows 6/1 wood double-hung; single entry door; carport addition at rear; ell plan.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	21	to 26	21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 902
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2218 Logansport (Next to 2220) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Farm Bungalow
 Address _____ 9. Original Use Farmstead
 4. Block/Lot Block 54 Present Use Farmstead

10. Description Rectangular plan, wood frame house with horizontal board siding, gable roofs, replacement windows, brick chimney on southeast facade; wood frame farm buildings, pasture in front of house.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 903
 City/Rural Nacogdoches UTM Sector _____
 2. Name Burrows / Hogan House 6. Date: Factual _____ Est. 1881-1882
 Address 2201 Logansport 7. Architect/Builder _____
 Contractor _____
 3. Owner Diana Register & William McCuller 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description 2-story; wood frame with lapped board siding; rectangular plan; gable roof with composition shingles, extended rafter ends; shed roof over back porch, screened, post supports; small sleeping porch/sunporch on second floor; windows 1/1 wood double-hung; exterior brick chimney on east; wood block foundation; originally central hall with stairs to second floor; rooms on either side; originally a dogtrot.
 11. Present Condition Good; appears to have been remodeled, view from road obscured by trees, private drive
 12. Significance Hogans purchased house in 1918 from Stone Fort Bank; Doc Burrows owned it previously; remodeled in 1918; exterior looks much the same as the 1918 remodeling; later owners than
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Mrs. Geneva Hogan Pulsipher, 4/24/86
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

12. the Hogans have made changes on the interior. 11. with locked entry.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 904
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 3003 Logansport 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage / Farmstead
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Poor; private property, could barely see structure.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 905
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3137 Logasport 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Fair - Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 906

City/Rural Nacogdoches UTM Sector _____

2. Name Collins 6. Date: Factual 1928 Est. _____

Address 3409 Logansport 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 54 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; intersecting gable roofs with composition shingles; windows 12/12 wood double-hung; 2 entry doors set at 90 degrees; carport on north.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant Mrs. Collins' sister, 4/1/86

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 907
 City/Rural Nacogdoches UTM Sector _____
 2. Name B. Williams 6. Date: Factual _____ Est. 1930s
 Address 1210 Looneyville Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 908
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1904 Looneyville Road 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; pier foundation with fiberglass skirt; irregular plan; intersecting gable roofs with extended rafter and beam ends, composition shingles; inset porch with metal supports; 2 entry doors set at 90 degrees, one wood frame with long vertical lights; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	1	to 20	1
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 909
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1910 Looneyville Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Burned
 10. Description Burned since initiation of survey project.

11. Present Condition Burned
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 910

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s

Address 1918 Looneyville Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roofs with extended rafter and beam ends, composition shingles; extended porch with paired 2 x 4 supports, multipane glass and wood door; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	2	to	20 2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 911
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2106 Looneyville Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 912

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 600 Lucas 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JGOrtonS/D(437), CityBlk 53, Blk 9, Lt 5 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; raised foundation; rectangular plan; gable roof with composition shingles; inset corner porch with corner post; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		41	17	to	41	17
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 913

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 603 Lucas 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JGOrtonS/D(437), City Bk 62, Bk 15, Lt 5 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; raised foundation; gable roof with extended rafter ends, composition shingles; extended porch with boxed columns, central entry door; windows 1/1 wood double-hung.

11. Present Condition _____

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	_____	1986		41	18	to	41	18
						to		
						to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 914
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 604 Lucas 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 53, Bk 9, Lt 4-A Present Use Vacant
 10. Description 1-story; wood frame with bull-nosed siding; raised foundation; rectangular plan; gable roof with composition shingles; inset corner porch with 4 x 4 post, 2 wood paneled entry doors set at 90 degrees; windows 4/1 wood double-hung.

11. Present Condition Fair - Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 41 19 to 41 19
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 915

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 608 Lucas 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow/Cottage

Address _____ 9. Original Use Residence

4. Block/Lot JGOrtonS/D(437), CityBlk 53, Blk 9, Lt 4 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, composition shingles; extended porch cover resting on built-up posts; wood panel entry door; windows 1/1 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 2, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		41	20	to	41	20
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 916
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 612 Lucas 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow/Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 53, Bk 9, Lt 3-A Present Use Residence
 10. Description 1-story; wood frame.

11. Present Condition Good - Fair; altered metal porch supports.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides _____
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 917
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 621 Lucas 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), City Blk 62, Blk 15, Lt 7 Present Use Vacant
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 918
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 634 Lucas 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), City Blk 53, Blk 9, Lt 1 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 919

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 635 Lucas 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot _____ 9. Original Use Residence

Ira Land Resub (336), City Block 62, Lot 3 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; raised foundation; rectangular plan; gable roof with composition shingles, exposed rafter ends; extended porch with 4 x 4 corner posts; windows 4/4 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		41	21	to	41 21
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 920

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 701 Lucas 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JGOronS/D(437), CityBlk 62, Blk 14, Lt 6 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; hip roofs with composition shingles; extended porch with 4 x 4 corner posts; wood paneled entry door with upper glass light; windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 2, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	22	to	41 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 921
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1940
 Address 722 Lucas 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 53, Bk 8, Lt 2-A Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter and beam ends; inset porch with corner post; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	23	to	41 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 922
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-45
 Address 817 Lucas 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Shotgun with Addition

4. Block/Lot JGOrtonS/D(437), CityBk 62, Bk 13, Lt 9A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; raised foundation; ell plan; gable roofs with extended rafter ends, composition shingles; extended porch with 4 x 4 posts; windows 6/6 wood double-hung.

11. Present Condition Fair - Good; addition to south.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	24	to	41 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 923

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20s

Address 110 Lynn 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan; projecting porch upheld by posts; composition shingle gable roof pierced by dormer; windows are 1/1 wood double-hung; possible moved to this site; extended rafter ends and knee braces.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		20	18	to	20	18
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 924

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 118 Macheckney 7. Architect/Bullder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Macheckney S/D, City Block 50, Lot 3 9. Original Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick pier foundation; ell plan;

intersecting gable roof with extended beam and rafter ends, composition shingles; inset porch

with corner post, wood floor, brick steps; windows 6/6 wood double-hung, singly and in pairs;

entry door wood panel with three vertical upper glass lights.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site Possibly _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1985		2	7	to	2	7
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 925

City/Rural Nacogdoches UTM Sector _____

2. Name Nacogdoches Leasing & Property Management 6. Date: Factual _____ Est. 1925

Address 124 Mackechney 7. Architect/Builder _____

3. Owner Mr. & Mrs. Charles Thomson Contractor _____

Address 3800 Idylwood, Nacogdoches 8. Style/Type Bungalow

4. Block/Lot Mackechney S/D, City Block 50, Lot 5 9. Original Use Residence

Present Use Commercial

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; straight front-facing gable with extended rafter ends, composition shingles; projecting porch with corner posts, wood floor and concrete steps (prefabricated); windows 6/6 wood double-hung, singly and in pairs; entry door paneled with multipane upper light (modern).

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	6	to 2	6
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 926
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 214 Mackechney 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Mackechney S/D, City Block 50, Lot 7 9. Original Use Residence
 Present Use Residence - Apartments

10. Description 1-story; wood frame construction with bull-nosed siding; brick pier foundation; ell plan; intersecting hip-and-gable roof with simple brackets, extended beam and rafter ends, composition shingles; inset asymmetrical wraparound porch with Tuscan boxed wood columns (no base), wood floor, prefabricated concrete steps; windows 1/1 wood double-hung in pairs and triples; 2 entry doors at either ends of porch wood paneled with upper glass lights.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	5	to 2	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 927
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2201 Maybell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63, Lot 42 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 928
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2215 Maybell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63, Lot 46 Present Use Burned
 10. Description Burned after initiation of survey project.

11. Present Condition Burned
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 929

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-35

Address 1111 Meisenheimer 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot J Thorn S/D (599), City Blk 5, Blk 6, Lt 5 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; pier foundation with foundation skirt; symmetrical facade with rectangular central hall plan with bathroom addition on south; hip roof with composition shingles and extended rafter ends; inset porch across front, wood post supports, central wood paneled door with upper glass; windows 2/2 aluminum replacement windows.

11. Present Condition Good; windows altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 930
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1112 Meisenheimer 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage / Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J Thorn S/D (599), City Blk 53, Blk 1, Lt 2 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 931

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 1305 Meisenheimer 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot JThorn S/D (599), City Blk 53, Blk 6, Lt 15 9. Original Use Residence

10. Description _____ Present Use Residence

11. Present Condition Good; altered by brick-patterned composition paper siding, alum. replacement windows

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 932
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 323 Magnolia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 30, Lot 16 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation with brick infill; irregular plan; pyramidal hip roof with extended rafter ends, composition shingles; inset porch wrapping around south and east, brick columns over brick piers, with 2 x 4 rail, 2 sets of entry doors, both set at 90 degrees, wood panel with upper glass light, screen doors; windows narrow 1/1 wood double-hung; one exterior brick chimney on east, one interior brick chimney; screened addition on west; car shed at rear.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	24	to	39 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 933
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 316 Magnolia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 30, Lot 15-A Present Use Residence
 10. Description _____

11. Present Condition Good; altered by asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 934
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 312 Magnolia 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 30, Lot 7-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation with brick infill; symmetrical rectangular plan with small addition on east; hip roof with extended rafter ends, composition shingles; projecting porch with gable roof, extended beam and rafter ends, short brick columns over brick piers, plain wood railing, centered entry door wood panel with upper glass light; windows 3/1 wood double-hung; exterior brick chimney on east.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	23	to 39	23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 935
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 325 Magnolia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 21, Lot 3-A Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 936
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 413 Magnolia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 21, Lot 3-A Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with central chimney, metal sheathing; extended shed roof over porch with battered wood columns, 2 entry doors; windows 4/4 wood double-hung.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site Possibly _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 40 2 to 40 2
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 937

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 426 Magnolia (on the railroad car siding) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 21, Lot 4-6-B 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, brackets, composition shingles; inset porch with small gable roof, boxed columns, wood panel entry door; windows 1/1 wood double-hung in ones and twos.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		40	3	to	40	3
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 938

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 614 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Classical Cottage

4. Block/Lot Clark S/D (122), City Block 43, Lot 9 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; hip roof with galvanized metal roofing; inset porch with boxed wood columns; 2 entry doors set at 90 degrees, wood paneled with upper glass light; 1/1 wood double-hung windows; shed addition at rear; plain entablature beneath eaves.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		31	5	to	31	5
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 939

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-1910

Address 622 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 43, Lot 27 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with lapped wood siding; brick pier foundation; irregular plan; hip-and-gable roof with boxed cornices, composition shingles, porch roof partially covered by galvanized metal roofing; inset porch wrapping around the southeast corner, oversized turned wood columns with plain capital and base, 2 entry doors set at 90 degrees, wood paneled with upper glass light, transom light above one door; windows 1/1 wood double-hung, some with hood mold; on south facade a Queen Anne upper sash.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	6	to 31	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 940
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-1910
 Address 702 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Classical Cottage
 9. Original Use Residence

4. Block/Lot Block 43, Lot 25-A Present Use Realty Office

10. Description 1-story; brick veneer over wood frame; brick pier foundation; rectangular plan with wood frame addition at rear; hip roof with shed dormer on south, composition shingles, stringer course under deep eave; inset porch with plain entablature and scalloped corner brackets on oversized brick columns on piers; wood paneled entry door with upper glass light, matching side lights; windows narrow 1/1 wood double-hung; attached frame garage on west.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		31	7	to	31	7
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 941

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1898-1905

Address 715 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 43, Lot OL 47 9. Original Use Residence

Present Use Residence

10. Description 2-1/2 story; wood frame with horizontal lapped wood siding; brick pier foundation; irregular plan with chamfered bays on north and east; hip roof with intersecting gables, bargeboards, fishscale shingles and arched windows at gable ends, Palladian windows on north, composition shingles, central brick chimney; wraparound porch with turned wood columns, spindle fretwork and scroll brackets, spindle railing; entry door wood paneled with raised molding, upper glass light, arched entry onto porch; windows 1/1, 2/2, and some with Queen Anne upper sash;

11. Present Condition Good

12. Significance Architectural

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	8	to 31	8
Other					to	
					to	

Continuation sheet

10. addition at rear (south) with new second story balcony; lattice work foundation skirt. House set on hill of West Main Street.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 942

City/Rural Nacogdoches UTM Sector _____

2. Name Sigma Chi Fraternity 6. Date: Factual _____ Est. 1897-1905

Address 723 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 43, Lot OL 38 9. Original Use Residence

Present Use Fraternity House / Residence

10. Description 2-1/2 story; wood frame with horizontal lapped wood siding; irregular plan with projecting bays on east and west; brick foundation; gable roofs with composition shingles, pedimented gable ends, bargeboards, ornamental shingle siding and arched or Palladian windows, vent on west; 1-story wraparound porch, portico entry with sunburst in the pediment, cylindrical wood columns with capitol and base, single entry door wood paneled with decorative moulding and upper glass light; inset second story balcony on northwest corner with cylindrical columns;

11. Present Condition Good

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	9	to 31	9
Other					to	
					to	

Continuation sheet

10. windows 1/1 wood double-hung; 3 brick chimneys --two on the east, one interior on the west with corbeled chimney cap; large yard with loop drive; at top of hill on West Main St.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 943
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 802 Main St. West (East of 810) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43, Lot 22-C Present Use Residence

10. Description 1-story; wood frame with asbestos siding; irregular plan; intersecting gable roofs with composition shingles, boxed cornices; inset front porch, partially filled in, single-turned wood post, entry door wood paneled with sunburst panels and moulding, upper glass light; windows 1/1 wood double-hung; wood frame addition at rear.

11. Present Condition Good; altered by asbestos siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	10	to 31	10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 944
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 810 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43, Lot 22-B Present Use Residence
 10. Description _____

11. Present Condition Good; windows altered to aluminum double-hung.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 945

City/Rural Nacogdoches UTM Sector _____

2. Name Sears House 6. Date: Factual 1897 Est. _____

Address 816 Main St. West 7. Architect/BUILDER _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Vict., Orig. Dog Run

9. Original Use Residence

4. Block/Lot Block 43, Lot 22-A Present Use Retail

10. Description 1-1/2 story; wood frame with horizontal lapped wood siding; brick foundation, galvanized metal foundation skirt; central hall rectangular plan; side-facing gable roof with composition shingles, boxed cornice, gable dormers on south, exterior brick chimney on west with corbeled cap; inset entry porch with boxed wood columns, central entry door wood paneled with upper glass light; windows 6/6 wood double-hung with drip cap; 1-story frame addition with bull-nosed siding at rear.

11. Present Condition Good; altered by dormers on S, shed addition on N, porch glassed in; dog run closed.

12. Significance Has recently been an antique shop.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography 1975 THC Survey

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		31	11	to	31	11
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 946

City/Rural Nacogdoches UTM Sector _____

2. Name Spradley House 6. Date: Factual _____ Est. 1895-1905

Address 904 Main St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 43, Lot OL 23-A Present Use Residence

10. Description 2-1/2 story; wood frame with lapped wood siding; brick pier foundation; irregular plan with addition at rear, chamfered bays on east and west, projecting bay on south with first story chamfered; hip roof with intersecting gables on east, south, and west with pedimented gable ends, shingle siding and Palladian windows; 1-story wraparound porch on east and south with pedimented entry, cylindrical Doric columns, spindle railing, narrow double entry doors wood paneled with upper glass light, ornamented double screen doors; second story porch with Doric

11. Present Condition Good

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography 1975 THC Survey

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		31	12	to	31	12
				to		
				to		

Other _____

Continuation sheet

10. columns, extended gable with arched opening, spindle railing; two interior brick chimneys with corbeled caps; lattice foundation skirt; composition shingles on roofs; windows 1/1 wood double-hung.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 947
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1119 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 80-A Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 948

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1208 Main St. West 7. Architect/Bullder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot OL 25 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof; inset wood porch, boxed columns; windows are 4/4 wood double-hung; rectangular plan; carport on south side; brick pier foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 949
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1315 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Mize S/D (393), Block 42, Lot 2 Present Use Residence
 10. Description _____

11. Present Condition Good; asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 950
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1319 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Mize SD 393, Block 42, Lot 3 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces; projecting porch has brick columns; 1/1 wood double-hung windows in twos and threes; brick pier foundation; carport on north facade.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 31 14 to 31 14
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 951
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1321 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Mize S/D 393, Block 42, Lot 4 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition hip-and-gable roof with extended boxed eaves; projecting porch has battered columns on brick base; multiple-light door; 1/1 wood double-hung windows; brick pier foundation; carport on south facade.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	15	to	31 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 952
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1501 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 44-D Present Use Residence
 10. Description 1-story frame with asbestos siding; composition gable roof with extended rafter ends; windows are 1/1 wood double-hung; brick pier foundation; inset porch has boxed columns; addition at rear.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	16	to	31 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 953

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1509 Main St. west 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 44-C East 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition hip-and-gable roof with extended rafter ends; projecting porch has lattice work; windows are 1/1 wood double-hung with awnings; brick pier foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		31	17	to 31	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 954
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1521 Main St. West, (north of 1519) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 44-A Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition hip roof; inset porch has boxed columns with bannister; windows are 1/1 wood double-hung; extended rafter ends; foundation skirted.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 31 18 to 31 18
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 955
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1623 Main St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 46 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 956
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1630 Main St. West (8 Shotgun Houses) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotguns
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot 46 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 957
 City/Rural Nacogdoches UTM Sector _____
 2. Name Swift House 6. Date: Factual _____ Est. 1890
 Address 703 Main St. East 7. Architect/Builder Dietrich Rulfs
 Contractor _____
 3. Owner _____ 8. Style/Type Stick-Style Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 5 Present Use Residence
 10. Description 2-1/2 story; wood frame with lapped board siding; brick pier foundation; irregular plan, 1975 survey notes Greek Revival influence in plan; hip-and-gable roofs with composition shingles, cornice returns, wood shingles or diagonal siding at gable ends; 2-story gallery porch across south (front) and east, turned wood posts with spindle railing at second floor, pedimented entry onto porch, entry door wood paneled with upper glass light, transom light above; chamfered bay at southwest corner with small balcony at second story window; full-height portico on west
 11. Present Condition Fair; remodeling in 1910, frontage on East Main sold to car wash.
 12. Significance Architectural.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography 1975 THC Survey
 15. Informant _____
 16. Recorder Dorothy Victor Date February 10, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		27	5	to	27	5
				to		
				to		

Continuation sheet

10. with boxed wood columns, small stick-style balcony at second story supported on brackets, not attached to box columns; windows 1/1, 2/2, 2/4, 4/4 wood double-hung, 2/4 windows extend to the finish floor level; a few windows with pedimented hood molds; one- and two-story wood frame additions to the rear of the house are not compatible. The house appears to have more than one phase of addition/remodeling. Very large elm in front yard; drive to house located on east on Lanana St.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 958
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 710 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot Block 18 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; pyramidal hip-and-gable roof with composition shingles; inset porch on front (north) extending to east, turned wood posts with spindle railing, pedimented gable over porch entry; wood panel entry door with upper glass, transom above; windows 2/2 wood double-hung with 1/2 screen, hood mold above; central brick chimney with corbeled cap; early addition at rear of the house.

11. Present Condition Fair - Poor

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	7	to 30	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 959

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890-1900

Address 716 Main St. East 7. Architect/Builder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 18 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation with wood lattice infill; irregular plan; intersecting gable roofs with boxed cornice, composition shingles; curved shed roof over porch, pedimented gable over entry, turned wood posts with spindle railing; entry door wood panel with applied ornamentation with upper glass light, transom light above, screen door with ball and spindle ornamentation; windows 2/2 wood double-hung with dripcap; central brick chimney; secondary entrance on east side of porch; small sunporch on southwest corner.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	8	to	30 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 960

City/Rural Nacogdoches UTM Sector _____

2. Name Lanana Cleaning & Laundry 6. Date: Factual _____ Est. 1920s

Address 802 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Commercial

4. Block/Lot City Block 19 9. Original Use Commercial

Present Use Laundry / Commercial

10. Description 1-story; brick load-bearing; rectangular plan; masonry foundation; two buildings, each 2-bay with central entry door flanked by aluminum storefront windows, west building with higher parapet which steps back to the rear; flat roof; small loading dock on west with sliding wood door; at rear of building tall stack made of oil drums.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		30	9	to 30	9
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 961
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 809 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Warehouse
 Address _____ 9. Original Use Commercial
 4. Block/Lot City Block 18 Present Use Vacant
 10. Description 1-story; wood frame with corrugated metal siding; rectangular plan; gable roof with shed roofs over porch and side loading dock, metal roofing; central double entry doors flanked by wood frame display windows.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 26, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		30	10	to 30	10
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 962
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-20
 Address 1407 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition pyramidal roof pierced by 1 corbeled chimney; ell plan; projecting bay; inset porch upheld by boxed columns; windows are 1/1 wood double-hung; additions at rear and on west facade.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	15	to	30 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 963
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 1400 Main St. East 7. Architect/Builder _____

3. Owner Manning Contractor _____
 Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 51 Present Use Residence
 9. Original Use Residence

10. Description 1-story; frame with hip-and-gable composition roof; gables have bargeboard; 1 corbeled brick chimney; drop siding; projecting porch supported by large brick columns; windows are 2/2 and 4/4 wood double-hung; brick pier foundation; multiple-light entry doors with transom; some Queen Anne windows with hood molds.

11. Present Condition Good

12. Significance Good example of style updated to Bungalow.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	14	to 30	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 964
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1601 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Good; altered front.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 965
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 1623 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Good; some alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

 to _____
 to _____
 to _____

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 966

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-40

Address 2002 Main St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 62 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces; projecting porch is supported by boxed columns on brick piers, screened; windows are 9/9, 6/6 wood double-hung; brick pier foundation; garage at rear.

11. Present Condition Good; needs painting.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	16	to	30 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 967
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 2016 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 62 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof with extended eaves; 2/2 and 4/4 wood double-hung windows; rectangular plan; projecting porch; supported by wood posts; brick pier foundation.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		30	18	to	30	18
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 968
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30s
 Address 2010 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 62 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof with knee braces and extended rafter ends; ell plan; projecting porch supported by boxed columns; windows are 6/1 wood double-hung with shutters; porte cochere on east facade; brick pier foundation; 1 brick chimney.

11. Present Condition Excellent
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	17	to	30 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 969
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2207 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description _____

11. Present Condition Good; front porch altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 970
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 2223 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; rectangular plan; composition gable roof; projecting porch with battered columns on brick piers; extended rafter ends and knee braces; brick pier foundation.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 30 19 to 30 19
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 971
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 2315 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 972
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 2322 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; rectangular plan; composition gable roof with extended rafter ends and knee braces; windows are 1/1 wood double-hung; shed addition at rear; brick pier foundation; garage of similar style.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 30 22 to 30 22
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 973
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 2403 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 974
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 2407 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description 1-story frame with lap siding; composition pyramidal roof; inset porch has boxed columns; 2 entry doors; 1/1 wood double-hung windows; brick pier foundation; garage at rear.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 30 20 to 30 20
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 975
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1895-1910
 Address 2419 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description 1-1/2 story frame with drop siding; hip-and-gable composition roof; window on front central gable; projecting porch supported by Doric columns; windows are 1/1 wood double-hung with hood mold; entry has transom light; brick pier foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	21	to	30 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 976
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 2404 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner Earl Nelson 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63 Present Use Residence
 10. Description _____

11. Present Condition Good; some alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 977
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 3205 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 978
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nettie Smith 6. Date: Factual _____ Est. 1920-30
 Address 3426 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Good; porch altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 979
 City/Rural Nacogdoches UTM Sector _____
 2. Name C. M. Day 6. Date: Factual _____ Est. _____
 Address 4727 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Good; vinyl siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 980
 City/Rural Nacogdoches UTM Sector _____
 2. Name Odin Alexander 6. Date: Factual _____ Est. 1910-30
 Address 4916 Main St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 982
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1880-1900
 Address 6400 Block Main St. East (at Robinhood) 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Greek Revival

4. Block/Lot Block 82 9. Original Use Residence & Farmstead
 Present Use Residence & Farmstead

10. Description 1-story frame with drop siding; composition gable roof with chimneys at either end (newer), projecting porch supported by chamfered columns; windows are 6/6 wood double-hung in pairs; brick pier foundation; farm buildings at rear; new entry door.

11. Present Condition Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	23	to	30 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 983

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 708 Martinsville 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 41, Lot 2-A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame; brick foundation; gable roof with composition shingles and corner brackets; windows 1/1 wood double-hung; pedimented entry with blind pilasters, wood paneled door; rectangular plan.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	20	to 36	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 984

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 809 Martinsville Rd. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

9. Original Use Residence

4. Block/Lot Block 41, Lot 1-E Present Use Residence

10. Description 1-story; wood frame; rectangular plan; gable roof with composition shingles; on concrete block foundation; windows wood 6/6; entry door wood paneled.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 985
 City/Rural Nacogdoches UTM Sector _____

2. Name George V. Pruitts 6. Date: Factual _____ Est. 1920
 Address 1722 Martinsville Road 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; symmetrical rectangular plan with chamfered bays at front facade (north); hip roofs with composition shingles; extended trimmed rafter ends, deep overhang; porch inset between two front bays; windows wood double-hung diamond-paned upper sash over single lower sash; central entry with wood door with large oval light flanked by double-hung windows.

11. Present Condition Excellent; addition at rear with smooth siding, part of car garage.

12. Significance Architectural; good example of type.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	18	to	36 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 986
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 2602 Martinsville Road (Three-tenths of a mile east of 1722) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description 1-story; frame with asbestos siding; rectangular plan; gable roofs with composition shingles; interior brick chimney; windows aluminum 2/2 single-hung; entry door wood paneled with upper light; board and batten shed at rear of house.

11. Present Condition Fair; all windows altered with 2/2 aluminum single-hung.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	19	to 36	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 987

City/Rural Nacogdoches UTM Sector _____

2. Name New St. Matthew Baptist Church 6. Date: Factual 1945 Est. _____

Address 2712 Matthew 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular

4. Block/Lot Block 61 9. Original Use Church

Present Use Church

10. Description 1-story; wood frame with beveled board siding; brick pier foundation; rectangular plan; gable roof with composition shingles; inset entry flanked by two narrow bell towers with pyramidal roofs, double wood paneled entry doors; windows horizontal 2/2 double-hung windows; parking area on east side; one-story hall on northwest corner.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	14	to 35	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 988
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2713 Mathew 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 61 Present Use Residence

10. Description 1-story frame with bull-nosed siding; gable sheet metal roof; inset porch supported by boxed columns; brick pier foundation; windows are 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		35	13	to	35	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 989
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2709 Matthew 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; sheet metal gable roof with extended rafter ends; and knee braces; inset porch supported by boxed column; windows are 4/1 wood double-hung; foundation skirted.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	12	to 35	12
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 990
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1213 Mims 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54, Present Use Residence

10. Description 1-story; wood frame with asbestos siding; galvanized metal foundation skirt; rectangular plan; gable roofs with composition shingle, brackets with faceted ends; extended porch with boxed columns; windows 6/6 wood double-hung; entry door wood paneled with upper glass light; carport on west side.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	15	to 36	15
Other					to	
					to	

-Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 991

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1220 Mims (Southwest Corner of Mims & University) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow & Farm Complex

4. Block/Lot Block 54 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation skirt; all plan; gable roofs with extended beam and rafter ends, composition shingles; inset porch with brick porch supports; windows 3/1 wood double-hung; entry door wood panel with three upper lights; large barn at rear, board siding, metal roof; detached garage.

11. Present Condition Good - Fair.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		36	16	to	36	16
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 992
 City/Rural Nacogdoches UTM Sector _____
 2. Name W. D. Koonce 6. Date: Factual _____ Est. 1920-30
 Address 1622 Mims Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description 1-story; rectangular plan; frame with bull-nosed siding; gable roofs; 6/1 wood double-hung windows; wood paneled entry door.

11. Present Condition Fair; porch columns and floor deteriorated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		36	17	to	36	17
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 993
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 110 Mitchell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot continued Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

4. T.J. Lloyd 2nd S/D (355), Block 1, Lot 8, City Block 50

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 994
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 112 Mitchell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot continued Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

4. T.J. Lloyd 2nd S/D (355), Block 1, Lot 8, City Block 50

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 995
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 204 Mitchell 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot continued Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

4. Rex McIver S/D (381), Lot 8, City Block 50.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 996
 City/Rural Nacogdoches UTM Sector _____
 2. Name Parsonage 6. Date: Factual _____ Est. 1912
 Address 601 Moore 7. Architect/Builder _____
 Contractor _____
 3. Owner C. L. Simon 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 53-A Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; originally rectangular plan, now ell plan; concrete block foundation; gable roofs with extended rafter ends, composition shingles; ell porch on northwest corner with 4 x 4 posts; windows 4/4, 6/6, wood double-hung.

11. Present Condition _____
 12. Significance Burned around 1957 and rebuilt same year, front bay added; moved in April 1986 to lot south. Church property bought in 1902.
 13. Relationship to Site: Moved Date 1986 Original Site _____

14. Bibliography Book on church.
 15. Informant Rosetta P. Collins, 4/7/86.
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		42	7A	to	42 7A
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 997
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1915-25
 Address 707 Moore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 54-A Present Use Residence
 10. Description 1-story; wood frame with board and batten siding; wood block foundation; rectangular plan; gable roof with sheet metal roofing, extended rafter and beam ends; extended porch with wood posts resting on larger wood piers; windows 4/4 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date Possibly Original Site

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		42	8A	to	42	8A
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 998
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 712 Moore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 52 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan with inset porch on southeast, boxed column; 2 wood paneled entry doors set at 90 degrees; gable roof with extended rafter ends, composition shingles; windows 1/1 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 42 9A to 42 9A
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 999

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-35

Address 807 Moore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Board & Batten Cottage

4. Block/Lot City Block 53, Lot 58 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with board and batten siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, corrugated metal roofing; interior brick chimney; extended porch with 4 x 4 wood posts; wood panel entry door; windows 4/4 wood double-hung.

11. Present Condition Fair; brick piers appear to be soft-worn brick.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1000
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 910 Moore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 62-B Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, corrugated metal roofing, interior brick chimney; extended porch with turned wood posts; wood panel entry door with upper glass; windows 6/6 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1001

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-40

Address 914 Moore 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot City Block 54, Lot 63 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends; inset porch on southeast corner with turned wood post, 2 entry doors wood paneled set at 90 degrees; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	_____	_____	_____	_____	to	_____	_____
	_____	_____	_____	_____	to	_____	_____
	_____	_____	_____	_____	to	_____	_____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1002
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 918 Moore 7. Architect/Builder _____
 Contractor _____
 3. Owner L. C. Henderson 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 65-A North Present Use Residence
 10. Description Similar to 914 Moore next door.

11. Present Condition Fair; windows altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1003
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 922 Moore 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 65-A North Present Use Residence
 10. Description 1-story residence.

11. Present Condition Fair; aluminum replacement windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

 to _____
 to _____
 to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1004
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 216 Mound St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Craftsman Bungalow/Stick-Style
 Address _____ 9. Original Use Residence
 4. Block/Lot Price-Sturd S/D, Bk 4, Bk 479, Lt 8 A&Pt 6 Present Use Residence

10. Description 1-1/2 story; wood frame construction with lapped siding and brick veneer at front facade; brick foundation; massed plan; intersecting gable and hip roofs with deep overhangs, bracketed extended beams, ornamental extended rafter ends; composition shingles; inset porch, partially enclosed with flattened arches, arched brick porch supports over brick piers, low brick wall with concrete cap; windows wood, originals 9/1 wood double-hung and 1/1 wood double-hung; second floor windows wood, multipaned, arched above porch; entry door multipaned glass and

11. Present Condition Good; altered enclosed porch.

12. Significance Architectural; good example of an elaborate Craftsman bungalow.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA _____
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 24 24 to 24 24
 Other _____ to _____
 _____ to _____

Continuation sheet

10. wood door with transom and treatment around door; brick chimneys on south and east; brick porte cochere on northwest corner; curved curb at entry walk.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1005
 City/Rural Nacogdoches UTM Sector _____
 2. Name Lyle S. Thorstenson, M.D. 6. Date: Factual _____ Est. _____
 Address 217 Mound St. North 7. Architect/Bullder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Office
 4. Block/Lot _____ Present Use Medical Office
 10. Description _____

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1006
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-1910
 Address 222 Mound St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner Milton Pitts 8. Style/Type Folk Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot Price-Sturdevant S/D, City Bk 4, Bk 479, Lt 6 Present Use Apartments

10. Description 2-1/2 story; wood frame construction with beveled and lapped wood siding; brick foundation; ell plan with additions at rear; hip roofs with dormer on west facade; composition shingles; plain entablature; 1-story gallery wraparound porch with boxed wooden columns and simple railing; two multipaned wood entry doors, third entry on south porch.

11. Present Condition Good; 3 different types of double-hung windows and of wood siding; extensively altered
 12. Significance Land abstract goes back to Hayden Edwards, who willed this land to wife and 3 slaves; brick in fireplace shipped from St. Louis, water closets installed in house in 1923.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant Mr. Milton Pitts, 1/21/86.
 16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	2	to 25	2
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1007
 City/Rural Nacogdoches UTM Sector _____
 2. Name Beck's Beauty Shop 6. Date: Factual _____ Est. 1920s
 Address 303 Mound St. North & Edwards 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Eclectic
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 3, Lot 10 Present Use Retail - Beauty Shop

10. Description 2-story; wood frame with lapped siding; brick foundation; rectangular plan, gable roof with later addition; projecting shed roof at porch; composition shingles; inset porch, partially closed in with wood box columns over brick piers; windows 1/1 wood double-hung, some with simple hood mold; single entry door; porte cochere on south, exterior brick chimney on south.

11. Present Condition Good; altered at second floor and porch area.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	2	to	26 2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1008
 City/Rural Nacogdoches UTM Sector _____
 2. Name Cason Monk & Company Funeral Home 6. Date: Factual 1897 Est. _____
 Address 310 Mound St. North 7. Architect/Builder Dietrich Rulfs
 Contractor _____
 3. Owner _____ 8. Style/Type Queen Anne/Eastlake
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 4, Lot 6 Present Use Funeral Home

10. Description 2-1/2 story; wood frame construction with lapped wood siding; brick foundation; all plan; intersecting hip and gable roofs with composition shingles, with decorative bargeboards; shingle siding under gables and above first floor; asymmetrical 2-story gallery porch with projecting bays at the southwest corner, turned wood posts, arched openings with spindlework, and low wooden railings with spindlework; windows 1/1 wood double-hung with continuous wood trim above, Palladian windows at second floor and attic on projecting bay on west facade, on the first

11. Present Condition Excellent; building has been altered to accommodate the funeral home.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	3	to	25 3
Other					to	
					to	

Continuation sheet

10. floor the front wall of this bay is slightly bowed with vertical siding above the windows; double entry door, wood with raised ornamentation and glass lights with chamfered corners, four other doors on first floor porch; gabled dormer on west facade with fan-shaped window.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1009

City/Rural Nacogdoches UTM Sector _____

2. Name Tolbert Hardeman House 6. Date: Factual _____ Est. 1899

Address 408 Mound St. North 7. Architect/Builder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 4, Lot 5 9. Original Use Residence

Present Use Residence

10. Description 2-1/2 story; wood frame construction with lapped siding; pier and beam foundation; massed plan; multiple hip-and-gable roofs with dormers, composition shingles; simple entablature with wood dentils, decorative shingles at gable ends; fan brackets at roof of small second floor balcony; gallery porches at first and second level; paired tuscan columns on boxed bases with simple wood railing, south portion of porch enclosed; windows 1/1 wood double-hung, some with hood mouldings; double entry doors with multipaned glass lights, transom light above

11. Present Condition Very Good

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	4	to 25	4
Other					to	
					to	

Continuation sheet

10. with hood moulding; interior brick chimneys at north and south; projecting bay on west facade with second floor balcony, Queen Anne glass at first floor window; Palladian window at attic floor.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1010
 City/Rural Nacogdoches UTM Sector _____
 2. Name Thomas J. Rusk Middle School 6. Date: Factual 1939 Est. _____
 Address 411 Mound St. North 7. Architect/Builder H. B. Tucker
 Contractor Hal C. Dyer
 3. Owner Nacogdoches Independent School District 8. Style/Type Moderne
 Address _____ 9. Original Use Educational
 4. Block/Lot Block 3, Lot 1 Present Use Educational

10. Description 2-story concrete block; 12 bays defined by carved limestone vertical ornamentation; 2 entries on east facade have cast concrete awnings; double entry doors are paneled with side lights and transom windows; linear east facade; west facade has three projecting bays; windows are steel awning; limestone steps.

11. Present Condition Good
 12. Significance Built by Federal Works Agency, Public Works Administration. Good example of Moderne style as utilized by federal agencies.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date November 16, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1011

City/Rural Nacogdoches UTM Sector _____

2. Name John Garrison House 6. Date: Factual _____ Est. 1905

Address 418 Mound St. North 7. Architect/Builder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot Block 4, Lot 4 9. Original Use Residence

Present Use Apartments

10. Description 2-1/2 story; wood frame construction with lapped wood siding; pier and beam foundation; massed plan; deck on hip roof with hipped dormers, composition shingles; portico with boxed columns at entry; windows wood 1/1 double-hung, on west facade wood single-hung windows with upper lights of stained glass and diamond and prism-paned glass; single entry door with applied ornamentation and upper glass light, matching sidelights; interior brick chimneys on the north and south.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	5	to	25 5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1012
 City/Rural Nacogdoches UTM Sector _____
 2. Name F. H. Tucker Residence 6. Date: Factual _____ Est. 1901
 Address 504 Mound St. North 7. Architect/Builder Dietrich Rulfs
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 4, Lot 3 Present Use Residence

10. Description 1-1/2 story; wood frame construction with lapped wood siding; lattice foundation skirt; ell plan with projecting bays; hip-and-gable roof with cresting and bargeboards, decorative shingles at gable ends; asymmetrical wraparound porch with boxed wooden columns and wood spindle railing; second enclosed and screened porch on southeast corner; windows 1/1 double-hung and 1/1 single-hung with diamond-patterned muntins in the upper light; diamond-patterned muntins in windows at attic level; recessed entry with an elliptical arch supported on slender wood

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Dr. Jere Jackson, 1975.

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	<u>/RTHL</u>	<u>/HABS (no.)</u>	<u>TEX-</u>	<u>PHOTO DATA</u>
NR:	<u>/Individual</u>	<u>/Historic District</u>	<u>B&W 4 x 5s</u>	<u>slides</u>
	<u>/Thematic</u>	<u>/Multiple-Resource</u>	<u>35 mm Negs.</u>	
NR File Name		YEAR	DRWR	ROLL
		1986		25
				6
Other				

Continuation sheet

10. columns, entry door wood paneled with upper glass light and matching side lights; interior brick chimneys on the north and south; wood frame detached garage at rear; large oaks in the yard.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1013

City/Rural Nacogdoches UTM Sector _____

2. Name L. House 6. Date: Factual _____ Est. 1920-30

Address 510 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Brick Tudor Cottage

9. Original Use Residence

4. Block/Lot Block 4, Lot 2-E Present Use Residence

10. Description 1-1/2 story; wood frame construction with brick veneer; brick foundation; massed plan; bay facade; steep gable roofs with a front-facing clipped gable end, slate shingles with no overhang and wood trim at the eaves; extended porch with gable roof and stone arched entry, brick half piers and low brick balustrade with stone cap; windows wood frame casements with arched transoms on the west facade and multipaned wood double-hung windows; keyed stone window surrounds and spiraled columns, window lead comes are set in ornamental patterns; entry door

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant Earl House

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	7	to	25 7
Other					to	
					to	

Continuation sheet

10. wood with arched head, iron hinges, and four small upper glass lights; exterior brick chimney on north with clay chimney pots; inset balcony on the south side of the front gable.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1014
 City/Rural Nacogdoches UTM Sector _____
 2. Name Charles Perkins/ Carroll Residence 6. Date: Factual _____ Est. 1900
 Address 516 Mound St. North 7. Architect/Builder Dietrich Rulfs
 Contractor _____
 3. Owner Dr. Robert P. and Ruth Carroll 8. Style/Type Victorian
 Address 516 Mound St. North 9. Original Use Residence
 4. Block/Lot Block 4, Lot 2-C Present Use Residence

10. Description 2-1/2 story; wood frame construction; brick pier foundation with metal skirt; massed plan with projecting bays; hip-and-gable roof with flared eaves, boxed cornice and pedimented gable ends, ornamental brackets under gable on west facade, plain entablature; asymmetrical one-story wraparound porch with wooden tuscan columns in singles and pairs resting on brick piers, low spindle railing; windows 1/1 wood double-hung with simple hood mold, storm windows that match original window configuration, arched windows in Palladian motif at west gable end;

11. Present Condition Excellent
 12. Significance Architectural. Caddoan burial mound in front yard is RTHL.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.
 15. Informant Dr. Jere Jackson, 1975.
 16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	<input type="checkbox"/> RTHL	<input type="checkbox"/> HABS (no.) TEX-	PHOTO DATA			
NR:	<input type="checkbox"/> Individual	<input type="checkbox"/> Historic District	<input type="checkbox"/> B&W 4 x 5s	<input type="checkbox"/> slides		
	<input type="checkbox"/> Thematic	<input type="checkbox"/> Multiple-Resource	<input type="checkbox"/> 35 mm Negs.			
NR File Name		YEAR	DRWR	ROLL	FRME	ROLL FRME
		1986		25	8	to 25 8
Other						to
						to

Continuation sheet

10. 2-story chamfered bay at northwest corner with peaked roof and small dormer, arched window with diamond-patterned lights; single entry door, wood paneled with upper glass light and transom, flanked by matching side lights; second entry door on south area of porch; interior brick chimneys, one at north and south ends. Interior of house is largely intact with original woodwork, stair railings, doors and some light fixtures; minor alterations in the kitchen; addition of a bathroom on the ground floor; at one time a portion of the ground floor was separated into an apartment. Prehistoric Indian mound on the southwest corner of the property; has an RTHL marker from 1966.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1015

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 600 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 4, Lot 2-B 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with asbestos siding; brick foundation; massed plan; intersecting gable roof with exposed rafter ends; small entry porch with gable roof flanked by porte cochere; windows 6/1 wood double-hung; single entry door with glass storm door, secondary entry door wood panel with upper glass lights; exterior brick chimney on front facade with flat chimney cap; wood shingles on roof; large oak tree in yard; detached garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		25	9	to	25	9
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1016
 City/Rural Nacogdoches UTM Sector _____
 2. Name W. H. Whited/Sigma Tau Gamma Residence 6. Date: Factual 1929 Est. _____
 Address 711 Mound St. North at Hughes 7. Architect/Builder Shirley Simons
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 40, Lot 16 Present Use Fraternal Organization Residence
 10. Description 2-story; wood frame with wide lapped siding; brick foundation; 3-bay facade, massed plan; gable roofs with hip roofs on 1-story additions; plain entablature, wood shingles; exaggerated proportions for the entablature at porch roof, slender wood porch supports; windows multi-paned wood double-hung with hood mold at 1st floor; classical pedimented entry with wood panel door & side lights; octagonal breakfast bay at north wing; attached porte cochere & garage or servants quarters; brick chimneys at north and south of main house block with gabled chimney caps.
 11. Present Condition Very Good; later one-story additions in similar style.
 12. Significance Simons also designed the Nacogdoches High School Auditorium and Gyn in Washington Square. He lived in Lufkin during the teens and 20s.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography THC Survey, 1975.
 15. Informant Dr. Jere Jackson, 1975.
 16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	24	to	25 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1017
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 722 / 720 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular Neoclassical

4. Block/Lot Block 26, Lot 10 9. Original Use Duplex Apartments
 Present Use Duplex Apartments; Vacant

10. Description 2-story; wood frame with brick veneer; brick foundation; rectangular plan; hip roof with composition shingles, medium overhang; pedimented portico with paired columns, brick steps, two entry doors with multipane glass; windows placed symmetrically on facades, multipaned wood double-hung; detached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		25	11	to 25	11
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1018
 City/Rural Nacogdoches UTM Sector _____
 2. Name Delta Sigma Phi / Hazelwood House 6. Date: Factual _____ Est. 1912
 Address 725 Mound St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Craftsman/Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 40, Lot 14 Present Use Fraternity House

10. Description 1-1/2 story; wood frame with brick veneer on the first floor, shingles on upper floor; brick foundation; massed plan; hip roofs with composition shingles; plain entablature across porches and porte cochere, brick porch supports over brick piers which extend to the foundation, low brick porch wall; windows wide 1/1 wood double-hung; entry door with large glass light, side lights matching, transom light above; interior brick chimneys on north and south; porte cochere on the northeast corner; front yard fence with square brick piers and low wrought iron rails;

11. Present Condition Good; some alterations on interior.
 12. Significance Architectural.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.
 15. Informant _____
 16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		25	23	to	25	23
Other					to		
					to		

Continuation sheet
 10. detached garage.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1019

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 726 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 10-A 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with lapped siding; brick foundation; rectangular plan; gabled roofs with extended beam and rafter ends, composition shingles; extended porch with square brick columns over brick piers, low brick wall; windows 6/1 wood double-hung in twos and threes; entry door wood and multipaned glass; exterior chimney on south.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	12	to	25 12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1020
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 736 Mound St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 26, Lot 8-A Present Use Residence

10. Description 1-story; wood frame with horizontal siding; brick foundation; massed plan; gable roofs with extended beam ends (faceted), composition shingles; inset porch with boxed wood columns; windows 1/1 wood double-hung; entry door wood and multipaned glass; two interior central brick chimneys.

11. Present Condition Good - Fair.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		25	13	to	25	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1021
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual 1909 Est. _____
 Address 803 Mound St. North 7. Architect/Bullder _____

3. Owner Dr. Lyle and Pamela Thorstenson Contractor _____
 Address 803 Mound St. North 8. Style/Type Folk Victorian

4. Block/Lot Block 40, Lot 12 9. Original Use Residence
 Present Use Residence

10. Description 2-story; wood frame with vinyl siding; brick foundation; ell plan; gable and hip roofs with composition shingles, bargeboards at front gable end; porch floor lowered, brick steps to door; paired Tuscan columns, heavy spindle rail at steps; windows wood double-hung 1/1 on front facade with multipaned on upper floor; two entry doors set at 90 degrees, wood paneled with upper glass light; small fixed window porch with diamond muntin pattern, shutters at windows.

11. Present Condition Good; altered; 2nd story is an addition, porch floor lowered, column supports changed.

12. Significance _____

13. Relationship to Site: Moved Date ca. 1915 Original Site Moved from 725 N. Mound St. location.

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	22	to	25 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1022
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-1910
 Address 810 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Neoclassical Bungalow

4. Block/Lot Block 26, Lot 3 9. Original Use Residence
 Present Use Apartments

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick pier and beam foundation; rectangular plan; hip roof with hip gables to north and west, composition shingles; plain entablature with wooden boxed columns at porch across front; windows 1/1 wood double-hung, ribbon of windows along south facade; two entry doors wood with large glass and wood with multipaned glass; central interior brick chimney.

11. Present Condition Poor; roof shingles deteriorated, north facade covered in plastic.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	14	to	25 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1023

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-20

Address 813 Moud St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 40, Lot 12-A 9. Original Use Residence

Present Use Residence/Apartments

10. Description 1-story; wood frame with beveled siding; brick pier foundation with metal foundation skirt around front; massed plan; steep hip and gable roofs with composition shingles; asymmetrical porch with plain entablature, Tuscan columns resting on boxed bases; windows wood 1/1 double-hung with hood mold; entry doors wood and multipaned glass.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	21	to	25 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1024

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 814 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 2-A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roofs with brackets and extended beam ends, composition shingles; inset porch with wooden boxed columns; windows 4/1 wood double-hung; entry door wood with rectangular glass lights; one central interior brick chimney, one exterior brick chimney on north facade.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	15	to	25 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1025

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10

Address 820 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

9. Original Use Residence

4. Block/Lot Block 26, Lot 2 Present Use Residence/Apartments

10. Description 1-1/2 story; wood frame with beveled siding; brick pier foundation; ell plan; steep hip-and-gable roof, composition shingles, pediment at west gable end with scrollwork and brackets, fan light window; majority of porch enclosed leaving small entry vestibule, boxed column at northwest corner; windows 1/1 wood double-hung, some with multipanes, west bay diamond prism-paned upper sash over single light sash; entry door wood paneled with upper glass light; steel exterior stair on north facade to upper floor.

11. Present Condition Good; altered by enclosing front porch and exterior stair on north facade.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	16	to	25 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1026

City/Rural Nacogdoches UTM Sector _____

2. Name Anesthesiology Services, P.A. 6. Date: Factual _____ Est. 1930-40

Address 907 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Brick Tudor Cottage

4. Block/Lot Block 40, Lot 3-A 9. Original Use Residence

Present Use Commercial Offices

10. Description 1-1/2 story; wood frame with brick veneer; brick foundation; massed plan with later addition at east (front) facade; gabled roofs with composition shingles, diamond-paned windows at gable ends; brick arched entry portal; windows wood frame with 2/2 aluminum sash with soldier course above; entry door wood with multipaned circular light; exterior chimney on east facade with tapered stack and twin chimney pots.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	20	to 25	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1027

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 908 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Tudor Cottage

4. Block/Lot Block 26, Lot 1-D 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with brick veneer; brick foundation; U-plan; gabled roofs with composition shingles, shed dormer on west facade; shallow entry portal with elliptical arch; windows 6/6 wood double-hung with soldier course above; entry door wood paneled with four small upper lights; exterior chimney on north facade with twin brick flues.

11. Present Condition Good; addition on south side.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		25	17	to	25 17
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1028
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____
 Address 911 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 40, Lot 3 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with vinyl siding; brick pier foundation; massed plan; gable roofs with composition shingles, solid brackets; extended porch with square brick porch supports resting on brick piers, low brick wall; windows 3/1 wood double-hung in twos and threes; entry door wood panel with elongated rectangular light; attached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	19	to	25 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1029
 City/Rural Nacogdoches UTM Sector _____
 2. Name Joe E. Davis, M.D. 6. Date: Factual _____ Est. 1930
 Address 1000 Mound St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 45, Lot 52-A Present Use Medical Office

10. Description 1-story; wood frame with lapped siding; brick foundation; massed plan; extended porch and porte cochere with square brick columns; gable roofs with composition shingles, extended beam and rafter ends, brackets; windows, wood 6/1 double-hung; entry door wood and multipaned glass flanked by windows; exterior chimney on north facade.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		25	18	to	25 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1030
 City/Rural Nacogdoches UTM Sector _____
 2. Name Bright House Fraternity House 6. Date: Factual _____ Est. 1940-45
 Address 1201 Mound St. North at Memorial Hospital 7. Architect/Builder Everett McKay, Builder
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 45, Lot 41-C Present Use Demolished
 10. Description Demolished in early January 1986, before it could be surveyed and photographed.

11. Present Condition Demolished
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant James Oliver, 1/14/86.
 16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1031

City/Rural Nacogdoches UTM Sector _____

2. Name Nacogdoches Allergy Clinic 6. Date: Factual _____ Est. 1930

Address 1209 Mound St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 45, Lot 39-C 9. Original Use Residence

Present Use Medical Offices

10. Description 1-story; wood frame with horizontal board siding; brick foundation; T-plan; gable roofs with clipped gable ends on north and south with cornice returns, composition shingles; arched roof over porch, metal roofing, plain entablature with wooden boxed columns; windows 4/1 wood double-hung; entry door wood with elongated glass lights and matching side lights; central brick chimney; addition at rear, yard asphalted for parking.

11. Present Condition Good - Fair.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		27	2	to	27	2
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1032

City/Rural Nacogdoches UTM Sector _____

2. Name Benjamin F. Sharp, Dr. & Mrs. Stephen B. Tucker 6. Date: Factual _____ Est. 1920

Address 1401 Mound St. North 7. Architect/Builder Dietrich Rulfs

Contractor _____

3. Owner Mrs. Stephen B. Tucker 8. Style/Type Neoclassical

Address _____ 9. Original Use Residence

4. Block/Lot Block 45, Lot 27 Present Use Residence

10. Description 2-story; wood frame with horizontal board siding; brick foundation; rectangular plan; side-facing gable roofs, pedimented gables, composition shingles; pent roof at first floor arches over the entry way and is supported on heavy lattice screens with faceted ends; windows are multipaned wood double-hung 12/12 and 9/9 with simple hood molds above; 3-sided bay on the northeast corner of the east facade; second story windows have shutters; entry door with side lights is in a Palladian arrangement with multipaned glass lights; porte cochere on the north facade; two

11. Present Condition Good

12. Significance Architectural, good example of style.

13. Relationship to Site: Moved Date _____ Original Site XX; Original Victorian

house on the lot was moved, then partially demolished to rebuild new house and 1417 Mound.

14. Bibliography _____

15. Informant Mrs. Tucker

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		27	3	to	27	3
					to		
					to		

Continuation sheet

10. interior brick chimneys; curved brick driveway; trees on property were planted by Mr. Sharp and his gardner after 1920; they are of specimen size -- holly trees, watermelon pink crape myrtles, and pecans.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1033
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-15
 Address 1417 Mound St. North 7. Architect/Builder Benjamin Franklin Sharp,
 Contractor _____
 3. Owner Mrs. Stephen B. Tucker 8. Style/Type Victorian Cottage
 Address 1401 Mound St. North 9. Original Use Portion of larger house
 4. Block/Lot Block 45, Lot 27 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan with sleeping porch at rear; gable roof with pedimented end gables, composition shingles; pedimented portico with boxed wooden columns; windows 9/9 wood double-hung with hood mold; entry door wood panel with rectangular glass lights; interior brick chimney.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date Unknown Original Site Larger house was moved to front of lot, partially demolished to build 1401; girls room/sleeping porch remained and is current house.

14. Bibliography _____
 15. Informant Mrs. Stephen B. Tucker, 1/14/86
 16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	4	to 27	4
Other _____					to	
					to	

Continuation sheet

7. Builder of remaining portion.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1035

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 311 Mound St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Greek Revival

4. Block/Lot City Block 20 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with lapped board siding; pier foundation; rectangular central hall plan; pyramidal hip roof with composition shingles; porch across front, boxed Doric columns, wood entry door with double arched glass lights, arched side lights; windows 4/4 double-hung wood frame with hood mold.

11. Present Condition Good

12. Significance Good example of type.

13. Relationship to Site: Moved _____ Date Unknown Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	3	to 30	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1036
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 320 Mound St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 20 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; clipped gable roofs, composition shingles; inset porch, decorative metal porch supports, wood entry door with diagonal glass lights; windows 1/1 wood double-hung, picture window on east; vertical board siding on the porch.

11. Present Condition Fair - Good, altered porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		30	2	to	30	2
Other					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1037
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 116 Muckleroy 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot W. Muckleroy S/D (405), Bk 2, Bk 1, Lt 2 Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1038

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 200 Muckleroy 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot W. Muckleroy S/D(405), Bk 63, Bk 1, Lt 3 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; corrugated metal foundation skirt; irregular plan; clipped gable end roof with composition shingles, extended rafter ends; extended porch cover resting on pipe columns; windows 6/6 wood double-hung; detached wood frame garage and carport.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1039

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 315 Muckleroy 7. Architect/Bulder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

Muckleroy S/D (405), Bk 63, Bk2, Lt 8 or 9 Present Use Residence

10. Description 1-story; wood frame with beveled siding; brick pier foudnation; rectangular plan; clipped gable roof with composition shingles; extended porch with boxed wood columns; central entry door wood paneled with 4 vertical upper glass lights; windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1040

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 601 Muckleroy 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Muckleroy S/D (405), Bk 63, Bk 2, Lt 8 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick and concrete pier foundation; irregular plan; gable roofs with extended rafter ends, composition shingles, brick chimney at rear; extended porch resting on metal supports; 2 wood entry doors with diamond light; windows 2/2 aluminum replacement.

11. Present Condition Good, altered by aluminum replacement windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1041
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 208 Muller 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 1, Lot 7-M Present Use Residence

10. Description 1-story; wood frame with asbestos siding; brick foundation; rectangular plan; gable roof with composition shingles; shed roof over porch with 4 x 4 wood porch supports; windows wood double-hung 2/2, placed symmetrically; entry door wood paneled with upper glass light.

11. Present Condition Good; altered by asbestos siding, replacement porch.
 12. Significance _____
 13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTH-L /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		33	15	to	33	15
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1042
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 212 Muller 7. Architect/Builder _____
 Contractor _____
 3. Owner Bill Bryan 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 1, Lot 7-N Present Use Residence
 10. Description 1-story; wood frame with vinyl siding; brick pier foundation; rectangular plan; gable roof with composition shingles; gable roof over porch steps; windows 1/1 and 2/2 wood double-hung; entry door wood paneled with upper glass light.

11. Present Condition Good; altered by vinyl siding, replacement porch, carport.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 33 16 to 33 16
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1043
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mrs. Lily Tuscana 6. Date: Factual _____ Est. 1900
 Address 213 Muller 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Lily Tuscana 8. Style/Type Victorian Cottage
 Address 213 Muller 9. Original Use Residence
 4. Block/Lot Block 1, Lot 10 Present Use Residence
 10. Description 1-story; wood frame with lapped and (at rear) bull-nosed siding; brick pier foundation; rectangular plan with irregular additions at rear; gable roof with bargeboards, composition shingles, 3-bay porch across the front with boxed wood columns; windows 4/4 wood double-hung with hood mold; two entry doors, wood paneled with upper glass light, hood mold; detached wood frame garage.
 11. Present Condition Good.
 12. Significance In 1960 purchased by Mr. & Mrs. Tuscana from Mr. & Mrs. Calvin Wilson, original owners.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography

15. Informant Mrs. Lily Tuscana, 1/21/86.

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		33	17	to 33	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1044
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 214 Muller 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 1, Lot 7-D Present Use Residence
 10. Description 1-story; wood frame; gable roof; rectangular plan.

11. Present Condition Fair; altered by aluminum windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1045
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10
 Address 219 Muller 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 1, Lt 10-B 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with lapped siding, bull-nosed siding at porch; brick foundation; T-plan with additions at rear; gable roofs with corner brackets, extended rafter and faceted beam ends, composition shingles; extended porch with boxed wood columns resting on brick piers, 3-bay facade with symmetrical window and door placement; windows 4/4 and 8/12 wood double-hung with dripcap; central brick chimney; detached car shed at rear; two entry doors with rectangular pattern on screen doors.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	<input type="checkbox"/> RTHL	<input type="checkbox"/> HABS (no.) TEX-	PHOTO DATA			
NR:	<input type="checkbox"/> Individual	<input type="checkbox"/> Historic District	B&W 4 x 5s		slides	
	<input type="checkbox"/> Thematic	<input type="checkbox"/> Multiple-Resource	35 mm Negs.			
NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		33	18	to 33	18
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1046

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 225 Muller & Taylor (Southeast Corner) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 1, Lot 10-A 9. Original Use Residence

Present Use Apartments

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; hip-and-gable roofs with composition shingles, corner brackets, extended rafter ends; inset porch with pipe columns; windows 1/1 wood double-hung and aluminum slider; modern wood doors.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		33	19	to	33 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1048
 City/Rural Nacogdoches UTM Sector _____

2. Name Sacred Heart Church 6. Date: Factual 1936 Est. _____
 Address 500 North St. 7. Architect/Builder H. F. Hawthorn, Arch.

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Mission

4. Block/Lot Block 2, Lots 12 & 13 9. Original Use Church
 Present Use Church

10. Description 1-story; brick laid in a running bond with buttressing at 10 ft. on center on sides, painted; brick foundation; rectangular plan, central aisle; gable roof with composition shingles, stepped mission-style parapet at front with bells in the arched openings; inset entry porch framed by broken arch, double wood doors with batten strips; stained glass windows north and south, leaded with arched ornamentation in glass, 1/1 sash.

11. Present Condition Good - Fair; brick has heavy paint, which is peeling away.

12. Significance Architectural, built in Texas Centennial year; congregation is planning a new church; 1936 State of Texas Marker; site of the home of Charles S. Taylor, signer, Texas Decl. of Ind.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	19	to	28 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1049
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 603 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 2, Lot 5 Present Use Residence
 9. Original Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick pier foundation, metal foundation skirt; irregular plan; hip and pedimented gable roofs with composition shingles, shed dormer on east; porch across half of front with cylindrical wood columns, entry door at each end wood paneled with rectangular glass light, transom above door on south end, side lights flanking door on north end; windows are varied -- 1/1, 9/9, 2/2, double-hung, "X" motif muntins in fixed sash in the dormer and gable end, prism-paned upper sash on front bay, all wood frame; interior brick

11. Present Condition Good; For sale.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		17	4	to 17	5
					to	
					to	

Continuation sheet

10. chimney on north and south, sun porch on south; large hackberry and oak trees in the front yard.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1050
 City/Rural Nacogdoches UTM Sector _____
 2. Name Anderson Electric 6. Date: Factual _____ Est. 1910
 Address 608 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type American Four-Square
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 1, Lot 18 Present Use Commercial

10. Description 2-story; wood frame with horizontal board siding; brick pier foundation with lattice skirt; rectangular plan, hip roof with composition shingles, boxed eave; extended shed roof porch with 4 x 4 porch supports, 2 x 4 rail with diagonals; entry doors at each end of porch wood paneled with upper glass light; windows 1/1 wood double-hung, some with hood mold; sunporch on southeast corner of one-story addition.

11. Present Condition Good; early 1-story addition on rear.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	18	to 28	18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1051

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 615 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neoclassical

4. Block/Lot Block 1, Lot 14 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with brick veneer; brick foundation; H-plan; gable roofs with composition shingles, boxed cornice returns, 3 dormers on east; extended porch with flat roof, balcony railing above, slender Doric boxed columns, classical entry with pilasters, wood paneled door; windows 6/6 wood double-hung with brick soldier course above; sunporch infill on south side; exterior brick chimney on north; gabled dormers with wood siding, multipaned windows; detached garage at rear; 2 large magnolia trees in the front yard.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		17	6	to 17	7
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1052
 City/Rural Nacogdoches UTM Sector _____
 2. Name Site of Mission Nuestra Senora de Guadalupe 6. Date: Factual 1936 Est. _____
 Address 701 North St. at Muller 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Historical Marker
 Address _____ 9. Original Use 1936 Historical Marker
 4. Block/Lot Block 1, Lot 13 Present Use 1936 Historical Marker
 10. Description 1936 Texas Centennial Marker.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	3	to	17 3
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1053
 City/Rural Nacogdoches UTM Sector _____

2. Name Coulter's Antiques 6. Date: Factual _____ Est. 1900
 Address 816 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian

4. Block/Lot Block 40 9. Original Use Residence
 Present Use Antique Shop

10. Description 2-story frame with lap siding; hip-and-gable composition roof is pierced by 1 corbeled brick chimney; windows are 1/1 wood double-hung with hood mold; small inset porch with hip roof and brick modern columns, wood bannisters, entry doors are ornate paneled door with Queen Anne light; projecting chamfered bay has brackets, fishscale shingles, vent, bargeboards, and Queen Anne window; dormer and two projecting additions on the north side; additions at rear; front porch has been altered and disrupts the scale of the front facade.

11. Present Condition Good; numerous alterations, some not consistent with style.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	17	to	28 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1054

City/Rural Nacogdoches UTM Sector _____

2. Name Rudissl House / Antique Shop 6. Date: Factual _____ Est. 1890s

Address 821 North St. 7. Architect/Bullder Dietrich Rulfs

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Queen Anne

4. Block/Lot Block 1, Lot 3 9. Original Use Residence

Present Use Retail

10. Description 1-story frame with lap siding; hip-and-gable composition roof pierced by dormers, 2 corbeled brick chimneys, and widow's walk without railing; brick foundation piers and skirt; ornate frieze, bannister, bargeboards, and turned columns on wraparound porch; entry door is paneled with large light; windows are 1/1 wood double-hung; stained glass and fishscale shingles in gables; irregular massed plan; 3 chamfered bays with corner brackets; newer addition at rear; no garage or carriage house.

11. Present Condition Good; recently renovated; some alterations.

12. Significance Site of 1936 Texas Centennial granite marker "La Calle Real Del Norte" celebrating an 18th century trail connecting Indian villages and traveled by Spanish missionaries, soldiers,

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	1	to 17	2
Other					to	
					to	

Continuation sheet

12. settlers, etc. House is excellent example of style.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1055
 City/Rural Nacogdoches UTM Sector _____
 2. Name La Hacienda / Hayter House 6. Date: Factual _____ Est. 1910-13
 Address 1411 North St. 7. Architect/Builder Dietrich Rulfs
 Contractor _____
 3. Owner _____ 8. Style/Type Prairie-Style Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 44, Lot 4 Present Use Commercial

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick foundation skirt; irregular plan; hip roofs with splayed eave, composition shingles, deep overhang, two interior narrow brick chimneys, one exterior brick chimney on west; entry porch with boxed paneled wood 1/2 columns over brick piers, triples of 4/4 windows fill inbetween the columns, double multi-paned wood entry doors; bands of 12/12 multipaned wood frame double-hung windows on the first floor, dormers have 2/2 sliding or casement windows and 3 paned fixed windows; secondary entry on the

11. Present Condition Good; altered; front porch enclosed with windows, kitchen for restaurant, skylights in

12. Significance Hayter family was an early logging family; house is architecturally significant.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		16	18	to 16	24
Other					to	
					to	

Continuation sheet

- 10. northeast corner with wood and multipaned glass door, which was the porte cochere; windows on the rear of the house 4/1 wood double-hung. Interior: large entry hall, extensive woodwork. Fence of brick and iron around property; front steps -- brick with lamp posts.
- 11. roof at rear; very large parking area around both sides and rear of the house.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1056

City/Rural Nacogdoches UTM Sector _____

2. Name Walter Gintz House 6. Date: Factual 1902 Est. _____

Address 1703 North St. 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Victorian Cottage

Address _____ 9. Original Use Residence

4. Block/Lot Block 50, Lot 24 Present Use Residence

10. Description 1-1/2 story; wood frame with stucco; raised masonry foundation (4 feet off ground at front); irregular plan; intersecting hip-and-gable roofs with wood shingles, elaborate bargeboards and trimmed gable ends, shingle siding at south gable end; inset porch, portico entry with arched ceiling; Eastlake-style of fretwork and brackets, turned wood posts with spindle railing, three entry doors on the porch, two at 90 degrees on the north end, wood paneled with upper rectangular light, side door with arch-ornamented screen door, one at southwest with arched

11. Present Condition Good; altered, stuccoed in the 1930s.

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant Mrs. Roger Montgomery, 1975.

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		17	16	to	17	17
					to		
					to		

Continuation sheet

10. ornamented screen door; windows are 1/1 wood double-hung, in northeast bay one window has a Queen Anne upper sash; detached wood frame garage.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1057

City/Rural Nacogdoches UTM Sector _____

2. Name Phi Delta Theta 6. Date: Factual _____ Est. 1928-30

Address 1613 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type English Tudor Cottage

4. Block/Lot Block 44, Lot 1-1/2 B Present Use Fraternity House

10. Description 2-story; wood frame with polychrome brick veneer; brick foundation; rectangular plan with porte cochere on south; hip-and-gable roof with gable dormers, wood shingles, small corbeled brick brackets at roof corners, interior brick chimney; raised brick platform porch, double wood entry door with small glass lights, cast stone lintel above door; windows 6/6 and wide 4/4 wood double-hung; dormers have wood siding, multipaned windows or vents; porte cochere on south has segmental arch openings; detached brick garage at rear appears to have been cut in

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	14	to 17	15
Other _____					to	
					to	

Continuation sheet

10. half; large juniper trees in front, yard partially paved for parking.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1058

City/Rural Nacogdoches UTM Sector _____

2. Name Nacogdoches Chamber of Commerce 6. Date: Factual 1923 Est. _____

Address 1801 North St. 7. Architect/Builder Dietrich Rulfs

Contractor _____

3. Owner _____ 8. Style/Type Renaissance Revival

Address _____ 9. Original Use Residence

4. Block/Lot Block 50, Lot 22 Present Use Nacog Chamber of Commerce

10. Description 2-1/2 story; wood frame with tan brick veneer and vertical wood siding on the north and south porch wings; brick foundation; rectangular 5-bay plan with central hall, porte cochere at rear; low hipped roof with deep eaves, extended rafter ends, hipped dormers, composition shingles, interior brick chimney at north and south; raised platform porch across front with half brick piers and heavy wood spindle railing, inset entry bay with projecting balcony resting upon cylindrical Corinthian colonnade; central entry door wood with large rectangular beveled glass

11. Present Condition Excellent

12. Significance Architectural; Historical - 1936 State of Texas Marker, site of the home of Thomas J. Rusk.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	8	to 17	13
Other					to	
					to	

Continuation sheet

10. light, flanked by brick pilasters with lanterns; symmetrical facades in massing and placement of windows; windows are wood frame double-hung in 12/12, 6/6, 4/4 configuration, at the two middle bays there is an arched sunburst transom on the first floor over paired windows; sunporches on the north and south ends have windows grouped between Corinthian columns on the second floor and paired multipaned French doors and side lights on the first floor; the porte cochere at the center of the west side is supported by Corinthian columns on brick bases; large yard with many trees.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1059

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 1911 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shingle Neoclassical

4. Block/Lot Block 50, Lot 19-B 9. Original Use 2 Houses- Residence & Cottage

Present Use 2 Houses- Residence & Cottage

10. Description 1900 North St: 1-story; wood frame with wood shingle siding; brick foundation; irregular plan; gable roofs with composition shingles, exterior brick chimney on southeast corner; extended porch roof with standing seam metal roof, paired Doric columns, wood entry door with multipaned upper lights; windows multipaned wood double-hung 12/12/, 6/6; secondary entry with columns on southeast. 1911 North St: same style, rectangular plan, 2 interior brick chimneys, bay windows on east facade; sunporch on south enclosed by multipaned French

11. Present Condition Good; Good.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	24	to	17 25
Other	1986		28	12	to	28 12
					to	

Continuation sheet

10. doors, side lights with transom lights; entry door is solid wood paneled with leaded glass side lights and transom lights.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1060
 City/Rural Nacogdoches UTM Sector _____
 2. Name Book Seller 6. Date: Factual _____ Est. 1920-30
 Address 2108 North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Langford Resub 342, Block 50, Lots 3-6 Present Use Commercial
 10. Description 1-story brick veneer, 4 bays articulated by arched cornice; one is obscured with mansard applied front; modern aluminum and glass storefronts; decorative brickwork in recessed panels on cornice.

11. Present Condition Fair - Good
 12. Significance Early strip shopping center associated with Stephen F. Austin University.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		28	10	to	28	10
Other				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1061
 City/Rural Nacogdoches UTM Sector _____
 2. Name Stephen F. Austin University Theatre 6. Date: Factual _____ Est. _____
 Address 2208 - 2210 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Theatre
 4. Block/Lot Block 50, Subdivision 458, Block 4, Lot 6 Present Use Theatre
 10. Description 2-story concrete block with brick veneer; rectangular plan; modern storefront with billing display windows; decorative brickwork; projecting sign read "SFA" with pine cone motif.

11. Present Condition Fair
 12. Significance Good example of early theatre.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 - _____ 1986 _____ 28 9 to 28 9
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1062

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 2015 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type English Tudor Cottage

4. Block/Lot Block 50, Lot 17-9 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with brick veneer; brick foundation; irregular plan; gable roofs with composition shingles, exterior brick chimney at east facade with tapered cap; extended entry with concrete steps, central wood paneled door with small glass light; windows 6/1 wood double-hung; southeast corner porch with arched openings, brick soldier course over doors, windows; 2-bay detached brick garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides _____

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		17	22	to	17	23
	1986		28	11	to	28	11
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1063
 City/Rural Nacogdoches UTM Sector _____
 2. Name Tau Kappa Epsilon Fraternity 6. Date: Factual _____ Est. 1920-30
 Address 2019 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50, Lot 17-8 Present Use Fraternity House
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1064
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2037 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Brick Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50, Lot 17-7 Present Use Commercial
 10. Description _____

11. Present Condition Good; front yard graveled for parking.

12. Significance Very little architectural merit.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 13, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1065
 City/Rural Nacogdoches UTM Sector _____
 2. Name Crossroads 6. Date: Factual _____ Est. 1930s
 Address 2116 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Langford Resub 342, Block 50, Lots 7 & 8 Present Use Commercial
 10. Description _____

11. Present Condition Good - Fair
 12. Significance Was McVickers Drugstore, then Lee's Records.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1066
 City/Rural Nacogdoches UTM Sector _____
 2. Name Wiggins Auto Parts 6. Date: Factual _____ Est. _____
 Address 2301 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot R. G. Upton Sub, Block 50, Lots 10 & 11 Present Use Commercial
 10. Description 1-story brick load-bearing walls; rectangular plan; plate glass storefront; awning overhang; windows at rear are 4/6 awnings.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	20	to 17	21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1067
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 2307 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot BBlock 50, Lot 16-C Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan; composition gable roof pierced by three brick interior chimney stacks and 1 dormer; windows are 5/1 wood double-hung; projecting porch has brick boxed columns and 2 paneled entry doors with large lights; foundation skirted.

11. Present Condition Good
 12. Significance Good example of style, some alterations.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		17	18	to 17	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1068

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 2909 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 50 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; clipped gable roofs with boxed eave, curved cornice return, composition shingles; extended porch with short paneled columns resting on brick piers, entry door wood with long rectangular glass lights; windows 4/1 wood double-hung with wood shutters; exterior brick chimney on north; detached frame garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 16, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	8	to 28	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1069

City/Rural Nacogdoches UTM Sector _____

2. Name Century 21 Real Estate Eastex Association, Inc. 6. Date: Factual _____ Est. 1935-40
Address 3007 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Tudor Cottage

4. Block/Lot City Block 50 9. Original Use Residence
Present Use Residence

10. Description 1-1/2 story; wood frame with wood shingle siding; brick foundation; rectangular plan; steep gable roofs with composition shingles, gabled dormers; extended entry with brick steps, shallow overhang with boxed column porch supports; wood entry door with small glass lights; windows 6/6 wood double-hung, dormers on east with shingle siding.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 16, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	7	to 28	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1070
 City/Rural Nacogdoches UTM Sector _____
 2. Name North Street Flowers & Gifts 6. Date: Factual _____ Est. 1935-40
 Address 3011 North & Bowie 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Commercial/Florist
 10. Description _____

11. Present Condition Good; front facade altered by two picture windows for display.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 16, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	6	to	28 6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1071
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nethery Electric/Used Books 6. Date: Factual _____ Est. 1910-20
 Address 303 North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Early 20th Century Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 2, Lot 36-B Present Use Commercial

10. Description 1-story; load-bearing brick; rectangular plan; parapet with tile coping, flat roof; inset signage panel above suspended wood canopy; 2-bay storefront, wood frame display windows with brick apron flanked by entry door-modern aluminum frame and glass; interior has high coffered metal ceiling.

11. Present Condition Good-Fair, canopy is deteriorated.

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRAME		ROLL	FRAME
	1986		28	22	to	28	22
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1072

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 3203 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 68 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; intersecting gable roofs with extended rafter ends, brackets, composition shingles, interior brick chimney; extended porch on southeast corner with boxed wood columns over brick piers; entry door wood paneled with upper glass light; windows 1/1 wood double-hung; detached wood frame garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 16, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	5	to 28	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1073
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40s
 Address 4418 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Rock Craftsman Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 67 Present Use Residence

10. Description 1-story; smooth small log structure; irregular plan; hip-and-gable roofs with wood shingles, extended rafter and beam ends; small rockface porch with canopy, wood door; windows 9/9 wood double-hung; rock chimney on west facade; interior brick chimney at northwest; 3 or 4-bay; 2-story garage at rear; large yard.

11. Present Condition Good
 12. Significance Good example of type.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	4	to 28	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1074

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 4715 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 70 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with brick veneer; brick foundation; irregular plan; inset porch partially enclosed, brick pier porch supports, decorative metal grille and door at entry; 4/1 wood double-hung windows in twos and threes, 3 fixed sash with diamond panes; hip roofs with deep eaves, composition shingles, wood frame garage at rear; interior brick chimney.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	3	to	28 3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1075
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 5122 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1076
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 5124 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1077
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 5212 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with extended beam and rafter ends, composition shingles; extended entry porch with wood posts with battered base, wood panel entry door with upper glass; windows 4/4 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date Possibly Original Site

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 28 2 to 28 2
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1078
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 5121 North St. (Across from 5124) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1079
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 5306 North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 70 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; extended porch with narrow battered wood columns over brick piers, low brick wall, wood and multipaned glass door; 1/1 wood double-hung windows; gable roof with composition shingles.

11. Present Condition Fair; in midst of mobile homes.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	24	to 27	24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1080

City/Rural Nacogdoches UTM Sector _____

2. Name S. G. Whitmire 6. Date: Factual _____ Est. 1890-1900

Address 5706 North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

9. Original Use Residence

4. Block/Lot City Block 69 Present Use Residence

10. Description 1-story; wood frame with beveled lapped board siding; brick and concrete pier foundation; ell plan; intersecting gable roofs with sheet metal roof; shed roof over porch with 4 x 4 wood supports, entry doors set at 90 degrees, one wood paneled, one wood with upper glass light; windows 4/4 with hood mold; brick exterior chimneys on north and south; shed addition at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	22	to	27
Other					to	22
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1081
 City/Rural Nacogdoches UTM Sector _____
 2. Name Bob Millard House/Joshua's Needle 6. Date: Factual 1919 Est. _____
 Address 5902 North St. 7. Architect/Builder Bob Millard
 Contractor _____
 3. Owner Marjorie McMurrey 8. Style/Type Victorian/Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 69 Present Use Residence/Retail
 10. Description 1-story; irregular plan; wood frame with asbestos siding; raised brick pier foundation with brick infill; intersecting gable roofs with extended rafter and beam ends, composition shingles, exterior brick chimney on north; porch across front on the west and part of the south, boxed wood columns with wood railing, newel posts with ornate railing down brick steps, ornate scroll brackets and spindle fetwork, south end of porch glassed in -- originally a sunporch with windows; classical entry with wood paneled door with sunburst light, cornice above flanked by
 11. Present Condition Good; all ornamentation original to house; siding altered.
 12. Significance Lumber cut on property and sun dried; labor to build house cost \$350.00; floors of heart pine; built same year as Mrs. Stephen Tucker home on Mount Street; Mr. Millard was a rancher.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography

15. Informant Marjorie Millard McMurrey, 3/19/86

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 27 23 to 27 23
 _____ to _____
 _____ to _____

Continuation sheet

10. pilasters; windows 3/1, 6/6, 4/4 wood double-hung; small chamfered bay at north facade with stained glass windows; rear entry has Ionic columns with geometric wood lattice, plain wood railing, storm door; brick chimney on southeast corner; wood frame and lattice gazebo in front yard, street lantern with five globes. Newer buildings at rear of house built in 1980.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1082
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 6702 North St. (at railroad tracks) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot North of City Block 69 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1083

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900

Address 0000 North St. (North of 6702 North St. -- at city limits) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Farm Complex

4. Block/Lot North of City Block 69 9. Original Use Residence, Farm

Present Use Residence, Farm

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick pier foundation with lattice infill; irregular ell plan with chamfered bays on south and west; hip and intersecting gable roofs, bargeboards on south bay, shingled gable ends with fixed Queen Anne windows, patterned sheet metal roofing with ridge cap, interior brick chimney; gallery porch with Doric columns, turned railing, entry door with arched glass light flanked by narrow arched sidelights; windows 1/1 wood double-hung with hood mold, one upper sash with prism panes, gingerbread woodwork at

11. Present Condition Residence: Good; Barns: Fair - Good.

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	21	to 27	21
Other					to	
					to	

Continuation sheet

10. chamfered bays; 2-story barn with side sheds, wood frame with sheet metal sheathing, gable roof. House has a white picket fence around the yard.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1084
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 8081 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot North of City Block 70 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered with asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1085
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 514 Ochiltree 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Craftsman
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 26, Lot 1-H Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1086
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 518 Ochiltree 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 26, Lot 1-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1087
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 805 Ola 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 7 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1088
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 806, 808 Ola 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-E Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1089
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 814 Ola 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-E Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1090
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 816, 900, 904, 908 Ola 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottages
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-G Present Use Residence
 10. Description 1-story frame, rectangular with sheet metal roofs.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 21 21 to 21 21
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1091
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 821, 903, 905, 907 Oia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-H Present Use Residence
 10. Description 1-story rectangular frame residences with sheet metal roofs.

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1092
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 716 Ola 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 9-E Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1093
 City/Rural Nacogdoches UTM Sector _____

2. Name Hawthorne's 6. Date: Factual _____ Est. 1910-30
 Address 2606 Old Lufkin Highway 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story frame with lap siding; brick pier foundation; rectangular plan; hip-and-gable roof with composition shingles; gallery porch across front, boxed wood columns, railing with cut silhouette pattern; central entry door with 4-paned transom above; windows 6/6 wood double-hung; attached carport on west.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	12	to	20 12
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1094

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 2720 Old Lufkin Highway 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with lap siding; patterned sheet metal hip-and-gable roof; windows are 6/6 wood double-hung; projecting porch; multipanel entry door; pier and beam foundation; garage at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	11	to	20 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1095
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3009 Old Lufkin Highway 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1096
 City/Rural Nacogdoches UTM Sector _____
 2. Name Blackburn's 6. Date: Factual _____ Est. 1910-30
 Address 4723 Old Lufkin Highway 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; symmetrical U or H-plan; gable roofs with composition shingles, interior brick chimney; centered dormer; shed roof over porch, boxed columns, centered multipane glass and wood door; windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	10	to	20 10
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1097
 City/Rural Nacogdoches UTM Sector _____
 2. Name Church and Cemetery 6. Date: Factual _____ Est. _____
 Address 2800 Old Post Oak Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Church and Cemetery
 4. Block/Lot _____ Present Use Church and Cemetery
 10. Description Out of city limits; should be assessed as historic resource if city extends and/or intensive development impacts site.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1098
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2823 Ye Old Post Oak Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1099
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40s
 Address 3408 Ye Old Post Oak Road 7. Architect/Bullder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1100
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address Across from 3513 Ye Old Post Oak Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Old Barn
 Address _____ 9. Original Use Barn
 4. Block/Lot Block 54 Present Use Barn
 10. Description 2-story frame barn with vertical board siding and hay loft; sheet metal gable roof.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	22	to	19 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1102
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 3904 Ye Old Post Oak Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use _____
 4. Block/Lot Block 54 Present Use Burned
 10. Description Burned since initiation of survey project.

11. Present Condition Burned
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1103
 City/Rural Nacogdoches UTM Sector _____
 2. Name Abernethy 6. Date: Factual _____ Est. 1940-50s
 Address 3907 Ye Old Post Oak Rd. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Colonial
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1104

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 4111 Ye Old Post Oak Rd. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence

10. Description _____ Present Use Residence

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1105

City/Rural Nacogdoches UTM Sector _____

2. Name Ramsey House 6. Date: Factual _____ Est. 1930

Address 3014 Old Spanish Bluff Road (Top of hill) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow/Farm Complex

4. Block/Lot Block 56 9. Original Use Bungalow/Farm Complex

Present Use Bungalow/Farm Complex

10. Description 1-story; wood frame with horizontal board siding; rectangular plan; brick foundation; gable roof with hipped skirt; on the south and southwest there is a long sleeping porch, enclosed; inset entry on south with 4 x 4 posts; windows 3/1 double-hung with half-screens; small metal sheathed outbuildings; 2 dug cisterns with brick neck foundation.

11. Present Condition _____

12. Significance Original Ramsey farm divided by the highway to the east.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	8	to 20	8
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1106
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3318 Old Spanish Bluff Road 7. Architect/Bullder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with narrow horizontal board siding; brick foundation; ell plan; clipped gable roof with composition shingles; inset porch with turned wood post; windows 1/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	9	to	20 9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1107
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-15
 Address 121 Orton (Across from 116) 7. Architect/Builder _____
 Contractor _____
 3. Owner Harold Whitaker 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Bk 51, Bk 12, Lt 8 Present Use Residence
 10. Description 1-story; wood frame with board and batten siding; raised foundation with sheet metal skirt; rectangular plan; intersecting gable roofs with composition shingles, extended rafter ends; projecting porch with 4 x 4 posts, wood panel door with upper glass; windows 4/4 wood double-hung, a few 3/3s at rear.

11. Present Condition Fair - Good; early additions at rear.
 12. Significance _____
 13. Relationship to Site: Moved Date 1950s Original Site Moved from Frost Johnson Lumber Mill property near present South University Drive at the Loop.

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL	/HABS (no.) TEX-	PHOTO DATA	
NR: /Individual	/Historic District	B&W 4 x 5s	slides
/Thematic	/Multiple-Resource	35 mm Negs.	
NR File Name	YEAR	DRWR	ROLL
	1986		42
			5A
Other			

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1108
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 603 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 9, Lt 6 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair; altered by vinyl siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1109
 City/Rural Nacogdoches UTM Sector _____
 2. Name Myrtle Benton 6. Date: Factual _____ Est. 1939
 Address 610 Orton 7. Architect/Builder M. Powell, Carpenter
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 3, Lt 9 Present Use Residence
 10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; gable roofs with extended rafter ends, composition shingles; inset porch with boxed columns, 2 wood paneled entry doors with upper glass, set at 90 degrees; windows 1/1 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant Myrtle Benton, 4/3/86.
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 41 25 to 41 25
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1110
 City/Rural Nacogdoches UTM Sector _____

2. Name Helen Gallon 6. Date: Factual 1936 Est. _____
 Address 614 Orton 7. Architect/Builder M. Powell, Carpenter

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow
 9. Original Use Residence

4. Block/Lot I. G. Orton S/D (437), Blk 53, Blk 3, Lt 8 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; inset porch with short boxed columns on brick piers, 2 wood paneled entry doors with upper glass, set at 90 degrees; windows 1/1 wood double-hung; carport on south.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Hellen Gallon, 4/3/86.

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		42	1A	to 42	1A
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1111
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 615 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 9, Lt 9 Present Use Residence
 10. Description _____

11. Present Condition Fair; asbestos siding over board siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1112

City/Rural Nacogdoches UTM Sector _____

2. Name Bronson Handy 6. Date: Factual 1939 Est. _____

Address 618 Orton 7. Architect/Builder _____

3. Owner _____ Contractor Ira Land

Address _____ 8. Style/Type Bungalow

4. Block/Lot J. G. Orton S/D (437), Blk 3, Lt 7 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation with skirt; rectangular plan; gable roof with composition shingles, extended rafter ends; extended porch with boxed columns, entry door wood paneled with four vertical upper lights, windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance According to Mrs. Handy the house was financed by an FHA loan from Commercial Bank, Nacogdoches.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant Mr. Bronson Handy, 4/3/86.

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		42	2A	to	42	2A
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1113
 City/Rural Nacogdoches UTM Sector _____
 2. Name Williams (deceased) 6. Date: Factual 1928-29 Est. _____
 Address 619 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner Mr. Mize 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 9, Lt 10 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roofs with extended rafter ends; composition shingles; inset porch with 4 x 4 posts; 2 entry doors set at 90 degrees; windows 4/4 wood double-hung.

11. Present Condition Fair
 12. Significance Frost Johnson Lumber Mill, built houses for the widows of men that worked at the mill, \$1000 insurance money; one of the earliest houses on the block.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 42 3A to 42 3A
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1114
 City/Rural Nacogdoches UTM Sector _____
 2. Name Louis Garcia (First - Willa Mae Johnson, deceased) 6. Date: Factual 1929 Est. _____
 Address 623 Orton 7. Architect/Builder Arthur Brewer, Builder,
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 9, Lt 11 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; clipped gable roof with extended rafter ends, knee braces, composition shingles; projecting porch with boxed columns, plain wood railing; windows 4/1 wood double-hung; interior brick chimney at rear.

11. Present Condition Good
 12. Significance Third house built on the street, which was a sand trail; was built for Widow Johnson by Frost Johnson Lumber Mill; logged trees out of this neighborhood, then people began to buy lots;
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant Mr. & Mrs. Louis Garcia
 16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		42	4A	to	42 4A
Other					to	
					to	

Continuation sheet
 7. lived on Main St. 12. Mr. Garcia bought the house in 1944; he was raised on Hayward Street, moved here in 1909, built house.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1115
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 704 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 3, Lt 4 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1116
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 708 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 3, Lt 3 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by vinyl siding, brick apron.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 3, 1986

DESIGNATIONS : TNRIS No. _____

Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1117

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 807 Orton 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Shotgun

4. Block/Lot J. G. Orton S/D (437), Blk 53, Blk 8, Lt 7 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with beveled siding; brick pier Y-plan; gable roof with composition shingles; windows 4/4 wood double-hung; central entry door, extended porch with builtup 2 x 4 columns.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1118
 City/Rural Nacogdoches UTM Sector _____
 2. Name Lily Field (earlier, Frank Ballengin) 6. Date: Factual _____ Est. 1925-30
 Address 814 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Orton S/D (437), Blk 53, Blk 2, Lt 5 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; pier foundation with concrete block infill; rectangular plan; gable roof with extended rafter ends, knee braces; inset porch with boxed columns, screened; windows 4/1 wood double-hung with half-screens.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant Ms. Lily Field, 4/1/86.

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1121

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 912 Orton 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot J. G. Orton S/D (437), Blk 62, Blk 1, Lt 12 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick pier foundation; rectangular plan; addition at rear; clipped gable roof with composition shingles, extended rafter ends; extended porch with boxed wood columns, central entry door; windows 1/1, 4/4 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL _____ /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1122
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1016 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot J. G. Orton S/D (437), Blk 62, Blk 1, Lt 4 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1123
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1308 Orton 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Store or Residence
 4. Block/Lot ADBrewerS/D, City Blk 62, Blk 8, Lot 1-C Present Use Residence
 10. Description _____

11. Present Condition Fair - Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1124
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mrs. Johanson 6. Date: Factual _____ Est. 1930-45
 Address 401 Sadler 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot O. Sadler S/D (517), City Block 51, Lot 8 Present Use Residence
 10. Description _____

11. Present Condition Fair; aluminum replacement windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1125

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-30

Address 403 Sadler 7. Architect/Builder _____

3. Owner Mrs. Sadler Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot City Block 51, Lot 30-B 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with brick-patterned roll composition siding; brick pier foundation; rectangular plan; gable roof with extended rafter ends, composition shingles; extended porch with 4 x 4 posts, wood railing; 2 wood paneled entry doors; 4/4 wood double-hung windows.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	7	to 41	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1126

City/Rural Nacogdoches UTM Sector _____

2. Name Old E. J. Campbell High School Gymnasium 6. Date: Factual _____ Est. 1925

Address 000 Alley off Shawnee and Hayward 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular

4. Block/Lot Block 51, Lot 49 9. Original Use Educational

Present Use Vacant

10. Description 2-story; load-bearing brick; concrete foundation; rectangular plan with projecting entry; pedimented gable roof with composition shingles, deep plain entablature above second story windows; projecting entry with engaged pilasters rising above the parapet, canopy over entry, 3 pairs of double wood paneled doors; windows are steel frame, multipane glass, on either side of the entry is an arched multipaned window.

11. Present Condition Fair - poor; windows broken and corroded; covered with ivy on east and part of south.

12. Significance Segregated, black high school in Nacogdoches.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District _____ B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource _____ 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		41	8	to	41	8
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1127
 City/Rural Nacogdoches UTM Sector _____
 2. Name Sadler Funeral Home 6. Date: Factual _____ Est. 1910-30
 Address 410 Otis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Farm House
 Address _____ 9. Original Use Funeral Home
 4. Block/Lot Block 51, Lot 30-A Present Use Apartments
 10. Description 2-1/2 story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; side-facing gable roof, 1-story gable roofs, composition shingles; inset gallery porch with oversized boxed wood columns, wood entry door with applied scroll ornamentation, upper glass; windows 1/1, 6/6, wood double-hung.
 11. Present Condition Fair
 12. Significance Local history; first a funeral home, now apartments.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 41 3 to 41 3
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1128

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-35

Address 414 Sadler 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot OSadlerS/D(517), City Blk 51, Lot 11 or 12 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; foundation covered by sheet metal skirt; rectangular plan; gable roof with extended rafter ends, corrugated metal roofing; shed roof over porch, pipe columns, wood entry door; windows 4/4 wood double-hung.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- PHOTO DATA
/Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	6	to 41	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1129
 City/Rural Nacogdoches UTM Sector _____

2. Name Old E. J. Campbell High School Campus 6. Date: Factual _____ Est. 1900-10
 Address 000 Alley off Shawnee and Hayward 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Vernacular

4. Block/Lot Block 51, Lot 49 9. Original Use High School
 Present Use Learning Center

10. Description 2-story; load-bearing brick; originally L-plan with later additions on west and east; hipped roof with standing seam metal roof; narrow inset entry on south with arched opening, double wood doors; windows are 4/4, 6/6, 12/6, 9/6 wood double-hung with segmental arches; some windows boarded; exterior steel stair with mezzanine-level entry on the south.

11. Present Condition Fair - Good

12. Significance Segregated, black high school in Nacogdoches.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	9	to 41	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1130

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 418 & 422 Sadler 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottages

4. Block/Lot OSadlerS/D(517), City Blk 51, Lts 13 & 14 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with roll composition siding; corrugated metal foundation skirt; rectangular plan; gable roof with lapped seam metal roof, extended rafter ends; shed roof over porch, resting on 4 x 4 posts; wood panel entry door; windows 6/6 wood double-hung; 425 Sadler, across the street, is very similar in plan and details; photo of 418 Sadler.

11. Present Condition Good - Fair

12. Significance Identical to one another.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	5	to	41 5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1131

City/Rural Nacogdoches UTM Sector _____

2. Name Ida Mae Sexton 6. Date: Factual _____ Est. 1920-35

Address 423 Sadler 7. Architect/Builder _____

3. Owner Glendyn Adams Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot OSadlerS/D(517), City Blk 51, Lot 15 or 16 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; irregular plan; gable roof with corrugated metal roofing; extended rafter ends; inset porch on southeast; windows 6/6, 4/4 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		41	4	to	41	4
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1132

City/Rural Nacogdoches UTM Sector _____

2. Name Dr. A. T. Mast III 6. Date: Factual _____ Est. 1920-30

Address 614 Mound St. North (Corner of Park & Mound) 7. Architect/Builder Dietrich Rulfs

Contractor _____

3. Owner Dr. A. T. Mast III 8. Style/Type Spanish Eclectic/Craftsman

Address _____ 9. Original Use Residence

4. Block/Lot Block 4, Lot 1 Present Use Residence

10. Description 1-story; wood frame construction with brick veneer in a running bond; brick foundation; massed plan; hip-and-gable roofs with extended rafter and beam ends, deep overhand, Spanish tile roofing; brick porch across west facade with half brick piers and low wall; windows wood double-hung 1/1; entry across west facade with arched openings, multipaned wood doors; porte cochere on northwest corner with elliptical arched openings; one interior brick chimney, one exterior brick chimney, with flared base on west facade; curved drives from Mound and Park

11. Present Condition Excellent; wing at southeast corner may be later addition.

12. Significance Architectural.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 13, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		25	10	to	25	10
					to		
					to		

Continuation sheet

10. Streets; large oak and pine trees in front yard.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1133
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940
 Address 523 / 525 Park 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 26, Lot 11-F 9. Original Use Residence
 Present Use Duplex

10. Description 1-story; wood frame with wide lapped siding; brick foundation; gable roofs and hip roofs at rear; massed plan; composition shingles on roof, flared eave at front-facing gable; concrete slab over brick foundation porch with small roof over entry to 523, turned wood porch supports; windows 1/1 wood double-hung; doors multipaned glass, 2 secondary entries on east facade.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	16	to 21	16
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1134

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 600 Park 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 4, Lot 1-A 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick foundation; massed plan; hip-and-gable roof with composition shingles, plain entablature, beaded wood soffit; pedimented portico with Palladian attic windows, turned wood porch supports and fan brackets (new), spindle railing; windows 1/1 wood double-hung with simple hood mold; sunporch with casement windows at southeast corner; rear porches at southeast and south; entry door with large glass light; interior brick chimney on north facade; detached wood frame garage.

11. Present Condition Good; recently remodeled with new Victorian trim at porches.

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	17	to	21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1135

City/Rural Nacogdoches UTM Sector _____

2. Name Hoya House 6. Date: Factual _____ Est. 1910-15

Address 610 Park 7. Architect/Builder Dietrich Rulfs (possibly)

3. Owner Mrs. Giles Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot BBlock 4, Lot 1-C 9. Original Use Residence

Present Use Residence

10. Description 1-story; brick veneer over wood frame; brick foundation; massed plan; hip-and-gable roofs with clay tile roofing and ridge caps and with deep overhang; central inset entry porch with elliptical arched opening; secondary entry at porte cochere on east side; windows are wood with upper sash in a geometric glazing pattern over a single pane sash; windows at front of house are multipaned wood casement set in groups of three under an elliptical arch and transom light, chamfered brick bay on west facade; entry porch has central windows with doors opposite one another, one with

11. Present Condition Good

12. Significance Architectural, historical; later home of Mr. & Mrs. Hoya.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	18	to	21 18
Other					to	
					to	

Continuation sheet
10. multipaned French doors with side lights and transom, one with wood door with geometric glazing. Roof has a deep overhang, extended rafter ends and faceted beam ends; some windows on north and west facades are wide, double-hung; basement with small windows; detached modern garage.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1136

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 618 Park 7. Architect/Builder _____

3. Owner Mrs. Giles Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 4, Lot 1-B Present Use Vacant

10. Description 1-story; wood frame with board siding; brick foundation; ell plan; hip-and-gable roof with extended rafter and beam ends, composition shingles; inset porch with battered wood 1/2 columns resting on brick piers, simple wood railing; windows 1/1 wood double-hung; entry door wood paneled with three upper lights.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		21	19	to	21 19
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1137

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 716 Park St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Folk Victorian

4. Block/Lot Block 5, Lot 1 or 5 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; galvanized metal foundation skirt; rectangular plan; gable roof with galvanized metal roofing; inset porch with narrow wood post supports; 4/4 wood double-hung windows; wood panel door.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 14, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		21	20	to	21 20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1138

City/Rural Nacogdoches UTM Sector _____

2. Name Zion Hill Baptist Church Cemetery 6. Date: Factual _____ Est. 1900

Address 0000 Park St., East, at Lanana Creek 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Historic Cemetery

4. Block/Lot Block 5, Lot 5 9. Original Use Cemetery

Present Use Cemetery

10. Description Fenced cemetery with granite, marble, and concrete gravestones. Fence was built by Mrs. Mast and may not include all the historic grave sites. Earliest marked graves date to ca. 1900; it is said that earlier graves are not marked or markers have deteriorated over the years.

11. Present Condition Good

12. Significance Part of an intact historic black neighborhood, Zion Hill. RTHL marker for Fr. Margill's Eyes is located at a spring adjacent to cemetery on Lanana Creek.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		20	20	to	20	20
Other				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1139

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-20

Address 320 Parker Rd. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Board & Batten House, Barns

4. Block/Lot City Block 68 9. Original Use Farmstead

Present Use Farmstead

10. Description 1-story board and batten house with gable roof with sheet metal roofing, inset porch, 2/2 wood windows; large barn: 6 bays x 3 bays, 2-story, metal roofing, wood frame with horizontal board siding, gable roof with ventilator gable at ridge; open shed barn: 6 bays, gable roof with metal roofing, horizontal post and timber dividers between bays; both barns: rectangular plan.

11. Present Condition House - Fair; Large Barn - Good; Open Shed Barn - Fair.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	18	to	27 18
Other					to	
					to	

Continuation sheet
6. 1915-20; Barns: 1920-30.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1140

City/Rural Nacogdoches UTM Sector _____

2. Name Anderson 6. Date: Factual _____ Est. 1930-40s

Address 521 Parker Road East 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Vernacular

Address _____ 9. Original Use Residence

4. Block/Lot City Block 67 Present Use Residence

10. Description 2-story; wood frame with lapped board siding; brick foundation; irregular plan; gable roofs with composition shingles, cornice returns, exterior brick chimney on west and east of one-story addition; porch with boxed column and pilasters, wood panel entry door with multipaned glass; windows 6/6, 8/8 with hood mold; 3-bay detached wood frame garage.

11. Present Condition Good; possibly a 4-square house with 1-story addition.

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	19	to	27 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1141
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 2014 Pat St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1142
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2018 Pat St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description New siding.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1143
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2112 Pat St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1144
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 1002 Peach 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 33 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; clipped gable roof with composition shingles; metal porch supports, wood door; windows 2/2 aluminum replacement; addition at rear.

11. Present Condition Good; windows altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		39	4	to 39	4
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1145
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1915-25
 Address 1501 Pearl 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick foundation; irregular plan with symmetrical front; hip roof with large hipped dormers on north, east, and south sides, deep eaves, composition shingles; 1-story porch on three sides of the front facade with paired slender Doric columns, plain wood railing, columns rest upon brick piers, 2 entry doors wood paneled with upper glass light, transom lights above, 4 multipaned French doors on front porch with stained glass transom lights; windows are 1/1 wood double-hung with cornstalk muntin pattern on

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 35 18 to 35 18
 Other _____ to _____
 _____ to _____

Continuation sheet

10. upper sash; windows on east facade dormer are recessed, flanked by Doric columns; chamfered bay on south facade, 1-story addition at rear; detached garage at rear; very large trees in yard, which slopes down away from the street.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1146

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 2110 Pearl St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; clipped gable roof with composition shingles, extended rafter and beam ends; extended porch with boxed wood columns on brick piers, wood entry door; 1/1 wood double-hung windows.

11. Present Condition Fair - Good; altered by asphalt drives and back yard.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	19	to 35	19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1147

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 2116 Pearl St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; extended entry porch with wood post supports, two wood and multipaned glass doors; windows 6/6 wood double-hung; detached carport on side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	20	to	35 20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1148
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 2123 Pearl 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Vacant
 10. Description _____

11. Present Condition Poor; severely deteriorated roof.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1149
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 2215 Pearl St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1150
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-35
 Address 2216 Pearl 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Apartments
 10. Description 2-story; wood frame.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1151
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 2222 Pearl St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; intersecting gable roofs with extended rafter ends, knee brackets, composition shingles; extended porch with boxed wood columns, wood paneled door with upper glass light, screen door; windows 6/6 wood double-hung; detached wood frame garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	21	to	35 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1152
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 2229 Pearl St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Vacant/For Sale
 10. Description _____

11. Present Condition Fair; porch supports replaced by pipe columns.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1153

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920s

Address 2307 Pearl 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot City Block 50 Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; brick foundation; rectangular plan; clipped gable roofs with shed dormer across front, composition shingles, interior brick chimney; extended porch with boxed wood columns, wood entry door with rectangular glass lights; windows 3/1 wood double-hung; porte cochere on south.

11. Present Condition Fair; roof is in poor condition.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		35	22	to	35	22
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1154
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2401 Pearl 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered by additions on the north.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1155
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 2410 Pearl 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; brick pier foundation; gable roofs with composition shingles, extended rafter ends; small porch with canopy supported by boxed columns, wood panel entry door with upper glass light, applied scroll ornamentation; windows 1/1 wood double-hung, in pairs.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		35	23	to	35 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1156

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 2501 Pearl 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roof with knee braces, extended rafter ends, composition shingles; inset porch with boxed wood columns, 2 entry doors at 90 degrees, wood paneled with three upper glass lights; windows 4/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		35	24	to	35	24
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1157
City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
Address 2504 Pearl 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by aluminum replacement windows, asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1158

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 2509 Pearl 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 Present Use Residence

10. Description 1-story; wood frame with wide horizontal board siding; brick foundation; irregular plan; gable roofs with composition shingles; extended porch with box columns, wood and multipane glass door; windows 3/1 wood double-hung; secondary entry on south with multipane glass and wood door; detached wood frame garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	2	to	36 2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1161

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1940

Address 2601 Pecan St. North 7. Architect/Bullder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot MCJohnsonS/D, City Block 50, Lot 29-A Present Use Residence

10. Description 1-1/2 story; wood frame structure with asbestos siding; brick foundation; rectangular plan; straight side-facing gable roof with eyebrow over porch with paired stylized beam ends and brackets; composition shingles; extended porch without roof, brick piers and low brick wall; concrete steps; windows 3/1 double-hung in singles, doubles, and triples; entry door wood and multipaned glass; large juniper tree on corner.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1985		3	10	to	3	10
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1162
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2700 Pecan St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot M.C. Johnson S/D, City Block 50, Lot 16 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; intersecting gable roofs with faceted extended beam ends and rafter ends, composition shingles; inset porch with brick columns, wood floor; windows 6/1 wood double-hung; singly and in pairs; brick chimney on west exterior; wood and multipaned glass entry door; detached garage at northeast corner.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	9	to 3	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1163
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 2715 Pecan St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot M.C. Johnson S/D, City Block 50, Lot 5 9. Original Use Residence
 Present Use Residence

10. Description 1-1/2 story; wood frame structure with lapped horizontal siding; brick foundation; rectangular plan with bay projection to south; clipped gable roof with composition shingles; porch with shed roof, decorative iron posts, brick floor and steps; entryway brick wall with single wood paneled door; stylized Corinthian pilasters at door; windows 6/1 in pairs and triples.

11. Present Condition Good; altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	8	to 3	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1164

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935

Address 2825 Pecan St. North at Pine 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Prairie-style Bungalow

4. Block/Lot North Mound Pl S/D, City Blk 50, Lt 7-A 9. Original Use Residence

Present Use Residence - Apartments

10. Description 2-story; wood frame construction with bull-nosed siding; brick foundation; massed plan; straight front-facing gable roofs with faceted beam ends, extended rafters, decorative panels at second story under eave, deep overhangs, composition shingles; extended asymmetrical wraparound porch on the northeast; simple post columns with capitol and base, and stick railing; windows 4/1, 5/1, 7/1 wood double-hung, singly and in pairs; 2 entry doors wood with upper vertical glass lights; attached carport at northwest corner; porch floor is wood, steps brick; brick apron

11. Present Condition _____

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		3	6	to 3	6
Other					to	
					to	

Continuation sheet

10. around foundation.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1165

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 2915 Pecan St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Nelson 1st S/D, City Block 50, Lot 8 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick pier foundation; rectangular plan; straight front-facing gable roof with clipped gables, extended beam ends and composition shingles; porch stoop with small clipped gable roof, concrete and brick porch and steps; windows 6/6 wood double-hung in pairs; entry door wood with multipane glass lights.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1985		3	7	to	3	7
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1166
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3004 Pecan St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot North Mound Pl S/D, City Block 50, Lot 40 Present Use Residence

10. Description 1-story; wood frame construction with asbestos siding and brick skirt; rectangular plan; straight side-facing gable roof with smaller gable and shed roof intersecting, composition shingles; projecting porch stoop with wrought iron corner posts, concrete floor and steps; windows 3/1 wood double-hung, in pairs, attached carport to south; single entry door with fluted pilaster trim.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1985 _____ 3 5 to 3 5
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1167
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 3201 Pecan St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 67 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick pier foundation; rectangular plan; straight front-facing gable with exposed beam ends, composition shingles; inset porch to southeast, with corner post, wood floor and steps; windows 1/1 double-hung in singles and pairs, two wood paneled entry doors; carport at rear.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved _____ Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1985		2	24	to 2	24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1168

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 3205 Pecan St. North 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot City Block 67 Present Use Residence

10. Description 1-story; wood frame construction with bull-nosed siding; brick pier foundation; rectangular plan; straight front-facing gable roof with knee brackets and extended beam ends; composition shingles; inverted porch on southeast with wood floor and steps; windows 1/1 wood double-hung; single entry door with glass light above.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date November 13, 1985

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1985		2	23	to	2	23
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1169
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 604 Perry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot North part of Lot 5, Block 66 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1170
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 613 Perry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot North part of Block 5-C, City Block 66 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1171
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 614 Perry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66, South part of Lot 5 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1172

City/Rural Nacogdoches UTM Sector _____

2. Name Jeff T. Deason, Atty 6. Date: Factual _____ Est. 1930-40s

Address 111 Pilar St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 25, Lot 2-A 9. Original Use Residence

Present Use Office

10. Description 1-story frame with drop siding; composition hip-and-gable roof has extended rafter ends and braces; projecting porch has king and queen post motif in gable; projecting porch supported by wood columns; entry door has three lights; windows are 3/1 wood double-hung; foundation skirted.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		28	24	to	28	24
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1173
 City/Rural Nacogdoches UTM Sector _____
 2. Name Ford Studio 6. Date: Factual _____ Est. 1900-20
 Address 201 Pilar St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 25, Lot 1-B Present Use Commercial
 10. Description 2-story frame with lap siding; massed plan; composition hip roof with wide eaves; windows are 2/2 wood double-hung; porch has been replaced with entry studio; brick pier foundation.

11. Present Condition Fair; altered.
 12. Significance Significant early twentieth century style; structure has been altered on the main facade.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

YEAR	DRWR	ROLL	FRME	ROLL	FRME
1986		29	2	to 29	2
				to	
				to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1174
 City/Rural Nacogdoches UTM Sector _____
 2. Name Randy's Auto Repair 6. Date: Factual _____ Est. 1930s
 Address 211 Pilar St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 25, Lot 1-A Present Use Commercial
 10. Description 1-story load-bearing; rectangular plan; gable sheet metal roof; overhead door entry.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		29	5	to	29	5
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1175

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 408 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Block 21, Lot 3 Present Use For Rent

10. Description 1-story frame with large brick basement; lap siding; composition gable roof with extended rafter ends; inset porch has been glassed in; brick columns at each corner; windows are 1/1 wood double-hung.

11. Present Condition Good; main facade has been significantly altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		29	19	to	29 19
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1176
 City/Rural Nacogdoches UTM Sector _____

2. Name East Texas Legal Services, Inc. 6. Date: Factual _____ Est. 1900
 Address 414 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Queen Anne Victorian
 9. Original Use Residence

4. Block/Lot Block 21, Lot 4 Present Use Office

10. Description 2-story frame with lap siding; composition hip roof; massed plan projecting chamfered bay ; inset porch has turned columns, bannister, and frieze; all windows have been replaced, have horizontal muntin to resemble double-hung; hood molds and brackets also appear new; large basement at rear; driveway and parking on north and east facades.

11. Present Condition Good; significantly altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

PHOTO DATA
 NR: /RTHL /HABS (no.) TEX- _____ B&W 4 x 5s _____ slides _____
 /Individual /Historic District
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	20	to	29 20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1177
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1890-1900
 Address 504 Pilar St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Ell Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 20, Lot 6 Present Use Burned
 10. Description 1-story frame; burned during survey and has been demolished.

11. Present Condition Burned
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1178

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 512 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 20, Lot 5 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; inset porch supported by wood columns; windows are 4/1 wood double-hung with surrounds; brick pier foundation and skirt; rectangular plan.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	21	to	29 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1179

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890

Address 520 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Greek Revival

4. Block/Lot Block 20, Lot 4 Present Use Residence

10. Description 1-1/2 story frame with lap siding; composition gable roof; central hall plan; blind pilasters at each corner; windows are 4/4 wood double-hung with pedimented hood molds; entry has side lights and transom; projecting porch supported by slender boxed columns; addition on east facade; brick pier foundation.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	22	to	29 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1180

City/Rural Nacogdoches UTM Sector _____

2. Name Gully 6. Date: Factual _____ Est. 1880-1900

Address 526 Pilar St. East 7. Architect/Builder _____

3. Owner Mr. and Mrs. Arnold Gully Contractor _____

Address 526 Pilar St. East 8. Style/Type Victorian Cottage

4. Block/Lot Block 20, Lot 3 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition hip-and-gable roof with cornice returns, bargeboard in gables; wraparound porch has turned columns and bannister; 3 entry doors onto porch, main entry has large light and side lights; brick pier foundation has laticework; windows are 1/1 wood double-hung with hood molds; decorative screen doors; projecting chamfered bay on main facade; extensive landscaping.

11. Present Condition Excellent

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography 1975 THC Survey

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	23	to	29 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1181
 City/Rural Nacogdoches UTM Sector _____

2. Name Robert A. Goodwin 6. Date: Factual _____ Est. 1870-90
 Address 536 Pilar St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Greek Revival

4. Block/Lot Block 20, Lot 2 Present Use Office
 9. Original Use Residence

10. Description 1-story; frame with lap siding; central hall plan; composition gable roof has cornice returns; 1 exterior chimney on west facade; blind pilasters on each corner of main facade; windows are 4/4 wood double-hung with decorative hood molds, windows on porch are 1/1 wood double-hung; projecting porch is supported by turned columns, simple bannister; entry has side lights and transom; foundation is brick pier with lattice; modern deck at rear.

11. Present Condition Good; some alterations.

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		29	24	to	29
Other					to	24
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1182
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1502 Pilot 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1183
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1514 Pilot 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1184
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1516 Pilot 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1185
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1519 Pilot 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1186
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1529 Pilot 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1187

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-36

Address 203 Pine 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot City Block 50 Present Use Residence

10. Description 1-story; wood frame wih bull-nosed siding; brick pier foundation with lattice infill; gable roofs with extended rafter and beam ends, composition shingles; extended porch with short battered columns resting on brick piers, simple wood rail and verticals for screening, entry door is wood and multipane glass; windows are 3/1 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District _____ B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource _____ 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	8	to	27 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1188
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 102 Popp St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Lot 45-C Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		33	7	to	33	7
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1189

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 110 / 108 Popp St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot 45-B 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with steel applied siding; composition gable roof with extended rafter ends; projecting wood porch supported by brick columns; windows are 4/1 wood double-hung; porte cochere on north side; foundation skirted with brick; rectangular plan.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		12	24	to	12	25
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1190

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 109 Popp 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 42, Lot 44-A-1 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with beveled siding; concrete block foundation; rectangular plan; gable roof with extended rafter ends and brackets, composition shingles; shed roof over small porch with chamfered 4 x 4 posts, 2 wood multipaned glass entry doors; windows 6/6 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site Possibly

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		12	23	to	12	23
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1191

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 118 Popp 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 42, Lot 45-A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan with porte cochere on north; hip roofs with deep overhang, extended rafter ends, composition shingles; porch across front with brick columns and battered boxed columns over brick piers, central entry door; windows 4/1 wood double-hung; 1 exterior chimney on north, 1 interior brick chimney on south

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	22	to	12 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1192
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1890-1900
 Address 123 Popp St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot OL 29-C Present Use Residence

10. Description 1-story frame with lap siding; composition gable roof with cornice returns, two exterior end chimneys; projecting concrete porch with balcony rail; supported by boxed columns; windows are 4/4 wood double-hung with hood molds; carport addition at rear.

11. Present Condition Fair; numerous alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 21 21 to 21 21
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1193
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 203 Popp St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 42, Lot OL-54-D Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1194
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 218 Popp St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 42, South half of Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1195
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 300 Popp St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Berger S/D (48), Block 42, Lot 18-A Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1196
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 318 Popp St. North 7. Architect/Bullder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Berger S/D (48), City Block 42, Lot 22-B 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; gable roof with composition shingles, extended rafter ends and knee braces; projecting porch with metal columns; windows 6/6; entry door with six lights over paneled wood.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	20	to 12	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1197
City/Rural Nacogdoches UTM Sector _____
2. Name _____ 6. Date: Factual _____ Est. _____
Address 416 Popp St. South 7. Architect/Builder _____
Contractor _____
3. Owner _____ 8. Style/Type Bungalow
Address _____ 9. Original Use Residence
4. Block/Lot CCWestmoreland S/D, City Block 42, Lot 8 Present Use Residence
10. Description _____

11. Present Condition Good
12. Significance _____
13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

 /RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
					to		
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1198
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-38
 Address 1203 Porter 7. Architect/Builder _____
 Contractor _____
 3. Owner Mr. & Mrs. Arnold 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 53, Lot 44 Present Use Residence
 10. Description 1-story; wood frame with vinyl siding; brick pier foundation; rectangular plan with inset corner porch; gable roof with composition shingles, extended rafter ends; windows 1/1, 4/4, wood double-hung.

11. Present Condition Good; altered by vinyl siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1199

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 1207 Porter 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot PorterS/D(473), City Block 53, Lot West 3 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; irregular plan; brick pier foundation; intersecting hip-and-gable roof with extended rafter ends, and composition shingles; inset porch with corner boxed column; 2 wood paneled entry doors with upper glass light; windows 1/1 wood double-hung arranged in pairs, awnings over some windows.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1200
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 1211 Porter 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Porter S/D (473), City Block 53, Lot 3-4-A Present Use Residence
 10. Description _____

11. Present Condition Fair - Good; altered by vinyl or alumiaum siding, metal porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1202
 City/Rural Nacogdoches UTM Sector _____
 2. Name Raguet Day Care 6. Date: Factual _____ Est. 1910-30
 Address 309 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 1 Present Use Day Care School

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces, several dormers; massed plan; windows are 4/1 double-hung; several porches on front and sides are supported by boxed columns; multiple light doors; brick pier foundation; 1 central brick chimney.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 33 20 to 33 20
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1203
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 320 Powers 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot _____ 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles, extended beam ends; extended porch with boxed wood columns, wood panel entry door with upper glass light; windows horizontal 2/2 sash double-hung windows; detached frame garage.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		33	21	to	33 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1205
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 711 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1206
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 802 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner Green 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 15-B Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1207
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1219 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43, Lot OL 8-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1208
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1405 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42 Present Use Residence
 10. Description _____

11. Present Condition Fair; siding altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1209
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1600 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, S/D of Lot 16-D (005) Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1210
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1610 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1211
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1621 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43, Lot 24, S/D of Lot 16-D (005) Present Use Residence
 10. Description _____

11. Present Condition Fair, altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

	/RTHL	/HABS (no.)	TEX-		PHOTO DATA
NR:	/Individual	/Historic District		B&W 4 x 5s	slides
	/Thematic	/Multiple-Resource		35 mm Negs.	
NR File Name				YEAR DRWR ROLL FRME	ROLL FRME
Other					

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1212
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1910 Powers 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 17, S/D Lot 16-E (006) Present Use Residence
 10. Description _____

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1213
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2716 Press Road (at Hunter) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow Farm Complex
 Address _____ 9. Original Use Residence & Farm Complex
 4. Block/Lot Block 56 Present Use Residence & Farm Complex
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1214
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 618 Price 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot Price-Sturdevant S/D (479), City Blk 4, Lt 2 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1215
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 619 Price 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Craftsman Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Price-SturdevantS/D(479), City Blk 4, Lt 13 Present Use Residence
 10. Description 1-story T-plan frame residence with cross-gable composition shingles roof; horizontal bull-nosed siding; 6/6 double-hung windows; hall parlor plan with twin multilight entry doors off small poured concrete porch with box columns, gable roof; side entry on each side; possibly a duplex.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		22	6	to	22	6
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1216
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 918 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 55-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1217
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1009 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 51-B Present Use Residence
 10. Description 1-story rectangular fram residence with composition shingles straight-gable roof; horizontal V-groove siding; 1/1 double-hung windows; knee braces; box columns on wood porch; glass panel entry door.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 26 22 to 26 22
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1218
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1014 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 54-A Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District * B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1219
 City/Rural Nacogdoches UTM Sector _____
 2. Name Malcomb K. Lyon, D.O. 6. Date: Factual _____ Est. _____
 Address 1017 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 50-C Present Use Residence
 10. Description _____

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1220

City/Rural Nacogdoches UTM Sector _____

2. Name Hannicutt House 6. Date: Factual _____ Est. 1938

Address 1210 Raguet 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neoclassical

4. Block/Lot BlountEstS/D(066), CityBk45, Bk3, Lts7&9 9. Original Use Residence

Present Use Residence

10. Description 2-story modified H-plan brick residential structure with hip-and-valley clipped gable roof with multiple dormer attic vents; composition shingles; 8/8 and 6/6 double-hung windows; recessed entry with wood panel door with fanlight with tracery, fluted pilasters, and molded frontispiece; decorative brick courses on projecting bays.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	23	to	26 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1221
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1302 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Gothic Revival
 Address _____ 9. Original Use Residence
 4. Block/Lot BlountEstS/D(066), CityBk 45, Bk 2, Lt 15 Present Use Dental Office
 10. Description 1-story irregular plan brick residential structure with multigabled cedar shake roof; 6/6 double-hung windows; arched entry door in arched alcove; glassed-in porch on south side.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		26	24	to	26 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1222
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 2719 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by aluminum replacement windows, asbestos siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1223

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 2807 Raguet 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 50 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with brick veneer; brick foundation; irregular plan; intersecting gable roofs, composition shingles; inset porch with metal support; windows 8/8 wood double-hung with shutters; multipane picture window; garage turned into garden room with multipane windows; tennis courts on east side of block.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	7	to 27	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1224
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-45
 Address 2909 Raguet 7. Architect/Bullder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 50 Present Use Residence
 9. Original Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roofs with wood shingles; brick porch steps with arched hood (wood) over wood paneled entry door; windows 6/6 wood double-hung; interior brick chimney.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	10	to	27 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1225
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 2910 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular I-House
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence

10. Description 2-story; brick; I-plan with one-story addition and attached garage to north; steep gable roof with cornice returns, wood shingles, exterior brick chimneys at north and south with corbeled chimney cap; 3-bay facade, central entry with classical pediment and pilasters; multipaned double-hung windows with shutters; extensive grounds, stream in front yard near street.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	11	to 27	11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1226
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 3028 Raguet and Austin 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description 2-story; wood frame with wood shingles; brick foundation; rectangular plan; gabled roof with shed dormer across front, wood shingles, interior brick chimney at rear; porch across front with boxed columns; windows 1/1 wood double-hung; attached carport on west.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		27	12	to	27	12
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1227
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 3102 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roof with composition shingles, exterior brick chimney on west (front) facade; inset side entry with metal porch support; windows 3/1, 6/6 wood double-hung with shutters.

11. Present Condition Good; late 1930s or early 1940s addition on north, compatible with rest of house.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	13	to	27 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1228
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 3116 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Tudor Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; brick foundation; irregular plan; steep gabled roofs with composition shingles, plastered exterior chimney on west (front) facade; awning over entry door; awnings over multipane wood frame windows; detached garage.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	14	to 27	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1229
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1940
 Address 3208 Raguet 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Classical Revival
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 67 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1230

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-40

Address 3516 Raguet 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neoclassical

9. Original Use Residence

4. Block/Lot Block 67 Present Use Residence

10. Description 1-1/2 story; wood frame with wood shingle siding; masonry foundation; irregular plan; intersecting gable roofs with cornice returns, gabled dormers, wood shingles, interior brick chimney; porch across front with boxed columns, ornate wood railing on flat roof, arched entry with paneled wood door, transom and sidelights, windows 6/6 wood double-hung with hood mold, Palladian windows arrangement at south gable end, second floor.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		27	15	to	27	15
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1231
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1611 Railroad 7. Architect/Bulder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 57 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick apron at front; rectangular plan; clipped gable roof with composition shingles; extended portico with arch entry, paired boxed columns; windows 1/1 wood double-hung.

11. Present Condition Good
 12. Significance Street associated with Frost/Johnson Lumber Mill and railroad grade immediately east of the street.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Mrs. Geraldine Brown
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		18	23	to	18	23
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1232
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 1625 Railroad 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 57 Present Use Residence
 10. Description 1-story frame with bull-nosed siding, ell plan; intersecting hip-and-gable roof with composition shingles; inset porch with 4 x 4 corner post; windows 1/4, 1/1, 4/4 wood double-hung.

11. Present Condition Poor
 12. Significance Street associated with Frost/Johnson Lumber Mill and railroad grade immediately east of the street.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Mrs. Geraldine Brown
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 18 22 to 18 22
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1233
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1801 Railroad 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 57 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Mrs. Geraldine Brown
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1234
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1811 Railroad 7. Architect/Builder _____
 Contractor _____
 3. Owner Raymond Gasaway 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 57 Present Use Residence

10. Description 1-story frame with bull-nosed siding and 105 siding; composition gable roof with extended rafter ends; projecting porch has iron columns; pier and beam foundation; windows are 1/1 wood double-hung.

11. Present Condition Good
 12. Significance Street associated with Frost/Johnson Lumber Mill and railroad grade immediately east of the street.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant Mrs. Geraldine Brown
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		18	21	to	18	21
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1235

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30

Address 926 Randall 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame; concrete block pier foundation; rectangular plan; gable roof with composition shingles; inset porch with 4 x 4 post, plain 2 x 4 railing; wood paneled door; 4/1 wood double-hung windows.

11. Present Condition Good; altered porch; appears to have been partially filled in with additional rooms.

12. Significance _____

13. Relationship to Site: Moved Date _____ Possibly _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1236
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1604 Rayburn 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1237

City/Rural Nacogdoches UTM Sector _____

2. Name Gene Low 6. Date: Factual _____ Est. _____

Address 1722 Rayburn 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Greek Revival

4. Block/Lot Block 59 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with horizontal board siding; rectangular plan; gable roof with wood shake shingles; exterior brick chimney on northeast; inset porch with boxed columns; central entry double doors wood sidelights and transom light; pier and beam foundation; windows 6/6 wood double-hung with hood mold shutters.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		19	12	to	19	14
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1238
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30s
 Address 1913 Rayburn 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence

10. Description 1-story frame with lap wood siding; rectangular plan; clipped gable composition roof with extended rafter ends; windows are 3/1 wood double-hung; pier and beam foundation; garage on south side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	15	to	19 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1239

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-20

Address 1915 Rayburn (South of 1913) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Neoclassical

9. Original Use Residence

4. Block/Lot Block 59 Present Use Residence

10. Description 2-story frame with horizontal board siding; rectangular plan; brick pier foundation with galvanized metl skirt; gable roof with composition shingles, hip roof over sunporch on south; shallow classical entry with deep entablature, Doric pilasters, multipaned glass and wood door; 3-bay facade; windows 1/1, 2/2 wood double-hung with screens with multiple muntins; arched fan light over small windows above the classical entry; sunporch on south with paired Doric columns, glassed in; windows arranged in twos and threes.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		19	16	to	19	16
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1240
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1940s
 Address 2407 Rayburn 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1241
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40s
 Address 2515 Rayburn 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends; inset porch with boxed columns; 1/1 wood double-hung windows arranged in pairs; carport on north.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 19 _____ 18 _____ to 19 _____ 18 _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1242
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 2607 Rayburn Road (at city limits sign) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence/Farm Complex
 4. Block/Lot Block 59 Present Use Residence/Farm Complex
 10. Description _____

11. Present Condition Vacant
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1243
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 714 Ready 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 65 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1244
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 316 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18-B Present Use Residence
 10. Description Twin to 314 Richardson.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1245
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 322 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18-A Present Use Residence

10. Description 1-story rectangular frame residence with horizontal V-groove center metal siding; gable sheet metal roof; 4/1 double-hung windows; dirt-floor porte cochere on north wall; small wood entry porch on west wall; glass panel entry door with dentils below glass.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	2	to	37 2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1246
 City/Rural Nacogdoches UTM Sector _____
 2. Name Oscar Tigner 6. Date: Factual _____ Est. _____
 Address 408 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Craftsman/Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-C Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1247
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 410 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-D Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1248
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 414 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-E Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1249
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 416 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 11-E Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1250
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 500 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 6 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1251
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 504 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 6 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 36 21 to 36 21
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1252
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 508 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 6 Present Use Residence
 10. Description Twin to 509 Richardson.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNFIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1253
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 314 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 18-B Present Use Residence

10. Description 1-story rectangular frame residence with straight-gable sheet metal roof; Horizontal bull-nosed siding; small 4/4 double-hung windows; inset wood porch with wood panel door; 4 x 4 porch post.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	3	to 37	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1254
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 315 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 12-F Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1255
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 319 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 12-E Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1256
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 407 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 10-B Present Use Residence
 10. Description 1-story T-plan frame residence with composition shingle crossed-gable roof; horizontal V-groove siding; 6/6 double-hung windows; small pent roof wood porch; six-light wood panel entry door.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		36	24	to	36	24
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1257
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 411 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 9-C Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle hip roof; horizontal bull-nosed siding; 1/1 double-hung windows; full-width wood porch with box columns; dormer with clipped gable over porch.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		36	23	to	36	23
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1258
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 415 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 9-D Present Use Residence

10. Description 1-story rectangular frame residence with hipped composition shingle roof; horizontal bull-nosed siding; 12/12 double-hung windows; full-width wood porch with box columns; gabled dormer over porch; central brick chimney; brick piers; multilight entry door, off center.

11. Present Condition Good

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		36	22	to	36 22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1259
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 501 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 5 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1260
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 505 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 5 Present Use Residence

10. Description 1-story rectangular frame residence with sheet metal saltbox roof; vertical board and batten siding; 4/4 double-hung windows; skirt-roof wood porch; 4 x 4 porch posts with stopped chamfers; hall parlor plan; central brick chimneys; twin to 510 Richardson.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1261
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910
 Address 509 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 5 Present Use Residence

10. Description 1-story rectangular frame residence with hip sheet metal roof; horizontal V-groove siding; 4/4 double-hung windows; central brick chimney; hall parlor plan with wood panel entry doors off full-width porch with 4 x 4 posts.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1262
City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
Address 510 Richardson 7. Architect/Builder _____

3. Owner _____ Contractor _____
Address _____ 8. Style/Type Vernacular

4. Block/Lot City Block 5, Lot 6 9. Original Use Residence
Present Use Residence

10. Description 1-story rectangular frame residence with saltbox sheet metal roof; vertical board and batten siding; 4/4 double-hung windows; skirt-roof wood porch with 4 x 4 posts with stopped chamfers; hall parlor plan; central brick chimney; twin to 505 Richardson.

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1263
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 511 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 5 Present Use Residence
 10. Description Twin to 505, 510 Richardson.

11. Present Condition Deteriorated
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1264
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 514 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 6 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1265
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 518 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 6 Present Use Residence
 10. Description Twin to 505, 510, 511, 523, 525 Richardson.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1266
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 523 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 5 Present Use Residence
 10. Description Twin to 505, 510, 511, 518, 525 Richardson.

11. Present Condition Deteriorated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1267
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 525 Richardson (Across from 526 Richardson) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 5, Lot 5 Present Use Residence
 10. Description Twin to 505, 510, 511, 518, 523 Richardson.

11. Present Condition Deteriorated.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1268
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 526 Richardson 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 6, Lot 6 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1269
 City/Rural Nacogdoches UTM Sector _____
 2. Name New Hope Baptist Church 6. Date: Factual _____ Est. _____
 Address 905 Ritchie 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Church
 4. Block/Lot Block 66 Present Use Church
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1270
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 903 Ritchie 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 66 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1272
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 213 Rudolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Burger S/D (48), Block 42, Lt 8 (South 1/2) Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1273
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 214 Rudolph 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Burger S/D (48), Block 42, Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1274
 City/Rural Nacogdoches UTM Sector _____
 2. Name Fulmer Motor Company 6. Date: Factual _____ Est. _____
 Address 115 Rulfs St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Modern
 Address _____ 9. Original Use Commercial
 4. Block/Lot _____ Present Use Commercial
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1275
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1890s
 Address 122 Sanders St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 49 Present Use Residence

10. Description 1-story frame with lap siding; ell plan; intersecting asphalt gable roof pierced by 1 exterior brick chimney on north facade; inset ell porch supported by turned columns, simple balustrade; ornate screen door; concrete steps; windows are 14/4 wood double-hung with hood molds; foundation skirted with open lattice brick; cornice returns; no bargeboard.

11. Present Condition Fair; currently being renovated; several alterations.

12. Significance Excellent example of architectural style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		9	5	to 9	5
Other _____			10	23	to 10	24
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1276
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 129 Sanders St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Bloc 35, Lot 2 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with boxed cornice, composition shingles; extended porch with cylindrical columns; windows 4/1 wood double-hung with shutters, burglar bars on the front; central entry door wood paneled with an upper glass light; detached wood frame garage with similar details.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		9	6	to	9	6
		10	22	to	10	22
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1277

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935

Address 132 Sanders St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot Block 35 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; clipped gable roofs with cornice returns, composition shingles; extended portico with arched entry and deep entablature resting on cylindrical columns; single entry door with screen door; windows 6/6 wood double-hung; porte cochere on south; interior brick chimney.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		9	7	to 9	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1278
 City/Rural Nacogdoches UTM Sector _____
 2. Name Powers 6. Date: Factual _____ Est. 1920s
 Address 135 Sanders St. North 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Hillenkamp S/D (271), Lot 2, City Block 43 Present Use Residence
 10. Description 1-story frame with wood bull-nosed siding; asphalt shingle gable roof with extended rafter ends; projecting gable front porch supported by a pair of 3 posts and low bannister; windows are 1/1 wood double-hung; garage of similar style at rear; concrete steps; skirted foundation.

11. Present Condition Good; several additions at rear.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		9	4	to 9	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1279

City/Rural Nacogdoches UTM Sector _____

2. Name The Quicks 6. Date: Factual _____ Est. 1890s

Address 220 Sanders St. South 7. Architect/Bullder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot A.V. Sanders S/D(S20), Lot 7 City Block 35 9. Original Use Residence

Present Use Residence

10. Description 2-1/2 story; wood frame w/ bull-nosed siding; brick foundation; rectangular plan; hip-and-gable roof, pedimented gable ends with patterned shingles, composition shingles; 1-story porch across the front with cylindrical columns and plain entablature, pedimented gable end over the entry; aluminum replacement windows, some with hood molds, balanced placement of windows on the facade; central wood entry door with large oval light and matching sidelights, spindlework framing the screen door; two interior brick chimneys with corbeled caps; on front facade at gable

11. Present Condition Good; altered windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		9	3	to 9	3
Other			10	21	to 10	21
					to	

Continuation sheet

10. end, one small fixed window with diamond panes.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1280
 City/Rural Nacogdoches UTM Sector _____
 2. Name Casey Jones Plumbing 6. Date: Factual _____ Est. 1950s
 Address 815 Sarah Anne 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Ranch Style
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 67 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance Good example of type; ranch-style home, brick with prairie-style characteristics.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 27 20 to 27 20
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1281

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 220 Seale St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow & Garage Apartment

4. Block/Lot Block 48, Lot 25 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; irregular plan; gable roofs with extended rafter and beam ends, composition shingles; extended porch with slender boxed columns resting on a low brick wall; two entry doors wood with long rectangular glass lights, screen doors; windows 9/9 wood double-hung; exterior brick chimney on east, 2-story garage/apartment with similar detailing.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1282

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925

Address 302 Seale (Corner of Seale & Hackberry & S. Fredonia) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; hip roof with corner porch gable, extended rafter and beam ends; composition shingles; rectangular plan; inset corner porch, now glassed in, boxed columns over brick piers; windows 3/1 wood double-hung arranged in pairs.

11. Present Condition Good; corner porch glassed in.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1283

City/Rural Nacogdoches UTM Sector _____

2. Name J. Homer King 6. Date: Factual _____ Est. 1930s

Address 314 Scale St. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with asbestos siding on upper floor; stucco on ground floor; gable roofs with composition shingles, extended rafter ends, knee braces; inset porch with arched openings, large rectangular porch support, side-facing entry door; windows 1/1 wood double-hung.

11. Present Condition Good; altered by mixture of sidings.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1284
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40
 Address 320 Seale St. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by asbestos siding, metal porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1285
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 321 Seale St. West 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 56 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with knee braces, extended rafter ends; composition shingles; extended porch with built-up corner posts; wood paneled entry door with upper glass; windows 1/1 wood double-hung; detached garage.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1286
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 324 Seale 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good; altered by asbestos siding and metal porch supports.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1287

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 329 Seale St. West 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Cottage

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; extended porch with boxed wood columns; two entry doors; detached apartment at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1288
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 502 Scale St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 10-A Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with extended rafter ends, composition shingles, exterior brick chimney on east; porch cover supported on ornamental knee braces; centered entry door; windows 1/1 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1289
 City/Rural Nacogdoches UTM Sector _____
 2. Name T. J. Rogers 6. Date: Factual _____ Est. 1935
 Address 1220 Seale St. West 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, S/D of Lot 59, Lot 9 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1290
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1610 Seale St. West and Tindall 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48 Present Use Residence
 10. Description _____

11. Present Condition Poor; windows altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 31, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1291
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 707 Second 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot ADHaltomS/D(78), CityBk 62, Bk 2, Lt 4A Present Use Residence
 10. Description _____

11. Present Condition Fair; altered by 2/2 aluminum replacement windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1292
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 715 Second 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ADHaltonS/D(78), CityBk 62, Bk 2, Lt 5B Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; extended porch with brick columns; windows 2/2 aluminum replacement windows; central entry door with storm door.

11. Present Condition Fair; altered by aluminum replacement windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1293
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 910 Second 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Residence

4. Block/Lot ADBrewerS/D(78), CityBk 62, Bk 7, Lt 5-C Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with extended rafter ends, composition shingles; inset porch with metal support; 2 wood entry doors with diamond light, set at 90 degrees; windows 6/6 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1295
 City/Rural Nacogdoches UTM Sector _____
 2. Name Dorsey Brown 6. Date: Factual _____ Est. 1930
 Address 1010 Second 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ADHaltomS/D(78), CityBk 62, Bk 7, Lt 8D Present Use Residence
 10. Description 1-story; wood frame with asbestos shingles, roll composition siding; raised foundation; gable roof with extended rafter ends, composition shingles; inset porch with battered, boxed wood columns over brick columns (polychrome), 2 entry doors set at 90 degrees; windows 1/1 wood double-hung.

11. Present Condition Fair; recently remodeled inside, insulation installed.
 12. Significance Ms. Brown's grandparents' house.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant Mrs. Brown, resident on Second Street.
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

_____	_____	_____	_____	to	_____	_____
_____	_____	_____	_____	to	_____	_____
_____	_____	_____	_____	to	_____	_____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1296
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 115 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow - Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 51, Lot 36-V Present Use Commercial
 10. Description 2-story masonry with brick facade, stepped parapet modern entry and windows; older windows are bricked in; load-bearing brick wall.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1297
 City/Rural Nacogdoches UTM Sector _____
 2. Name Chef Latin's 6. Date: Factual _____ Est. 1930-40s
 Address 108 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 14 Present Use Commercial Restaurant

10. Description 1-story; wood frame with beveled and vertical board siding; rectangular plan; gable roof with metal roofing; canopy over 2 entry doors, wood frame picture windows on front, 1/1 wood double-hung windows.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		37	4	to 37	4
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1298
 City/Rural Nacogdoches UTM Sector _____
 2. Name Design Line Hair Studio 6. Date: Factual _____ Est. _____
 Address 107 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 36-U Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1299

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 210 Shawnee St. South (Across from Design Line) 7. Architect/Builder _____ Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Block 51, Lot 16 Present Use Residence

10. Description 1-story; wood frame with beveled siding; rectangular plan; hip roof with gable dormer, composition shingles; porch across front with boxed columns, central entry door, replacement aluminum windows.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	5	to 37	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1300
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 201 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 36-M Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1301
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 214 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 17 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; pyramidal hip roof with sheet metal roofing; porch across front with post supports; windows 4/4, 1/1; wood panel entry doors.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	6	to 37	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1302
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 216 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 18 Present Use Residence
 10. Description 1-story frame with lap siding; hip-and-gable composition roof pierced by one chimney stack; 6/6 wood double-hung windows with shutters.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	7	to 37	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1303
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 302 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 19 Present Use Residence
 10. Description 1-story frame with board and batten siding; gable sheet metal roof; shed porch supported by wood posts; pier and beam foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		37	8	to	37	8
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1304

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 304 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 51, Lot 19 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; gable sheet metal roof; projecting porch supported by wood posts; windows are 1/1 wood double-hung; pier and beam foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	9	to 37	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1305

City/Rural Nacogdoches UTM Sector _____

2. Name Little Zion Baptist Church 6. Date: Factual _____ Est. 1930-40s

Address 305 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot Block 51, Lots 36-Q, 36-R 9. Original Use Church

Present Use Church

10. Description 1-story; wood frame with brick veneer, rectangular plan; front-facing gable roof with composition shingles; extended portico with battered boxed wood columns resting on brick piers; raised brick foundation; windows 6/6 wood double-hung; entry doors pair of wood paneled doors with pediment above.

11. Present Condition Good

12. Significance Dedication plaque on pedestal with large bell.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- PHOTO DATA
/Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	10	to	37 10
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1306

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 319 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 51, Lot 14-B 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; raised brick pier foundation; rectangular plan; porch across front with boxed wood columns; central entry door and side door wood paneled with upper glass; windows 1/1 wood double-hung; gable roof with composition shingles, extreme slope toward street.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		37	12	to	37	12
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1307
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 402 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 22 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1308
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 408 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 24-1 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition hip and clipped gable roof; massed plan; inset porch is screened; windows are 1/1 wood double-hung, some with awnings; extended rafter ends; pier and beam foundation.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	13	to	37 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1309
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 414 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 24-4 Present Use Residence
 10. Description 2-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with composition shingles, extended rafter and gable ends; extended 2-story gallery porch with boxed wood columns at each floor, low wall with siding at second story, columns rest on brick piers at first floor; wood windows 1/1 double-hung; wood paneled entry doors.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		37	14	to	37	14
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1310
 City/Rural Nacogdoches UTM Sector _____
 2. Name Sid Roberts Funeral Home 6. Date: Factual _____ Est. 1920-30s
 Address 503 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 52 Present Use Funeral Home

10. Description 1-1/2 story; wood frame with beveled board siding; raised brick foundation; irregular plan; hip and intersecting gable roofs with composition shingles, extended rafter ends, gabled dormers; inset porch with boxed wood columns, plain wood railing, double wood panel entry doors with upper glass light; windows 4/4, 1/1 wood double-hung; parking lot at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	15	to 37	15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1311

City/Rural Nacogdoches UTM Sector _____

2. Name Blue's BBQ 6. Date: Factual _____ Est. 1910-20

Address 515 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 51, Lot 53-1 9. Original Use Residence/Commercial

Present Use Commercial

10. Description 1-story frame with lap siding; ell plan; composition gable roof; projecting porch supported by wood columns; windows are 4/4 wood double-hung; double entry doors; ell on south side is addition.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		37	16	to	37	16
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1312
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address Shawnee St. South & Greer (corner) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 53-2 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair; altered by aluminum replacement windows, brick foundation apron.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1313
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 522 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 51, Lot 335-B Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; inset porch supported by boxed columns; windows are 4/1 wood double-hung; brick pier foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	17	to 37	17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1314
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 606 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 3-B Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1315

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 613 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 49 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; raised foundation; rectangular plan; gable roofs with extended rafter ends, knee braces, composition shingles; extended porch with metal supports over brick piers, central entry door wood paneled with four upper glass lights; windows 4/1 wood double-hung.

11. Present Condition Good; porch columns replaced by ornamental metal posts.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	18	to	37 18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1316
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 614 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 3-A Present Use Residence
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1317
 City/Rural Nacogdoches UTM Sector _____

2. Name Staaks 6. Date: Factual _____ Est. 1920-30
 Address 621 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 51 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof pierced by two chimney stacks; extended rafter ends; windows are 1/1 wood double-hung; brick pier foundation; projecting porch supported by metal columns.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	19	to	37 19
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1318

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 702 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 8 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roof with composition shingles; extended porch with pipe columns; windows 3/1 wood double-hung; porte cochere on south.

11. Present Condition Good; altered pipe column porch supports, addition on north.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		37	20	to	37	20
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1319
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 703 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 52 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good; applied siding added, other alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1320
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 709 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 53 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1321
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 802 / 806 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 24 Present Use Residence
 10. Description Three cottages on one lot.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1322
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 810 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 26-A Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof; inset porch supported by boxed columns; windows are 4/4 wood double-hung; brick pier foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	21	to	37 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1323
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 814 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 26 Present Use Residence
 10. Description _____

11. Present Condition Good; applied siding.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1324

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 818 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 27 9. Original Use Residence

Present Use Residence

10. Description _____

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1325

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1915-25

Address 819 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 53, Lot 59 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with bull-nosed siding; raised pier foundation; pyramidal hip roof with intersecting gable and tent tower over porch, composition shingles; irregular ell plan with chamfered bay; porch wraps around from west to north, turned wood columns, wood railing with ornamented top rail; wood door with arched light; windows 4/4, 1/1; porch at rear; gabled dormer on front.

11. Present Condition Good

12. Significance Moved in from the countryside within the past few years. Good example of style.

13. Relationship to Site: Moved Date Unknown Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		37	22	to 37	22
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1326
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 903 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 61 Present Use Residence
 10. Description _____

11. Present Condition Good; many alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1327

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930

Address 909 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 62 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; clipped gable roof with extended rafter and beam ends; extended porch with paired boxed columns, wood paneled door with glass light; windows 6/6 wood double-hung.

11. Present Condition Fair; roof requires repair.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		37	23	to	37	23
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1328
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 910 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Nannie Blount S/D (63), Block 53, Lot 2 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1329
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 912 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Nannie Blount S/D (63), Block 53, Lot 3 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1330

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 917 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 63 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with extended rafter ends; projecting entry with wood paneled door, small side lights; windows 6/6 wood double-hung; exterior brick chimney on west.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

	1986		37	24	to	37	24
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1331

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 920 Shawnee St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 53, Lot 30 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends, inset porch supported by brick columns; windows are 3/1 wood double-hung; brick pier foundation; shotgun at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	2	to 38	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1332
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 923 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 53, Lot 72 Present Use Residence
 10. Description _____

11. Present Condition Good; windows altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1333
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1004 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Nannie Blount S/D (63), Block 53, Lot 4-C Present Use Vacant
 10. Description _____

11. Present Condition Deteriorated

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1334
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1006 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Nannie Blount S/D (63), Block 53, Lot 4-C Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1335

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920s

Address 1008 Shawnee St. South (Corner) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Nannie Blount S/D (63), Block 53, Lot 4 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with composition shingles, extended rafter ends, knee braces, two exterior brick chimneys; extended porch with battered boxed wood columns resting upon brick piers, central door; windows 3/1 wood double-hung; detached garage in poor condition.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	3	to 38	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1336
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1110 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Cleaver S/D (129), Block 53, Lot 1336 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1337
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1114 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Cleaver S/D (129), Block 63, Lot 1336 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1338
 City/Rural Nacogdoches UTM Sector _____
 2. Name Cumberland Presbyterian Church 6. Date: Factual _____ Est. 1910-25
 Address 1128 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Gothic
 Address _____ 9. Original Use Church
 4. Block/Lot Julia Thorn S/D, Block 53, Lot 2 Present Use Church
 10. Description 1-story; wood frame with lapped board siding; brick skirt at foundation; rectangular plan; gable roof with composition shingles; projecting entry with arched opening, double wood paneled doors; lancet arched windows, with upper half boarded up, lower sash with obscure glass.

11. Present Condition Fair, windows altered.

12. Significance Informant whose name I did not get states that building was built ca. 1869; was moved to site from where school now is on Shawnee ca. 1960; once had a very tall, steeply pitched roof.

13. Relationship to Site: Moved Date ca. 1960 Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		38	4	to 38	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1339
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1313 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1340
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 1315 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1341
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 1322 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description _____

11. Present Condition Good; applied siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1342
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 1403 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Greek Revival Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Vacant
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1343
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1412 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; windows are 1/1 wood double-hung; projecting porch has boxed columns; 2 entry doors; brick pier foundation.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 38 5 to 38 5
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1344
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 1418 Shawnee St. South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick piers; ell plan; gable roof with composition shingles, knee braces; inset porch, boxed wood column; 2 entry doors at 90 degrees; windows 1/1 wood double-hung.

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 20, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ 1986 _____ 38 6 to 38 6
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1345

City/Rural Nacogdoches UTM Sector _____

2. Name Louis Byrd 6. Date: Factual _____ Est. 1920-30

Address 104 Smith 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Cottage

4. Block/Lot Block 38, Lot 5-B 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding, aluminum siding on west; irregular plan; hip roof with composition shingles, boxed cornice; small extended porch on south, porch on west, front entry doors on south wood paneled with uper glass light; windows 1/1 wood double-hung; 2 entry doors on west.

11. Present Condition Fair

12. Significance This block used to be the feedlot. Owner concerned that highway would take his house; no other houses on this block of Smith St.; before 1930 some other houses were moved onto

13. Relationship to Site: Moved Date 1925 Original Site Moved from Virginia St.

14. Bibliography _____

15. Informant Louis Byrd, 2/24/86.

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		39	22	to 39	22
Other					to	
					to	

Continuation sheet

12. street, then some additional houses were built.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1346
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 121 Smith 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board and Batten Shotgun
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 5-H Present Use Residence
 10. Description _____

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1347
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-10
 Address 125 Smith 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 5-H Present Use Residence
 10. Description _____

11. Present Condition Deteriorated; Poor.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1348
 City/Rural Nacogdoches UTM Sector _____
 2. Name Brooks 6. Date: Factual _____ Est. 1925-35
 Address 215 Smith 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lot 5-G Present Use Residence
 10. Description 1-story; wood frame with asbestos shingles; ell plan; gable roofs with extended rafter ends, composition shingles; extended porch, screened with low wall, single entry door; 3/1 wood double-hung windows.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		39	21	to	39	21
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1349
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 219, 221, 223 Smith 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Shotguns
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 38, Lots 5-A, 5-J Present Use Residence
 10. Description 1-story; wood frame with board and batten siding and vertical board siding; pier foundation; rectangular plan; gable roof with galvanized metal roofing; 223 and 219 with inset entry porch, 221 with gable roof, paneled wood door; windows 4/4 wood double-hung.

11. Present Condition Fair - Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site Possibly moved onto site.

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 1986 _____ 39 20 to 39 20
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1350
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1632 South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1351
 City/Rural Nacogdoches UTM Sector _____
 2. Name Hair Hut Antiques 6. Date: Factual _____ Est. 1930s
 Address 1822 South 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Commercial
 10. Description _____

11. Present Condition Altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1352
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3100 South St. (Behind J & J Auto Repair at Loop) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Storage
 10. Description 1-story white frame.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1353

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1210 Spokane 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Berger S/D 48, Block 42, Lot 2-A Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof; projecting poured concrete porch, decorative columns; 2 entry doors; 1/1 wood double-hung windows, foundation skirted.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		33	4	to 33	4
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1354
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1301 Spokane 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Greenwood S/D, Block 42, Lot 31 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1355

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1304 Spokane 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Berger S/D 48, Block 42, Lot 5 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; 1/1 wood double-hung windows; inset wood porch has 2 x 4 posts; foundation skirted; shed carport on east facade.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____

1986		33	5	to	33	5
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1356
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1602 Spokane 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot OL 32F Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces; 2/2 wood double-hung windows; foundation skirted.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		33	6	to	33	6
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1357
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1617 Spokane 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot OL 30-D Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1358
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1625 Spokane 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 42, Lot OL 30-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1359
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-20
 Address 764 Stallings Drive Northeast (West across
from 763) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Barn
 Address _____ 9. Original Use Farm building
 4. Block/Lot Block 54 Present Use Farm building
 10. Description Board and batten-sided barn with shed roof porch with wood posts, gable roof; side-facing with
corrugated metal roofing, lean-to shed on south; standing in field.

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

	<input type="checkbox"/> RTHL	<input type="checkbox"/> HABS (no.) TEX-	PHOTO DATA			
NR:	<input type="checkbox"/> Individual	<input type="checkbox"/> Historic District	<input type="checkbox"/> B&W 4 x 5s	<input type="checkbox"/> slides		
	<input type="checkbox"/> Thematic	<input type="checkbox"/> Multiple-Resource	<input type="checkbox"/> 35 mm Negs.			
NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1360

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 763 Stallings Drive Northeast 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow and Farm Complex

4. Block/Lot Block 54 9. Original Use Residence & Farm Complex

Present Use Residence & Farm Complex

10. Description 1-story; wood frame with asbestos siding; rectangular plan; gable roof with extended rafter ends, composition shingles; inset porch with metal porch supports; windows 6/6 wood double-hung; long wood frame shed with corrugated metal siding; small shed; stock tank in pasture.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1361

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10

Address 2000 Stallings Drive Northeast 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 54 9. Original Use Residence & Guest House

Present Use Residence & Guest House

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; intersecting hip-and-gable roofs with composition shingles; small brackets over entrance to porch, boxed wood columns with one-quarter wheel brackets and spindle fretwork, spindle railing; 1/1 windows with hood mold, shutters, oversized 1/1 on porch; exterior brick chimney on front bay. Small bungalow guest house, wood frame with bull nose siding; gable roof with composition shingles, projecting porch with wood supports.

11. Present Condition Good

12. Significance Good example of type.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 1, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1362
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 115 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 9-E Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR.	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1363

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920

Address 117 Starr Ave. East 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 9-D 9. Original Use Residence

Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle gable roof; horizontal bull-nosed siding; 3/1 and 6/1 double-hung windows; projecting chamfered bays on west wall; red brick fireplace on west wall; gabled porch with bay columns on brick piers; knee braces; porch partially screened; 9-light entry door with side lights.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		24	6	to	24	6
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1364
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 207 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Clty Block 45, Lot 9-B Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1365
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 211 Starr Ave. East 7. Architect/Bullder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 45, Lot 9-F 9. Original Use Residence
 Present Use Residence

10. Description 1-story irregular plan frame residence with composition shingle hip-and-gable roof; horizontal bull-nosed siding; 1/1 double-hung windows; gabled wood porch and flat-roofed porte cochere have battered box columns on brick piers; one column "missing" by stoop; chamfered ends on purlins.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	7	to	24 7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1366
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 301 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 9-G Present Use Residence
 10. Description Vinyl Siding.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1367
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 309 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 9-I Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1368
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 313 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 10-G Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1369
 City/Rural Nacogdoches UTM Sector _____

2. Name Christ Episcopal Church 6. Date: Factual _____ Est. 1902
 Address 502 Starr Ave. East 7. Architect/Builder Deitrich Rulfs

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Gothic Revival

4. Block/Lot BlountEstS/D(066), CityBk 45, Bk 1, Lt 1 9. Original Use Church
 Present Use Church

10. Description 1-story cross-plan brick church with cross-shaped classroom addition to east; slate gable roof with standing seam sheet metal cladding on steeple; lancet stained glass windows; pronounced headers form compound arch surrounds; corbeled cornice; corner and wall buttresses with concrete weatherings.

11. Present Condition Good

12. Significance Moved from Washington Square in 1937 and reconstructed. Congregation founded in 1848, first Protestant church in Nacogdoches.

13. Relationship to Site: Moved Date 1937 Original Site Washington Square

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	8	to	24 8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1370
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 319 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Craftsman
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 10-H Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1371
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 501 Starr Ave. East 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Greek Revival

4. Block/Lot City Block 45, Lot 13 9. Original Use Residence
 Present Use Residence

10. Description 2-story rectangular brick residence with cedar shake hip roof; 6/6 double-hung windows upstairs, 6/9 double-hung windows downstairs; corbeled hood molds; full-width two-story porch with Tuscan columns; pedimented frontispiece with fluted pilasters; wood panel double entry doors; porte cochere on west wall; one-story wing on east wall.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		24	9	to	24 9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1372
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 702 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot Robert Lindsey S/D (351), City Blk 45, Lt 1 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1373
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 706 Starr Ave. East 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot R Lindsey S/D (351), City Blk 45, Lot 1-A Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1374

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40

Address 2207 Stewart 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Hollywood S/D 283, Block 63, Lot 23 9. Original Use Residence

10. Description _____ Present Use Residence

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1375
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-30
 Address 117 Stone St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Cottage with Garage Apartment

4. Block/Lot Mize S/D (393), City Block 42, Lot 5-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; ell plan; gable roof with extended rafter ends, composition shingles; inset porch with 2 x 4 built-up porch supports; entry door wood paneled with three upper glass lights; windows 1/1 wood double-hung; 2-story garage at rear with apartments above, wood frame with gable roof, composition shingles, 4/1 wood windows.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	14	to	12 14
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1376

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 121 Stone St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

9. Original Use Residence

4. Block/Lot Mize S/D (393), City Block 42, Lot 6-A Present Use Residence

10. Description 1-story frame with bull-nosed siding; gable composition roof with extended rafters and knee braces; windows are 1/1 wood double-hung; inset porch supported by boxed columns on brick piers; brick pier foundation.

11. Present Condition Good; one window closed in.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		12	15	to	12	15
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1377

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-35

Address 124 Stone St. South 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 42, Lot OL 53-B 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt hip roof pierced by one interior chimney stack; windows are 3/1 wood double-hung; inset wood porch supported by boxed columns; foundation skinned with sheet metal; 2 new entry doors; extended rafter ends; garage on north side.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		12	16	to	12 16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1378

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 420 Sunset 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot June C. Harris S/D 254 9. Original Use Residence

Present Use Vacant

10. Description 1-story; wood frame with bull-nosed siding; irregular plan with central hall; brick foundation; gable roofs with hipped roof at porch, composition shingles; gallery porch across south and part of the west facades with turned wood post porch supports, chamfered bay extending onto the porch on the southwest corner; central entry door with glass light, flanked by sidelights and with a transom light above; windows 1/1 wood double-hung and across the front windows with diamond and prism panes in the upper sash, 3 small windows at the front facing gable end;

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 3, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		9	2	to 9	2
Other			9	9	to 9	10
					to	

Continuation sheet

10. secondary porch and entry on the east, another entry on the west.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1379

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 109 Sweet Gum 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Ferguson S/D (195), Block 63, Lot 2 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; hip roof with composition shingles, extended rafter ends, interior brick chimney; inset porch on northwest corner with battered columns over brick pier; windows 4/1 wood double-hung arranged in pairs.

11. Present Condition Good; some alterations at porch.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		18	18	to	18	18
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1380

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s

Address 119 Sweet Gum 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Ferguson S/D (195), Block 63, Lot 3 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces; projecting porch has 2 entry doors; pier and beam foundation; windows are 1/1 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18	19	to	18 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1381
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 401 Sweet Gum 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Ferguson S/D 195, Block 63, Lot 12 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition gable roof; inset porch; windows are 6/6 wood double-hung and jalousie; pier and beam foundation is skirted.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		18	16	to	18	16
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1382
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 405 Sweet Gum 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Ferguson S/D 195, Block 63, Lot 13 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered by aluminum windows, metal porch supports.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1383
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 503 Sweet Gum 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 63, Lot 9-N Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1384
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 700 Sweet Gum 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 63, Lot 11 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan; composition hip-and-gable roof; inset porch; pier and beam foundation is skirted; extended rafter ends; windows are 2/2 aluminum replacement.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18	15	to	18 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1385
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 712 Sweet Gum 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Hollywood S/D (283), Block 63, Lot 10 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered by later additions.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1386
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 721 Sweet Gum 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____

8. Style/Type Bungalow
 9. Original Use Residence

4. Block/Lot Block 63, Lot 9-C Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with 1 exterior chimney on south facade; projecting porch; extended rafter ends; windows are 1/1 wood double-hung; pier and beam foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18	13	to	18 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1387
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 802 Sweet Gum 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 63, Lt 3 Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roof with extended rafter and beam ends, composition shingles; inset porch with corner boxed column; 2 entry doors set at 90 degrees; windows aluminum replacement.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		18		to 18	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1388
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 725 Swift 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Neoclassical

4. Block/Lot Swift 1st Addition (586), City Blk 5, Lt 4 9. Original Use Residence
 Present Use Residence

10. Description 1-story rectangular frame residence with composition shingle hip roof; horizontal bull-nosed siding; 1/1 double-hung windows; hall parlor plan with twin 3-light entry doors; screen doors with spindles; wood porch with box columns wraps two sides of house; gable with twin single-pane windows on tympanum; textured brick piers indicate building may be moved in.

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986.		27	6	to 27	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1389
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1602 John 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1390
 City/Rural Nacogdoches UTM Sector _____
 2. Name H. L. Wade 6. Date: Factual _____ Est. 1930
 Address 2015 Terry 7. Architect/Bulder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Good; altered windows and asbestos siding.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1391
 City/Rural Nacogdoches UTM Sector _____
 2. Name Clara Etter Whitaker 6. Date: Factual _____ Est. 1940
 Address 2209 Terry 7. Architect/Builder _____
 Contractor _____
 3. Owner C. E. Whitaker 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story frame with drop siding; gable composition roof with extended rafter ends; inset porch supported by iron columns 1/1 wood double-hung windows; foundation skirted.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	23	to	34 23
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1392
 City/Rural Nacogdoches UTM Sector _____
 2. Name Christopher 6. Date: Factual _____ Est. 1930s
 Address 2217 Terry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; sheet metal gable roof with extended rafter ends; projecting porch supported by 4 x 4 wood posts; aluminum replacement windows; brick pier foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 34 22 to 34 22
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1393
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 2223 Terry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; irregular plan; brick foundation; gable roof with composition shingles, extended rafter and beam ends; extended porch with metal porch supports; windows 1/1, 6/6 wood double-hung; exterior brick chimney.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	21	to 34	21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1394
 City/Rural Nacogdoches UTM Sector _____
 2. Name Whitaker Grocery 6. Date: Factual _____ Est. 1940
 Address 2307 Terry St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 61 Present Use Commercial
 10. Description 1-story; wood frame with 105 siding; rectangular plan with small addition on northeast corner; gable roof with extended rafter ends, galvanized roofing.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	19	to	34 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1395
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2305 Terry 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; inset porch supported by boxed column; windows are 6/6 wood double-hung; brick pier foundation; entry door is covered with plywood.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: RTHL HABS (no.) TEX- _____ PHOTO DATA
 Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	20	to	34 20
Other					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1396
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 601 Third 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot ADBrewerS/D(78), CityBk 62, Bk 1, Lt 1-A Present Use Residence
 10. Description _____

11. Present Condition Fair - Good; altered by aluminum replacement windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1397

City/Rural Nacogdoches UTM Sector _____

2. Name Johnson Chapel CME 6. Date: Factual 1948-52 Est. _____

Address 608 Third St. 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Eclectic

Address _____ 9. Original Use Church

4. Block/Lot ADHaltomS/D(78), CityBk 62, Bk 2, Lt 2 Present Use Church

10. Description 1-story; hollow clay tile with brick quoining at corners, windows, doors; rectangular plan with side tower; gable roof with pyramidal roof at tower, composition shingles; central entry with double doors; arched windows on east (front) facade; windows horizontal 2/2 wood double-hung; dedication plaque on front; painted dark tan.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____ to _____

_____ to _____

_____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1398
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935-40 (?)
 Address 708 Third 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot ADHaltomS/D(78), CityBk 62, Bk 2, Lt 5A Present Use Vacant
 10. Description _____

11. Present Condition Deteriorated
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1399
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 709 Third 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board and Batten Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot ADHaltomS/D(78), CityBk 62, Bk 1, Lt 5 Present Use Vacant
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1400
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mrs. Mary Hampton (1st Owner) 6. Date: Factual _____ Est. 1930
 Address 1204 Timberlake 7. Architect/Builder _____
 Contractor _____
 3. Owner Betty Gillard 8. Style/Type Bungalow
 Address California 9. Original Use Residence
 4. Block/Lot Block 51, Lot 36-H Present Use Residence
 10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; gable roofs with extended rafter ends, composition shingles; extended porch screened with battered boxed wood columns on brick piers, second porch on east with shed roof resting on brackets; windows 1/1 and 4/1 wood double-hung; detached wood frame garage.

11. Present Condition Fair
 12. Significance Built by Mrs. Mary Hampton, school teacher.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Betty Lathom

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		41	13	to	41	13
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1401
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1222 Timberlake 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot JGOrtonS/D(437), CityBk 51, Bk 5, Lt 2 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; brick pier foundation with skirt of sheet metal; rectangular plan; clipped gable end roof with extended rafter ends, composition shingles; shed roof over porch on north and east supported by plain brackets; wood panel entry door; windows 1/1 and 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		41	14	to	41 14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1402
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1316 Timberlake 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 51, Bk 11, Lt 4 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good; replacement aluminum windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1403
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 1405 Timberlake 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot JGOrtonS/D(437), CityBk 51, Bk 12, Lt 2C Present Use Residence
 10. Description _____

11. Present Condition Fair; altered by asbestos siding and tarpaper foundation skirt.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 9, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1404
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1821, 1823, 1825 Timberlake 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Shotgun

4. Block/Lot JGOrtonS/D(437),CityBk62,Bk24, Lt8,9,9A 9. Original Use Residence
 Present Use Residence

10. Description 3 similar shotgun houses; 1-story wood frame with bull-nosed siding, one with roll composition siding; brick pier; rectangular plan; gable roof with corrugated metal roofing; extended porch with 4 x 4 posts; central door; windows 4/4 wood double-hung.

11. Present Condition Fair - Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1405
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1935-45
 Address 1911 Timberlake 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot JGOrtonS/D(437), CityBk 62, Bk 23, Lt 5 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with composition shingles, extended rafter ends; extended porch cover with 4 x 4 posts; windows 6/6 wood double-hung; carport on south.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1407

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 2002 Timberlake 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot IGOrtonS/D(437), CityBk 62, Bk 18, Lt 2A 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; intersecting gable roofs with extended rafter ends, knee braces, corrugated metal roofing; inset porch with boxed wood columns, wood railing; two wood panel entry doors set at 90 degrees; windows 3/1 wood double-hung; sun porch at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date April 7, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1408
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1308 Tindall 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot BLock 56 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1409
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 120 Travis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
					to	
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1410
City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 203 Travis 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 50 Present Use Residence
 10. Description _____

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ to _____
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1412
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 903 Townsend 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1413
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920
 Address 917 Townsend 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description 1-story frame with lap wood siding; rectangular plan; composition gable roof; windows are 3/1 wood double-hung; pier and beam foundation.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		20	17	to	20 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1414
 City/Rural Nacogdoches UTM Sector _____
 2. Name Nacogdoches Grocery/Rossini's Restaurant 6. Date: Factual _____ Est. 1900
 Address 211 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Commercial
 Address _____ 9. Original Use Warehouse
 4. Block/Lot Block 43, Part of Lot 44 Present Use Restaurant
 10. Description 2-story; load-bearing brick; rectangular plan with one-story addition on southwest; brick foundation; flat roof, raised parapets with inset geometric panels below; modern metal frame canopy on south over aluminum/glass entry; windows -- one 2/2 wood double-hung with arched head, remainder bricked in, on first floor fixed glass windows -- one jack arch above; burglar bars.
 11. Present Condition Good; significantly altered.
 12. Significance Significant older building; however, extensive alterations are not consistent with style.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography 1975 THC Survey
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to 1986 34 3 to 34 3
 _____ to _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1415

City/Rural Nacogdoches UTM Sector _____

2. Name Warehouse behind Rossini's Restaurant 6. Date: Factual _____ Est. 1900-20

Address 211-B Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Stucco Warehouse

4. Block/Lot Block 43 9. Original Use Warehouse

Present Use Warehouse

10. Description 1-story stuccoed building; rectangular plan; composition gable roof; central arched door opening; 2 shuttered windows.

11. Present Condition Fair; stucco is cracked.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		33	23	to	33	23
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1416
 City/Rural Nacogdoches UTM Sector _____
 2. Name Schott Veterinary Hospital 6. Date: Factual _____ Est. 1913
 Address 410 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner Dr. F. J. Schott 8. Style/Type Victorian Cottage
 Address 312 Tyler Road 9. Original Use Residence
 4. Block/Lot Block 43 Present Use Office
 10. Description 1-story frame with lap siding; T-plan; corrugated gable sheet metal roof with cornice returns; brick pier foundation, projecting porch has turned columns, brackets, and frieze; windows are 4/4 wood double-hung with hood molds; entry has sidelights and transom.

11. Present Condition Good - Fair; new foundation.

12. Significance Good example of style.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		33	24	to	33 24
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1417

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1880-1900

Address 411 Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Farmhouse

4. Block/Lot City Block 43 9. Original Use Residence

Present Use Storage

10. Description 2-story; wood frame with lapped board siding; brick pier foundation; rectangular plan with one-story addition at rear; gable roof with sheet metal roofing, exterior brick chimney on south; centered entry door with transom light (broken out); windows 4/4 wood double-hung with hood mold - deteriorated; front facade appears to have originally been one bay with early additions to north and south.

11. Present Condition Severely deteriorated; Poor.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other	1986		34	2	to	34	2
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1418
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 615 Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____

8. Style/Type Bungalow Commercial
 9. Original Use Commercial Gas Station

4. Block/Lot Block 43 Present Use Used Car Sales

10. Description 1-story frame with lapped siding; rectangular plan with projecting service bay; 2 additions at rear; double entry doors; porch has frame plain bannister; composition shingle roof with extended rafter ends; 4/4 and 1/1 double-hung windows with burglar bars.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		34	4	to 34	4
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1419
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 705 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 43 Present Use Residence

10. Description 1-story frame with modern vertical siding; composition clipped gable roof with extended rafter ends; rectangular plan; brick pier foundation; windows are 4/4 wood double-hung; projecting porch supported by boxed columns on brick base.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 34 5 to 34 5
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1420
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900-20
 Address 819 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 47 Present Use Residence

10. Description 1-story frame with lap siding; composition gable roof pierced by two central chimney stacks; extended rafter ends; projecting porch supported by boxed columns; windows are 3/1 wood double-hung; brick foundation piers; garage at rear.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	6	to 34	6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1421
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1401 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence

10. Description 1-story frame with asbestos siding; composition gable roof with extended rafter ends; rectangular plan, inset porch supported by metal columns; windows are 3/1 wood double-hung; foundation skirted.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		34	7	to	34	7
Other				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1422
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 1467 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 47 Present Use _____

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; hip roof with projecting gable over porch, extended rafter ends, composition shingles; wood post porch supports, 2 entry doors; windows 2/2 wood double-hung.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA-
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		34	8	to	34 8
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1423
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1313 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence
 10. Description _____

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DFWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1424

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 1321 Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 47 9. Original Use Residence

10. Description _____ Present Use Residence

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1425
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1415 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Lot 3 Present Use Residence
 10. Description 1-story; wood frame with roll composition siding; hip roof with composition shingles, brick foundation; windows 2/2, 4/4 wood double-hung; extended rafter ends, brackets at roof; metal porch supports.

11. Present Condition _____
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		34	9	to	34	9
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1426
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1507 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 47 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1427
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 1617 Tyler Road 7. Architect/Bullder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; rectangular plan; gable roof with sheet metal roofing, exposed rafter ends, knee braces, exterior brick chimney; inset porch with wood post supports; windows 4/1 wood double-hung with wood trim.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____	1986		34	10	to	34 10
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1428
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mamie's 6. Date: Factual _____ Est. 1900-30
 Address 1717 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition hip-and-gable roof with extended rafter ends and knee braces; inset porch supported by paired Doric columns on brick piers; 1 interior chimney stack; windows are 4/1 wood double-hung; brick pier foundation.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 34 11 to 34 11
 Other _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1429

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 1815 Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 50 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan with addition on east facade; composition gable roof pierced by two dormers; extended rafter ends; replacement aluminum windows; projecting porch supported by metal columns; foundation skirted.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	12	to	34 12
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1430
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1818 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Part of Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1431
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1935
 Address 1819 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; pier foundation; irregular plan; gable roofs with composition shingles, extended rafter ends; inset porch with boxed wood columns; windows 6/6 wood double-hung.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

1986		34	13	to	34	13
Other				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1432
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 1933 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Good; aluminum replacement windows.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1433
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 2119 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 50 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1434
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 2524 Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends and knee braces; 1/1 wood double-hung windows; projecting porch supported by boxed columns; brick pier foundation.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		34	14	to	34	14
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1436
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 2620 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description _____

11. Present Condition Fair; windows altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1437

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-20

Address 0000 Tyler at Loop 224 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow/Farmstead

4. Block/Lot Block 95 9. Original Use Residence/Farmstead

Present Use Residence/Farmstead

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; sheet metal gable roof; 4/4 windows; shed porch with boxed columns; wood frame farm outbuildings with sheet metal roofing and siding.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		34	18	to	34	18
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1438
 City/Rural Nacogdoches UTM Sector _____
 2. Name M. Perry 6. Date: Factual _____ Est. 1920-30
 Address 3219 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; composition roof with clipped gable ends, extended rafter ends and knee braces; projecting porch with metal columns; 1/1 wood double-hung windows.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	15	to	34 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1439
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3306 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence & Farm Complex

10. Description 1-story frame with drop siding; composition gable roof with extended rafter ends and knee braces; wraparound porch supported by boxed columns on piers and bannister; windows are 1/1 wood double-hung; brick pier foundation with skirt; exterior brick chimney; irregular plan; barn at rear.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	16	to 34	16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1440

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 3738 Tyler Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 61 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with vinyl siding; composition gable roof with extended rafter ends and knee braces; projecting porch upheld by boxed columns on brick piers; windows are 3/1 wood double-hung; brick pier foundation.

11. Present Condition Demolished, before photo could be taken.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1441
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930
 Address 3937 Tyler Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 61 Present Use Residence
 10. Description Set back far from road.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1442
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 4029 Tyler Road 7. Architect/Builder _____
 Contractor _____

3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence

4. Block/Lot Block 61 Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan; composition gable roof with extended rafter ends; and knee braces; inset porch supported by 4 x 4 wood posts; windows are 6/6 wood double-hung; brick pier foundation.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		34	17	to	34 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1444
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 511 University St. South (Across from E. J. Campbell Administration Building) 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot _____ Present Use Residence
 10. Description 2-story.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1445
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40s
 Address 3406 Upper Melrose 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Fair; altered windows.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1446
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 3506 Upper Melrose 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1447
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 3522 Upper Melrose 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Board & Batten Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 64 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1448

City/Rural Nacogdoches UTM Sector _____

2. Name Sidnell House 6. Date: Factual _____ Est. 1886

Address 522 Virginia Ave. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type _____

4. Block/Lot Block 35, Lot 17 9. Original Use Residence

Present Use Residence

10. Description 2-story brick; rectangular plan; cedar shake hip roof; windows are 4/4 wood double-hung with segmental arches; 1-story addition at rear; 1 newer exterior chimney on south facade; entry door is recessed; rock fence surrounds the property; symmetrical I-house; load-bearing, attic converted to weight room; wrought iron balcony at primary entry on east facade.

11. Present Condition Good; exterior chimney has been added; addition on north side added seven years ago;

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Surveys, 1975 & 1979.

15. Informant Gregg Goodnight

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		10	15	to	10 15
Other	1986		13	20	to	13 20
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1449

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 523 Virginia 7. Architect/Bullder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 35, Lot 21-B 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with flat bull-nosed siding; rectangular plan; asphalt gable roof with extended rafter ends; windows are 3/1 wood double-hung; 1 central chimney stack; small stoop porch on north facade; surrounded by brick retaining wall.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		10	15	to	10
Other					to	16
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1450
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1985-86
 Address 613 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Style
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 21 Present Use Residence
 10. Description 1-story; appears to be new construction.

11. Present Condition Good
 12. Significance Non-contributing.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		10	12	to	10	12
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1451
 City/Rural Nacogdoches UTM Sector _____
 2. Name June Harris House 6. Date: Factual _____ Est. _____
 Address 612 Virginia 7. Architect/Builder Dietrich Rulfs
 Contractor _____
 3. Owner Tom Davison 8. Style/Type Neoclassical
 Address 612 Virginia 9. Original Use Residence
 4. Block/Lot Block 35, Lot 18 Present Use Residence

10. Description 2-1/2 story; masonry ground floor, wood frame at the piano nobile and above; brick foundation; central hall, irregular plan; cedar shingle hip-and-gable roof pierced by central gable dormer with Palladian-style window; windows are 1/1 and 2/2 wood double-hung; entry seems to have been altered; fishscale shingles in gable; pedimented portico projects from main facade; front lawn slopes dramatically close to street with brick steps set into terrace; wood lap siding.

11. Present Condition Good; some alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography THC Survey, 1975.
 15. Informant _____
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		10	10	to 10	11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1452
 City/Rural Nacogdoches UTM Sector _____
 2. Name Baxter Home 6. Date: Factual 1904 Est. _____
 Address 703 Virginia 7. Architect/Builder Built by the Baxters
 Contractor _____
 3. Owner John Watt 8. Style/Type Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Lot 22 Present Use Residence
 10. Description 2-1/2 story wood frame with bull-nosed siding; brick foundation; T-plan; intersecting gable roofs with painted metal roof, pedimented gable ends with decorative shingle work, Palladian windows on south facade, plain entablature below eaves; one-story porch with cylindrical columns and pilasters, double wood paneled entry doors; windows wood frame 1/1, some with hood mold, shutters on the front; carport on north with gable roof and cylindrical columns, over a low brick wall; interior brick chimney on north with corbeled cap; site slopes away from the
 11. Present Condition Alterations - sunroom over 50 years with knotty pine panel, brick floor, & 1980s
 12. Significance Baxters owned the Baxter Hotel, at site of post office; Baxter Duncan St. was named for them; original woodwork intact, 2 fireplaces; marble countertop from soda fountain in downtown
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant John Watt, 2/17/86
 16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		10	7	to	10	7
				to		
				to		

Continuation sheet

10. street down the hill.
 12. Nacogdoches at the time the house was built; antique light fixtures converted from kerosene to electricity; owners: Baxters, Ray Driver, John Watt.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1453

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 708 Virginia Ave. (Corner of Sunset) 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Style

4. Block/Lot Block 35, Lot 19 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame construction with bull-nosed siding; brick pier foundation with brick infill; irregular plan; hip-and-gable roof with composition shingles, single light windows and fishscale shingles at gable ends; chamfered bay on north; projecting front porch upheld by wrought iron columns with railing; windows 1/1 wood double-hung; 3 interior brick chimneys; front porch altered; screened rear porch; shutters on front facade windows; scrollwork at chamfered bay.

11. Present Condition Good; porch altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		10	8	to 10	9
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1454
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920s
 Address 709 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 35, Block 22-A Present Use Residence

10. Description 1-story frame with lap wood siding; rectangular plan; asphalt gable roof with extended rafter ends and knee braces; eyebrow roof on porch is supported by two Doric columns; 1 exterior brick chimney on north facade; windows are 6/1 wood double-hung; foundation skirted with brick.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DFWR	ROLL	FRME	ROLL	FRME
	1986		10	6	to	10 6
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1455

City/Rural Nacogdoches UTM Sector _____

2. Name Bell /Anderson House 8. Date: Factual _____ Est. 1890-1900

Address 706 Virginia Ave. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian, Queen Anne

4. Block/Lot Block 35, Lot 20 9. Original Use Residence

Present Use Residence

10. Description 2-1/2 story frame with bull-nosed siding; massed plan; hip-and-gable asphalt shingle roof with octagonal turret on northeast corner, roof pierced by 1 corbeled interior chimney; fishscale shingles and roof vents in gables; 1-story porch is supported by slender Doric columns; newel posts and bannisters lead to raised first floor; foundation is brick pier skirted in wood lattice; brackets at cornice on tower and south 1-story wing; window are 1/1 wood double-hung; entry door has leaded glass side lights; cast concrete steps with urns at street entry; large lot with

11. Present Condition Excellent; addition on south end.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography THC Survey, 1975.

15. Informant _____

16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		10	2	to	10	5
Other					to		
					to		

Continuation sheet

10. pine, crape myrtle, and ash trees.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1456
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900
 Address 723 Virginia Ave. 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 35, Lot 24-A 9. Original Use Residence
 Present Use Residence

10. Description 1-story frame with wood lap siding; massed plan with projecting chamfered bay and wraparound frame porch with slender Doric columns on boxed column bases; ornate entry door and screen door; windows are 1/1 wood double-hung with hood molds; hip-and-gable shingle roof pierced by 1 brick stack; brackets and vergeboard in front gable; raised foundation at rear.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		10	00	to	10 00
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1467

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910-30

Address 720 Virginia 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 35, Lot 20-A 9. Original Use Residence

Present Use Residence

10. Description 1-story yellow frame with bull-nosed siding; rectangular plan; asphalt shingle clipped gable roof pierced by one exterior red brick chimney on north facade; windows are 2/2 aluminum single-hung; stoop front porch supported by brackets; extended rafter ends.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 3, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		10	1	to	10	1
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1468
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-25
 Address 1307 / 1309 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Vernacular Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 28-A Present Use Duplex
 10. Description 1-story; wood frame with asbestos siding; wood foundation skirt; rectangular plan; hipped roof with composition shingles; inset porch with boxed wood columns; windows 2/2 aluminum double-hung; 2 entry doors wood paneled; driveway on each side of house with back entry door.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	1	to 11	1
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1469
 City/Rural Nacogdoches UTM Sector _____
 2. Name Darnell 6. Date: Factual _____ Est. 1930s
 Address 1313 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 28 Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1470
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1314 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 31 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1471
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1320 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 32 Present Use Residence
 10. Description _____

11. Present Condition Good; greatly altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1472
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1513 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 6 Present Use Residence

10. Description 1-story frame with bull-nosed siding; rectangular plan; asphalt gable roof; projecting gable front porch supported by boxed columns on brick piers; windows are 1/1 wood double-hung; garage of similar style on east side; extended rafter ends; brick pier foundation.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	2	to 11	2
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1473

City/Rural Nacogdoches UTM Sector _____

2. Name Clevinger 6. Date: Factual 1897 Est. _____

Address 1526 Virginia 7. Architect/Builder George W. Clevinger, Bldr.

Contractor _____

3. Owner Fritz and Bernice Muckleroy 8. Style/Type Victorian

Address _____ 9. Original Use Residence

4. Block/Lot Block 48, Lot 20-B Present Use Residence

10. Description 1-story; wood frame with beveled wood siding; brick foundation; irregular plan; hip-and-gable roofs with pedimented gable ends with wood shingles on the front gable, composition shingles; asymmetrical three-sided porch on southeast corner with pipe column supports, decorative brackets and sawtooth ornamentation; two entry doors set at 90 degrees; one with transom light above, secondary entry at east end of porch; windows 2/2 wood double-hung; chamfered bay on south facade with brackets and finials at the corners. Interior has 14 foot ceilings.

11. Present Condition Good; alterations on interior, chimney removed 1946 and den addition.

12. Significance Three owners of house: Mr. Clevinger, his daughter, his daughter's child.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant Mrs. Bernice Muckleroy, 2/17/86

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s slides

/Thematic /Multiple-Resource 35 mm Negs.

NR File Name YEAR DRWR ROLL FRME ROLL FRME

	1986		11	3	to	11	3
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1474
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1602 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48 Present Use Residence
 10. Description _____

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1475
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1614 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 21-3 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1476
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1615 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Ethel Wallace S/D(620), Block 1, Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 17, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1478
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1625 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 56 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1479

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10

Address 1718 Virginia 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 48, Lot 23-B 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with beveled and bull-nosed siding; brick foundation; ell plan; gable and hipped roof with boxed cornice, galvanized metal roofing, shed roof with tarpaper over porch, slender cylindrical columns with plain capitol and base; entry door wood with three small glass lights (altered); windows 2/2 wood double-hung with half-screens; carport on east.

11. Present Condition Good - Fair (porch roof).

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	25	to	11 25
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1480
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 1815 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 48 Present Use Residence

10. Description 1-story frame with bull-nosed siding; asphalt gable roof with knee braces and extended rafter ends; windows are 4/1 wood double-hung; porch is inset supported by boxed column; brick foundation skirt; garage of similar style on east side.

11. Present Condition Good; few alterations.
 12. Significance Good example of style.
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	20	to 11	20
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1481
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1903 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 48 Present Use Residence
 10. Description _____

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1482
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 1910 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 48 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; sheet metal foundation skirt; ell plan; gable roof with extended rafter and beam ends; inset porch with one turned wood porch support; 2 wood paneled entry doors set at 90 degrees, with screened doors; windows 4/4, 6/6 wood double-hung; frame garage at rear.

11. Present Condition Fair - Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	19	to	11 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1483
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 1923 Virginia 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 60 Present Use Residence
 10. Description _____

11. Present Condition Fair; porch and windows altered.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1484
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 2227 Virginia Ave. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, S/D of Lot 59, Lot 1 Present Use Residence
 10. Description _____

11. Present Condition Good; windows altered.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1485
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 926 Wade 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 47, Part of Lot 14-J Present Use Residence
 10. Description Vinyl siding; yellow.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 24, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1486
 City/Rural Nacogdoches UTM Sector _____
 2. Name Shady Oaks 6. Date: Factual _____ Est. _____
 Address 300 Weaver at Runaway Lane 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Ecclectic
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48 Present Use Residence

10. Description 2-story frame with partial brick veneer and bull-nosed siding; massed plan with 1-story addition and 2-story ceramic tile garage on west facade; windows are 6/6 double-hung and jalousie; asphalt gable roof; older gambrel roof barn on far west facade seems to predate house.

11. Present Condition House - Good; Barn - Poor.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		13	22	to	13	23
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1487

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1900-10

Address 312 Weaver 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Greek Revival

4. Block/Lot Block 48, Lot 2-B 9. Original Use Residence

Present Use Residence

10. Description 1-1/2 story; wood frame with horizontal wood siding; brick foundation; 5-bay central hall plan; intersecting gable roofs with composition shingles, cornice returns; gallery porch across front with boxed wood columns with simple base and capitol, central entry door wood paneled with large glass light with side and transom lights; windows wood frame 1/1 and some 4/4 with hood molds, shutters on the front; plastered exterior brick chimney on the northeast; carport on the northwest; blind pilasters on the building corners.

11. Present Condition Excellent

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides _____
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	21	to	13 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1488

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1890-1900

Address 500 Weaver 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Classical/Victorian Cottage

4. Block/Lot Block 35, Lot 16 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with wood lap siding; massed plan; asphalt hip-and-gable roof; projecting chamfered bay with bargeboard and sunray brackets; inset wraparound porch with brick steps, apron and boxed columns; roof pierced by central corbeled chimney; brick pier foundation skirted with brick infill; windows are 1/1 wood double-hung; entry door is paneled.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA
NR: Individual Historic District B&W 4 x 5s _____ slides
 Thematic Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	17	to 13	18
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1489

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1880-95

Address 521 Weaver 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Victorian Cottage

4. Block/Lot Block 35, Lot 17-A 9. Original Use Residence

Present Use Residence

10. Description 1-story frame with beveled lap siding; massed plan; asphalt hip-and-gable roof pierced by one external corbeled chimney on the west facade; cornice returns; inset porch supported by Doric columns; windows are 2/2 and 6/6 wood double-hung with hood molds; was ell plan before porch was altered.

11. Present Condition Fair - Good; some alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date February 17, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		13	19	to	13 19
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1490
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1910-30
 Address 816 Wells 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 48, Lot 2-B Present Use Residence

10. Description 1-story frame with lap siding, asphalt hip roof with extended rafter ends; inset porch upheld by boxed columns; rectangular plan; windows are 3/1 double-hung; paneled door with three lights; brick pier foundation; skirted.

11. Present Condition Fair to Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date February 18, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		11	21	to	11 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1491

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 1212 Wells 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 56 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; L-plan; clipped gable roof with extended rafter and beam ends, composition shingles; small gable roof over entry with 4 x 4 supports, brackets and chamfered beam ends, central entry door; windows 1/1 wood double-hung; frame car shed at rear.

11. Present Condition Good; roof is in fair-poor condition.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date February 18, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		11	22	to	11	22
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1492

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 121 / 123 Wettermark 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 9. Original Use Residence

Present Use Residence/Duplex

10. Description 1-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; clipped gable roofs with composition shingles, extended rafter ends; 2 porches with segmental arch canopy over wood paneled door, concrete and brick steps; windows 4/1 wood double-hung, generally in pairs.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	15	to	28 15
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1493

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 122 Wethermark 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 9. Original Use Apartments

Present Use Apartments

10. Description 2-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with deep overhang, composition shingles; small covered porch with 4 x 4 post supports, wood entry door with screen door; windows 1/1 wood double-hung; detached garage; car parking in yard; 2 exterior wood frame staircases on east and west.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	16	to 28	16
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1494
 City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30
 Address 129 Wettermark 7. Architect/Builder _____

3. Owner _____ Contractor _____
 Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 50 Present Use Residence/Apartments
 9. Original Use Residence

10. Description 2-story; wood frame with bull-nosed siding; brick foundation; rectangular plan; hip roof with deep eave, scroll brackets, composition shingles; extended one-story porch across front, paired 6x6 posts with mortice and tenon brace resting upon battered stucco piers, cambered arch opening, wood entry door; windows 1/1 wood double-hung; exterior brick chimney on west and east; rock retaining wall at street.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	14	to 28	14
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1495
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 201 Wettenmark 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Apartments
 4. Block/Lot City Block 50 Present Use Apartments
 10. Description _____

11. Present Condition Good; some windows replaced by aluminum single-hung.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1496
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1925-35
 Address 622 Wildwood 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding, brick foundation skirt; gable roof with composition shingles; projecting porch with metal supports; windows 4/1 wood double-hung, arranged in pairs.

11. Present Condition Altered - brick skirt.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		18	20	to	18 20
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1497
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1509 Woden Road 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description _____

11. Present Condition Fair; extensive alterations.
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
 NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
Other _____					to		
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1498
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1715 Woden at Fields St. 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description _____

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1499

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1930s

Address 1609 Woden Road 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 58 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan with addition on west; hip roof with corrugated metal roof; shed roof over porch with paired 2 x 4 supports; entry door wood paneled with upper glass; windows 1/1 wood double-hung arranged in pairs.

11. Present Condition Good - Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	4	to 19	4
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1501
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 1805 Woden 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence

10. Description 1-story frame with bull-nosed siding; composition gable roof with extended rafter ends; inset porch; 1 extended chimney on south facade; windows are aluminum replacement with diamond pattern screens; carport on east facade.

11. Present Condition Good - Fair; many alterations.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		19	5	to	19	5
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1502
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1920-30s
 Address 1900 Woden 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 59 Present Use Residence
 10. Description 1-story frame with bull-nosed siding; composition pyramidal roof with extended rafter ends; windows are 4/4 wood double-hung; rectangular plan.

11. Present Condition Good - Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date April 22, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		19	7	to 19	8
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1503

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1920-30

Address 1910 Woden 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot Block 59 Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; rectangular plan; gable roofs with composition shingles, extended rafter ends; extended porch with metal supports; entry door wood paneled with upper glass; windows 4/4 wood double-hung.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		19	6	to	19	6
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1504
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 2007 Woden 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 58 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date April 22, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1506
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 723 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 66 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1507
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 725 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 71 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1508
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 614 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 58-A West Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1509
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 618 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 58-A East Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1510
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 619 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Neoclassical
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 57-A Present Use Residence
 10. Description _____

11. Present Condition Poor

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
_____					to	
Other _____					to	
_____					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1511
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 704 / 706 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 76 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet _____

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1512

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1910

Address 715 Woods 7. Architect/Builder _____

Contractor _____

3. Owner _____ 8. Style/Type Bungalow

Address _____ 9. Original Use Residence

4. Block/Lot City Block 45, Lot 64 Present Use Residence

10. Description 1-story rectangular frame residence with hip sheet metal roof; horizontal bull-nosed siding; 1/1 double-hung windows; hall parlor plan; shed roofed, poured concrete porch; glass panel and wood entry door.

11. Present Condition Fair

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		8	19	to	8	19
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1513
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. _____
 Address 719 Woods 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 45, Lot 65 Present Use Residence
 10. Description _____

11. Present Condition Poor
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Larry Hodge Date January 8, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1514
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930s
 Address 126 Wortham 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Bungalow
 Address _____ 9. Original Use Residence
 4. Block/Lot City Block 67 Present Use Residence
 10. Description _____

11. Present Condition Altered with brick veneer.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____					to	
					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1515

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 203 Zeno 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 67 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with bull-nosed siding; brick pier foundation; irregular plan; gable roofs with extended rafter and beam ends, composition shingles, brick chimney on northwest corner; extended porch with boxed wood columns over brick piers, 2 wood panel doors, with upper glass, set at 90 degrees; screen doors; windows 1/1 wood double-hung, in pairs; detached wood frame garage in poor repair.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		27	17	to	27 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1516

City/Rural Nacogdoches UTM Sector _____

2. Name Harris 6. Date: Factual _____ Est. 1930-40

Address 206 Zeno 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot City Block 67 9. Original Use Residence w Large Barnlike Garage

Present Use Residence w Large Barnlike Garage

10. Description 1-1/2 story; wood frame with beveled siding; brick foundation skirt; rectangular plan; massive gable roof with extended rafters, composition shingles, dormer on north, brick chimney at house/garage junction; small inset porch with brick piers, wood pilasters flanking wood panel door; windows 6/6, 8/8 wood double-hung, windows inset at east gable ends, windows have drip cap; garage on west very large yard.

11. Present Condition Good; altered: appears barn/garage was attached to main house by infill construction.

12. Significance Could be a historic farmstead.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 19, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- PHOTO DATA
NR: Individual Historic District B&W 4 x 5s slides
 Thematic Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		27	16	to	27	16
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1517
 City/Rural Nacogdoches UTM Sector _____
 2. Name L. E. Griffith, Jr., Fine Arts Building 6. Date: Factual 1958 Est. _____
 Address Stephen F. Austin University 7. Architect/Builder _____
 Contractor _____
 3. Owner Stephen F. Austin University 8. Style/Type Art Moderne Influence
 Address _____ 9. Original Use Educational
 4. Block/Lot _____ Present Use Educational
 10. Description _____

11. Present Condition Good; currently being renovated.
 12. Significance Good example of architectural style. Even though the structure is only 28 years old, it is significant. The style and scale are important to the overall campus plan and architecture.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

				to		
				to		
				to		

Continuation sheet
 12. Renovations should be sensitive and consistent with the architectural style.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1518
 City/Rural Nacogdoches UTM Sector _____

2. Name Administration Building 6. Date: Factual 1922 Est. _____
 Address Stephen F. Austin University 7. Architect/Builder W. E. Ketchum

3. Owner Stephen F. Austin University Contractor E. A. Mote
 Address _____ 8. Style/Type Classical Revival

4. Block/Lot _____ 9. Original Use Educational
 Present Use Educational

10. Description 3-story brick veneer with limestone trim, carved limestone string course at basement, first floor, and cornice; raised entry on second floor has entablature with massive Doric columns; windows are in twos and threes, 1/1 wood double-hung defined by Doric pilasters; ornamental brickwork on first floor; entry is recessed with modern aluminum doors.

11. Present Condition Good; some windows are bricked in.

12. Significance Constructed during term of Governor Pat M. Neff. Consistant with style and scale of original campus buildings.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		16	8	to 16	13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1519
 City/Rural Nacogdoches UTM Sector _____
 2. Name Thomas J. Rusk Building 6. Date: Factual 1925 Est. _____
 Address Stephen F. Austin University 7. Architect/Builder W. E. Ketchum
 Contractor F. A. Mote
 3. Owner Stephen F. Austin University 8. Style/Type Classical Revival
 Address _____ 9. Original Use Educational
 4. Block/Lot _____ Present Use Educational
 10. Description 3-story brick veneer with carved limestone trim; raised entry is on second floor, pedimented entablature with massive Doric columns; carved limestone string course at basement, second floor, and cornice; 1/1 double-hung windows are arranged in twos and threes, defined by Doric pilasters; carved limestone decorations at each end; entry doors are recessed behind arched entryway; openings at first floor have been bricked in; Texas star wreath in laurel is carved limestone ornamentation above entry.
 11. Present Condition Good; alterations are minimal.
 12. Significance Good example of style. Consistant with style and scale of original campus buildings.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		16	4	to 16	7
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1520
 City/Rural Nacogdoches UTM Sector _____

2. Name Chemistry Building 6. Date: Factual _____ Est. Late 1930s
 Address Stephen F. Austin University 7. Architect/Builder _____

3. Owner Stephen F. Austin University Contractor _____
 Address _____ 8. Style/Type Classical Revival

4. Block/Lot _____ 9. Original Use Educational
 Present Use Educational

10. Description 3-story brick veneer; rectangular plan; 3-story carved limestone pedimented entry with arched opening, modern aluminum doors; windows are 8/8 aluminum replacement with flat keyed arch or round keyed arch; limestone waterable course at basement, first floor, and cornice; pedimented entry has paired Corinthian pilasters flanking balconette; entry arch is keyed with carved figure; handicap access on main facade.

11. Present Condition Good; alterations include entry doors, windows, handicap ramp; some windows bricked.

12. Significance Good example of style, despite changes to windows. Consistant with style and scale of original campus buildings.

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		16	1	to 16	3
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1521
 City/Rural Nacogdoches UTM Sector _____
 2. Name Old Stone Fort 6. Date: Factual Reerected 1936 Est.
 Address Stephen F. Austin University 7. Architect/Builder H. B. Tucker
 Contractor H. C. Hatchl
 3. Owner Stephen F. Austin University 8. Style/Type I-house
 Address _____ 9. Original Use Fort
 4. Block/Lot _____ Present Use Museum
 10. Description 2-story native rock; gable cedar shake roof; 2-story gallery supported by boxed columns across main facade; windows are double-hung, deepset with shutters; two interior brick chimneys; rusticated quoins; exterior frame stairway on east facade.

11. Present Condition Good; altered.

12. Significance Built in 1778; re-erected in 1936. Currently a Recorded Texas Historic Landmark.

13. Relationship to Site: Moved Date 1936 Original Site was on Main Street in downtown Nacogdoches.

14. Bibliography 1970 THC Survey

15. Informant _____

16. Recorder Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____

Old THC Code _____

/RTHL /HABS (no.) TEX- _____

PHOTO DATA

NR: /Individual /Historic District

B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource

35 mm Negs. _____

NR File Name _____

YEAR DRWR ROLL FRME

ROLL FRME

Other _____

1986		16	14	to	16	17
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1522
 City/Rural Nacogdoches UTM Sector _____
 2. Name 900 East Main St. Bridge 6. Date: Factual _____ Est. 1940s
 Address Lanana Creek 7. Architect/Builder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Reinforced Concrete
 Address _____ 9. Original Use Bridge
 4. Block/Lot Block 19 Present Use Bridge
 10. Description Single span reinforced concrete bridge; seven support piers into creek bed; decorative concrete and iron railing, two lanes of traffic.

11. Present Condition Good
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	11	to	30 11
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1523
 City/Rural Nacogdoches UTM Sector _____
 2. Name Banita Creek Bridge 6. Date: Factual 1939 Est. _____
 Address 100 South Street 7. Architect/Builder J. Montgomery, Hwy Eng.
 Contractor Gage Bros. & FMReeves & Sons
 3. Owner _____ 8. Style/Type _____
 Address _____ 9. Original Use Bridge
 4. Block/Lot Block 24 Present Use Bridge

10. Description Single-span reinforced concret bridge over Banita Creek and railyard; original portion on east side, expansion on west side; older side has concrete and steel decorative railing; approximately 20 supporting piers; four lanes of traffic with median; decorative lamp posts on concrete bases.

11. Present Condition Good; new addition on west side.
 12. Significance Built by the Texas Highway Department and United States Bureau of Public Roads.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		39	15	to	39	15
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1524
 City/Rural Nacogdoches UTM Sector _____
 2. Name _____ 6. Date: Factual _____ Est. 1930-40
 Address 923 Main St. East (parallel to University) 7. Architect/Bullder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Three Cottages
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 54 Present Use Rental Residence
 10. Description 1-story; wood frame with 105 board siding; rectangular and U-plan; gable roofs with extended brackets, composition shingles; extended entry; windows 6/6 wood double-hung; attached garage; arranged perpendicular to East Main.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site Possibly _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		30	12	to	30	12
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1525

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. 1925-35

Address 1005 Main St. East (Behind Paradise Florist) 7. Architect/Bullder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Bungalow

4. Block/Lot Block 54 9. Original Use Residence

Present Use Residence

10. Description 1-story; wood frame with horizontal board siding; irregular plan; brick foundation; gable roofs with boxed cornice, composition shingles, exterior brick chimney; small porch with concrete steps; windows 4/1, 6/6 wood double-hung.

11. Present Condition Good

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
NR: /Individual /Historic District B&W 4 x 5s slides
/Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		30	13	to	30 13
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1526
 City/Rural Nacogdoches UTM Sector _____
 2. Name Pecan St. Bridge 6. Date: Factual _____ Est. 1941
 Address Over Banita Creek 7. Architect/Builder A. D. Muckleroy, Engineer
 Contractor E. B. Haley, Const. Supt.
 3. Owner _____ 8. Style/Type Reinforced Concrete Bridge
 Address _____ 9. Original Use Bridge
 4. Block/Lot Block 23 Present Use Bridge
 10. Description Single span reinforced concrete bridge over Banita Creek; reinforced concrete bannister railing; 2 supporting piers into creek bed.

11. Present Condition _____
 12. Significance Built by the City of Nacogdoches and the Works Projects Administration, 1938-40.
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor Date March 24, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to _____
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1527

City/Rural Nacogdoches UTM Sector _____

2. Name _____ 6. Date: Factual _____ Est. _____

Address 304 North St. 7. Architect/Builder _____

3. Owner _____ Contractor _____

Address _____ 8. Style/Type Vernacular Victorian Cottage

4. Block/Lot Block 2, Lot 27-2 9. Original Use Residence

Present Use Vacant

10. Description 1-1/2 story; wood frame with horizontal board siding; rectangular plan; gallery porch across front with 4 x 4 wood posts and plain wood railing; gable roof in poor repair with two hipped dormers on front (west); windows 2/2 wood double-hung with hood mold, shuttered on front; two entry doors side by side, wood paneled.

11. Present Condition Fair - Poor; roof and eaves deteriorated, rest of house is fair.

12. Significance _____

13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		28	23	to	28	23
					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1528
 City/Rural Nacogdoches UTM Sector _____
 2. Name Drapemaster 6. Date: Factual _____ Est. 1910-25
 Address 305 North St. 7. Architect/Bulder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Early 20th Century Commercial
 Address _____ 9. Original Use Commercial
 4. Block/Lot Block 1, Lot 36-C Present Use Commercial

10. Description 1-story; load-bearing brick; rectangular plan; flat roof with parapet, stepped on sides to the rear; suspended wood canopy over wood frame display windows; central double door entry, wood panel door with upper glass lights; louvered transom above doors.

11. Present Condition Fair
 12. Significance _____
 13. Relationship to Site: Moved Date _____ Original Site XX

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		28	21	to	28 21
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1529
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mize Bros. Manufacturing Co. 6. Date: Factual _____ Est. 1940
 Address 412 North St. 7. Architect/Bullder _____
 Contractor _____
 3. Owner _____ 8. Style/Type Art Moderne
 Address _____ 9. Original Use Manufacturing Facility
 4. Block/Lot Block 2, Lot 23 Present Use Manufacturing Facility
 10. Description 2-story; load-bearing masonry; brick foundation; rectangular plan; flat roof with parapet, stone coping; 3-bay front facade, 8-bay side facade; facades are broken up by "Chicago style" steel windows, multipaned with operable awning sash, (1) on west (front) by alternating bands of brick coursing, 3 stretcher courses to one header course (English bond), and central entry; (2) on north (side) by alternating pilasters and bays of windows. Front corners of the building are accented by a fluted effect of vertical alternating header and stretcher courses. The front
 11. Present Condition Good
 12. Significance Architectural.
 13. Relationship to Site: Moved Date _____ Original Site XX
 14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor Date January 21, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA _____
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		28	20	to	28	20
				to		
				to		

Continuation sheet

10. facade is balanced with four sets of windows on either side of the slightly extended entrance. The parapet steps up above the entrance, four narrow columns of raised header brick flanked by horizontal louvers terminated above a suspended metal entry canopy; a centered wood panel and glass entry door with narrow side lights is flanked by square windows; MIZE BROS. MANUFACTURING CO. is across the front in large blue enamel letters. The front lawn has large oaks; a narrow service drive on the north leads to a loading dock with a "car siding" door and a side entry. Both entries have a suspended metal canopy with ornamental hook plates in the wall.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1531

City/Rural Nacogdoches UTM Sector _____

2. Name Watkins Whitehead House 6. Date: Factual _____ Est. 1830

Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____

3. Owner Mrs. Albert Thomas Contractor _____

Address _____ 8. Style/Type Log House

4. Block/Lot Block 71, Lot 7-4 9. Original Use Residence

Present Use Museum

10. Description 1-story log; cedar shake gable roof; shed porch upheld by chamfered columns; two symmetrical exterior rock chimneys at either end; windows are 4/4 double-hung; porch has new bannister; currently part of a historic village complex; chinking is modern mortar; exterior covered with weatherboard.

11. Present Condition Good; alterations include reconstructed chimneys, foundation, plumbing, kitchen, and

12. Significance Alterations and new setting decrease the architectural and historic integrity of the structure.

13. Relationship to Site: Moved Date 1972 Original Site Moved from Watkins

Farm in northwest Nacogdoches County.

14. Bibliography THC Survey, 1975

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides _____

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name YEAR DRWR ROLL FRME ROLL FRME

Other	1986		14	0	to	14	1
					to		
					to		

Continuation sheet

11. porch bannister.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1532
 City/Rural Nacogdoches UTM Sector _____
 2. Name Burrows - Millard - Muckleroy House 6. Date: Factual _____ Est. 1840
 Address Millard's Crossing, 6020 North Street 7. Architect/Bulder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Vernacular Hall & Parlor
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 71, Lots 7-2 Present Use Museum

10. Description 1-story; wood frame wih board siding; rectangular plan, 5-bay with central entry, a dogrun house configuration; side-facing gable roof with wood shingles; brick chimney at each end; porch across front with square wood porch supports, central entry door; windows wood double-hung, 9/6 lights.

11. Present Condition Good; alterations include reconstructed chimneys and foundation.
 12. Significance Early structure in the county; architectural and historic context of the structure have been decreased by relocation.
 13. Relationship to Site: Moved Date _____ Original Site From rural area 4 miles north of Nacogdoches.

14. Bibliography THC Survey, 1975
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		14	4	to 14	5
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1533

City/Rural Nacogdoches UTM Sector _____

2. Name First Methodist Parsonage 6. Date: Factual _____ Est. 1900

Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____

3. Owner Mrs. Albert Thomas Contractor _____

Address _____ 8. Style/Type Victorian

4. Block/Lot Block 71, Lots 7-1 9. Original Use Residence

Present Use Museum

10. Description 1-story frame with central hall plan; composition shingle gable roof with cornice returns, interior central chimney stack is brick; windows are 4/4 and 6/6 double-hung; projecting porch has ornamental bannisters, frieze, and brackets, addition at rear; site is surrounded by picket fence; modern wood paneling throughout interior.

11. Present Condition Good; alterations include new foundation, kitchen, and bath; extensive alterations on

12. Significance First Methodist Parsonage originally located on Washington Square; good example of style; alterations and new setting decrease the architectural and historic integrity of the structure.

13. Relationship to Site: Moved Date 1967 Original Site Moved from Washington Square in Nacogdoches.

14. Bibliography THC Survey, 1975

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
/Individual /Historic District B&W 4 x 5s _____ slides
/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
Other _____	1986		14	2	to 14	3
					to	
					to	

Continuation sheet

11. interior.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1534

City/Rural Nacogdoches UTM Sector _____

2. Name Millard - Lee House 6. Date: Factual _____ Est. 1837

Address Millard's Crossing, 6020 North Street 7. Architect/Bullder _____

Contractor _____

3. Owner Mrs. Albert Thomas 8. Style/Type I-House

Address _____ 9. Original Use Residence

4. Block/Lot Block 71, Lot 7-3 Present Use Museum

10. Description 2-story; wood frame with horizontal board siding; central hall rectangular plan; side-facing gable and shed roofs over first floor, wood shingles, brick chimney at each end; windows 9/6 and 6/6 wood double-hung; porch across front with square posts, entry doors double wood paneled, side and transom lights.

11. Present Condition Good; early additon at rear, possibly expanded porch, alterations - new chimney and

12. Significance Built by the Nacogdoches Merchant-Postmaster; later (1859-1960) owned by the David Lee Family; now part of a historic village complex; architectural and historic context decreased by

13. Relationship to Site: Moved Date 1970 Original Site From near Nacogdoches
Town Square. _____

14. Bibliography THC Survey, 1975, RTHL file

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA

NR: /Individual /Historic District B&W 4 x 5s _____ slides

/Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME

Other _____	1986		14	8	to	14	9
					to		
					to		

Continuation sheet

11. foundation. 12. relocation.

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1535
 City/Rural Nacogdoches UTM Sector _____
 2. Name Watkins House 6. Date: Factual _____ Est. 1895
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 71 Present Use Museum
 10. Description 1-story; wood frame with lapped board siding; concrete pier; ell plan; intersecting gable roofs; chamfered bay on front; shed roof over porch, turned wood porch supports with railing.

11. Present Condition Good

12. Significance Now a part of a historic village complex; architectural and historical context decreased by relocation.

13. Relationship to Site: Moved Date _____ Original Site _____

14. Bibliography _____

15. Informant _____

16. Recorder Dorothy Victor, Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s slides
 /Thematic /Multiple-Resource 35 mm Negs.

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		14	17	to	14 17
Other					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1536
 City/Rural Nacogdoches UTM Sector _____
 2. Name Railroad Caboose 6. Date: Factual _____ Est. _____
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Railroad Car
 Address _____ 9. Original Use Railroad Caboose
 4. Block/Lot Block 71 Present Use Museum
 10. Description 1-story frame railroad caboose with second-story observation cupola; rectangular plan; cambered roof; new square windows with fixed lights.

11. Present Condition Good; windows added.
 12. Significance Good example of style.
 13. Relationship to Site: Moved Date Unknown Original Site

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		14	25	to	14 25
Other	1986		15	1	to	15 2
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1537
 City/Rural Nacogdoches UTM Sector _____
 2. Name Ingram - Gaston House 6. Date: Factual _____ Est. 1900
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Victorian
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 71, Lot 7-6 Present Use Residence
 10. Description 1-1/2 story; wood frame with horizontal board siding; brick foundation; irregular plan; intersecting gable roofs with pedimented gable ends, composition shingles, bargeboards; extended front porch with boxed columns and ornamental brackets; 1/1 wood double-hung windows, on south side with transom; single entry door with beveled leaded glass side lights and transom; brick chimney at rear.
 11. Present Condition Good; altered, combination of two houses in altered configuration.
 12. Significance Part of a historic village complex; alterations and new setting decrease the architectural and historic integrity.
 13. Relationship to Site: Moved Date _____ Original Site North Street, Nacogdoches

14. Bibliography THC Survey, 1975.
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		15	7	to	15	9
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1538
 City/Rural Nacogdoches UTM Sector _____
 2. Name Double Corn Crib 6. Date: Factual _____ Est. 1860s
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Farm Building
 Address _____ 9. Original Use Corn Crib
 4. Block/Lot Block 71, Lot 7-5 Present Use Museum
 10. Description 1-story log; rectangular plan; gable cedar shake roof; logs are round with V-notch; foundation is log sill on stones; mortar chinking; currently part of a historic village complex.

11. Present Condition Good; alterations include foundation, addition on east facade, new roof.
 12. Significance Good example of farm building; alterations and new setting decrease the architectural and historical integrity of the structure.
 13. Relationship to Site: Moved Date _____ Original Site Moved from Millard Farm north of present site; in Nacogdoches County.
 14. Bibliography THC Survey, 1975.
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		14	6	to	14	7
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1539
 City/Rural Nacogdoches UTM Sector _____
 2. Name Millard's Crossing Office 6. Date: Factual _____ Est. _____
 Address Millard's Crossing, 6020 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Log Cabin
 Address _____ 9. Original Use _____
 4. Block/Lot Block 71 Present Use Office
 10. Description 1-story log with gable cedar shake shingles.

11. Present Condition Good; extensively altered.
 12. Significance Now part of a historic village complex; architectural and historical context decreased by relocation.
 13. Relationship to Site: Moved _____ Date Unknown Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Dorothy Victor, Sally Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRAME ROLL FRAME
 Other _____ 1986 _____ 14 10 to 14 11
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1540
 City/Rural Nacogdoches UTM Sector _____
 2. Name Methodist Church 6. Date: Factual _____ Est. 1843
 Address Millard's Crossing, 6020 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Folk Vernacular
 Address _____ 9. Original Use Church
 4. Block/Lot Block 71 Present Use Museum/Church
 10. Description 1-story wood frame, rectangular plan; washboard siding; 1/1 wood double-hung; chamfered columns on front porch; cedar shake gable roof; concrete pier foundation; interior back wall was torn out.

11. Present Condition Good; altered.

12. Significance Free Methodist Church from Sacal area; now part of a historic village complex; architectural and historical context decreased by relocation.

13. Relationship to Site: Moved Date _____ Original Site Sacal area.

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

NR: /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME	ROLL	FRME
	1986		14	12	to 14	13
Other _____					to	
					to	

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1541
 City/Rural Nacogdoches UTM Sector _____
 2. Name Log School 6. Date: Factual _____ Est. _____
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Log House
 Address _____ 9. Original Use School
 4. Block/Lot Block 71 Present Use Museum
 10. Description 1-story log, rough-dressed on interior with V-notch; mortar chinking; log sill on stone foundation; gable roof with shake shingles; central doorway.

11. Present Condition Good; altered.
 12. Significance Now a part of a historic village complex; architectural and historical context decreased by relocation.
 13. Relationship to Site: Moved Date Unknown Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name _____ YEAR DRWR ROLL FRME ROLL FRME
 Other _____

1986		14	14	to	14	15
				to		
				to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1542
 City/Rural Nacogdoches UTM Sector _____
 2. Name Albert Thomas Museum 6. Date: Factual _____ Est. _____
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Log Dogtrot
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 71 Present Use Museum
 10. Description 1-story log; gable cedar shake roof; rock exterior chimneys at either end.

11. Present Condition Good; altered.

12. Significance Will house the papers and memorabilia of Congressman Albert Thomas; now a part of a historic village complex; architectural and historical context decreased by relocation.

13. Relationship to Site: Moved Date Unknown Original Site

14. Bibliography _____

15. Informant _____

16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS : TNRIS No. _____

Old THC Code _____

RTHL HABS (no.) TEX- _____ PHOTO DATA

NR: Individual Historic District B&W 4 x 5s _____ slides _____

Thematic Multiple-Resource 35 mm Negs. _____

NR File Name _____

YEAR DRWR ROLL FRME ROLL FRME

1986		14	18	to	14	19
				to		
				to		

Other _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1543
 City/Rural Nacogdoches UTM Sector _____
 2. Name Carriage House 6. Date: Factual _____ Est. 1910-13
 Address Millard's Crossing, 6020 North Street 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Bungalow
 Address _____ 9. Original Use Carriage House
 4. Block/Lot Block 71 Present Use Museum
 10. Description 1-story frame with extended rafter ends; bull-nosed siding.

11. Present Condition Good; altered.
 12. Significance Now a part of a historic village complex; architectural and historical context decreased by relocation.
 13. Relationship to Site: Moved Date _____ Original Site Moved from 1411 North Street; Hayter House.

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____

/RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides
 /Thematic /Multiple-Resource 35 mm Negs. _____

NR File Name	YEAR	DRWR	ROLL	FRME		ROLL	FRME
	1986		14	20	to	14	22
Other					to		
					to		

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1544
 City/Rural Nacogdoches UTM Sector _____
 2. Name Mercantile Store 6. Date: Factual _____ Est. _____
 Address Millard's Crossing, 6020 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Vernacular Commercial
 Address _____ 9. Original Use Country Store
 4. Block/Lot Block 71 Present Use Museum
 10. Description 1-story frame with board and batten siding; gable roof with wood shake shingles; 6/6 windows; central double paneled doors; stepped parapet on roof; corn crib on end.

11. Present Condition Good; altered.
 12. Significance Now a part of a historic village complex; architectural and historical context decreased by relocation.
 13. Relationship to Site: Moved Date Unknown Original Site _____

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 Other _____ to 15 4
 _____ to _____
 _____ to _____

Continuation sheet

1. County Nacogdoches 5. USGS Quad No. _____ Site No. 1545
 City/Rural Nacogdoches UTM Sector _____
 2. Name Red House 6. Date: Factual _____ Est. _____
 Address Millard's Crossing, 6020 North St. 7. Architect/Builder _____
 Contractor _____
 3. Owner Mrs. Albert Thomas 8. Style/Type Victorian Cottage
 Address _____ 9. Original Use Residence
 4. Block/Lot Block 71 Present Use Residence
 10. Description 1-story frame; ell plan; gable roof; porch has gingerbread trim.

11. Present Condition Good; altered.
 12. Significance Now a part of a historic village complex; architectural and historical context decreased by relocation.
 13. Relationship to Site: Moved Date _____ Original Site from Marshall, Texas.

14. Bibliography _____
 15. Informant _____
 16. Recorder Sally Victor, Dorothy Victor Date March 12, 1986

DESIGNATIONS: TNRIS No. _____ Old THC Code _____
 /RTHL /HABS (no.) TEX- _____ PHOTO DATA
 NR: /Individual /Historic District B&W 4 x 5s _____ slides _____
 /Thematic /Multiple-Resource 35 mm Negs. _____
 NR File Name YEAR DRWR ROLL FRME ROLL FRME
 _____ 1986 _____ 15 5 to 15 6
 Other _____ to _____
 _____ to _____

Continuation sheet