City of Nacogdoches Historic Survey Form New New Delete Find

Thew Delete Thid	
Name jms_519 E. Hospital	Commercial Types Non-House Date/Vernacular Date
Address 519 E. Hospital Recorded by Misty Date Surveyed 8/2/2011 Overall Condition	□ One-Part C. Block □ Temple Front □ 1. 1820-1865 □ Two-Part C. Block □ Temple Front □ 2. 1865-1900 □ Enframed Window Wall □ Enframed Block □ 3. 1900-1929 □ Stacked Vertical Block □ Central Block with Wings □ 4. 1929-1945 □ Two-Part Vertical Block □ Arcaded Block □ 5. 1945-1980 □ Three-Part Vertical Block □ Mix □ 6. 1980-today
Roof Type Gable Shed Dormers - Gable Hipped Flat Dormers - Hipped Gambrel Other Dormers - Shed	Agricultural
Roof Materials ☐ Wood shingles ☐ Tile ☐ Other ☐ Composition shingles ☐ Metal	Domestic Parks/Gardens/Plantings Educational Petroleum Local Marker Recreational/Cultural Hall-and-parlor (1story) Gable-front-and-wing (1) Gable front (2 story)
Roof Condition Excellent Good Fair Poor Bad Wall Facade	Shotgun (1 story)
Stucco Other Number of bays Stone Vinyl Siding Terracota Brick Fieldstone V. Awning(s) Log Wood Siding Metal Wood Shingle	01. Sp. Colon. 1565-1821
Numbers of bays 1 2 3 4 5 Other	05. Italianate 1840s-80s 18. Mission 1890-1920 30. Lg. Ranch 1946-1980 06.2nd Empire 1850s-1880s 19. Pueblo Rev 1910-today 31. Split-L 1955-1980 07. Stick Style 1860s-80s 20. Sp. Eclectic 1915-40 32. Contemp. 1940-1980 08. Q. Anne 1880-1910 21. Monterey 1925-1955 33. Shed 1960-today 09. Shingle 1880-1900 22. Prairie 1900s-1920s 34. Neoeclect 1965-today
Wall Condition ☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Bad	☐ 10. RRoman R 1870s-1890s ☐ 23. Craftsman 1900-1930 ☐ 36. Prefab H 1940s-1950s ☐ 24. Fireproof H 1900s-30s ☐ 37. Mobile H 1945-today ☐ 12. Col. Rev. 1880s-1955 ☐ 25. Moderne 1920-1940 ☐ 13. Neoclassical 1885-40s ☐ 26. Art Deco 1920-1940